




1490 Santa Clara Street Santa Clara, CA 95050 408.564.5943 mayer robert@com cast net DEMOLITION PLAN GENERAL NOTES DEMOLITION LEGEND ATENTIONAL MORREST THIS IS A HISTORIC STRUCTURE RECOVERED BY THE CITY AS A HISTORIC SECONDATE OF THE CITY AS A HISTORIC RESOURCE AND MODERN THE CITY AS A HISTORIC RESOURCE AND MODERN THE CITY AS A HISTORIC RESOURCE AND THE STRUCTURE. PROUR TO COMMENCEMENT OF WORK ALL WORKSTER MADE THE CITY AND THE CITY WALL TO REMAIN WALL TO REMOVE - ITEM TO REMAIN ----- ITEM TO REMOVE ROBERT MAYER GOLD RAVIERENI.

GENERAL CONTRACTOR SHALL: EXERCISE REASONABLE PRECUMON IN THE PROTEIN CONTRACTOR STANDARD PROBLEMS PRECUMON IN THE PROTEIN CONTRACTOR STANDARD PROBLEMS FOR SHALL PROBLEM STANDARD PROBLEMS CONTRACTOR AND CONTRACTOR AND THE PROBLEMS CONTRACTOR AND CONTRACTOR STANDARD CONTRACTOR STANDARD PROBLEMS FOR SHALL PROBLEMS FOR SHALL PROBLEMS FOR SHALL PROBLEMS FOR THE MANUAL PROBLEMS FOR SHALL PROBLEMS 324 MADISON STREET SANTA CLARA, CA 95050 APN: 28941-030 ADDITION & REMODEL TO THE RESIDENCE AT: HATCH DENOTES RETAINING WALL, TYP. (E) CRAWLSPACE (E) F.A.U. (E) CONCRETE BATTERED FOUNDATION, TYP. BASEMENT DEMOLITION

A2.1














EXTERIOR MATERIA	M S	
FEATURE	DESCRIPTION AND CONDITION	TREATMENT
ROOFING	ORIGINAL INTERLOCKING TERRA-COTTATILE ROOFING IN GREAT CONDITION AND IS A CHARACTER-DEFINING FEATURE OF THIS HOUSE. THERE ARE SOME BROKEN TILES AT THE REAR ROOF PLANE.	I REAL MENT EXISTING ROOFING TO REMAIN WITH ALL ROOF ADDITIONS TO USE THE SAME ROOFING MATERIAL SALVAGED FROM ANOTHER HOME IN THE CITY. EXISTING BROKEN ROOF TILES WILL BE REPLACED WITH SALVAGED MATCHING ROOF TILE.
STUCCO WALL FINISH	THE ORIGINAL TEXTURED STUCCO FINISH IS IN GOOD CONDITION AND IS A CHARACTER DEFINING FEATURE. THIS INCLUDES THE STUCCO CORBELS AT THE ENTRY PORCH COLUMNS.	THE STUCCO IS TO REMAIN EXCEPT WHERE WINDOWS ARE TO BE RELOCATED OR REMOVED. ALL SURFACE CRACKS SHALL BE CAULKED AND THE ENTIRE HOUSE WILL BE REPAINTED.
	STUCCO AT BRICK CHIMNEY ON RIGHT SIDE OF LIVING ROOM IS EXPERIENCING SOME CRACKING DUE TO THE FIREPLACE SETTLING.	THE BRICK CHIMENY IS TO BE STABILIZED AND THE STUCCO IS TO BE CAREFULLY PATCHED TO MATCH EXISTING.
GUTTERS & DOWNSPOUTS	NON-ORIGINAL METAL OGEE GUTTERS WITH RECTANGULAR METAL DOWNSPOUTS ARE IN FAIR CONDITION AND ARE NOT A CHARACTER-DEFINING FEATURE.	NEW METAL OGEE GUTTER TO BE INSTALLED AT THE EXISTING AND NEW ROOFS WITH ROUND RAIN WATER LEADER / DOWNSPOUTS.
EXTERIOR WALL CLADDING AND TRIM	MAIN RESIDENCE: THE ORIGINAL STUCCO SIDING IS IN GOOD CONDITION AND IS A CHARACTER-DEFINING FEATURE.	THE ORIGINAL STUCCO SIDING IS PROPOSED TO BE PRESERVED EXCEPT FOR WHERE IT WILL BE REMOVED FOR RELOCATION OF WINDOWS OR WHERE COVERED BY THE ADDITION. OR GREAT CARE SHOULD BE TAKEN TO REMOVE AS LITTLE STUCCO AS REQUIRED. STUCCO SHALL BE PATCHEN AND MATCH THE EXISTING TEXTURE, BUT IT IS LIKELY THAT FERTOH WILL BE VISIBLE INDICATING THAT AN ALTERATION WAS MADE TO THE ORIGINAL STUCCO.
WANDOWS AND TRIM	FRONT ELEVATION: TWO THERMAN, WICHO TRIPARTITE WINDOWS CONSISTING OF TWO DOUBLE-HAINING WINDOWS FLANIONG A FIXED WINDOW ARE ALL IN GOOD CONDITION. THE WINDOWS ARE A CHARACTER-DEFINION FEATURE IN THEIR ENTIRETY BUT ALSO A REPETITIVE HISTORIC FEATURE.	THESE WINDOWS (SASH TRIM PULLEYS, WEIGHTS) TO REMAIN IN SITU AND ARE PROPOSED TO BE PRESERVED. WHERE GLAZING PUTTH HAS FALED IT SHALL BE CAREFULLY REMOVED AND REPLACED. ALL SASHES AND TRIM TO BE PREPARED FOR PARTIND USING THE GENTLEST MEANS POSSIBLE AND REPAIRTED. REPLACE DETERIORATED WEIGHT RODE WITH COTTON ROPE AS REQUIRED.
	LEFT ELEVATION AT DINNIOR ROOM. TWO DRIGINAL WOOD DOUBLE-HUNG WINDOWS IN GOOD CONDITION. THE WINDOWS ARE A CHARACTER DEFINING FEATURE IN THEIR ENTIRETY BUT ALSO A REPETITIVE HISTORIO FEATURE.	THESE WINDOWS (BASH TRIM PULLEYS, WEIGHTS) TO REMAIN IN STUI AND ARE PROPOSED TO BE PRESERVED. WHERE GLAZING PUTTH HAS FALED IT SHALL BE CAREFULLY REMOVED AND REPLACED. ALL SASHES AND TRIM TO BE PREPARED FOR PARTIND USING THE GENTLEST MEANS POSSIBLE AND REPAINTED. REPLACE DETERIORATED WEIGHT RODE WITH COTTON ROPE AS REQUIRED.
	LEFT ELEVATION AT KITCHEN: TYPO ORKINAL WOOD DOUBLE-HUNG WINDOWS (ONE-OVER-ONE LIGHTS) MULLED TOGETHER ARE IN GOOD CONDITION. THE WINDOWS ARE A CHARACTER DEFINING FEATURE IN THEIR ENTIRETY BUT ALSO A REPETITIVE HISTORIC FEATURE.	THESE WINDOWS ARE PROPOSED TO BE REMOVED FROM THE RESIDENCE.
	LEFT ELEVATION AT LAUNDRY: ONE OFRIGINAL WOOD DOUBLE-HUNG WINDOW (ONE-OVER-ONE LIGHTS) IS IN GOOD CONDITION. THE WINDOW IS A CHARACTER-DEFINING FEATURE IN THEIR ENTIRETY BUT ALSO A REPETITIVE HIS TORIC FEATURE.	THIS WINDOW IS PROPOSED TO BE REMOVED FROM THE RESIDENCE.
	TEFT ELEVATION AT BEDROOMS ' WYO ORIGINARY WOOD DOUBLE-HUNG WINDOWS (ONE-OVER-ONE LIGHTS) MULLED TOGETHER ARE IN GOOD CONDITION. THE WINDOWS ARE A CHARACHERS DEFINING PEATURE IN THEIR ENTIRETY BUT ALSO A REPETITIVE MISTORIO FEATURE.	THESE WINDOWS ARE PROFOSED TO BE RELOCATED TO THE LEFT WALL OF THE KITCHEN AND CENTERED ON THE NEW BLAND AND ARE PROPOSED TO BE PRESERVED. WHERE GLAZING PUTTY HAS PRIZED IT SHALL BE CAMPETUL FROMOVED AND REPLACED. ALL GLAZING PUTTY HAS PRIZED THE SHALL BE CAMPETUL FROMOVED AND REPLACED. ALL GIENTLEST MEANS POSSIBLE AND REPAINTED. REPLACE DETERIORATED WHIGHT FOR WITH COTTON ROPE AS REQUIRED.
	REAR LEWATION BEDROOM 3: ONE OFFICE OF THE PROPERTY OF THE PRO	THIS WINDOW IS PROPOSED TO BE RELOCATED TO THE LEFT WALL OF THE ADDITION AT THE NEW FAMILY ROOM AND IS PROPOSED TO BE PRESERVED. WHERE CLAZING PUTTY HAS FAILED IS SHALL BE CAREFULLY REMOVED AND REPLACED. ALL SASHES AND THAN TO BE PREPARED FOR PANTING USHON THE GONTLEST MEMAS POSSIBLE AND REPAIRED. REPLACE DETERIORATED WEIGHT ROPE WITH COTTON ROPE AS REQUIRED.
	REAR LEWATION BEDROOM 2: ONE OF THE MEMORY WORD OF THE LIGHTS) IS IN SHAT TO GOOD CONDITION. THE WINDOW (AN CONTROL LIGHTS) IS IN SHAT TO GOOD CONDITION. THE WINDOW IS A CHARACTER-SCHOOL PREVIOUS IN ITS ENTIRETY BUT ALSO A REPETITIVE HISTORIO FEATURE.	THIS WINDOW IS PROPOSED TO BE RELOCATED TO THE LEFT WALL OF THE ADDITION AT THE NEW FAMILY FROM IS PROPOSED TO BE PRESERVED. WHERE GLAZING PUTTY HAS FAILED IT SHALL BE CAREFILLY REMOVED AND BY ALCO. ALL DEFINES AND THIS IT OF BE AND REPORTED FOR THE ADDITION OF THE ADDI
	REAR ELEVATION BATH 1: ONE ORIGINAL RELIMINEST SLIDER WINDOW IS IN GOOD CONDITION. THE WINDOW IS NOT ORIGINAL TO THE HOUSE AND IS NOT A CHARACTER- DEFINING FEATURE. RIGHT ELEVATION REPROPERS.	THIS WINDOW IS PROPOSED TO BE REMOVED FROM THE RESIDENCE.
	NOME LEVAN LIN BELENCANCE. **HOME CHROMEN FROM CHROMO (MINE CAVER A CHE LIGHTS) FOR CHROMEN FROM CHROMO (SA CHARACTER GENERAL) FEATURE IN ITS ENTIRETY BUT ALSO A REPETITIVE HISTORIC FEATURE. RIGHT ELEVATION BEDROOM 1: **MEDICAL PROPERTY OF THE WINDOW (ONE-OVER ONE LIGHTS) IS IN GOOD CONDITION. THE WINDOW (ONE-OVER ONE LIGHTS) IS IN GOOD CONDITION. THE WINDOW (SA CHARACTER CEETING) FEATURE IN ITS ENTIRETY BUT LASO. A REPETITIVE HISTORIC PEATURE.	THESE WINDOWS (BASH TRAN PULLEYS WEIGHTS) TO REMAIN IN SITU AND ARE PROPOSED TO SE PRESERVED. WHERE GLAZING PUTT HAS FALLED IT SHALL BE CAREFULLY REMOVED AND REPLACED. ALL SASHES AND TRAN TO SE PREMATED FOR PAINTING LIGHT GENTLED'S MEMOR POSSIBLE AND REPRIANTED. REPLACE CENTLED'S MEMOR POSSIBLE AND REPRIANTED. REPLACE DETERMANED WEIGHT ROPE WITH COTTON ROPE AS REQUIRED.
	RIGHT ELEVATION LIVING: TWO ORGANE, WOOD DOUBLE-HUNG WINDOWS (ONE-OVER-ONE LIGHTS) ARE IN GOOD CONDITION. THE WINDOWS ARE A LIGHTS ARE IN GOOD CONDITION. THE WINDOWS ARE A REPETITIVE HISTORIC FEATURE.	
DOORS AND TRIM	FRONT ENTRY DOOR ORGINAL "3-0" X-6"S" WOOD DOOR WITH VERTICAL PLANKS AND DECORATIVE BRASS GRILLE AND BRASS HARDWARE IS IN GREAT CONDITION.	THE DOOR IS PROPOSED TO REMAIN INSITU AND BE PRESERVED AND TO BE PREPARED FOR PAINTING USING THE GENTLEST MEANS POSSIBLE AND REPAINTED.
	LEFT ELEVATION LAUNDRY: ONE ORIGINAL WOOD DOOR (ONE-LIGHT OVER SOLID WOOD PANEL) IS IN POOR CONDITION. THE WINDOWS IS NOT CONSIDERED A CHARACTER-DEFINING FEATURE.	THE DOOR IS PROPOSED TO BE REMOVED FROM THE RESIDENCE.
INTERIOR FINISHES	3	1
FEATURE	DESCRIPTION AND CONDITION	TREATMENT
FLOORING	ORIGINAL 314" THICK: OAK FLOORING IS IN GREAT CONDITION IN THE EXISTING ENTRY, LIVING ROOM, DININING ROOM & HALL.	FLOORING TO BE PRESERVED AND UNTOUCHED EXCEPT WHERE THE DOOR BETWEEN THE KITCHEN AND DINING IS TO BE RELOCATED. AT THE NEW OPENING OAK FLOORING SHALL BE INSTALLED AND FINISHED TO MATCH EXISTING.
	ORIGINAL 134 T&G FIR FLOORING AT BEDROOM 1, BEDROOM 2 & 3.	FLOORING TO BE PRESERVED AND UNTOUCHED AT BEDROOMS 1S 2 BUT TO BE REPLACED WITH OAK FLOORING AT BEDROOM 3 WHICH IS BEING CONVERTED INTO A FAMILY ROOM.
	MODERN LAMINATE FLOORING AT KITCHEN & LAUNDRY.	FLOORING IS PROPPOSED TO BE REMOVED AND TO BE REPLACED WIT

FEATURE	DESCRIPTION AND CONDITION	TREATMENT
ROOF	MAIN SESSEMME. THE CROWNER HOPE ROOF FORM, WITH 5.5.12 PITCH REMAINS IN ACT, THE ENTIRE ROOFS IS COVERED WITH INTERCOCKING INTERCOCKIN	THE DESIGN PROPOSES TO ALTER THE EXISTING ROOF FORM RAR (WEST MINH A SMALLER HIP ROOF EXTENSION TO ACCOMMINATE THE ROAF ACCOTIONS. THE NEW HIP WALL BE THE ROAF ACCOTIONS. THE NEW HIP WILL BE THE ROAF ACCOTION TO THE CHIRAL THE CHIR
FLOOR PLAN	THE ORIGINAL FLOOR PLAN REMAINS MOSTLY INTECT WITH THE HOUSE RETAINING ITS ORIGINALS BEDENOM, 1 BATH, FORMAL LIVING AND DINING ROOMS, AND LAUNDRY ROOM.	THE SHITTY LIVINO, DINING, BEDROOM 1, AND BEDROOM 2 ARE PROPOSED TO REMAIN HITACT IN WILL OR WINDOW CHANGES BEDROOM 3 IS BEING CONVERTED TO A FAMILY ROOM AND STOOM TO BASEMENT. THE LANDRY ROOM IS REVOKED TO ACCOMMODATE A LANGE KITCHEN THAT IS OPEN TO THE FAMILY ROOM. AN ADDITION IS PROPOSED TO ACCOMMODATE A BEDROOM AND STOOM AND THE SHAPP OF THE SHAP THAT IS A SHAPP OF THE SHAP OF THE SHAPP O
STRUCTURAL SYSTEM, FRAMING	THE CONVENTIONAL WOOD FRAMING IS MOSTLY IN GOOD CONDITION. THE FRAMING IS NOT A CHARACTER DEFINIOR FEATURE, EXCEPT HOW IT IS EXPRESSED IN THE MASSING AND FORM OF THE PLAN.	THE DESIGN PROPOSES ALTERATIONS AND ADDITIONS TO REPORTION OF THE HOUSE TO ACCOMMONATE A SIN DEPRODMINE TO HE DEFROOM SENSURE 2D BOATROOM WITH LANGE WALLEN CLOSET. THE KITCHEN IS BEING EXPANDED INTO THE EXISTING LAUNDRY RAND OPENDE UP TO THE NEW PAMILY PROMI. THE ADDITIONS ALTERATIONS WILL REQUIRE MODIFICATIONS TO THE WALL. RAND FLOOR FRAMING AT THE REAP PORTION OF THE STRUCT
FOUNDATIONS	THE EXISTING PERIMETER CONCRETE BRICK FOUNDATION ARE IN FAIR TO GOOD CONDITION.	THE DESIGN PROPOSES TO INSTALL NEW FOUNDATION SYSTE BELOW THE PROPOSED ADDITION WITH SOME MINOR FOUNDATIONS.
FRONT ENTRY PORCH	THE ORIGINAL HIPPED PORCH ROOF LINE WITH STUCCO COLUMNS WITH STUCCO CORBELS ARE IN GOOD CONDITION.	THE DESIGN PROPOSES PERSERVE THE PORCH ROOF AND AL ELEMEMENTS OF THE STUCCO COLUMNS.
	THE CONCRETE PORCH SLAB AND STEPS ARE IN FAIR TO GOOD CONDITION WITH SOME VISIBLE CRACKING.	THE DESIGN PROPOSES TO PRESERVE THE PORCH SLAB AND AND INJECT EPOXY AT THE CRACKS.

ROBERT MAYER

ADDITION & REMODEL TO THE RESIDENCE AT:

1490 Santa Clara, CA 95050 Santa Clara, CA 95050 408.564.5943 mayer.roben@comcast.net

324 MADISON STREET SANTA CLARA, CA 55050 APN: 28941-030

HISTORIC PRESERVATION PLAN

HP1