## **Mills Act Historic Property Evaluation**

Property Address: 864 Madison Street	APN: 269 - 26 - 019
Owners: Patrick Nikolai	Date of Inspection: November 2, 2017 @ 4 pm

Please state N/A under comments if characteristic does not apply to the historic property.

**Primary Characteristics:** 

-	Poor	Fair	Good	Excellent	Comments:
Aesthetics (Overall Appearance; Is there a <i>plaque</i> visible?)		×			
Paint Condition (Is there any paint peeling off? Interior & Exterior)		X			needs repainting
Gutters & Downspouts (Are they blocked or filled? Are they intact?)			×		
Windows (Overall condition including glass and frame)		×.			Some frames need replacing owner is slowly doing this work
Roof Condition (Are there any shingles detached or missing? Moss growth?)			X		7 (0,70
Trim: Eaves, Fascia, Soffits (Do these features look serviceable or worn?)		Х			
Exterior Walls (Are there any cracks, stains, etc.? Look at South facing wall)	$\rightarrow$	X			siding needs repeating along w/ some shingle
Foundation Condition (Does it seem weak? Look for balanced or leaning walls)			X		
Exterior Stairs (Do they look safe or serviceable? Railings condition?)		N			owner would like to redo entry of add railings
Architectural Style (Do the features match the stated style on HRI? Are there character defining elements?			X		shingle

A moved in 2005.

HVAC System			·
(Is there a system installed? Is it functional? Efficiency?)			NA

Secondary Characteristics

Secondary Characteristics:					
	Poor	Fair	Good	Excellent	Comments:
Landscaping (Does the lawn look well groomed? Are there any overgrown weeds/plants?)			X		back yard landscaped, front yard to be done
Fencing Condition (What type of material is being used?)					N/a
Driveway & Garage (Are there any cracks or uneven pavement? How is the structure of the garage?)			×		Carport rebuilt
Front Walkway Condition (Are they any cracks or uneven pavement?)		χ			See previous comments
Sprinklers (Does there seem to be a system installed? Is it functional?)			X		
Chimney Condition (Does it look functional or worn? Is there a spark arrestor?)			A		
Porch/Patio Condition (Is it worn? Are there any parts missing?)		X			

**Points Tally:** 

	Amount Checked per Category	Tally (	Conversion	
Excellent (4)		4 x	-	
Good (3)		3 x		
Fair (2)		2 x	==	
Poor (1)		1 x		
N/A (0)		0 x		
	Total Accumulated Points:			

## **Percentage Calculation:**

18 - (Number of characteristics that were N/A) = [Answer]

[Answer] x 4 = Total Possible Points

Total Accumulated Points/Total Possible Points =

ther honeits of the City of Santa Ciura. Recorded free of charge under Section 6103 of the Pavernatons Code.

## The Description of the Historic Property Preservation and Restoration Efforts Exhibit "C"

## 864 Madison Street, Santa Clara, CA

Ask	1999 - 2000	Termite Work on Main House yes
Hek	2000 - 2001	Termite Work on Garage yes
	2001 - 2002	Roof yes
	2002 - 2003	Landscaping (Rear only)
	2003 - 2004	Painting of House and Garage yes
	2004 - 2006	Basement - Structural
	2006 - 2007	Repairs to Basement Ceiling yes
	20098- 2009	Review and Plan with City next 10 years