**Mills Act Historic Property Evaluation** 

Effective	:	2010	
DIJOC CITO		2010	

Property Address:	APN:
758 Jackson Street	269-26-097
Owners:	Date of Inspection:
Paul Yang	November 2, 2017 @ 3:30 p

Please state N/A under comments if characteristic does not apply to the historic property.

**Primary Characteristics:** 

	Poor	Fair	Good	Excellent	Comments:
Aesthetics (Overall Appearance; Is there a plaque visible?)		X			
Paint Condition (Is there any paint peeling off? Interior & Exterior)			X		new-exterior interior-missing patches
Gutters & Downspouts (Are they blocked or filled? Are they intact?)		×	X		new but clogged in front
Windows (Overall condition including glass and frame)		X			old, worn
Roof Condition (Are there any shingles detached or missing? Moss growth?)		v	X		
Trim: Eaves, Fascia, Soffits (Do these features look serviceable or worn?)			X		some exposed areas
Exterior Walls (Are there any cracks, stains, etc.? Look at South facing wall)			X		
<b>Foundation Condition</b> (Does it seem weak? Look for balanced or leaning walls)			X		no cracks on facting
Exterior Stairs (Do they look safe or serviceable? Railings condition?)		X			brack steps look unsafe
Architectural Style (Do the features match the stated style on HRI? Are there character defining elements?		•	X		national

builing-permits future-add central heating system

HVAC System	DIV 10-03-51 Class for
(Is there a system installed? Is it	no central system
functional? Efficiency?)	NA

Secondary Characteristics

Secondary Characteristi	US:				
	Poor	Fair	Good	Excellent	Comments:
Landscaping (Does the lawn look well groomed? Are there any overgrown weeds/plants?)	X				no irnganian system
<b>Fencing Condition</b> (What type of material is being used?)			X		Hearing a bit-
Driveway & Garage (Are there any cracks or uneven pavement? How is the structure of the garage?)			X		anvenary not finished
Front Walkway Condition (Are they any cracks or uneven pavement?)			X	g	
<b>Sprinklers</b> (Does there seem to be a system installed? Is it functional?)				,	MA
Chimney Condition (Does it look functional or worn? Is there a spark arrestor?)		X			spannour unserviceable wein on typ
<b>Porch/Patio Condition</b> (Is it worn? Are there any parts missing?)			X		,

**Points Tally:** 

	Amount Checked per Category	Tally Conversion				
Excellent (4)		4 x =				
Good (3)	11	$3 \times 11 = 33$				
Fair (2)	i	2 x 4 = 8				
Poor (1)		1 x   =				
N/A (0)		0 x =				
	Total Accumulated Points:	42				

P	ercentage	Cal	CII	latio	n:
	cicciitage	Ca	cui	acio	, , , ,

18 - (Number of characteristics that were N/A) = [Answer] [Answer] x 4 = Total Possible Points [Answer] [

758 Jackston St. Santa Clara, CA

APN# 269-52-048

Mills Act – The description of the preservation or restoration efforts to be undertaken;

Molding

Updated the interior of the property with new paint - 2009:

2010: Refinish the floor, add a stair rail

**— 2011**: Bathrooms remodel

> 2012: Rewire electrical wire and upgrade electrical service

2013: Replace roof and gutter

2014: Kitchen remodel

> 2015: Repair and paint exterior siding

interior parme

2016: Drive way

2017-2019: Landscaping, sprinkle system - not dare dan't have plans to change window

down wolging

## **ADDITIONS:**

In addition to restoring the house, I'd like to add an addition to the house. Due to the limit of additions to the 25% maximum allowed by the Mills Act, however, I may request some additional square footage if I am having difficulty BLD 2010-23997 accessory unit fitting 3 bedrooms and 2 baths upstairs.

(760 Jackson Street) It is my intention to make sure that any additions I make are sensitive to the historic character of the existing home.

BLD 2012-27527 water line relocation BPR 2017 - 01184 water heater replaced BLD 2009-20309 Remne portion of house