

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>RAT Hist. Only Flag:</b>					<b>SH Seq:</b>	
<b>RAT NSI Indicator:</b>	B				<b>SH Start Date:</b>	
<b>RAT Level:</b>	1				<b>SH Complete Date:</b>	
<b>RAT DEF OU:</b>	00				<b>SH Lead:</b>	
<b>RFBS Code:</b>					<b>SH Qual:</b>	
<b>SPA Code:</b>	13				<b>RAQ Act. Qual Short:</b>	
<b>RALT Short Name:</b>	EPA In-House				<b>RNPL Status Code:</b>	N
<b>RAT Def:</b>	The decision is made that no further activity is planned at the site.					
<b>RNON NPL Status Desc:</b>	NFRAP-Site does not qualify for the NPL based on existing information					

**CERCLIS-NFRAP Assess History**

<b>OU ID:</b>	0	<b>Act Start Date:</b>	
<b>Act Code ID:</b>	2	<b>Act Complete Date:</b>	6/1/1988
<b>RAT Code:</b>	PA	<b>AGT Order No.:</b>	130
<b>RAT Short Name:</b>	PA	<b>SH OU:</b>	
<b>RAT Name:</b>	PRELIMINARY ASSESSMENT	<b>SH Code:</b>	
<b>RAT Hist. Only Flag:</b>		<b>SH Seq:</b>	
<b>RAT NSI Indicator:</b>	B	<b>SH Start Date:</b>	
<b>RAT Level:</b>	1	<b>SH Complete Date:</b>	
<b>RAT DEF OU:</b>	00	<b>SH Lead:</b>	
<b>RFBS Code:</b>	P	<b>SH Qual:</b>	
<b>SPA Code:</b>	13	<b>RAQ Act. Qual Short:</b>	NFRAP
<b>RALT Short Name:</b>	State (Fund)	<b>RNPL Status Code:</b>	N
<b>RAT Def:</b>	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
<b>RNON NPL Status Desc:</b>	NFRAP-Site does not qualify for the NPL based on existing information		

[10](#)    3 of 3    **SW**    0.12 / 637.13    78.98 / 4    **UNIVERSITY OF SANTA CLARA**  
**820 ALVISO ST**  
**SANTA CLARA CA 95053**    **SEMS ARCHIVE**

<b>Site ID:</b>	0901444	<b>FIPS Code:</b>	06085
<b>EPA ID:</b>	CAD054800214	<b>Cong District:</b>	13
<b>Superfund Alt Agmt:</b>	No	<b>Region:</b>	09
<b>Federal Facility:</b>	No	<b>County:</b>	SANTA CLARA
<b>FF Docket:</b>	No		
<b>NPL:</b>	Not on the NPL		
<b>Non NPL Status:</b>	NFRAP-Site does not qualify for the NPL based on existing information		

**Action Information**

<b>Operable Units:</b>	00	<b>Start Actual:</b>	
<b>Action Code:</b>	VS	<b>Finish Actual:</b>	06/01/1988
<b>Action Name:</b>	ARCH SITE	<b>Qual:</b>	
<b>SEQ:</b>	1	<b>Curr Action Lead:</b>	EPA Perf In-Hse
<b>Operable Units:</b>	00	<b>Start Actual:</b>	10/01/1986
<b>Action Code:</b>	DS	<b>Finish Actual:</b>	10/01/1986
<b>Action Name:</b>	DISCVRY	<b>Qual:</b>	
<b>SEQ:</b>	1	<b>Curr Action Lead:</b>	St Perf
<b>Operable Units:</b>	00	<b>Start Actual:</b>	
<b>Action Code:</b>	PA	<b>Finish Actual:</b>	06/01/1988
<b>Action Name:</b>	PA	<b>Qual:</b>	N
<b>SEQ:</b>	2	<b>Curr Action Lead:</b>	St Perf
<b>Operable Units:</b>	00	<b>Start Actual:</b>	
<b>Action Code:</b>	PA	<b>Finish Actual:</b>	02/01/1987
<b>Action Name:</b>	PA	<b>Qual:</b>	H
<b>SEQ:</b>	1	<b>Curr Action Lead:</b>	St Perf

[11](#)    1 of 2    **ESE**    0.14 / 764.37    75.29 / 0    **Musso Property**  
**2491 The Alameda Santa Clara**  
**CA**    **LOP SANTA CLARA**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
SCVWD ID:		07S1W11A02f				
Closure Date:		4/24/1999				
Link:		http://lustop.sccgov.org/files/07S1W11A02f/				

<a href="#">11</a>	2 of 2	ESE	0.14 / 764.37	75.29 / 0	MUSSO PROPERTY 2491 THE ALAMEDA SANTA CLARA CA 95050	LUST
Global ID:	T0608501326	County:	SANTA CLARA			
Status:	COMPLETED - CASE CLOSED	Latitude:				
Status Date:		Longitude:				
Case Type:	LUST CLEANUP SITE					
Date Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download					

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:		Potential COC:	Gasoline
Local Case No:		How Discovered:	
Begin Date:	8/13/1990	Stop Method:	
Lead Agency:	SANTA CLARA COUNTY LOP	Stop Description:	
Local Agency:	SANTA CLARA COUNTY LOP	Case Worker:	UST
CUF Case:	YES	File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media of Concern:	Other Groundwater (uses other than drinking water)		
How Discovered Description:			
Calwater Watershed Name:	Santa Clara - Palo Alto (205.50)		
DWR GW Subbasin Name:	Santa Clara Valley - Santa Clara (2-009.02)		
Disadvantaged Community:			
Calenviroscreen Score:	41-45%		
Site History:			

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type:	RESPONSE
Date :	4/23/1999
Action:	Other Report / Document
Action Type:	ENFORCEMENT
Date :	4/23/1999
Action:	Closure/No Further Action Letter
Action Type:	RESPONSE
Date :	10/27/1997
Action:	Monitoring Report - Quarterly
Action Type:	ENFORCEMENT
Date :	10/23/1997
Action:	Staff Letter - #22534
Action Type:	REMEDIATION
Date :	2/1/1997
Action:	Soil Vapor Extraction (SVE)
Action Type:	REMEDIATION
Date :	2/1/1997
Action:	Pump & Treat (P&T) Groundwater
Action Type:	RESPONSE
Date :	6/21/1996
Action:	Monitoring Report - Quarterly
Action Type:	ENFORCEMENT

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<i>Date :</i>		6/4/1996				
<i>Action:</i>		Staff Letter - #22529				
<i>Action Type:</i>		RESPONSE				
<i>Date :</i>		9/1/1995				
<i>Action:</i>		Soil and Water Investigation Report				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		6/27/1995				
<i>Action:</i>		Staff Letter - #22522				
<i>Action Type:</i>		RESPONSE				
<i>Date :</i>		5/1/1995				
<i>Action:</i>		Monitoring Report - Quarterly				
<i>Action Type:</i>		RESPONSE				
<i>Date :</i>		3/30/1995				
<i>Action:</i>		Soil and Water Investigation Report				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		3/1/1995				
<i>Action:</i>		Staff Letter - #22517				
<i>Action Type:</i>		RESPONSE				
<i>Date :</i>		1/30/1995				
<i>Action:</i>		Monitoring Report - Quarterly				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		1/5/1995				
<i>Action:</i>		Staff Letter - #22515				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		12/16/1994				
<i>Action:</i>		Staff Letter - #22513				
<i>Action Type:</i>		RESPONSE				
<i>Date :</i>		7/7/1994				
<i>Action:</i>		Other Report / Document				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		6/30/1994				
<i>Action:</i>		Staff Letter - #22511				
<i>Action Type:</i>		RESPONSE				
<i>Date :</i>		6/16/1993				
<i>Action:</i>		Soil and Water Investigation Report				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		6/15/1993				
<i>Action:</i>		Staff Letter - #22509				
<i>Action Type:</i>		ENFORCEMENT				
<i>Date :</i>		1/5/1992				
<i>Action:</i>		Notice of Responsibility - #39643				
<i>Action Type:</i>		Other				
<i>Date :</i>		10/26/1990				
<i>Action:</i>		Leak Reported				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

City: SAN JOSE Phone No: 4089183400  
 Organization Name: SANTA CLARA COUNTY LOP

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

Status: Completed - Case Closed  
 Status Date: 4/24/1999

Status: Open - Verification Monitoring  
 Status Date: 12/1/1997

Status: Open - Remediation  
 Status Date: 2/1/1997

Status: Open - Site Assessment  
 Status Date: 12/24/1992

Status: Open - Case Begin Date  
 Status Date: 8/13/1990

Status: Open - Site Assessment  
 Status Date: 8/13/1990

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	MUSSO PROPERTY	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	2491 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>	B	<b>CUF Claim:</b>	2621
<b>CUF Amount Paid:</b>	\$277,237		
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608501326">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608501326</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 4/24/1999		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608501326&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608501326&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W11A02f		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use Desc:</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Site History:</b>			

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

Status: Completed - Case Closed  
 Date : 4/24/1999

Status: Open - Verification Monitoring  
 Date : 12/1/1997

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Status:** Open - Remediation  
**Date :** 2/1/1997  
**Status:** Open - Site Assessment  
**Date :** 12/24/1992  
**Status:** Open - Case Begin Date  
**Date :** 8/13/1990  
**Status:** Open - Site Assessment  
**Date :** 8/13/1990

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

<b>Action Type:</b>	PUMP & TREAT (P&T) GROUNDWATER	<b>Begin Date:</b>	2/1/1997
<b>Phase:</b>		<b>End Date:</b>	11/1/1997
<b>Contaminant Mass Removed:</b>			
<b>Description:</b>			
<b>Action Type:</b>	SOIL VAPOR EXTRACTION (SVE)	<b>Begin Date:</b>	2/1/1997
<b>Phase:</b>		<b>End Date:</b>	11/1/1997
<b>Contaminant Mass Removed:</b>			
<b>Description:</b>			

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 4/23/1999  
**Received Issue Date:** 4/23/1999  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501326&doc\\_id=5843416](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501326&doc_id=5843416)  
**Title Description Comments:**

SCVWD Electronic Files

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/23/1999  
**Received Issue Date:** 4/23/1999  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501326&enforcement\\_id=6247133&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501326&enforcement_id=6247133&temptable=ENFORCEMENT)  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 10/27/1997  
**Received Issue Date:** 10/27/1997  
**Action:** Monitoring Report - Quarterly  
**Doc Link:**  
**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/23/1997  
**Received Issue Date:** 10/23/1997  
**Action:** Staff Letter - #22534  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 6/21/1996  
**Received Issue Date:** 6/21/1996

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Monitoring Report - Quarterly				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/4/1996				
<b>Received Issue Date:</b>		6/4/1996				
<b>Action:</b>		Staff Letter - #22529				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		9/1/1995				
<b>Received Issue Date:</b>		9/6/1995				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Soil and Water Investigation Report				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/27/1995				
<b>Received Issue Date:</b>		6/27/1995				
<b>Action:</b>		Staff Letter - #22522				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		5/1/1995				
<b>Received Issue Date:</b>		5/2/1995				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Monitoring Report - Quarterly				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		3/30/1995				
<b>Received Issue Date:</b>		9/6/1995				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Soil and Water Investigation Report				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		3/1/1995				
<b>Received Issue Date:</b>		3/1/1995				
<b>Action:</b>		Staff Letter - #22517				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		1/30/1995				
<b>Received Issue Date:</b>		2/1/1995				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Monitoring Report - Quarterly				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		1/5/1995				
<b>Received Issue Date:</b>		1/5/1995				
<b>Action:</b>		Staff Letter - #22515				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		12/16/1994				
<b>Received Issue Date:</b>		12/16/1994				
<b>Action:</b>		Staff Letter - #22513				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		7/7/1994				
<b>Received Issue Date:</b>		7/7/1994				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
Other Type of Submission by RP						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/30/1994				
<b>Received Issue Date:</b>		6/30/1994				
<b>Action:</b>		Staff Letter - #22511				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		6/16/1993				
<b>Received Issue Date:</b>		6/16/1993				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
Soil and Water Investigation Report						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/15/1993				
<b>Received Issue Date:</b>		6/15/1993				
<b>Action:</b>		Staff Letter - #22509				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Notices				
<b>Action Date:</b>		1/5/1992				
<b>Received Issue Date:</b>		1/5/1992				
<b>Action:</b>		Notice of Responsibility - #39643				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		2/1/1997				
<b>Received Issue Date:</b>						
<b>Action:</b>		Pump & Treat (P&T) Groundwater				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		2/1/1997				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Received Issue Date:**  
**Action:** Soil Vapor Extraction (SVE)  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 10/26/1990  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :**  
**Document Date:** 4/23/1999 **Submitted By:** COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER **Submitted:**  
**Title:** UNKNOWN  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501326&enforcement\\_id=6247133](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501326&enforcement_id=6247133)

**Document Type:** Site Documents **Size :**  
**Document Date:** 4/23/1999 **Submitted By:** COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** SCVWD ELECTRONIC FILES  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501326&document\\_id=5843416](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501326&document_id=5843416)

<a href="#">12</a>	1 of 1	WSW	0.18 / 948.10	81.15 / 6	431 LAFAYETTE APARTMENTS 431 LAFAYETTE WAY, SANTA CLARA CA 95050	RCRA NON GEN
--------------------	--------	-----	---------------	-----------	--	-----------------

**EPA Handler ID:** CAC003074864  
**Gen Status Universe:** No Report  
**Contact Name:** COLIN GRAY  
**Contact Address:** 431 LAFAYETTE WAY, , , SANTA CLARA , CA, 95050 ,  
**Contact Phone No and Ext:** 408-410-2430  
**Contact Email:** JAMIE.JIRAN@ATIRESTORATION.COM  
**Contact Country:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Land Type:**  
**Receive Date:** 20200715  
**Location Latitude:**  
**Location Longitude:**

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Furnace Exemption:** No  
**Underground Injection Activity:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

**Hazardous Waste Handler Details**

Sequence No: 1  
 Receive Date: 20200715  
 Handler Name: 431 LAFAYETTE APARTMENTS  
 Source Type: Implementer  
 Federal Waste Generator Code: N  
 Generator Code Description: Not a Generator, Verified

**Owner/Operator Details**

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street 1:	431 LAFAYETTE WAY,
Name:	COLIN GRAY	Street 2:	
Date Became Current:		City:	SANTA CLARA
Date Ended Current:		State:	CA
Phone:	408-410-2430	Country:	
Source Type:	Implementer	Zip Code:	95050

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street 1:	431 LAFAYETTE WAY,
Name:	COLIN GRAY	Street 2:	
Date Became Current:		City:	SANTA CLARA
Date Ended Current:		State:	CA
Phone:	408-410-2430	Country:	
Source Type:	Implementer	Zip Code:	95050

<a href="#">13</a>	1 of 5	ESE	0.18 / 960.56	74.80 / 0	Gasco 007 2391 The Alameda Santa Clara CA	LOP SANTA CLARA
--------------------	--------	-----	---------------	-----------	---	--------------------

SCVWD ID: 07S1W11A01f  
 Closure Date: 1/27/1999  
 Link: <http://lustop.sccgov.org/files/07S1W11A01f/>

<a href="#">13</a>	2 of 5	ESE	0.18 / 960.56	74.80 / 0	GASCO 007 2391 THE ALAMEDA SANTA CLARA CA 95050	LUST
--------------------	--------	-----	---------------	-----------	---	------

Global ID: T0608500669  
 Status: COMPLETED - CASE CLOSED  
 Status Date:  
 Case Type: LUST CLEANUP SITE  
 Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

County: SANTA CLARA  
 Latitude:  
 Longitude:

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

RB Case No:		Potential COC:	Gasoline
Local Case No:		How Discovered:	
Begin Date:	10/17/1988	Stop Method:	
Lead Agency:	SANTA CLARA COUNTY LOP	Stop Description:	
Local Agency:	SANTA CLARA COUNTY LOP	Case Worker:	UST
CUF Case:	YES	File Location:	All Files are on GeoTracker or in the Local Agency Database

Potential Media of Concern: Other Groundwater (uses other than drinking water)  
 How Discovered Description:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Calwater Watershed Name:</b>		Santa Clara - Palo Alto (205.50)				
<b>DWR GW Subbasin Name:</b>		Santa Clara Valley - Santa Clara (2-009.02)				
<b>Disadvantaged Community:</b>						
<b>Calenviroscreen Score:</b>		41-45%				
<b>Site History:</b>						

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	RESPONSE
<b>Date :</b>	1/27/1999
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	1/27/1999
<b>Action:</b>	Closure/No Further Action Letter
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	2/7/1997
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	1/14/1997
<b>Action:</b>	Staff Letter - #22503
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	5/24/1996
<b>Action:</b>	Warning Letter - #22495
<b>Action Type:</b>	REMEDIATION
<b>Date :</b>	10/10/1995
<b>Action:</b>	Excavation
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	2/15/1995
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	11/14/1994
<b>Action:</b>	Staff Letter - #22493
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/22/1994
<b>Action:</b>	Referral to Local Agency - #43-0635
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/13/1993
<b>Action:</b>	13267 Requirement - #43-0635
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/3/1993
<b>Action:</b>	Notice of Violation - #39642
<b>Action Type:</b>	Other
<b>Date :</b>	10/17/1988
<b>Action:</b>	Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Organization Name: SANTA CLARA COUNTY LOP

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

Status:	Completed - Case Closed
Status Date:	1/27/1999
Status:	Open - Site Assessment
Status Date:	4/27/1992
Status:	Open - Site Assessment
Status Date:	10/24/1988
Status:	Open - Case Begin Date
Status Date:	10/17/1988

**LUST Sites from GeoTracker Search - Regulatory Profile**

Site Facility Name:	GASCO 007	Potential COC:	GASOLINE
Site Facility Type:	LUST CLEANUP SITE	Facility Type:	
Cleanup Status:	COMPLETED - CASE CLOSED	Composting Method:	
Project Status:		Address:	2391 THE ALAMEDA
WDR Place Type:		City:	SANTA CLARA
WDR File:		Zip:	95050
WDR Order:		County:	SANTA CLARA
CUF Priority Assig:	C	CUF Claim:	5160
CUF Amount Paid:	\$305,240		
File Location:	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
Designated Beneficial Use:	MUN, AGR, IND, PROC		
Project Oversight Agencies:			
Report Link:	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500669">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500669</a>		
Cleanup Status Detail:	COMPLETED - CASE CLOSED AS OF 1/27/1999		
Cleanup History Link:	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500669&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500669&amp;tabname=regulatoryhistory</a>		
Potential Media of Concern:	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
User Defined Beneficial Use:			
DWR GW Sub Basin:	Santa Clara Valley - Santa Clara (2-009.02)		
Calwater Watershed Name:	Santa Clara - Palo Alto (205.50)		
Post Closure Site Management:			
Future Land Use:			
Cleanup Oversight Agencies:	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W11A01f		
Gndwater Monitoring Freque:			
Designated Beneficial Use Desc:	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
Site History:			

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

Status:	Completed - Case Closed
Date :	1/27/1999
Status:	Open - Site Assessment
Date :	4/27/1992
Status:	Open - Site Assessment
Date :	10/24/1988
Status:	Open - Case Begin Date
Date :	10/17/1988

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** EXCAVATION **Begin Date:** 10/10/1995  
**Phase:** **End Date:** 1/27/1999  
**Contaminant Mass Removed:**  
**Description:**

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 1/27/1999  
**Received Issue Date:** 1/27/1999  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500669&doc\\_id=5842163](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500669&doc_id=5842163)  
**Title Description Comments:**

SCVWD Electronic Files

**Action Type:** Other Regulatory Actions  
**Action Date:** 1/27/1999  
**Received Issue Date:** 1/27/1999  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&enforcement\\_id=6245912&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&enforcement_id=6245912&temptable=ENFORCEMENT)  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 2/7/1997  
**Received Issue Date:** 2/7/1997  
**Action:** Monitoring Report - Quarterly  
**Doc Link:**  
**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Other Regulatory Actions  
**Action Date:** 1/14/1997  
**Received Issue Date:** 1/14/1997  
**Action:** Staff Letter - #22503  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Enforcement/Orders  
**Action Date:** 5/24/1996  
**Received Issue Date:** 5/24/1996  
**Action:** Warning Letter - #22495  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 2/15/1995  
**Received Issue Date:** 10/7/1997  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 11/14/1994  
**Received Issue Date:** 11/14/1994  
**Action:** Staff Letter - #22493

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Doc Link:**

**Title Description Comments:**

**Action Type:** Referral to Other Agency  
**Action Date:** 8/22/1994  
**Received Issue Date:** 8/22/1994  
**Action:** Referral to Local Agency - #43-0635  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&enforcement\\_id=6261824&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&enforcement_id=6261824&temptable=ENFORCEMENT)

**Title Description Comments:**

Reinstatement of Lead Oversight Request

**Action Type:** Enforcement/Orders  
**Action Date:** 8/13/1993  
**Received Issue Date:** 8/13/1993  
**Action:** 13267 Requirement - #43-0635  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&enforcement\\_id=6264811&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&enforcement_id=6264811&temptable=ENFORCEMENT)

**Title Description Comments:**

Workplan for Cleanup Requested

**Action Type:** Enforcement/Orders  
**Action Date:** 8/3/1993  
**Received Issue Date:** 8/3/1993  
**Action:** Notice of Violation - #39642  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 10/17/1988  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Cleanup Action  
**Action Date:** 10/10/1995  
**Received Issue Date:**  
**Action:** Excavation  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents  
**Document Date:** 1/27/1999  
**Size :**  
**Submitted By:** COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT  
**Title:** SCVWD ELECTRONIC FILES  
**Submitted:**  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&document\\_id=5842163](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&document_id=5842163)

**Document Type:** Site Documents  
**Document Date:** 1/27/1999  
**Size :**  
**Submitted By:** COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER  
**Title:** UNKNOWN  
**Submitted:**  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&enforcement\\_id=6245912](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&enforcement_id=6245912)

**Document Type:** Site Documents  
**Document Date:** 8/22/1994  
**Size :**  
**Submitted By:** ASHA TURMAN (REGULATOR)  
**Type:** REFERRAL TO LOCAL AGENCY  
**Submitted:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Title:** REINSTATEMENT OF LEAD OVERSIGHT REQUEST  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&enforcement\\_id=6261824](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&enforcement_id=6261824)

**Document Type:** Site Documents **Size :**  
**Document Date:** 8/13/1993 **Submitted By:** ASHA TURMAN (REGULATOR)  
**Type:** 13267 REQUIREMENT **Submitted:**

**Title:** WORKPLAN FOR CLEANUP REQUESTED  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500669&enforcement\\_id=6264811](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500669&enforcement_id=6264811)

<a href="#">13</a>	3 of 5	ESE	0.18 / 960.56	74.80 / 0	GASCO SERVICE STATION 007 2391 THE ALAMEDA SANTA CLARA CA 95050	HHSS
--------------------	--------	-----	---------------	-----------	---	------

**County:** Santa Clara  
**Tank Details Microfiche:** <http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002d279.pdf>

<a href="#">13</a>	4 of 5	ESE	0.18 / 960.56	74.80 / 0	GASCO SERVICE STATION #007 2391 THE ALAMEDA SANTA CLARA CA	HIST TANK
--------------------	--------	-----	---------------	-----------	--	-----------

**Owner Name:** DESERT PETROLEUM, INC. **No of Containers:** 4  
**Owner Street:** POST OFFICE BOX 1601 **County:** SANTA CLARA  
**Owner City:** OXNARD **Facility State:** CA  
**Owner State:** CA **Facility Zip:** 95050  
**Owner Zip:** 93032

<a href="#">13</a>	5 of 5	ESE	0.18 / 960.56	74.80 / 0	GASCO SERVICE STATION #007 2391 THE ALAMEDA SANTA CLARA CA	UST SWEEPS
--------------------	--------	-----	---------------	-----------	--	------------

**C C:** 143-010-9193 **D Filename:** NSITE6  
**BOE:** 44-011175 **Page No:** 429  
**Comp:** 9193 **County:** SANTA CLARA  
**Status:** INACTIVE **State :** CA  
**No of Tanks:** 4 **Zip:** 95050  
**Jurisdic:** CITY OF SANTA CLARA **Latitude:** 0  
**Agency:** FIRE DEPARTMENT **Longitude:** 0  
**Phone:** (408) 296-9969 **Georesult:** N

**Tank Details**

**Tank ID:** 000003 **S Contain:** NONE  
**O Tank ID:** **Stg:**  
**SWRCB No:** 43-010-009193-000003 **Storage :** PRODUCT  
**Removed:** 01-26-90 **Storag Type:** PRODUCT  
**Installed:** 01-01-01 **P Contain:** BARE STEEL  
**A Date:** **Content:** REG UNLEADED  
**Capac:** 12000 **ONA:**  
**Tank Use:** M.V. FUEL **D File Name:** NTANK6

**Tank Details**

**Tank ID:** 000004 **S Contain:** NONE  
**O Tank ID:** **Stg:**  
**SWRCB No:** 43-010-009193-000004 **Storage :** PRODUCT  
**Removed:** 01-26-90 **Storag Type:** PRODUCT  
**Installed:** 01-01-01 **P Contain:** BARE STEEL  
**A Date:** **Content:** LEADED  
**Capac:** 5000 **ONA:**  
**Tank Use:** M.V. FUEL **D File Name:** NTANK6

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Tank Details**

<b>Tank ID:</b>	000002	<b>S Contain:</b>	NONE
<b>O Tank ID:</b>		<b>Stg:</b>	
<b>SWRCB No:</b>	43-010-009193-000002	<b>Storage :</b>	PRODUCT
<b>Removed:</b>	01-26-90	<b>Storag Type:</b>	PRODUCT
<b>Installed:</b>	01-01-01	<b>P Contain:</b>	BARE STEEL
<b>A Date:</b>		<b>Content:</b>	LEADED
<b>Capac:</b>	5000	<b>ONA:</b>	
<b>Tank Use:</b>	M.V. FUEL	<b>D File Name:</b>	NTANK6

**Tank Details**

<b>Tank ID:</b>	000001	<b>S Contain:</b>	NONE
<b>O Tank ID:</b>		<b>Stg:</b>	
<b>SWRCB No:</b>	43-010-009193-000001	<b>Storage :</b>	PRODUCT
<b>Removed:</b>	01-26-90	<b>Storag Type:</b>	PRODUCT
<b>Installed:</b>	01-01-01	<b>P Contain:</b>	BARE STEEL
<b>A Date:</b>		<b>Content:</b>	LEADED
<b>Capac:</b>	5000	<b>ONA:</b>	
<b>Tank Use:</b>	M.V. FUEL	<b>D File Name:</b>	NTANK6

<a href="#"><u>14</u></a>	1 of 1	<b>SSE</b>	<b>0.18 / 970.97</b>	<b>77.65 / 3</b>	<b>Summerhill Development 2655 Park Ave CA</b>	<b>HSOL SANTA CLARA</b>
---------------------------	--------	------------	----------------------	------------------	--	-----------------------------

**SCVWD ID:** 06S3W12G07s  
**Solvent Files:** <http://cf.valleywater.org/Zim/Zim%20Files/06/06S3W12G07s/>  
**County:** Santa Clara

<a href="#"><u>15</u></a>	1 of 1	<b>SE</b>	<b>0.19 / 991.94</b>	<b>77.92 / 3</b>	<b>ALBERT RUIZ 600 MISSION ST SANTA CLARA CA 95050-6041</b>	<b>RCRA NON GEN</b>
---------------------------	--------	-----------	----------------------	------------------	---	-------------------------

**EPA Handler ID:** CAC003043442  
**Gen Status Universe:** No Report  
**Contact Name:** ALBERT RUIZ  
**Contact Address:** 600 MISSION ST , , SANTA CLARA , CA, 95050-6041 ,  
**Contact Phone No and Ext:** 626-327-2722  
**Contact Email:** MARIAE@PWSEI.COM  
**Contact Country:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Land Type:**  
**Receive Date:** 20191115  
**Location Latitude:**  
**Location Longitude:**

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Furnace Exemption:** No  
**Underground Injection Activity:** No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

**Hazardous Waste Handler Details**

Sequence No: 1  
 Receive Date: 20191115  
 Handler Name: ALBERT RUIZ  
 Source Type: Implementer  
 Federal Waste Generator Code: N  
 Generator Code Description: Not a Generator, Verified

**Owner/Operator Details**

<b>Owner/Operator Ind:</b>	Current Operator	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	600 MISSION ST
<b>Name:</b>	ALBERT RUIZ	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	626-327-2722	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95050-6041

  

<b>Owner/Operator Ind:</b>	Current Owner	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	600 MISSION ST
<b>Name:</b>	ALBERT RUIZ	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	626-327-2722	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95050-6041

[16](#) 1 of 1 SSW 0.20 / 1,071.34 80.82 / 6 HUBBLE SAND AND GRAVEL SANTA CLARA COUNTY SANTA CLARA CA 95050 MRDS

Dep ID: 10116582 I1: 16  
 Dev Status: UNKNOWN Latitude: 37.343323  
 Code List: SDG Longitude: -121.939087  
 Url: [http://mrddata.usgs.gov/mrds/show-mrds.php?dep\\_id=10116582](http://mrddata.usgs.gov/mrds/show-mrds.php?dep_id=10116582)

**Commodity**

<b>I1:</b>	25	<b>Line:</b>	1
<b>Code:</b>	SDG	<b>Inserted By:</b>	MAS migration
<b>Commodity:</b>	Sand and Gravel, Cons	<b>Insert Date:</b>	29-OCT-2002 09:00:24
<b>Commodity Type:</b>	Non-metallic	<b>Updated By:</b>	USGS
<b>Commodity Group:</b>	Sand and Gravel	<b>Update Date:</b>	29-OCT-2002 09:01:20
<b>Importance:</b>	Primary		

**Names**

<b>I1:</b>	13	<b>Inserted By:</b>	MAS migration
<b>Status:</b>	Current	<b>Insert Date:</b>	29-OCT-02
<b>Site Name:</b>	Hubble Sand and Gravel	<b>Updated By:</b>	USGS
<b>Line:</b>	1	<b>Update Date:</b>	29-OCT-02

[17](#) 1 of 2 E 0.21 / 73.28 / SANTA CLARA U. LOYOLA HALL ALT FUELS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
			1,109.23	-2	LT1 425 El Camino Real Santa Clara CA 95050	
<b>Fuel Type Code:</b>	ELEC: Electric				<b>ID:</b> 160868	
<b>Station Phone:</b>	888-758-4389				<b>Updated at:</b> 2021-12-21 00:28:58 UTC	
<b>Expected Date:</b>					<b>CNG Dispenser No:</b>	
<b>BD Blends:</b>					<b>CNG Site Renew Src:</b>	
<b>NG Fill Type Code:</b>					<b>CNG Tot Compr Cap:</b>	
<b>NG PSI:</b>					<b>CNG Storage Cap:</b>	
<b>Federal Agency ID:</b>					<b>CNG Fill Type Code:</b>	
<b>Open Date:</b>	2020-06-12				<b>CNG PSI:</b>	
<b>NG Vehicle Class:</b>					<b>CNG Vehicle Class:</b>	
<b>LPG Primary:</b>					<b>LNG Site Renew Src:</b>	
<b>E85 Blender Pump:</b>					<b>LNG Vehicle Class:</b>	
<b>NG Fill Type Desc:</b>					<b>LPG Nozzle Types:</b>	
<b>Hydrogen is Retail:</b>					<b>Hydrogen Pressures:</b>	
<b>Federal Agency:</b>					<b>Hydrogen Standards:</b>	
<b>Facility Type:</b>					<b>Latitude:</b> 37.346172	
<b>Dt Last Confirmed:</b>	2021-12-21				<b>Longitude:</b> -121.932849	
<b>Restricted Access:</b>						
<b>Fed Agency Name:</b>						
<b>Hydrogen Status Link:</b>						
<b>Status:</b>		Open: The station is open.				
<b>Owner Type Desc:</b>						
<b>E85 Blender Pump Desc:</b>						
<b>NG Vehicle Class Desc:</b>						
<b>Geocode Status Desc:</b>		The location is from a real GPS readout at the station.				
<b>LPG Primary Desc:</b>						
<b>E85 Other Ethanol Blends:</b>						
<b>EV Pricing:</b>						
<b>EV Pricing French:</b>						
<b>EV on Site Renewable Source:</b>						
<b>Intersection Directions:</b>						

<a href="#">17</a>	2 of 2	E	0.21 / 1,109.23	73.28 / -2	SANTA CLARA U. LOYOLA HALL LT3 425 El Camino Real Santa Clara CA 95050	ALT FUELS
<b>Fuel Type Code:</b>	ELEC: Electric				<b>ID:</b> 179429	
<b>Station Phone:</b>	888-758-4389				<b>Updated at:</b> 2021-12-21 00:28:58 UTC	
<b>Expected Date:</b>					<b>CNG Dispenser No:</b>	
<b>BD Blends:</b>					<b>CNG Site Renew Src:</b>	
<b>NG Fill Type Code:</b>					<b>CNG Tot Compr Cap:</b>	
<b>NG PSI:</b>					<b>CNG Storage Cap:</b>	
<b>Federal Agency ID:</b>					<b>CNG Fill Type Code:</b>	
<b>Open Date:</b>	2021-01-27				<b>CNG PSI:</b>	
<b>NG Vehicle Class:</b>					<b>CNG Vehicle Class:</b>	
<b>LPG Primary:</b>					<b>LNG Site Renew Src:</b>	
<b>E85 Blender Pump:</b>					<b>LNG Vehicle Class:</b>	
<b>NG Fill Type Desc:</b>					<b>LPG Nozzle Types:</b>	
<b>Hydrogen is Retail:</b>					<b>Hydrogen Pressures:</b>	
<b>Federal Agency:</b>					<b>Hydrogen Standards:</b>	
<b>Facility Type:</b>					<b>Latitude:</b> 37.346467	
<b>Dt Last Confirmed:</b>	2021-12-21				<b>Longitude:</b> -121.93263	
<b>Restricted Access:</b>						
<b>Fed Agency Name:</b>						
<b>Hydrogen Status Link:</b>						
<b>Status:</b>		Open: The station is open.				
<b>Owner Type Desc:</b>						
<b>E85 Blender Pump Desc:</b>						
<b>NG Vehicle Class Desc:</b>						
<b>Geocode Status Desc:</b>		The location is from a real GPS readout at the station.				
<b>LPG Primary Desc:</b>						
<b>E85 Other Ethanol Blends:</b>						
<b>EV Pricing:</b>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

EV Pricing French:  
 EV on Site Renewable Source:  
 Intersection Directions:

<a href="#">18</a>	1 of 1	SSE	0.21 / 1,134.86	78.84 / 4	RADOSLAW WASNIEWSKI 764 COLLEGE AVENUE SANTA CLARA CA 95051	RCRA NON GEN
--------------------	--------	-----	--------------------	--------------	---	-----------------

**EPA Handler ID:** CAC002981704  
**Gen Status Universe:** No Report  
**Contact Name:** RADOSLAW WASNIEWSKI  
**Contact Address:** 764 COLLEGE AVENUE , , SANTA CLARA , CA, 95051 ,  
**Contact Phone No and Ext:** 408-375-8874  
**Contact Email:** SHACARRAHENDERSON@ALLIANCE-ENVIRO.COM  
**Contact Country:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Land Type:**  
**Receive Date:** 20180924  
**Location Latitude:** 37.342963  
**Location Longitude:** -121.93659

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Furnace Exemption:** No  
**Underground Injection Activity:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No  
**Used Oil Burner:** No  
**Used Oil Market Burner:** No  
**Used Oil Spec Marketer:** No

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 20180924  
**Handler Name:** RADOSLAW WASNIEWSKI  
**Source Type:** Implementer  
**Federal Waste Generator Code:** N  
**Generator Code Description:** Not a Generator, Verified

**Owner/Operator Details**

<b>Owner/Operator Ind:</b> Current Operator	<b>Street No:</b>
<b>Type:</b> Other	<b>Street 1:</b> 764 COLLEGE AVENUE
<b>Name:</b> RADOSLAW WASNIEWSKI	<b>Street 2:</b>
<b>Date Became Current:</b>	<b>City:</b> SANTA CLARA
<b>Date Ended Current:</b>	<b>State:</b> CA
<b>Phone:</b> 408-375-8874	<b>Country:</b>

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Source Type:</b>		Implementer	<b>Zip Code:</b>		95051	
<b>Owner/Operator Ind:</b>		Current Owner	<b>Street No:</b>			
<b>Type:</b>		Other	<b>Street 1:</b>		764 COLLEGE AVENUE	
<b>Name:</b>		RADOSLAW WASNIEWSKI	<b>Street 2:</b>			
<b>Date Became Current:</b>			<b>City:</b>		SANTA CLARA	
<b>Date Ended Current:</b>			<b>State:</b>		CA	
<b>Phone:</b>		408-375-8874	<b>Country:</b>			
<b>Source Type:</b>		Implementer	<b>Zip Code:</b>		95051	
<a href="#">19</a>	1 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Santa Clara University 500 El Camino Real Santa Clara CA	LOP SANTA CLARA
<b>SCVWD ID:</b>		07S1W02R01f				
<b>Closure Date:</b>		6/29/2005				
<b>Link:</b>		http://lustop.sccgov.org/files/07S1W02R01f/				
<a href="#">19</a>	2 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Santa Clara University 500 El Camino Real, 604 Santa Clara CA	AST
<b>Total Capacity(Gal):</b>		1,650	<b>Owner Name:</b>			
<b>CUPA:</b>		Santa Clara City	<b>County:</b>		Santa Clara	
<a href="#">19</a>	3 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Santa Clara University 500 El Camino Real, 304 Santa Clara CA	AST
<b>Total Capacity(Gal):</b>		2,000	<b>Owner Name:</b>			
<b>CUPA:</b>		Santa Clara City	<b>County:</b>		Santa Clara	
<a href="#">19</a>	4 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Santa Clara University 500 El Camino Real, 401 Santa Clara CA	AST
<b>Total Capacity(Gal):</b>		2,000	<b>Owner Name:</b>			
<b>CUPA:</b>		Santa Clara City	<b>County:</b>		Santa Clara	
<a href="#">19</a>	5 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Santa Clara University 500 El Camino Real CA	HSOL SANTA CLARA
<b>SCVWD ID:</b>		07S1W02L02s				
<b>Solvent Files:</b>		http://cf.valleywater.org/Zim/Zim%20Files/07/07S1W02L02s/				
<b>County:</b>		Santa Clara				
<a href="#">19</a>	6 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 405: Bannan Hall 500 EL CAMINO REAL BLDG 405 SANTA CLARA CA 95053	DELISTED CTNK
<b>Site ID:</b>		100511	<b>Latitude:</b>		37.351820	
<b>County:</b>			<b>Longitude:</b>		-121.937290	
<b>Tank Type:</b>						
<b>Original Source:</b>		CTNK				
<b>Record Date:</b>		13-FEB-2019				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<a href="#">19</a>	7 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 201: Walsh Admin 500 EL CAMINO REAL BLDG 201 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100500			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	8 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 106: Varsi Hall 500 EL CAMINO REAL BLDG 106 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13950			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	9 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 301: Benson Center 500 EL CAMINO REAL BLDG 301 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100505			Latitude:	37.347500	
County:				Longitude:	-121.939400	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	10 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 505: Campisi Residence Hall 500 EL CAMINO REAL BLDG 505 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13963			Latitude:	37.347800	
County:				Longitude:	-121.936800	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	11 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 204: Kenna Hall 500 EL CAMINO REAL BLDG 204 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13955			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	12 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 307: Swig Residence Hall 500 EL CAMINO REAL BLDG 307 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13958			Latitude:	37.347000	
County:				Longitude:	-121.940300	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<a href="#">19</a>	13 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 605A: Sobrato Residence Hall 500 EL CAMINO REAL BLDG 605A SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100515			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	14 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 702: Sullivan Aquatic Center 500 EL CAMINO REAL BLDG 702 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100517			Latitude:	37.348900	
County:				Longitude:	-121.935900	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	15 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 706: Buck Shaw Stadium 500 EL CAMINO REAL BLDG 706 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13965			Latitude:	37.350900	
County:				Longitude:	-121.936300	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	16 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 403: Bannan Engineering Labs 500 EL CAMINO REAL BLDG 403 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100509			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	17 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 109: Nobili Hall 500 EL CAMINO REAL BLDG 109 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13951			Latitude:	37.348900	
County:				Longitude:	-121.942400	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	18 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 303: Bookstore 500 EL CAMINO REAL BLDG 303 SANTA CLARA CA 95053	DELISTED CTNK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Site ID:	100506				Latitude: 37.351820 Longitude: -121.937290	
County:						
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	19 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 102: St. Joseph Hall 500 EL CAMINO REAL SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13949				Latitude: 37.351820 Longitude: -121.937290	
County:						
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	20 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 443: Schott Stadium 500 EL CAMINO REAL BLDG 443 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13961				Latitude: 37.347140 Longitude: -121.934520	
County:						
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	21 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 602: Casa Italiana Residence Hall 500 EL CAMINO REAL BLDG 602 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100514				Latitude: 37.351820 Longitude: -121.937290	
County:						
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	22 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 605B: Sobrato Residence Hall 500 EL CAMINO REAL BLDG 605B SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100516				Latitude: 37.351820 Longitude: -121.937290	
County:						
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	23 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 210: Daly Science 100 Chemistry Building 500 EL CAMINO REAL BLDG 210 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100503				Latitude: 37.350500 Longitude: -121.940500	
County:						
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<a href="#">19</a>	24 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 202: Heafey Law Library 500 EL CAMINO REAL BLDG 202 SANTA CLARA CA 95050	DELISTED CTNK
Site ID:	100501			Latitude:	37.349100	
County:				Longitude:	-121.939600	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	25 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 404: Bannan Engineering 500 EL CAMINO REAL BLDG 404 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	388310			Latitude:	37.349200	
County:				Longitude:	-121.938200	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	26 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 506: Sanfilippo Residence Hall 500 EL CAMINO REAL BLDG 506 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100512			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	27 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 715: Pat Malley Fitness Center 500 EL CAMINO REAL BLDG 715 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	13967			Latitude:	37.348600	
County:				Longitude:	-121.936700	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	28 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 208: Alumni Science 500 EL CAMINO REAL BLDG 208 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100502			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						
Original Source:		CTNK				
Record Date:		04-JAN-2018				
<a href="#">19</a>	29 of 35	WNW	0.23 / 1,189.65	83.20 / 8	Building 211: Daly Science 200 500 EL CAMINO REAL BLDG 211 SANTA CLARA CA 95053	DELISTED CTNK
Site ID:	100504			Latitude:	37.351820	
County:				Longitude:	-121.937290	
Tank Type:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Original Source:</b>		CTNK				
<b>Record Date:</b>		04-JAN-2018				
<a href="#">19</a>	30 of 35	WNW	0.23 / 1,189.65	83.20 / 8	<b>Building 710: Locatelli Student Activity Center</b> 500 EL CAMINO REAL BLDG 710 SANTA CLARA CA 95053	DELISTED CTNK
<b>Site ID:</b>		100518			<b>Latitude:</b> 37.349900	
<b>County:</b>					<b>Longitude:</b> -121.935200	
<b>Tank Type:</b>						
<b>Original Source:</b>		CTNK				
<b>Record Date:</b>		04-JAN-2018				
<a href="#">19</a>	31 of 35	WNW	0.23 / 1,189.65	83.20 / 8	<b>Building 402: Mechanical Engineering</b> 500 EL CAMINO REAL BLDG 402 SANTA CLARA CA 95053	DELISTED CTNK
<b>Site ID:</b>		13960			<b>Latitude:</b> 37.351820	
<b>County:</b>					<b>Longitude:</b> -121.937290	
<b>Tank Type:</b>						
<b>Original Source:</b>		CTNK				
<b>Record Date:</b>		04-JAN-2018				
<a href="#">19</a>	32 of 35	WNW	0.23 / 1,189.65	83.20 / 8	<b>Building 802: Lucas Hall</b> 500 EL CAMINO REAL BLDG 802 SANTA CLARA CA 95053	DELISTED CTNK
<b>Site ID:</b>		13968			<b>Latitude:</b> 37.351820	
<b>County:</b>					<b>Longitude:</b> -121.937290	
<b>Tank Type:</b>						
<b>Original Source:</b>		CTNK				
<b>Record Date:</b>		04-JAN-2018				
<a href="#">19</a>	33 of 35	WNW	0.23 / 1,189.65	83.20 / 8	<b>Building 714: Parking Structure</b> 500 EL CAMINO REAL BLDG 714 SANTA CLARA CA 95053	DELISTED CTNK
<b>Site ID:</b>		13966			<b>Latitude:</b> 37.349400	
<b>County:</b>					<b>Longitude:</b> -121.937400	
<b>Tank Type:</b>						
<b>Original Source:</b>		CTNK				
<b>Record Date:</b>		04-JAN-2018				
<a href="#">19</a>	34 of 35	WNW	0.23 / 1,189.65	83.20 / 8	<b>SANTA CLARA U. CAMPISI GW OLD</b> 500 El Camino Real Cowell Service Road Santa Clara CA 95053	ALT FUELS
<b>Fuel Type Code:</b>		ELEC: Electric			<b>ID:</b> 196194	
<b>Station Phone:</b>		888-758-4389			<b>Updated at:</b> 2021-12-21 00:28:58 UTC	
<b>Expected Date:</b>						
<b>BD Blends:</b>						
<b>NG Fill Type Code:</b>						
<b>NG PSI:</b>						
<b>Federal Agency ID:</b>						
<b>Open Date:</b>		2021-09-23			<b>CNG Dispenser No:</b>	
<b>NG Vehicle Class:</b>		<b>CNG Site Renew Src:</b>				
		<b>CNG Tot Compr Cap:</b>				
		<b>CNG Storage Cap:</b>				
		<b>CNG Fill Type Code:</b>				
		<b>CNG PSI:</b>				
		<b>CNG Vehicle Class:</b>				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>LPG Primary:</b> <b>E85 Blender Pump:</b> <b>NG Fill Type Desc:</b> <b>Hydrogen is Retail:</b> <b>Federal Agency:</b> <b>Facility Type:</b> <b>Dt Last Confirmed:</b> 2021-12-21 <b>Restricted Access:</b> <b>Fed Agency Name:</b> <b>Hydrogen Status Link:</b> <b>Status:</b> <b>Owner Type Desc:</b> <b>E85 Blender Pump Desc:</b> <b>NG Vehicle Class Desc:</b> <b>Geocode Status Desc:</b> <b>LPG Primary Desc:</b> <b>E85 Other Ethanol Blends:</b> <b>EV Pricing:</b> <b>EV Pricing French:</b> <b>EV on Site Renewable Source:</b> <b>Intersection Directions:</b>					<b>LNG Site Renew Src:</b> <b>LNG Vehicle Class:</b> <b>LPG Nozzle Types:</b> <b>Hydrogen Pressures:</b> <b>Hydrogen Standards:</b> <b>Latitude:</b> 37.348253 <b>Longitude:</b> -121.93603	
		Open: The station is open.				
		The location is from a real GPS readout at the station.				

<a href="#">19</a>	35 of 35	WNW	0.23 / 1,189.65	83.20 / 8	SANTA CLARA U. CAMPISI GW 2 500 El Camino Real Cowell Service Road Santa Clara CA 95053	ALT FUELS
--------------------	----------	-----	-----------------	-----------	--	-----------

<b>Fuel Type Code:</b>	ELEC: Electric	<b>ID:</b>	196199
<b>Station Phone:</b>	888-758-4389	<b>Updated at:</b>	2021-12-21 00:28:58 UTC
<b>Expected Date:</b>		<b>CNG Dispenser No:</b>	
<b>BD Blends:</b>		<b>CNG Site Renew Src:</b>	
<b>NG Fill Type Code:</b>		<b>CNG Tot Compr Cap:</b>	
<b>NG PSI:</b>		<b>CNG Storage Cap:</b>	
<b>Federal Agency ID:</b>		<b>CNG Fill Type Code:</b>	
<b>Open Date:</b>	2021-09-23	<b>CNG PSI:</b>	
<b>NG Vehicle Class:</b>		<b>CNG Vehicle Class:</b>	
<b>LPG Primary:</b>		<b>LNG Site Renew Src:</b>	
<b>E85 Blender Pump:</b>		<b>LNG Vehicle Class:</b>	
<b>NG Fill Type Desc:</b>		<b>LPG Nozzle Types:</b>	
<b>Hydrogen is Retail:</b>		<b>Hydrogen Pressures:</b>	
<b>Federal Agency:</b>		<b>Hydrogen Standards:</b>	
<b>Facility Type:</b>		<b>Latitude:</b>	37.348251
<b>Dt Last Confirmed:</b>	2021-12-21	<b>Longitude:</b>	-121.935991
<b>Restricted Access:</b>			
<b>Fed Agency Name:</b>			
<b>Hydrogen Status Link:</b>			
<b>Status:</b>	Open: The station is open.		
<b>Owner Type Desc:</b>			
<b>E85 Blender Pump Desc:</b>			
<b>NG Vehicle Class Desc:</b>			
<b>Geocode Status Desc:</b>	The location is from a real GPS readout at the station.		
<b>LPG Primary Desc:</b>			
<b>E85 Other Ethanol Blends:</b>			
<b>EV Pricing:</b>			
<b>EV Pricing French:</b>			
<b>EV on Site Renewable Source:</b>			
<b>Intersection Directions:</b>			

<a href="#">20</a>	1 of 2	WNW	0.23 / 1,230.08	82.73 / 8	SANTA CLARA U. VARSİ LOT #2 601-699 Lafayette St Santa Clara CA 95050	ALT FUELS
--------------------	--------	-----	-----------------	-----------	---	-----------

<b>Fuel Type Code:</b>	ELEC: Electric	<b>ID:</b>	196200
<b>Station Phone:</b>	888-758-4389	<b>Updated at:</b>	2021-12-21 00:28:58 UTC
<b>Expected Date:</b>		<b>CNG Dispenser No:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>BD Blends:</b> <b>NG Fill Type Code:</b> <b>NG PSI:</b> <b>Federal Agency ID:</b> <b>Open Date:</b> 2021-09-23 <b>NG Vehicle Class:</b> <b>LPG Primary:</b> <b>E85 Blender Pump:</b> <b>NG Fill Type Desc:</b> <b>Hydrogen is Retail:</b> <b>Federal Agency:</b> <b>Facility Type:</b> <b>Dt Last Confirmed:</b> 2021-12-21 <b>Restricted Access:</b> <b>Fed Agency Name:</b> <b>Hydrogen Status Link:</b> <b>Status:</b> Open: The station is open. <b>Owner Type Desc:</b> <b>E85 Blender Pump Desc:</b> <b>NG Vehicle Class Desc:</b> <b>Geocode Status Desc:</b> The location is from a real GPS readout at the station. <b>LPG Primary Desc:</b> <b>E85 Other Ethanol Blends:</b> <b>EV Pricing:</b> <b>EV Pricing French:</b> <b>EV on Site Renewable Source:</b> <b>Intersection Directions:</b>					<b>CNG Site Renew Src:</b> <b>CNG Tot Compr Cap:</b> <b>CNG Storage Cap:</b> <b>CNG Fill Type Code:</b> <b>CNG PSI:</b> <b>CNG Vehicle Class:</b> <b>LNG Site Renew Src:</b> <b>LNG Vehicle Class:</b> <b>LPG Nozzle Types:</b> <b>Hydrogen Pressures:</b> <b>Hydrogen Standards:</b> <b>Latitude:</b> 37.347804 <b>Longitude:</b> -121.941644	

[20](#) 2 of 2 **WNW** 0.23 / 1,230.08 82.73 / 8 **SANTA CLARA U. VARS! LOT #1** **601-699 Lafayette St** **Santa Clara CA 95050** **ALT FUELS**

<b>Fuel Type Code:</b> ELEC: Electric <b>Station Phone:</b> 888-758-4389 <b>Expected Date:</b> <b>BD Blends:</b> <b>NG Fill Type Code:</b> <b>NG PSI:</b> <b>Federal Agency ID:</b> <b>Open Date:</b> 2021-09-23 <b>NG Vehicle Class:</b> <b>LPG Primary:</b> <b>E85 Blender Pump:</b> <b>NG Fill Type Desc:</b> <b>Hydrogen is Retail:</b> <b>Federal Agency:</b> <b>Facility Type:</b> <b>Dt Last Confirmed:</b> 2021-12-21 <b>Restricted Access:</b> <b>Fed Agency Name:</b> <b>Hydrogen Status Link:</b> <b>Status:</b> Open: The station is open. <b>Owner Type Desc:</b> <b>E85 Blender Pump Desc:</b> <b>NG Vehicle Class Desc:</b> <b>Geocode Status Desc:</b> The location is from a real GPS readout at the station. <b>LPG Primary Desc:</b> <b>E85 Other Ethanol Blends:</b> <b>EV Pricing:</b> <b>EV Pricing French:</b> <b>EV on Site Renewable Source:</b> <b>Intersection Directions:</b>					<b>ID:</b> 196204 <b>Updated at:</b> 2021-12-21 00:28:58 UTC <b>CNG Dispenser No:</b> <b>CNG Site Renew Src:</b> <b>CNG Tot Compr Cap:</b> <b>CNG Storage Cap:</b> <b>CNG Fill Type Code:</b> <b>CNG PSI:</b> <b>CNG Vehicle Class:</b> <b>LNG Site Renew Src:</b> <b>LNG Vehicle Class:</b> <b>LPG Nozzle Types:</b> <b>Hydrogen Pressures:</b> <b>Hydrogen Standards:</b> <b>Latitude:</b> 37.347897 <b>Longitude:</b> -121.941738	
--	--	--	--	--	---	--

[21](#) 1 of 1 **SSE** 0.24 / 1,280.06 79.49 / 4 **MARK & TIFFANY HAIGH** **763 CAMINO DRIVE** **RCRA NON GEN**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

SANTA CLARA CA 95050

**EPA Handler ID:** CAC002965490  
**Gen Status Universe:** No Report  
**Contact Name:** MARK & TIFFANY HAIGH  
**Contact Address:** 763 CAMINO DRIVE , , SANTA CLARA , CA, 95050 ,  
**Contact Phone No and Ext:** 408-667-0149  
**Contact Email:** JOHN@JWHARS.COM  
**Contact Country:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Land Type:**  
**Receive Date:** 20180607  
**Location Latitude:** 37.342391  
**Location Longitude:** -121.936102

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Furnace Exemption:** No  
**Underground Injection Activity:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No  
**Used Oil Burner:** No  
**Used Oil Market Burner:** No  
**Used Oil Spec Marketer:** No

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 20180607  
**Handler Name:** MARK & TIFFANY HAIGH  
**Source Type:** Implementer  
**Federal Waste Generator Code:** N  
**Generator Code Description:** Not a Generator, Verified

**Owner/Operator Details**

<b>Owner/Operator Ind:</b> Current Owner	<b>Street No:</b>
<b>Type:</b> Other	<b>Street 1:</b> 763 CAMINO DRIVE
<b>Name:</b> MARK & TIFFANY HAIGH	<b>Street 2:</b>
<b>Date Became Current:</b>	<b>City:</b> SANTA CLARA
<b>Date Ended Current:</b>	<b>State:</b> CA
<b>Phone:</b> 408-667-0149	<b>Country:</b>
<b>Source Type:</b> Implementer	<b>Zip Code:</b> 95050

  

<b>Owner/Operator Ind:</b> Current Operator	<b>Street No:</b>
<b>Type:</b> Other	<b>Street 1:</b> 763 CAMINO DRIVE
<b>Name:</b> MARK & TIFFANY HAIGH	<b>Street 2:</b>
<b>Date Became Current:</b>	<b>City:</b> SANTA CLARA
<b>Date Ended Current:</b>	<b>State:</b> CA
<b>Phone:</b> 408-667-0149	<b>Country:</b>

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Source Type:</b>		Implementer	<b>Zip Code:</b>		95050	

[22](#) 1 of 2 ESE 0.24 / 1,292.78 73.49 / -2 Highway 82 Segment 5 2245 The Alameda Santa Clara CA LOP SANTA CLARA

SCVWD ID: 07S1W11A03f  
 Closure Date: 9/30/2008  
 Link: http://lustop.sccgov.org/files/07S1W11A03f/

[22](#) 2 of 2 ESE 0.24 / 1,292.78 73.49 / -2 HIGHWAY 82 SEGMENT 5 2245 THE ALAMEDA SANTA CLARA CA 95050 LUST

Global ID: T0608502090 County: SANTA CLARA  
 Status: COMPLETED - CASE CLOSED Latitude:  
 Status Date: Longitude:  
 Case Type: LUST CLEANUP SITE  
 Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

RB Case No: Potential COC: Gasoline  
 Local Case No: 07S1W11A03f How Discovered:  
 Begin Date: 10/13/1994 Stop Method:  
 Lead Agency: SANTA CLARA COUNTY LOP Stop Description:  
 Local Agency: Case Worker:  
 CUF Case: NO File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media of Concern: Other Groundwater (uses other than drinking water)  
 How Discovered Description:  
 Calwater Watershed Name: Santa Clara - Palo Alto (205.50)  
 DWR GW Subbasin Name: Santa Clara Valley - Santa Clara (2-009.02)  
 Disadvantaged Community:  
 Calenviroscreen Score: 41-45%  
 Site History:

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

Action Type: ENFORCEMENT  
 Date : 9/30/2008  
 Action: Closure/No Further Action Letter

Action Type: RESPONSE  
 Date : 6/3/2005  
 Action: Other Report / Document

Action Type: ENFORCEMENT  
 Date : 6/3/2005  
 Action: Other Report

Action Type: RESPONSE  
 Date : 5/31/2005  
 Action: Well Destruction Report

Action Type: RESPONSE  
 Date : 3/30/2004  
 Action: Well Installation Report

Action Type: RESPONSE  
 Date : 3/30/2004  
 Action: Monitoring Report - Quarterly

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		7/14/2003				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		5/7/2003				
<b>Action:</b>		Staff Letter - #41277				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		4/9/2003				
<b>Action:</b>		Other Workplan				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		1/13/2003				
<b>Action:</b>		Soil and Water Investigation Workplan				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		10/21/2002				
<b>Action:</b>		Staff Letter - #38792				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		7/22/2002				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		3/16/2001				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		1/25/2001				
<b>Action:</b>		Staff Letter - #22544				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		7/5/1999				
<b>Action:</b>		Soil and Water Investigation Workplan				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		6/2/1999				
<b>Action:</b>		Staff Letter - #22540				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		3/27/1997				
<b>Action:</b>		Notice of Responsibility - #39644				
<b>Action Type:</b>		Other				
<b>Date :</b>		12/23/1994				
<b>Action:</b>		Leak Reported				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		12/20/1994				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		11/29/1994				
<b>Action:</b>		Unauthorized Release Form				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		10/14/1994				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		1/1/1994				
<b>Action:</b>		Correspondence				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Regional Board Caseworker **Address:** 1515 CLAY ST SUITE 1400

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Contact Name:** Regional Water Board  
**City:** OAKLAND  
**Organization Name:** SAN FRANCISCO BAY RWQCB (REGION 2)  
**Email:**  
**Phone No:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 9/30/2008  
  
**Status:** Open - Case Begin Date  
**Status Date:** 10/13/1994  
  
**Status:** Open - Site Assessment  
**Status Date:** 10/13/1994

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	HIGHWAY 82 SEGMENT 5	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	2245 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502090">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502090</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 9/30/2008		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502090&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502090&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>	NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL NOTIFY PRIOR TO DEVELOPMENT NOTIFY PRIOR TO SUBSURFACE WORK		
<b>Future Land Use:</b>	COMMERCIAL		
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) - CASE #: 07S1W11A03f SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use Desc:</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Site History:</b>			

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 9/30/2008  
  
**Status:** Open - Case Begin Date  
**Date :** 10/13/1994  
  
**Status:** Open - Site Assessment  
**Date :** 10/13/1994

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Date:</b>		9/30/2008				
<b>Received Issue Date:</b>		9/30/2008				
<b>Action:</b>		Closure/No Further Action Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&enforcement_id=5989329&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Closure Letter				
<b>Action Type:</b>		Reports				
<b>Action Date:</b>		6/3/2005				
<b>Received Issue Date:</b>		6/3/2005				
<b>Action:</b>		Other Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&enforcement_id=6324347&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Map & Metroscan Information 06/03/2005				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		6/3/2005				
<b>Received Issue Date:</b>		6/3/2005				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927516				
<b>Title Description Comments:</b>		State Information 06/03/2005				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		6/3/2005				
<b>Received Issue Date:</b>		6/3/2005				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927515				
<b>Title Description Comments:</b>		Phone Log 06/03/2005				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		5/31/2005				
<b>Received Issue Date:</b>		5/31/2005				
<b>Action:</b>		Well Destruction Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927520				
<b>Title Description Comments:</b>		Well Abandonment/Destruction 05/31/2005				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		3/30/2004				
<b>Received Issue Date:</b>		3/30/2004				
<b>Action:</b>		Well Installation Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927519				
<b>Title Description Comments:</b>		Well Construction Application 03/30/2004				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		3/30/2004				
<b>Received Issue Date:</b>		3/30/2004				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927512				
<b>Title Description Comments:</b>		GW Monitoring Report 03/30/2004 - 05/21/2004				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					7/14/2003	
<b>Received Issue Date:</b>					4/16/2004	
<b>Action:</b>					Soil and Water Investigation Report	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Soil and Water Investigation Report	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					5/7/2003	
<b>Received Issue Date:</b>					5/7/2003	
<b>Action:</b>					Staff Letter - #41277	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Workplans	
<b>Action Date:</b>					4/9/2003	
<b>Received Issue Date:</b>					4/9/2003	
<b>Action:</b>					Other Workplan	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&amp;doc_id=5927521">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&amp;doc_id=5927521</a>	
<b>Title Description Comments:</b>						
					Work Plan 04/09/2003	
<b>Action Type:</b>					Response Requested - Workplans	
<b>Action Date:</b>					1/13/2003	
<b>Received Issue Date:</b>					4/10/2003	
<b>Action:</b>					Soil and Water Investigation Workplan	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Soil and Water Investigation Workplan	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					10/21/2002	
<b>Received Issue Date:</b>					10/21/2002	
<b>Action:</b>					Staff Letter - #38792	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					7/22/2002	
<b>Received Issue Date:</b>					7/22/2002	
<b>Action:</b>					Other Report / Document	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&amp;doc_id=5927513">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&amp;doc_id=5927513</a>	
<b>Title Description Comments:</b>						
					Miscellaneous Report 07/22/2002	
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					3/16/2001	
<b>Received Issue Date:</b>					10/1/2002	
<b>Action:</b>					Soil and Water Investigation Report	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Soil and Water Investigation Report	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					1/25/2001	
<b>Received Issue Date:</b>					1/25/2001	
<b>Action:</b>					Staff Letter - #22544	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/2/1999  
**Received Issue Date:** 6/2/1999  
**Action:** Staff Letter - #22540

**Doc Link:**  
**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 3/27/1997  
**Received Issue Date:** 3/27/1997  
**Action:** Notice of Responsibility - #39644

**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 12/20/1994  
**Received Issue Date:** 12/20/1994  
**Action:** Soil and Water Investigation Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502090&doc\\_id=5927517](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927517)

**Title Description Comments:**

Soil & Water Investigation Report 12/20/1994

**Action Type:** Response Requested - Other  
**Action Date:** 11/29/1994  
**Received Issue Date:** 11/29/1994  
**Action:** Unauthorized Release Form  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502090&doc\\_id=5927518](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927518)

**Title Description Comments:**

Unauthorized Release Report 11/29/1994

**Action Type:** Response Requested - Other  
**Action Date:** 10/14/1994  
**Received Issue Date:** 10/14/1994  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502090&doc\\_id=5927514](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927514)

**Title Description Comments:**

Miscellaneous Sample Results 10/14/1994

**Action Type:** Response Requested - Other  
**Action Date:** 1/1/1994  
**Received Issue Date:** 1/1/1994  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502090&doc\\_id=5927511](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502090&doc_id=5927511)

**Title Description Comments:**

Correspondence 1994

**Action Type:** Response Requested - Workplans  
**Action Date:** 7/5/1999  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Workplan

**Doc Link:**

**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Leak Action

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Date:</b>		12/23/1994				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b><u>LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)</u></b>						
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	9/30/2008			<b>Submitted By:</b>	KRISTI CONG (REGULATOR)	
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER			<b>Submitted:</b>		
<b>Title:</b>	CLOSURE LETTER					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;enforcement_id=5989329">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;enforcement_id=5989329</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/3/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT			<b>Submitted:</b>		
<b>Title:</b>	MAP & METROSCAN INFORMATION 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;enforcement_id=6324347">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;enforcement_id=6324347</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/3/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	STATE INFORMATION 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927516">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927516</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/3/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	PHONE LOG 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927515">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927515</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	5/31/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	WELL DESTRUCTION REPORT			<b>Submitted:</b>		
<b>Title:</b>	WELL ABANDONMENT/DESTRUCTION 05/31/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927520">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927520</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,220 KB	
<b>Document Date:</b>	3/30/2004			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 03/30/2004 - 05/21/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7200911581/GWM%5FR%5F2004%2D05%2D21%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7200911581/GWM%5FR%5F2004%2D05%2D21%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,343 KB	
<b>Document Date:</b>	3/30/2004			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 03/30/2004 - 05/21/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7200911581/GWM%5FR%5F2004%2D03%2D30%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7200911581/GWM%5FR%5F2004%2D03%2D30%2Epdf</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	3/30/2004			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	WELL INSTALLATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	WELL CONSTRUCTION APPLICATION 03/30/2004					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927519">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927519</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	4/9/2003			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER WORKPLAN			<b>Submitted:</b>		
<b>Title:</b>	WORK PLAN 04/09/2003					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927521">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927521</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	7/22/2002			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title:</b>		MISCELLANEOUS REPORT 07/22/2002				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927513">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927513</a>				
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/20/1994			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT			<b>Submitted:</b>		
<b>Title:</b>		SOIL & WATER INVESTIGATION REPORT 12/20/1994				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927517">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927517</a>				
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	11/29/1994			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	UNAUTHORIZED RELEASE FORM			<b>Submitted:</b>		
<b>Title:</b>		UNAUTHORIZED RELEASE REPORT 11/29/1994				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927518">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927518</a>				
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	10/14/1994			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>		MISCELLANEOUS SAMPLE RESULTS 10/14/1994				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927514">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927514</a>				
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/1/1994			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	CORRESPONDENCE			<b>Submitted:</b>		
<b>Title:</b>		CORRESPONDENCE 1994				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927511">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502090&amp;document_id=5927511</a>				

23

1 of 1

WSW

0.25 /  
1,294.0083.17 /  
8SANTA CLARA USD/BUCHSER  
MIDDLE SCHOOL  
1111 BELLOMY ST  
SANTA CLARA CA 95050-0000RCRA  
NON GEN

**EPA Handler ID:** CAL000015847  
**Gen Status Universe:** No Report  
**Contact Name:** HILDA ZUNIGA  
**Contact Address:** 1889 LAWRENCE RD , , SANTA CLARA , CA, 95051 ,  
**Contact Phone No and Ext:** 408-423-2001  
**Contact Email:** HZUNIGA@SCUSD.NET  
**Contact Country:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Land Type:**  
**Receive Date:** 19891114  
**Location Latitude:** 37.345202  
**Location Longitude:** -121.941899

#### Violation/Evaluation Summary

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

#### Handler Summary

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Furnace Exemption:** No  
**Underground Injection Activity:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Used Oil Burner: No  
 Used Oil Market Burner: No  
 Used Oil Spec Marketer: No

**Hazardous Waste Handler Details**

Sequence No: 1  
 Receive Date: 19891114  
 Handler Name: SANTA CLARA USD/BUCHSER MIDDLE SCHOOL  
 Source Type: Implementer  
 Federal Waste Generator Code: N  
 Generator Code Description: Not a Generator, Verified

**Owner/Operator Details**

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street 1:	1889 LAWRENCE RD
Name:	HILDA ZUNIGA	Street 2:	
Date Became Current:		City:	SANTA CLARA
Date Ended Current:		State:	CA
Phone:	408-423-2001	Country:	
Source Type:	Implementer	Zip Code:	95051

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street 1:	1889 LAWRENCE RD
Name:	SANTA CLARA USD	Street 2:	
Date Became Current:		City:	SANTA CLARA
Date Ended Current:		State:	CA
Phone:	408-423-2000	Country:	
Source Type:	Implementer	Zip Code:	95051-2162

<a href="#">24</a>	1 of 1	SSW	0.25 / 1,297.08	80.04 / 5	DANIELLE KALITERNA 848 COLLEGE AVENUE SANTA CLARA CA 95060	RCRA NON GEN
--------------------	--------	-----	--------------------	--------------	--	-----------------

EPA Handler ID: CAC003130748  
 Gen Status Universe: No Report  
 Contact Name: DANIELLE KALITERNA  
 Contact Address: 848 COLLEGE AVENUE , , SANTA CLARA , CA, 95060 ,  
 Contact Phone No and Ext: 530-524-6168  
 Contact Email: DMKALITERNA@GMAIL.COM  
 Contact Country:  
 County Name: SANTA CLARA  
 EPA Region: 09  
 Land Type:  
 Receive Date: 20210722  
 Location Latitude:  
 Location Longitude:

**Violation/Evaluation Summary**

Note: NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

Importer Activity: No  
 Mixed Waste Generator: No  
 Transporter Activity: No  
 Transfer Facility: No  
 Onsite Burner Exemption: No  
 Furnace Exemption: No  
 Underground Injection Activity: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

**Hazardous Waste Handler Details**

Sequence No: 1  
 Receive Date: 20210722  
 Handler Name: DANIELLE KALITERNA  
 Source Type: Implementer  
 Federal Waste Generator Code: N  
 Generator Code Description: Not a Generator, Verified

**Owner/Operator Details**

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street 1:	848 COLLEGE AVENUE
Name:	DANIELLE KALITERNA	Street 2:	
Date Became Current:		City:	SANTA CLARA
Date Ended Current:		State:	CA
Phone:	530-524-6168	Country:	
Source Type:	Implementer	Zip Code:	95060

  

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street 1:	848 COLLEGE AVENUE
Name:	DANIELLE KALITERNA	Street 2:	
Date Became Current:		City:	SANTA CLARA
Date Ended Current:		State:	CA
Phone:	530-524-6168	Country:	
Source Type:	Implementer	Zip Code:	95060

[25](#) 1 of 1 ESE 0.27 / 73.38 / ANTONIO BUNTING RCRA TSD  
 1,415.77 -2 529 CHAPMAN CT  
 SANTA CLARA CA 95050

EPA Handler ID: CAC003015579  
 Gen Status Universe: No Report  
 Contact Name: ANTONIO BUNTING  
 Contact Address: 529 CHAPMAN CT , , SANTA CLARA , CA, 95050 ,  
 Contact Phone No and Ext: 707-799-3230  
 Contact Email: MARIA.CARBAJAL@SYNERGYCOMPANIES.ORG  
 Contact Country:  
 Land Type:  
 County Name: SANTA CLARA  
 EPA Region: 09  
 Receive Date: 20190517  
 Location Latitude: 37.344097  
 Location Longitude: -121.932979

**Violation/Evaluation Summary**

Note: NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

Importer Activity: No  
 Mixed Waste Generator: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Transporter Activity:</b>		No				
<b>Transfer Facility:</b>		No				
<b>Onsite Burner Exemption:</b>		No				
<b>Smelting, Melting and Refining:</b>		No				
<b>Underground Injection Control:</b>		No				
<b>Commercial TSD:</b>		No				
<b>Used Oil Transporter:</b>		No				
<b>Used Oil Transfer Facility:</b>		No				
<b>Used Oil Processor:</b>		No				
<b>Used Oil Refiner:</b>		No				
<b>Used Oil Burner:</b>		No				
<b>Used Oil Market Burner:</b>		No				
<b>Used Oil Spec Marketer:</b>		No				

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 20190517  
**Handler Name:** ANTONIO BUNTING  
**Federal Waste Generator Code:** N  
**Generator Code Description:** Not a Generator, Verified  
**Source Type:** Implementer

**Owner/Operator Details**

<b>Owner/Operator Ind:</b>	Current Owner	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	529 CHAPMAN CT
<b>Name:</b>	ANTONIO BUNTING	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	707-799-3230	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95050
<b>Owner/Operator Ind:</b>	Current Operator	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	529 CHAPMAN CT
<b>Name:</b>	ANTONIO BUNTING	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	707-799-3230	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95050

[26](#) 1 of 1 **W** **0.28 / 1,466.71** **86.61 / 11** **SANTA CLARA UNIVERSITY** **680 WASHINGTON ST #3** **SANTA CLARA CA 95050** **RCRA TSD**

**EPA Handler ID:** CAC003018746  
**Gen Status Universe:** No Report  
**Contact Name:** SANTA CLARA UNIVERSITY  
**Contact Address:** 500 EL CAMINO REAL , , SANTA CLARA , CA, 95053 ,  
**Contact Phone No and Ext:** 408-554-4736  
**Contact Email:** SARA.GOMEZ@SYNERGYCOMPANIES.ORG  
**Contact Country:**  
**Land Type:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Receive Date:** 20190607  
**Location Latitude:** 37.346737  
**Location Longitude:** -121.942925

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Smelting, Melting and Refining:** No  
**Underground Injection Control:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No  
**Used Oil Burner:** No  
**Used Oil Market Burner:** No  
**Used Oil Spec Marketer:** No

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 20190607  
**Handler Name:** SANTA CLARA UNIVERSITY  
**Federal Waste Generator Code:** N  
**Generator Code Description:** Not a Generator, Verified Implementer  
**Source Type:** Implementer

**Owner/Operator Details**

<b>Owner/Operator Ind:</b> Current Owner	<b>Street No:</b>	
<b>Type:</b> Other	<b>Street 1:</b>	500 EL CAMINO REAL
<b>Name:</b> SANTA CLARA UNIVERSITY	<b>Street 2:</b>	
<b>Date Became Current:</b>	<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>	<b>State:</b>	CA
<b>Phone:</b> 408-554-4736	<b>Country:</b>	
<b>Source Type:</b> Implementer	<b>Zip Code:</b>	95053

<b>Owner/Operator Ind:</b> Current Operator	<b>Street No:</b>	
<b>Type:</b> Other	<b>Street 1:</b>	500 EL CAMINO REAL
<b>Name:</b> SANTA CLARA UNIVERSITY	<b>Street 2:</b>	
<b>Date Became Current:</b>	<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>	<b>State:</b>	CA
<b>Phone:</b> 408-554-4736	<b>Country:</b>	
<b>Source Type:</b> Implementer	<b>Zip Code:</b>	95053

<a href="#">27</a>	1 of 2	NW	0.28 / 1,489.70	79.60 / 4	SANTA CLARA UNIVERSITY 500 EL CAMINO REAL SANTA CLARA CA 95053	LUST
--------------------	--------	----	--------------------	--------------	--	------

**Global ID:** T0608561207  
**Status:** COMPLETED - CASE CLOSED  
**Status Date:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**County:** SANTA CLARA  
**Latitude:**  
**Longitude:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>		<b>Potential COC:</b>	Waste Oil / Motor / Hydraulic / Lubricating
<b>Local Case No:</b>		<b>How Discovered:</b>	Tank Closure
<b>Begin Date:</b>	10/28/2002	<b>Stop Method:</b>	Close and Remove Tank
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP	<b>Stop Description:</b>	
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP	<b>Case Worker:</b>	UST
<b>CUF Case:</b>	NO	<b>File Location:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Potential Media of Concern:</b>		Soil				
<b>How Discovered Description:</b>						
<b>Calwater Watershed Name:</b>		Santa Clara - Palo Alto (205.50)				
<b>DWR GW Subbasin Name:</b>		Santa Clara Valley - Santa Clara (2-009.02)				
<b>Disadvantaged Community:</b>						
<b>Calenviroscreen Score:</b>		41-45%				
<b>Site History:</b>						

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	6/29/2005
<b>Action:</b>	Closure/No Further Action Letter
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/31/2003
<b>Action:</b>	Unauthorized Release Form
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/17/2003
<b>Action:</b>	Correspondence
<b>Action Type:</b>	Other
<b>Date :</b>	11/25/2002
<b>Action:</b>	Leak Reported
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	11/21/2002
<b>Action:</b>	Unauthorized Release Form
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	11/21/2002
<b>Action:</b>	Tank Removal Report / UST Sampling Report
<b>Action Type:</b>	Other
<b>Date :</b>	10/28/2002
<b>Action:</b>	Leak Discovery
<b>Action Type:</b>	REMEDIATION
<b>Date :</b>	10/28/2002
<b>Action:</b>	

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		
<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	6/29/2005
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	6/28/2005
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	10/28/2002

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**LUST Sites from GeoTracker Search - Regulatory Profile**

**Site Facility Name:** SANTA CLARA UNIVERSITY      **Potential COC:** WASTE OIL / MOTOR / HYDRAULIC / LUBRICATING  
**Site Facility Type:** LUST CLEANUP SITE      **Facility Type:**  
**Cleanup Status:** COMPLETED - CASE CLOSED      **Composting Method:**  
**Project Status:**      **Address:** 500 EL CAMINO REAL  
**WDR Place Type:**      **City:** SANTA CLARA  
**WDR File:**      **Zip:** 95053  
**WDR Order:**      **County:** SANTA CLARA  
**CUF Priority Assig:**      **CUF Claim:**  
**CUF Amount Paid:**  
**File Location:**  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T0608561207](https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608561207)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 6/29/2005  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608561207&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608561207&tabname=regulatoryhistory)  
**Potential Media of Concern:** SOIL  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02R01f  
  
**Gndwater Monitoring Freque:**  
**Designated Beneficial Use** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Desc:**  
**Site History:**

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 6/29/2005  
  
**Status:** Open - Site Assessment  
**Date :** 6/28/2005  
  
**Status:** Open - Case Begin Date  
**Date :** 10/28/2002

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** UNKNOWN      **Begin Date:** 10/28/2002  
**Phase:**      **End Date:** 10/28/2002  
**Contaminant Mass Removed:**  
**Description:**

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/29/2005  
**Received Issue Date:** 6/29/2005  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&enforcement\\_id=6237484&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&enforcement_id=6237484&temptable=ENFORCEMENT)  
**Title Description Comments:**

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

CLOSURE LETTER

**Action Type:** Response Requested - Other  
**Action Date:** 3/31/2003  
**Received Issue Date:** 3/31/2003  
**Action:** Unauthorized Release Form  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608561207&doc\\_id=5832408](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608561207&doc_id=5832408)  
**Title Description Comments:**

Unauthorized Release Form

**Action Type:** Response Requested - Other  
**Action Date:** 3/17/2003  
**Received Issue Date:** 3/17/2003  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608561207&doc\\_id=5832405](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608561207&doc_id=5832405)  
**Title Description Comments:**

Correspondence 03/17/2003-09/27/2005

**Action Type:** Response Requested - Other  
**Action Date:** 11/21/2002  
**Received Issue Date:** 11/21/2002  
**Action:** Unauthorized Release Form  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608561207&doc\\_id=5832406](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608561207&doc_id=5832406)  
**Title Description Comments:**

Unauthorized Release Form

**Action Type:** Response Requested - Reports  
**Action Date:** 11/21/2002  
**Received Issue Date:** 11/21/2002  
**Action:** Tank Removal Report / UST Sampling Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608561207&doc\\_id=5832410](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608561207&doc_id=5832410)  
**Title Description Comments:**

UST Sampling Report

**Action Type:** Response Requested - Reports  
**Action Date:** 11/21/2002  
**Received Issue Date:** 11/21/2002  
**Action:** Tank Removal Report / UST Sampling Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608561207&doc\\_id=5832409](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608561207&doc_id=5832409)  
**Title Description Comments:**

UST Sampling Report

**Action Type:** Leak Action  
**Action Date:** 10/28/2002  
**Received Issue Date:**  
**Action:** Leak Discovery  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Cleanup Action  
**Action Date:** 10/28/2002  
**Received Issue Date:**  
**Action:**  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 11/25/2002

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Received Issue Date:**

**Action:** Leak Reported

**Doc Link:**

**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/29/2005 **Submitted By:** JOANNA KINCAID (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER **Submitted:**  
**Title:** CLOSURE LETTER  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&enforcement\\_id=6237484](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&enforcement_id=6237484)

**Document Type:** Site Documents **Size :**  
**Document Date:** 3/31/2003 **Submitted By:** JOANNA KINCAID (REGULATOR)  
**Type:** UNAUTHORIZED RELEASE FORM **Submitted:**  
**Title:** UNAUTHORIZED RELEASE FORM - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&document\\_id=5832408](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&document_id=5832408)

**Document Type:** Site Documents **Size :**  
**Document Date:** 3/17/2003 **Submitted By:** JOANNA KINCAID (REGULATOR)  
**Type:** CORRESPONDENCE **Submitted:**  
**Title:** CORRESPONDENCE 03/17/2003-09/27/2005 - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&document\\_id=5832405](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&document_id=5832405)

**Document Type:** Site Documents **Size :**  
**Document Date:** 11/21/2002 **Submitted By:** JOANNA KINCAID (REGULATOR)  
**Type:** TANK REMOVAL REPORT / UST SAMPLING REPORT **Submitted:**  
**Title:** UST SAMPLING REPORT - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&document\\_id=5832410](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&document_id=5832410)

**Document Type:** Site Documents **Size :**  
**Document Date:** 11/21/2002 **Submitted By:** JOANNA KINCAID (REGULATOR)  
**Type:** TANK REMOVAL REPORT / UST SAMPLING REPORT **Submitted:**  
**Title:** UST SAMPLING REPORT - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&document\\_id=5832409](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&document_id=5832409)

**Document Type:** Site Documents **Size :**  
**Document Date:** 11/21/2002 **Submitted By:** JOANNA KINCAID (REGULATOR)  
**Type:** UNAUTHORIZED RELEASE FORM **Submitted:**  
**Title:** UNAUTHORIZED RELEASE FORM - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608561207&document\\_id=5832406](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608561207&document_id=5832406)

<a href="#">27</a>	2 of 2	NW	0.28 / 1,489.70	79.60 / 4	SANTA CLARA UNIVERSITY NEW LAW BUILDING 500 EL CAMINO REAL SANTA CLARA CA 95050	CLEANUP SITES
--------------------	--------	----	--------------------	--------------	--	------------------

**Global ID:** T10000009273 **Latitude:** 37.35104  
**Status:** COMPLETED - CASE CLOSED **Longitude:** -121.93849  
**Status Date:** 9/8/2017 **County:** SANTA CLARA  
**Site Facility Type:** CLEANUP PROGRAM SITE  
**Data Source:** Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Stop Method:**  
**Local Case No:** 2016-31s **CUF Case:** NO  
**Begin Date:** 8/1/2016 **Case Worker:**  
**File Location:** All Files are on GeoTracker or in the Local Agency Database  
**Lead Agency:** SANTA CLARA COUNTY LOP  
**Local Agency:**  
**Potential COC:** Ethylbenzene, Gasoline, Total Petroleum Hydrocarbons (TPH)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Potential Media of Concern:**

**How Discovered:**

**How Discovered Description:**

**Stop Description:**

**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)

**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)

**Disadvantaged Community:**

**CalEnviroScreen Score:** 56-60%

**Site History:**

Small UST was discovered during site redevelopment for the new law building on campus. UST was removed and low levels of TPH were reported. SCU wishes to remediate contaminated soil to 100 ppm TPH through excavation.

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2017-09-08 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2016-08-24 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2016-08-18 00:00:00
<b>Action:</b>	Cost Recovery Agreement / N. of Reimbursement
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2016-08-11 00:00:00
<b>Action:</b>	Letter - Notice
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2016-08-11 00:00:00
<b>Action:</b>	Site Assessment Report
<b>Action Type:</b>	Other
<b>Date:</b>	2016-08-01 00:00:00
<b>Action:</b>	Leak Began
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2016-08-01 00:00:00
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	Other
<b>Date:</b>	2016-08-01 00:00:00
<b>Action:</b>	Leak Reported
<b>Action Type:</b>	Other
<b>Date:</b>	2016-08-01 00:00:00
<b>Action:</b>	Leak Discovery

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	2017-09-08 00:00:00
<b>Status:</b>	Open - Remediation
<b>Status Date:</b>	2016-08-22 00:00:00
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	2016-08-01 00:00:00

**Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of Sep 15, 2021)**

**Project Status:** **Facility Type:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Cuf Claim No:**  
**CUF Priority Assign:**  
**CUF Amount Paid:**  
**Composting Method:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**User Defined Beneficial Use:**  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T10000009273](https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000009273)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 9/8/2017  
**Potential COC:** ETHYLBENZENE, GASOLINE, TOTAL PETROLEUM HYDROCARBONS (TPH)  
**Potential Media of Concern:** NONE SPECIFIED  
**Groundwater Monitoring**  
**Frequen:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD) - CASE #: 2016-31s  
 SAN FRANCISCO BAY RWQCB (REGION 2)  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T10000009273&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000009273&tabname=regulatoryhistory)  
**Site History:**

Small UST was discovered during site redevelopment for the new law building on campus. UST was removed and low levels of TPH were reported. SCU wishes to remediate contaminated soil to 100 ppm TPH through excavation.

**Sites from GeoTracker Search - Regulatory Activities (as of Sep 15, 2021)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/8/2017  
**Received Issue Date:** 9/8/2017  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6335885&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6335885&temptable=ENFORCEMENT)

**Title Description Comments:**

No Further Action Letter

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/24/2016  
**Received Issue Date:** 8/24/2016  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6295898&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6295898&temptable=ENFORCEMENT)

**Title Description Comments:**

Opening Letter

**Action Type:** Agreements  
**Action Date:** 8/18/2016  
**Received Issue Date:** 8/18/2016  
**Action:** Cost Recovery Agreement / N. of Reimbursement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6295633&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6295633&temptable=ENFORCEMENT)

**Title Description Comments:**

Remedial Action Agreement

**Action Type:** Notices  
**Action Date:** 8/11/2016  
**Received Issue Date:** 8/11/2016  
**Action:** Letter - Notice  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?](https://geotracker.waterboards.ca.gov/view_documents?)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

global\_id=T10000009273&enforcement\_id=6295632&temptable=ENFORCEMENT

**Title Description Comments:**

HSC 101480 State Notice

**Action Type:** Response Requested - Reports  
**Action Date:** 8/11/2016  
**Received Issue Date:** 8/11/2016  
**Action:** Site Assessment Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000009273&doc\\_id=5898097](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000009273&doc_id=5898097)  
**Title Description Comments:**

Supplemental Environmental Sampling Report

**Action Type:** Leak Action  
**Action Date:** 8/1/2016  
**Received Issue Date:**  
**Action:** Leak Began  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 8/1/2016  
**Received Issue Date:**  
**Action:** Leak Discovery  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 8/1/2016  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 8/1/2016  
**Received Issue Date:** 8/1/2016  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000009273&doc\\_id=5898095](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000009273&doc_id=5898095)  
**Title Description Comments:**

Request for Oversight - VCP application

**Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents  
**Document Date:** 9/8/2017  
**Submitted:**  
**Submitted By:** SOMIRA PECH (REGULATOR)  
**Size :**  
**Title:** NO FURTHER ACTION LETTER \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6335885](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6335885)  
**Type:** STAFF LETTER

**Document Type:** Site Documents  
**Document Date:** 11/30/2016\*  
**Submitted:**  
**Submitted By:** ALEX KASSAI (AUTH\_RP)  
**Size :** 8,857 KB  
**Title:** REMEDIAL WORK - EXCAVATION & OFF-HAUL \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/4001455724/T10000009273.PDF](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4001455724/T10000009273.PDF)  
**Type:** REQUEST FOR CLOSURE

**Document Type:** Site Documents  
**Document Date:** 8/24/2016  
**Submitted:**  
**Submitted By:** AARON COSTA (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Size :**  
**Title:** OPENING LETTER \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6295898](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6295898)  
**Type:** STAFF LETTER

**Document Type:** Site Documents **Submitted:**  
**Document Date:** 8/18/2016 **Submitted By:** AARON COSTA (REGULATOR)

**Size :**  
**Title:** REMEDIAL ACTION AGREEMENT \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6295633](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6295633)  
**Type:** COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT

**Document Type:** Site Documents **Submitted:**  
**Document Date:** 8/11/2016 **Submitted By:** AARON COSTA (REGULATOR)

**Size :**  
**Title:** SUPPLEMENTAL ENVIRONMENTAL SAMPLING REPORT \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&document\\_id=5898097](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&document_id=5898097)  
**Type:** SITE ASSESSMENT REPORT

**Document Type:** Site Documents **Submitted:**  
**Document Date:** 8/11/2016 **Submitted By:** AARON COSTA (REGULATOR)

**Size :**  
**Title:** HSC 101480 STATE NOTICE \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&enforcement\\_id=6295632](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&enforcement_id=6295632)  
**Type:** LETTER - NOTICE

**Document Type:** Site Documents **Submitted:**  
**Document Date:** 8/1/2016 **Submitted By:** AARON COSTA (REGULATOR)

**Size :**  
**Title:** REQUEST FOR OVERSIGHT - VCP APPLICATION \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009273&document\\_id=5898095](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009273&document_id=5898095)  
**Type:** OTHER REPORT / DOCUMENT

**Sites from GeoTracker Search - Cleanup Status History (as of Sep 15, 2021)**

**Status:** Completed - Case Closed  
**Date:** 9/8/2017

**Status:** Open - Remediation  
**Date:** 8/22/2016

**Status:** Open - Case Begin Date  
**Date:** 8/1/2016

<a href="#">28</a>	1 of 1	ENE	0.31 / 1,623.61	68.52 / -7	HADCO SANTA CLARA, INC. 445 EL CAMINO REAL SANTA CLARA CA 95050	ENVIROSTOR
--------------------	--------	-----	-----------------	------------	---	------------

<b>Estor/EPA ID:</b>	71003722	<b>Assembly District:</b>	25
<b>Site Code:</b>		<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	NONE SPECIFIED	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	TIERED PERMIT	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	445 EL CAMINO REAL	<b>Latitude:</b>	37.3485903
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.9323189
<b>Special Program:</b>		<b>Acres:</b>	NONE SPECIFIED
<b>Funding:</b>		<b>Supervisor:</b>	
<b>Cleanup Status:</b>	INACTIVE - NEEDS EVALUATION AS OF		
<b>Cleanup Oversight Agencies:</b>	NONE SPECIFIED		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	NONE SPECIFIED		
<b>Potential Media Affected:</b>	NONE SPECIFIED		
<b>Potential Contamin of Concern:</b>			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

NONE SPECIFIED

**Site History:**

**Status:** INACTIVE - NEEDS EVALUATION  
**Program Type:** TIERED PERMIT  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=71003722](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71003722)

<a href="#">29</a>	1 of 1	ENE	0.32 / 1,678.46	68.00 / -7	SANMINA-SCI SANTA CLARA 445 EL CAMINO REAL SANTA CLARA CA 95050	RCRA TSD
--------------------	--------	-----	--------------------	---------------	---	----------

**EPA Handler ID:** CAD982520421  
**Gen Status Universe:** Small Quantity Generator  
**Contact Name:** KHALID R RUHULLAH  
**Contact Address:** US  
**Contact Phone No and Ext:** 408-892-0191  
**Contact Email:** KHALID.RUHULLAH@SANMINA-SCI.COM  
**Contact Country:** US  
**Land Type:** Private  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Receive Date:** 20040210  
**Location Latitude:** 37.348978  
**Location Longitude:** -121.932409

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Smelting, Melting and Refining:** No  
**Underground Injection Control:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No  
**Used Oil Burner:** No  
**Used Oil Market Burner:** No  
**Used Oil Spec Marketer:** No

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 19890510  
**Handler Name:** SANMINA SANTA CLARA FACILITY  
**Federal Waste Generator Code:** 2  
**Generator Code Description:** Small Quantity Generator  
**Source Type:** Notification

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 19900413

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Handler Name:** ZYCON CORPORATION  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Annual/Biennial Report

**Hazardous Waste Handler Details**

**Sequence No:** 2  
**Receive Date:** 19920922  
**Handler Name:** ZYCON CORPORATION  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Annual/Biennial Report

**Hazardous Waste Handler Details**

**Sequence No:** 3  
**Receive Date:** 19940718  
**Handler Name:** ZYCON CORPORATION  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Annual/Biennial Report

**Hazardous Waste Handler Details**

**Sequence No:** 4  
**Receive Date:** 19960401  
**Handler Name:** ZYCON CORPORATION  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Annual/Biennial Report

**Hazardous Waste Handler Details**

**Sequence No:** 1  
**Receive Date:** 19960901  
**Handler Name:** SANMINA SANTA CLARA FACILITY  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Implementer

**Hazardous Waste Handler Details**

**Sequence No:** 2  
**Receive Date:** 19970815  
**Handler Name:** SANMINA SANTA CLARA FACILITY  
**Federal Waste Generator Code:** N  
**Generator Code Description:** Not a Generator, Verified  
**Source Type:** Notification

**Hazardous Waste Handler Details**

**Sequence No:** 5  
**Receive Date:** 19990304  
**Handler Name:** HADCO SANTA CLARA, INC.  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Annual/Biennial Report

**Hazardous Waste Handler Details**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sequence No:</b>	3					
<b>Receive Date:</b>	20000915					
<b>Handler Name:</b>	SANMINA SANTA CLARA FACILITY					
<b>Federal Waste Generator Code:</b>	1					
<b>Generator Code Description:</b>	Large Quantity Generator					
<b>Source Type:</b>	Notification					
<b><u>Waste Code Details</u></b>						
<b>Hazardous Waste Code:</b>	D001					
<b>Waste Code Description:</b>	IGNITABLE WASTE					
<b>Hazardous Waste Code:</b>	D002					
<b>Waste Code Description:</b>	CORROSIVE WASTE					
<b>Hazardous Waste Code:</b>	D003					
<b>Waste Code Description:</b>	REACTIVE WASTE					
<b>Hazardous Waste Code:</b>	D004					
<b>Waste Code Description:</b>	ARSENIC					
<b>Hazardous Waste Code:</b>	D008					
<b>Waste Code Description:</b>	LEAD					
<b>Hazardous Waste Code:</b>	D011					
<b>Waste Code Description:</b>	SILVER					
<b>Hazardous Waste Code:</b>	F003					
<b>Waste Code Description:</b>	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.					
<b>Hazardous Waste Code:</b>	F005					
<b>Waste Code Description:</b>	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.					
<b>Hazardous Waste Code:</b>	F006					
<b>Waste Code Description:</b>	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.					
<b>Hazardous Waste Code:</b>	F007					
<b>Waste Code Description:</b>	SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.					
<b><u>Hazardous Waste Handler Details</u></b>						
<b>Sequence No:</b>	6					
<b>Receive Date:</b>	20001012					
<b>Handler Name:</b>	HADCO SANTA CLARA, INC.					
<b>Federal Waste Generator Code:</b>	1					
<b>Generator Code Description:</b>	Large Quantity Generator					
<b>Source Type:</b>	Annual/Biennial Report					
<b><u>Hazardous Waste Handler Details</u></b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sequence No:</b>			7			
<b>Receive Date:</b>			20020225			
<b>Handler Name:</b>			SANMINA SANTA CLARA			
<b>Federal Waste Generator Code:</b>			1			
<b>Generator Code Description:</b>			Large Quantity Generator			
<b>Source Type:</b>			Annual/Biennial Report			
<b><u>Waste Code Details</u></b>						
<b>Hazardous Waste Code:</b>			122			
<b>Waste Code Description:</b>			Alkaline solution without metals (pH > 12.5)			
<b>Hazardous Waste Code:</b>			131			
<b>Waste Code Description:</b>			Aqueous solution (2 < pH < 12.5) containing reactive anions (azide, bromate, chlorate, cyanide, fluoride, hypochlorite, nitrite, perchlorate, and sulfide anions)			
<b>Hazardous Waste Code:</b>			132			
<b>Waste Code Description:</b>			Aqueous solution w/metals (< restricted levels and see waste code 121 for a list of metals)			
<b>Hazardous Waste Code:</b>			135			
<b>Waste Code Description:</b>			Unspecified aqueous solution			
<b>Hazardous Waste Code:</b>			171			
<b>Waste Code Description:</b>			Metal sludge (see 121)			
<b>Hazardous Waste Code:</b>			181			
<b>Waste Code Description:</b>			Other inorganic solid waste			
<b>Hazardous Waste Code:</b>			213			
<b>Waste Code Description:</b>			Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)			
<b>Hazardous Waste Code:</b>			343			
<b>Waste Code Description:</b>			Unspecified organic liquid mixture			
<b>Hazardous Waste Code:</b>			352			
<b>Waste Code Description:</b>			Other organic solids			
<b>Hazardous Waste Code:</b>			491			
<b>Waste Code Description:</b>			Unspecified sludge waste			
<b>Hazardous Waste Code:</b>			711			
<b>Waste Code Description:</b>			Liquids with cyanides > 1000 mg/l			
<b>Hazardous Waste Code:</b>			792			
<b>Waste Code Description:</b>			Liquids with pH < 2 with metals			
<b>Hazardous Waste Code:</b>			D001			
<b>Waste Code Description:</b>			IGNITABLE WASTE			
<b>Hazardous Waste Code:</b>			D002			
<b>Waste Code Description:</b>			CORROSIVE WASTE			
<b>Hazardous Waste Code:</b>			D003			
<b>Waste Code Description:</b>			REACTIVE WASTE			
<b>Hazardous Waste Code:</b>			D004			
<b>Waste Code Description:</b>			ARSENIC			
<b>Hazardous Waste Code:</b>			D008			
<b>Waste Code Description:</b>			LEAD			
<b>Hazardous Waste Code:</b>			F003			
<b>Waste Code Description:</b>			THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004,			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

**Hazardous Waste Code:** F005  
**Waste Code Description:** THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

**Hazardous Waste Code:** F006  
**Waste Code Description:** WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

**Hazardous Waste Code:** F007  
**Waste Code Description:** SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

**Hazardous Waste Handler Details**

**Sequence No:** 2  
**Receive Date:** 20040210  
**Handler Name:** SANMINA-SCI SANTA CLARA  
**Federal Waste Generator Code:** 2  
**Generator Code Description:** Small Quantity Generator  
**Source Type:** Implementer

**Hazardous Waste Handler Details**

**Sequence No:** 8  
**Receive Date:** 20040210  
**Handler Name:** SANMINA-SCI SANTA CLARA  
**Federal Waste Generator Code:** 1  
**Generator Code Description:** Large Quantity Generator  
**Source Type:** Annual/Biennial Report

**Waste Code Details**

**Hazardous Waste Code:** D002  
**Waste Code Description:** CORROSIVE WASTE

**Hazardous Waste Code:** D008  
**Waste Code Description:** LEAD

**Hazardous Waste Code:** F006  
**Waste Code Description:** WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

**Owner/Operator Details**

<b>Owner/Operator Ind:</b>	Current Operator	<b>Street No:</b>	
<b>Type:</b>	Private	<b>Street 1:</b>	
<b>Name:</b>	SANMINA-SCI	<b>Street 2:</b>	
<b>Date Became Current:</b>	19990608	<b>City:</b>	
<b>Date Ended Current:</b>		<b>State:</b>	
<b>Phone:</b>		<b>Country:</b>	US
<b>Source Type:</b>	Annual/Biennial Report	<b>Zip Code:</b>	

**Owner/Operator Ind:** Current Owner **Street No:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Type:</b>	Private				<b>Street 1:</b> 445 EL CAMINO REAL	
<b>Name:</b>	SANMINA SANTA CLARA FACILITY				<b>Street 2:</b>	
<b>Date Became Current:</b>					<b>City:</b> SANTA CLARA	
<b>Date Ended Current:</b>					<b>State:</b> CA	
<b>Phone:</b>	408-241-9900				<b>Country:</b>	
<b>Source Type:</b>	Notification				<b>Zip Code:</b> 95050	
<b>Owner/Operator Ind:</b>	Current Owner				<b>Street No:</b>	
<b>Type:</b>	Private				<b>Street 1:</b> 2068 BERING DR	
<b>Name:</b>	SOBRATO DEVELOPMENT				<b>Street 2:</b>	
<b>Date Became Current:</b>	19880101				<b>City:</b> SAN JOSE	
<b>Date Ended Current:</b>					<b>State:</b> CA	
<b>Phone:</b>					<b>Country:</b> US	
<b>Source Type:</b>	Implementer				<b>Zip Code:</b> 95131	
<b>Owner/Operator Ind:</b>	Current Owner				<b>Street No:</b>	
<b>Type:</b>	Municipal				<b>Street 1:</b> NOT REQUIRED	
<b>Name:</b>	RON DONATI				<b>Street 2:</b>	
<b>Date Became Current:</b>					<b>City:</b> NOT REQUIRED	
<b>Date Ended Current:</b>					<b>State:</b> ME	
<b>Phone:</b>	415-555-1212				<b>Country:</b>	
<b>Source Type:</b>	Notification				<b>Zip Code:</b> 99999	
<b>Owner/Operator Ind:</b>	Current Operator				<b>Street No:</b>	
<b>Type:</b>	Private				<b>Street 1:</b>	
<b>Name:</b>	SANMINA-SCI				<b>Street 2:</b>	
<b>Date Became Current:</b>	19990608				<b>City:</b>	
<b>Date Ended Current:</b>					<b>State:</b>	
<b>Phone:</b>					<b>Country:</b> US	
<b>Source Type:</b>	Implementer				<b>Zip Code:</b>	
<b>Owner/Operator Ind:</b>	Current Owner				<b>Street No:</b>	
<b>Type:</b>	Private				<b>Street 1:</b> 2068 BERING DR	
<b>Name:</b>	SOBRATO DEVELOPMENT				<b>Street 2:</b>	
<b>Date Became Current:</b>	19880101				<b>City:</b> SAN JOSE	
<b>Date Ended Current:</b>					<b>State:</b> CA	
<b>Phone:</b>					<b>Country:</b> US	
<b>Source Type:</b>	Annual/Biennial Report				<b>Zip Code:</b> 95131	
<b>Owner/Operator Ind:</b>	Current Operator				<b>Street No:</b>	
<b>Type:</b>	Municipal				<b>Street 1:</b> NOT REQUIRED	
<b>Name:</b>	NOT REQUIRED				<b>Street 2:</b>	
<b>Date Became Current:</b>					<b>City:</b> NOT REQUIRED	
<b>Date Ended Current:</b>					<b>State:</b> ME	
<b>Phone:</b>	415-555-1212				<b>Country:</b>	
<b>Source Type:</b>	Implementer				<b>Zip Code:</b> 99999	

#### Historical Handler Details

<b>Receive Dt:</b>	20040210
<b>Generator Code Description:</b>	Large Quantity Generator
<b>Handler Name:</b>	SANMINA-SCI SANTA CLARA
<b>Receive Dt:</b>	20020225
<b>Generator Code Description:</b>	Large Quantity Generator
<b>Handler Name:</b>	SANMINA SANTA CLARA
<b>Receive Dt:</b>	20001012
<b>Generator Code Description:</b>	Large Quantity Generator
<b>Handler Name:</b>	HADCO SANTA CLARA, INC.
<b>Receive Dt:</b>	20000915
<b>Generator Code Description:</b>	Large Quantity Generator
<b>Handler Name:</b>	SANMINA SANTA CLARA FACILITY
<b>Receive Dt:</b>	19990304
<b>Generator Code Description:</b>	Large Quantity Generator
<b>Handler Name:</b>	HADCO SANTA CLARA, INC.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Receive Dt:</b>		19970815				
<b>Generator Code Description:</b>		Not a Generator, Verified				
<b>Handler Name:</b>		SANMINA SANTA CLARA FACILITY				
<b>Receive Dt:</b>		19960901				
<b>Generator Code Description:</b>		Large Quantity Generator				
<b>Handler Name:</b>		SANMINA SANTA CLARA FACILITY				
<b>Receive Dt:</b>		19960401				
<b>Generator Code Description:</b>		Large Quantity Generator				
<b>Handler Name:</b>		ZYCON CORPORATION				
<b>Receive Dt:</b>		19940718				
<b>Generator Code Description:</b>		Large Quantity Generator				
<b>Handler Name:</b>		ZYCON CORPORATION				
<b>Receive Dt:</b>		19920922				
<b>Generator Code Description:</b>		Large Quantity Generator				
<b>Handler Name:</b>		ZYCON CORPORATION				
<b>Receive Dt:</b>		19900413				
<b>Generator Code Description:</b>		Large Quantity Generator				
<b>Handler Name:</b>		ZYCON CORPORATION				
<b>Receive Dt:</b>		19890510				
<b>Generator Code Description:</b>		Small Quantity Generator				
<b>Handler Name:</b>		SANMINA SANTA CLARA FACILITY				

[30](#) 1 of 2 **NNE** **0.34 / 1,770.23** **67.32 / -8** **Mayfair Packing Plant #4**  
**475 El Camino Real Ave Santa Clara CA** **LOP SANTA CLARA**

**SCVWD ID:** 07S1W02J03f  
**Closure Date:** 6/10/2004  
**Link:** <http://lustop.sccgov.org/files/07S1W02J03f/>

[30](#) 2 of 2 **NNE** **0.34 / 1,770.23** **67.32 / -8** **MAYFAIR PACKING PLANT #4**  
**475 EL CAMINO REAL AVE SANTA CLARA CA 95050** **LUST**

**Global ID:** T0608500879 **County:** SANTA CLARA  
**Status:** COMPLETED - CASE CLOSED **Latitude:**  
**Status Date:** **Longitude:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Potential COC:** Gasoline  
**Local Case No:** **How Discovered:**  
**Begin Date:** 3/14/1996 **Stop Method:**  
**Lead Agency:** SANTA CLARA COUNTY LOP **Stop Description:**  
**Local Agency:** SANTA CLARA COUNTY LOP **Case Worker:** UST  
**CUF Case:** NO **File Location:** All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 41-45%  
**Site History:**

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/29/2005
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	5/28/2004
<b>Action:</b>	Well Destruction Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	7/3/2003
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/7/2002
<b>Action:</b>	Other Workplan
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	2/5/2002
<b>Action:</b>	Request for Closure
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	1/31/2000
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/31/1999
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/26/1999
<b>Action:</b>	Staff Letter - #23482
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/31/1998
<b>Action:</b>	Well Installation Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/27/1998
<b>Action:</b>	Tank Removal Report / UST Sampling Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/14/1996
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/7/1996
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/4/1996
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	6/4/1996
<b>Action:</b>	Staff Letter - #23478

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			5/24/1996			
<b>Action:</b>			Other Report / Document			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date :</b>			5/21/1996			
<b>Action:</b>			Staff Letter - #23476			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			5/21/1996			
<b>Action:</b>			Monitoring Report - Quarterly			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			5/21/1996			
<b>Action:</b>			Other Report / Document			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			4/30/1996			
<b>Action:</b>			Corrective Action Plan / Remedial Action Plan			
<b>Action Type:</b>			REMEDIATION			
<b>Date :</b>			4/30/1996			
<b>Action:</b>			Ex Situ Physical/Chemical Treatment (other than P&T, SVE, or Excavation)			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date :</b>			4/29/1996			
<b>Action:</b>			Staff Letter - #23474			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			4/24/1996			
<b>Action:</b>			Corrective Action Plan / Remedial Action Plan			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			4/24/1996			
<b>Action:</b>			CAP/RAP - Other Report			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date :</b>			4/24/1996			
<b>Action:</b>			Staff Letter - #23472			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			4/18/1996			
<b>Action:</b>			Other Report / Document			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			4/18/1996			
<b>Action:</b>			Preliminary Site Assessment Report			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date :</b>			4/18/1996			
<b>Action:</b>			Notice of Responsibility - #39703			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date :</b>			4/18/1996			
<b>Action:</b>			Staff Letter - #23667			
<b>Action Type:</b>			Other			
<b>Date :</b>			4/17/1996			
<b>Action:</b>			Leak Reported			
<b>Action Type:</b>			RESPONSE			
<b>Date :</b>			1/1/1996			
<b>Action:</b>			Correspondence			

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Local Agency Caseworker **Address:** 1555 Berger Drive, Suite 300  
**Contact Name:** UST CASE WORKER **Email:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>City:</b>	SAN JOSE				<b>Phone No:</b> 4089183400	
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP					
<b>Contact Type:</b>	Regional Board Caseworker				<b>Address:</b> 1515 CLAY ST SUITE 1400	
<b>Contact Name:</b>	Regional Water Board				<b>Email:</b>	
<b>City:</b>	OAKLAND				<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)					

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	6/10/2004
<b>Status:</b>	Open - Remediation
<b>Status Date:</b>	4/30/1996
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	4/12/1996
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	3/14/1996
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	3/14/1996

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	MAYFAIR PACKING PLANT #4	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	475 EL CAMINO REAL AVE
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500879">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500879</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 6/10/2004		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500879&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500879&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02J03f		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use Desc:</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Site History:</b>			

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

<b>Status:</b>	Completed - Case Closed
<b>Date :</b>	6/10/2004

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Status:		Open - Remediation				
Date :		4/30/1996				
Status:		Open - Site Assessment				
Date :		4/12/1996				
Status:		Open - Case Begin Date				
Date :		3/14/1996				
Status:		Open - Site Assessment				
Date :		3/14/1996				

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

Action Type:	EX SITU PHYSICAL/CHEMICAL TREATMENT (OTHER THAN P&T, SVE, OR EXCAVATION)	Begin Date:	4/30/1996
Phase:		End Date:	9/12/2002
Contaminant Mass Removed:			
Description:			

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

Action Type:	Other Regulatory Actions
Action Date:	8/29/2005
Received Issue Date:	8/29/2005
Action:	Staff Letter
Doc Link:	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6342056&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6342056&amp;temptable=ENFORCEMENT</a>

**Title Description Comments:**

DEH letter re: deed restriction amendment

Action Type:	Response Requested - Other
Action Date:	6/3/2005
Received Issue Date:	6/3/2005
Action:	Other Report / Document
Doc Link:	<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927365">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927365</a>

**Title Description Comments:**

State Information 06/03/2005

Action Type:	Response Requested - Other
Action Date:	6/3/2005
Received Issue Date:	6/3/2005
Action:	Other Report / Document
Doc Link:	<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927362">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927362</a>

**Title Description Comments:**

Phone Log 06/03/2005

Action Type:	Reports
Action Date:	6/3/2005
Received Issue Date:	6/3/2005
Action:	Other Report
Doc Link:	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6324288&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6324288&amp;temptable=ENFORCEMENT</a>

**Title Description Comments:**

Map & Metroscan Information 06/03/2005

Action Type:	Response Requested - Reports
Action Date:	5/28/2004
Received Issue Date:	5/28/2004

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>					Well Destruction Report	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927370">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927370</a>	
<b>Title Description Comments:</b>						
					Well Abandonment/Destruction 05/28/2004	
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					7/3/2003	
<b>Received Issue Date:</b>					7/3/2003	
<b>Action:</b>					Other Report / Document	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927358">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927358</a>	
<b>Title Description Comments:</b>						
					Draft Closure Summary 07/03/2003	
<b>Action Type:</b>					Response Requested - Workplans	
<b>Action Date:</b>					8/7/2002	
<b>Received Issue Date:</b>					8/7/2002	
<b>Action:</b>					Other Workplan	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927371">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927371</a>	
<b>Title Description Comments:</b>						
					Work Plan 08/07/2002	
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					2/5/2002	
<b>Received Issue Date:</b>					2/5/2002	
<b>Action:</b>					Request for Closure	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927363">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927363</a>	
<b>Title Description Comments:</b>						
					Request For Closure	
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					1/31/2000	
<b>Received Issue Date:</b>					11/18/1999	
<b>Action:</b>					Monitoring Report - Quarterly	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Monitoring Report - Quarterly	
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					8/31/1999	
<b>Received Issue Date:</b>					8/31/1999	
<b>Action:</b>					Monitoring Report - Quarterly	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Monitoring Report - Quarterly	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					8/26/1999	
<b>Received Issue Date:</b>					8/26/1999	
<b>Action:</b>					Staff Letter - #23482	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					8/31/1998	
<b>Received Issue Date:</b>					8/31/1998	
<b>Action:</b>					Well Installation Report	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927369">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927369</a>	

**Title Description Comments:**

Well Construction Application 08/31/1998

**Action Type:** Response Requested - Reports  
**Action Date:** 3/27/1998  
**Received Issue Date:** 3/27/1998  
**Action:** Tank Removal Report / UST Sampling Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500879&doc\\_id=5927368](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&doc_id=5927368)

**Title Description Comments:**

Tank Removal Report 03/27/1998

**Action Type:** Response Requested - Reports  
**Action Date:** 8/14/1996  
**Received Issue Date:** 8/14/1996  
**Action:** Soil and Water Investigation Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500879&doc\\_id=5927367](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&doc_id=5927367)

**Title Description Comments:**

Soil & Water Investigation Report 08/14/1996 - 10/11/1996

**Action Type:** Response Requested - Other  
**Action Date:** 6/7/1996  
**Received Issue Date:** 6/7/1996  
**Action:** Other Report / Document

**Title Description Comments:**

Additional Information Report

**Action Type:** Response Requested - Other  
**Action Date:** 6/4/1996  
**Received Issue Date:** 6/4/1996  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500879&doc\\_id=5927360](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&doc_id=5927360)

**Title Description Comments:**

Miscellaneous Letter 06/04/1996

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/4/1996  
**Received Issue Date:** 6/4/1996  
**Action:** Staff Letter - #23478

**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 5/24/1996  
**Received Issue Date:** 5/24/1996  
**Action:** Other Report / Document

**Title Description Comments:**

Additional Information Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/21/1996  
**Received Issue Date:** 5/21/1996  
**Action:** Staff Letter - #23476

**Title Description Comments:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<hr/>						
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		5/21/1996				
<b>Received Issue Date:</b>		5/21/1996				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927361">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927361</a>				
<b>Title Description Comments:</b>		Miscellaneous Sample Results 05/21/1996				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		5/21/1996				
<b>Received Issue Date:</b>		5/21/1996				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927359">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927359</a>				
<b>Title Description Comments:</b>		GW Monitoring Report 05/21/1996 - 05/04/2004				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		4/30/1996				
<b>Received Issue Date:</b>		4/30/1996				
<b>Action:</b>		Corrective Action Plan / Remedial Action Plan				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Corrective Action Plan / Remedial Action Plan				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		4/29/1996				
<b>Received Issue Date:</b>		4/29/1996				
<b>Action:</b>		Staff Letter - #23474				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		4/24/1996				
<b>Received Issue Date:</b>		4/24/1996				
<b>Action:</b>		Staff Letter - #23472				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		4/24/1996				
<b>Received Issue Date:</b>		4/24/1996				
<b>Action:</b>		CAP/RAP - Other Report				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927356">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&amp;doc_id=5927356</a>				
<b>Title Description Comments:</b>		Corrective Action Plan 04/24/1996 - 07/25/1996				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		4/24/1996				
<b>Received Issue Date:</b>		4/24/1996				
<b>Action:</b>		Corrective Action Plan / Remedial Action Plan				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Corrective Action Plan / Remedial Action Plan				
<b>Action Type:</b>		Notices				
<b>Action Date:</b>		4/18/1996				
<b>Received Issue Date:</b>		4/18/1996				
<b>Action:</b>		Notice of Responsibility - #39703				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Doc Link:**

**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 4/18/1996  
**Received Issue Date:** 4/18/1996  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500879&doc\\_id=5927355](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&doc_id=5927355)  
**Title Description Comments:**

Additional Information Report 04/18/1996

**Action Type:** Response Requested - Reports  
**Action Date:** 4/18/1996  
**Received Issue Date:** 4/18/1996  
**Action:** Preliminary Site Assessment Report  
**Doc Link:**  
**Title Description Comments:**

Preliminary Site Assessment Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/18/1996  
**Received Issue Date:** 4/18/1996  
**Action:** Staff Letter - #23667  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 1/1/1996  
**Received Issue Date:** 1/1/1996  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500879&doc\\_id=5927357](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500879&doc_id=5927357)  
**Title Description Comments:**

Correspondence 1996

**Action Type:** Cleanup Action  
**Action Date:** 4/30/1996  
**Received Issue Date:**  
**Action:** Ex Situ Physical/Chemical Treatment (other than P&T, SVE, or Excavation)  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 4/17/1996  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Size :</b>	2,614 KB
<b>Document Date:</b>	10/4/2007	<b>Submitted By:</b>	CYNTHIA MANA-AY (REGULATOR)
<b>Type:</b>	LETTER	<b>Submitted:</b>	
<b>Title:</b>	CLOSURE LETTER & SITE CLOSURE SUMMARY		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/site_documents/3757359147/CLOS%5FL%5F2004%2D06%2D10%2Epdf">https://geotracker.waterboards.ca.gov/site_documents/3757359147/CLOS%5FL%5F2004%2D06%2D10%2Epdf</a>		

<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	8/29/2005	<b>Submitted By:</b>	TRAVIS FLORA (REGULATOR)
<b>Type:</b>	STAFF LETTER	<b>Submitted:</b>	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>		DEH LETTER RE: DEED RESTRICTION AMENDMENT				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6342056">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6342056</a>				
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/3/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT			<b>Submitted:</b>		
<b>Title:</b>	MAP & METROSCAN INFORMATION 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6324288">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;enforcement_id=6324288</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/3/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	STATE INFORMATION 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927365">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927365</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/3/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	PHONE LOG 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927362">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927362</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	5/28/2004			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	WELL DESTRUCTION REPORT			<b>Submitted:</b>		
<b>Title:</b>	WELL ABANDONMENT/DESTRUCTION 05/28/2004					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927370">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927370</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	7/3/2003			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	DRAFT CLOSURE SUMMARY 07/03/2003					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927358">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927358</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	8/7/2002			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER WORKPLAN			<b>Submitted:</b>		
<b>Title:</b>	WORK PLAN 08/07/2002					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927371">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927371</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	2/5/2002			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	REQUEST FOR CLOSURE			<b>Submitted:</b>		
<b>Title:</b>	REQUEST FOR CLOSURE					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927363">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927363</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	8/31/1998			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	WELL INSTALLATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	WELL CONSTRUCTION APPLICATION 08/31/1998					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927369">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927369</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	3/27/1998			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	TANK REMOVAL REPORT / UST SAMPLING REPORT			<b>Submitted:</b>		
<b>Title:</b>	TANK REMOVAL REPORT 03/27/1998					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927368">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927368</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	8/14/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	SOIL & WATER INVESTIGATION REPORT 08/14/1996 - 10/11/1996					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927367">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927367</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/4/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	MISCELLANEOUS LETTER 06/04/1996					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927360">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&amp;document_id=5927360</a>				
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	750 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2000%2D08%2D28%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2000%2D08%2D28%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	310 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2638166666/GWM%5FR%5F1996%2D05%2D21%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2638166666/GWM%5FR%5F1996%2D05%2D21%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	712 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2001%2D08%2D24%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2001%2D08%2D24%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	3,775 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1999%2D02%2D26%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1999%2D02%2D26%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,136 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2002%2D02%2D28%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2002%2D02%2D28%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,323 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2000%2D02%2D29%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2000%2D02%2D29%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,861 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1998%2D05%2D07%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1998%2D05%2D07%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,396 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2004%2D05%2D04%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2004%2D05%2D04%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	892 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1999%2D08%2D26%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1999%2D08%2D26%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,257 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>		https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F2001%2D02%2D28%2Epdf				
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	739 KB	
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 05/21/1996 - 05/04/2004 -					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8791423976/GWM%5FR%5F1999%2D11%2D12%2Epdf					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	5/21/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	MISCELLANEOUS SAMPLE RESULTS 05/21/1996					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&document_id=5927361					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	4/24/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	CAP/RAP - OTHER REPORT			<b>Submitted:</b>		
<b>Title:</b>	CORRECTIVE ACTION PLAN 04/24/1996 - 07/25/1996					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&document_id=5927356					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	4/18/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	ADDITIONAL INFORMATION REPORT 04/18/1996					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&document_id=5927355					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/1/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	CORRESPONDENCE			<b>Submitted:</b>		
<b>Title:</b>	CORRESPONDENCE 1996					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500879&document_id=5927357					

[31](#) 1 of 1 NE 0.35 / 1,856.16 66.60 / -9 SANTA CLARA UNIVERSITY PHYSICAL PLANT FY 751 CAMPBELL AVENUE SANTA CLARA CA 95050 ENVIROSTOR

**Estor/EPA ID:** 43820002 **Assembly District:** 25  
**Site Code:** **Senate District:** 10  
**Nat Priority List:** NO **Permit Renewal Lead:**  
**APN:** NONE SPECIFIED **Public Partici Spclst:**  
**Census Tract:** 6085505203 **Project Manager:**  
**Site Type:** \* HISTORICAL **County:** SANTA CLARA  
**Address Description:** 751 CAMPBELL AVENUE **Latitude:** 37.350596  
**Office:** CLEANUP BERKELEY **Longitude:** -121.933837  
**Special Program:** **Acres:** NONE SPECIFIED  
**Funding:** **Supervisor:**  
**Cleanup Status:** REFER: OTHER AGENCY AS OF 3/18/1993  
**Cleanup Oversight Agencies:** NONE SPECIFIED  
**School District:**  
**Past Use that Caused Contam:** NONE SPECIFIED  
**Potential Media Affected:** NONE SPECIFIED  
**Potential Contamin of Concern:**

CONTAMINATED SOIL HYDROCARBON SOLVENTS

**Site History:**

**Status:** REFER: OTHER AGENCY  
**Program Type:** HISTORICAL  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** https://www.envirostor.dtsc.ca.gov/public/profile\_report?global\_id=43820002

**Completed Activities**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<p><b>Title:</b> Site Screening</p> <p><b>Title Link:</b></p> <p><b>Area Name:</b></p> <p><b>Area Link:</b></p> <p><b>Sub Area:</b></p> <p><b>Sub Area Link:</b></p> <p><b>Document Type:</b> Site Screening</p> <p><b>Date Completed:</b> 3/18/1993</p> <p><b>Comments:</b> This approximately 1-acre facility is situated in an industrial area of the city. The site was used in the past variously as a swine farm, a pear storage facility, and a laundry. Subsequently SCU developed it to its current use in the 60's and purchased it in 1981. Site soils below ground surface have been found contaminated with TPH (Total Petroleum Hydrocarbons) as gasoline (600 ppm) diesel (2900 ppm), oil and grease (2200 ppm). Due to the presence of leaky underground fuel tanks that were installed by the past operators of the site. The leaky tanks and most of the contaminated site soils have been excavated after determining the extent of contamination and removed for off-site disposal. Post removal sampling indicate substantial reduction of residual contamination (TPH 174). Groundwater has been contaminated with gasoline (12 ppm), diesel (11 ppm), benzene (0.24 ppm), toluene (.064 ppm), ethylbenzene (.0015 ppm) and xylene (0.470 ppm). Contamination was discovered by SCU in 1980 during tank renovation. DTSC files were reviewed. No RWQCB/US EPA file was located. County has report on the site and it is in DTSC files. Role of RWQCB has been deferred to County. County has active lead role on this facility. Extent of contamination currently unknown.</p>						
<p><b>Title:</b> Site Screening</p> <p><b>Title Link:</b></p> <p><b>Area Name:</b></p> <p><b>Area Link:</b></p> <p><b>Sub Area:</b></p> <p><b>Sub Area Link:</b></p> <p><b>Document Type:</b> Site Screening</p> <p><b>Date Completed:</b> 9/21/1990</p> <p><b>Comments:</b> SITE STARTED AS A HOG FARM IN THE 1950S, ALSO FRUIT STORAGE, GREENHOUSE, PAINT SHOP. CURRENTLY, IT IS USED AS THE PHYSICAL PLANT FACILITY FOR THE UNIVERSITY. LEAKY UNDERGROUND STORAGE TANKS &amp; OTHER SPILLAGES CAUSED CONTAMINATION OF SURFACE &amp; SUBSURFACE. TANKS &amp; CONTAMINATED SOILS REMOVED (TPH 100 PPM, 174 PPM FROM SIDES &amp; BOTTOM OF TANKS) TO A DEPTH OF 34' BELOW GRADE &amp; TRANSPORTED TO CLASS I LANDFILL. THE SITE HAS BEEN BACKFILLED WITH IMPORTED CLEAN DRAIN ROCK &amp; UNCONTAMINATED EXCAVATED SOIL FROM SITE. SITE SCREENING DONE PENDING: SITE REFERRED TO SANTA CLARA COUNTY.</p>						
<a href="#">32</a>	1 of 4	NE	0.35 / 1,864.19	66.72 / -8	Santa Clara University 455 El Camino Real Santa Clara CA	LOP SANTA CLARA
<p><b>SCVWD ID:</b> 07S1W02J01f</p> <p><b>Closure Date:</b> 10/16/1996</p> <p><b>Link:</b> <a href="http://lustop.sccgov.org/files/07S1W02J01f/">http://lustop.sccgov.org/files/07S1W02J01f/</a></p>						
<a href="#">32</a>	2 of 4	NE	0.35 / 1,864.19	66.72 / -8	Santa Clara University 455 El Camino Real Santa Clara CA	LOP SANTA CLARA
<p><b>SCVWD ID:</b> 07S1W02J04f</p> <p><b>Closure Date:</b> 4/3/2003</p> <p><b>Link:</b> <a href="http://lustop.sccgov.org/files/07S1W02J04f/">http://lustop.sccgov.org/files/07S1W02J04f/</a></p>						
<a href="#">32</a>	3 of 4	NE	0.35 / 1,864.19	66.72 / -8	SANTA CLARA UNIVERSITY 455 EL CAMINO REAL SANTA CLARA CA 95050	LUST
<p><b>Global ID:</b> T0608516069</p> <p><b>Status:</b> COMPLETED - CASE CLOSED</p> <p><b>Status Date:</b></p> <p><b>Case Type:</b> LUST CLEANUP SITE</p> <p><b>Date Source:</b> LUST Cleanup Sites &amp; Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites &amp; Military UST Site from GeoTracker Cleanup Sites Data Download</p> <p><b>County:</b> SANTA CLARA</p> <p><b>Latitude:</b></p> <p><b>Longitude:</b></p>						

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>		<b>Potential COC:</b>	Gasoline
<b>Local Case No:</b>		<b>How Discovered:</b>	Tank Closure
<b>Begin Date:</b>	6/15/2001	<b>Stop Method:</b>	Close and Remove Tank
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP	<b>Stop Description:</b>	
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP	<b>Case Worker:</b>	UST
<b>CUF Case:</b>	NO	<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)

**How Discovered Description:**

**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)

**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)

**Disadvantaged Community:**

**Calenviroscreen Score:** 41-45%

**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	4/3/2003
<b>Action:</b>	Closure/No Further Action Letter
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/20/2003
<b>Action:</b>	Preliminary Site Assessment Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/18/2003
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	12/20/2002
<b>Action:</b>	Soil and Water Investigation Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	12/19/2002
<b>Action:</b>	Staff Letter - #40549
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	12/18/2002
<b>Action:</b>	Correspondence
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	12/18/2002
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	12/11/2002
<b>Action:</b>	Soil and Water Investigation Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	11/4/2002
<b>Action:</b>	Staff Letter - #38916
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/19/2002
<b>Action:</b>	Unauthorized Release Form
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/6/2002
<b>Action:</b>	Notice of Responsibility - #38385
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/6/2002
<b>Action:</b>	Correspondence

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action Type:** Other  
**Date :** 1/28/2002  
**Action:** Leak Reported

**Action Type:** RESPONSE  
**Date :** 1/28/2002  
**Action:** Unauthorized Release Form

**Action Type:** Other  
**Date :** 6/15/2001  
**Action:** Leak Stopped

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Regional Board Caseworker  
**Contact Name:** Regional Water Board  
**City:** OAKLAND  
**Organization Name:** SAN FRANCISCO BAY RWQCB (REGION 2)  
**Address:** 1515 CLAY ST SUITE 1400  
**Email:**  
**Phone No:**

**Contact Type:** Local Agency Caseworker  
**Contact Name:** UST CASE WORKER  
**City:** SAN JOSE  
**Organization Name:** SANTA CLARA COUNTY LOP  
**Address:** 1555 Berger Drive, Suite 300  
**Email:**  
**Phone No:** 4089183400

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 4/3/2003

**Status:** Open - Case Begin Date  
**Status Date:** 6/15/2001

**LUST Sites from GeoTracker Search - Regulatory Profile**

**Site Facility Name:** SANTA CLARA UNIVERSITY  
**Site Facility Type:** LUST CLEANUP SITE  
**Cleanup Status:** COMPLETED - CASE CLOSED  
**Project Status:**  
**WDR Place Type:**  
**WDR File:**  
**WDR Order:**  
**CUF Priority Assig:**  
**CUF Amount Paid:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T0608516069](https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608516069)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 4/3/2003  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608516069&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608516069&tabname=regulatoryhistory)  
**Potential Media of Concern:** OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02J04f  
**Gndwater Monitoring Freque:**  
**Designated Beneficial Use** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Desc:**  
**Site History:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 4/3/2003

**Status:** Open - Case Begin Date  
**Date :** 6/15/2001

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/3/2003  
**Received Issue Date:** 4/3/2003  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608516069&enforcement\\_id=6260179&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&enforcement_id=6260179&temptable=ENFORCEMENT)

**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 3/18/2003  
**Received Issue Date:** 3/18/2003  
**Action:** Monitoring Report - Quarterly  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608516069&doc\\_id=5857023](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&doc_id=5857023)

**Title Description Comments:**

QUARTERLY GROUNDWATER REPORT

**Action Type:** Response Requested - Workplans  
**Action Date:** 12/20/2002  
**Received Issue Date:** 12/16/2002  
**Action:** Soil and Water Investigation Workplan

**Doc Link:**

**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/19/2002  
**Received Issue Date:** 12/19/2002  
**Action:** Staff Letter - #40549

**Doc Link:**

**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 12/18/2002  
**Received Issue Date:** 12/18/2002  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608516069&doc\\_id=5857021](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&doc_id=5857021)

**Title Description Comments:**

CORRESPONDENCE FILE FROM LUSTOP 8/21/2002-12/18/2002

**Action Type:** Response Requested - Other  
**Action Date:** 12/18/2002  
**Received Issue Date:** 12/18/2002  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608516069&doc\\_id=5857022](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&doc_id=5857022)

**Title Description Comments:**

MAPS METROSCAN FROM LUSTOP

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>					Response Requested - Workplans	
<b>Action Date:</b>					12/11/2002	
<b>Received Issue Date:</b>					12/11/2002	
<b>Action:</b>					Soil and Water Investigation Workplan	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857024">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857024</a>	
<b>Title Description Comments:</b>						
					WORKPLAN	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					11/4/2002	
<b>Received Issue Date:</b>					11/4/2002	
<b>Action:</b>					Staff Letter - #38916	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					8/19/2002	
<b>Received Issue Date:</b>					8/19/2002	
<b>Action:</b>					Unauthorized Release Form	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857027">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857027</a>	
<b>Title Description Comments:</b>						
					URF	
<b>Action Type:</b>					Notices	
<b>Action Date:</b>					8/6/2002	
<b>Received Issue Date:</b>					8/6/2002	
<b>Action:</b>					Notice of Responsibility - #38385	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					8/6/2002	
<b>Received Issue Date:</b>					8/6/2002	
<b>Action:</b>					Correspondence	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857025">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857025</a>	
<b>Title Description Comments:</b>						
					STATE RELATED CORESPONDENCE FROM LUSTOP 08/8/2002-8/6/2002	
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					1/28/2002	
<b>Received Issue Date:</b>					1/28/2002	
<b>Action:</b>					Unauthorized Release Form	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857026">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608516069&amp;doc_id=5857026</a>	
<b>Title Description Comments:</b>						
					URF	
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					3/20/2003	
<b>Received Issue Date:</b>						
<b>Action:</b>					Preliminary Site Assessment Report	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Preliminary Site Assessment Report	
<b>Action Type:</b>					Leak Action	
<b>Action Date:</b>					1/28/2002	
<b>Received Issue Date:</b>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		6/15/2001				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Stopped				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b><u>LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)</u></b>						
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	4/3/2003			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER			<b>Submitted:</b>		
<b>Title:</b>	UNKNOWN					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&enforcement_id=6260179					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	794 KB	
<b>Document Date:</b>	3/18/2003			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	QUARTERLY GROUNDWATER REPORT -					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3781651377/GWM%5FR%5F2003%2D03%2D18%2Epdf					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/18/2002			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	MAPS METROSCAN FROM LUSTOP					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&document_id=5857022					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/18/2002			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	CORRESPONDENCE			<b>Submitted:</b>		
<b>Title:</b>	CORRESPONDENCE FILE FROM LUSTOP 8/21/2002-12/18/2002					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&document_id=5857021					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/11/2002			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	SOIL AND WATER INVESTIGATION WORKPLAN			<b>Submitted:</b>		
<b>Title:</b>	WORKPLAN					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&document_id=5857024					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	8/19/2002			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	UNAUTHORIZED RELEASE FORM			<b>Submitted:</b>		
<b>Title:</b>	URF					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&document_id=5857027					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	8/6/2002			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	CORRESPONDENCE			<b>Submitted:</b>		
<b>Title:</b>	STATE RELATED COORESPONDENCE FROM LUSTOP 08/8/2002-8/6/2002					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&document_id=5857025					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/28/2002			<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)	
<b>Type:</b>	UNAUTHORIZED RELEASE FORM			<b>Submitted:</b>		
<b>Title:</b>	URF					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608516069&document_id=5857026					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

SANTA CLARA CA 95053

**Global ID:** T0608501809  
**Status:** COMPLETED - CASE CLOSED  
**Status Date:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download  
**County:** SANTA CLARA  
**Latitude:**  
**Longitude:**

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

**RB Case No:**  
**Local Case No:**  
**Begin Date:** 8/5/1988  
**Lead Agency:** SANTA CLARA COUNTY LOP  
**Local Agency:** SANTA CLARA COUNTY LOP  
**CUF Case:** NO  
**Potential COC:** Diesel  
**How Discovered:**  
**Stop Method:**  
**Stop Description:**  
**Case Worker:** UST  
**File Location:** All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 41-45%  
**Site History:**

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

**Action Type:** RESPONSE  
**Date :** 10/16/1996  
**Action:** Other Report / Document  
**Action Type:** ENFORCEMENT  
**Date :** 10/16/1996  
**Action:** Closure/No Further Action Letter  
**Action Type:** RESPONSE  
**Date :** 7/31/1996  
**Action:** Soil and Water Investigation Report  
**Action Type:** ENFORCEMENT  
**Date :** 5/2/1996  
**Action:** Staff Letter - #23663  
**Action Type:** RESPONSE  
**Date :** 3/31/1996  
**Action:** Soil and Water Investigation Report  
**Action Type:** ENFORCEMENT  
**Date :** 1/1/1996  
**Action:** Staff Letter - #23661  
**Action Type:** ENFORCEMENT  
**Date :** 11/17/1989  
**Action:** Notice of Responsibility - #39701  
**Action Type:** REMEDIATION  
**Date :** 9/25/1988  
**Action:** Pump & Treat (P&T) Groundwater  
**Action Type:** REMEDIATION  
**Date :** 9/25/1988  
**Action:** Excavation  
**Action Type:** Other

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Date : 8/5/1988  
 Action: Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 10/16/1996

**Status:** Open - Site Assessment  
**Status Date:** 9/25/1988

**Status:** Open - Site Assessment  
**Status Date:** 9/23/1988

**Status:** Open - Case Begin Date  
**Status Date:** 8/5/1988

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	SANTA CLARA UNIVERSITY	<b>Potential COC:</b>	DIESEL
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	455 EL CAMINO REAL
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95053
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608501809">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608501809</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 10/16/1996		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608501809&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608501809&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02J01f		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Desc:</b>			
<b>Site History:</b>			

No site history available

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 10/16/1996

**Status:** Open - Site Assessment  
**Date :** 9/25/1988

**Status:** Open - Site Assessment  
**Date :** 9/23/1988

**Status:** Open - Case Begin Date  
**Date :** 8/5/1988

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** EXCAVATION  
**Phase:**  
**Contaminant Mass Removed:**  
**Description:**

**Begin Date:** 9/25/1988  
**End Date:** 1/1/1995

**Action Type:** PUMP & TREAT (P&T) GROUNDWATER  
**Phase:**  
**Contaminant Mass Removed:**  
**Description:**

**Begin Date:** 9/25/1988  
**End Date:** 1/1/1995

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/16/1996  
**Received Issue Date:** 10/16/1996  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501809&enforcement\\_id=6234863&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501809&enforcement_id=6234863&temptable=ENFORCEMENT)  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 10/16/1996  
**Received Issue Date:** 10/16/1996  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501809&doc\\_id=5828633](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501809&doc_id=5828633)  
**Title Description Comments:**

SCVWD Electronic Files

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/2/1996  
**Received Issue Date:** 5/2/1996  
**Action:** Staff Letter - #23663  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 3/31/1996  
**Received Issue Date:** 4/14/1996  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 1/1/1996

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Received Issue Date:</b>		1/1/1996				
<b>Action:</b>		Staff Letter - #23661				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Notices				
<b>Action Date:</b>		11/17/1989				
<b>Received Issue Date:</b>		11/17/1989				
<b>Action:</b>		Notice of Responsibility - #39701				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		7/31/1996				
<b>Received Issue Date:</b>						
<b>Action:</b>		Soil and Water Investigation Report				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
Soil and Water Investigation Report						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		9/25/1988				
<b>Received Issue Date:</b>						
<b>Action:</b>		Excavation				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		9/25/1988				
<b>Received Issue Date:</b>						
<b>Action:</b>		Pump & Treat (P&T) Groundwater				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		8/5/1988				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b><u>LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)</u></b>						
<b>Document Type:</b>		Site Documents			<b>Size :</b>	
<b>Document Date:</b>		10/16/1996			<b>Submitted By:</b> COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)	
<b>Type:</b>		OTHER REPORT / DOCUMENT			<b>Submitted:</b>	
<b>Title:</b>		SCVWD ELECTRONIC FILES				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501809&amp;document_id=5828633">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501809&amp;document_id=5828633</a>				
<b>Document Type:</b>		Site Documents			<b>Size :</b>	
<b>Document Date:</b>		10/16/1996			<b>Submitted By:</b> COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)	
<b>Type:</b>		CLOSURE/NO FURTHER ACTION LETTER			<b>Submitted:</b>	
<b>Title:</b>		UNKNOWN				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501809&amp;enforcement_id=6234863">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501809&amp;enforcement_id=6234863</a>				
<a href="#">33</a>	1 of 1	N	0.38 / 1,989.18	69.65 / -5	SANTA CLARA POLICE STATION 501 EL CAMINO REAL SANTA CLARA CA 95050	CALSITES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>ID No:</b>	43360129				<b>Assembly:</b> 20	
<b>Status Date:</b>	10/10/1997				<b>Senate:</b> 10	
<b>NPL:</b>	N				<b>Region:</b> 2	
<b>Tier:</b>					<b>Region Name:</b> BERKELEY	
<b>Fund:</b>	C				<b>County Co:</b> 43	
<b>Access :</b>	C				<b>Facility County:</b> SANTA CLARA	
<b>Access Code:</b>	CONTROLLED				<b>Lat Deg:</b> 37	
<b>Cortese:</b>					<b>Lat Min:</b> 21	
<b>Hrscore:</b>					<b>Lat Sec:</b> 15	
<b>Hrsdate:</b>					<b>Lat Dir:</b> W	
<b>Groundwater Contam:</b>					<b>Long Deg:</b> 122	
<b>GW Code:</b>	NOT REPORTED				<b>Long Min:</b> 56	
<b>No Sources:</b>	0				<b>Long Sec:</b> 15	
<b>RWQCB Name:</b>	SAN FRANCISCO BAY				<b>Long Dir:</b> N	
<b>Branch Name:</b>	NORTH COAST				<b>LImethod:</b>	
<b>Staff:</b>	AWANGER				<b>LIdesc:</b>	
<b>Senior:</b>	KTOTH					
<b>Status Name:</b>	VOLUNTARY CLEANUP PROGRAM					
<b>Type Name:</b>	VOLUNTARY CLEANUP PROGRAM					
<b>Lead Name:</b>	DEPT OF TOXIC SUBSTANCES CONTROL					
<b>SIC Name:</b>	MANU - ELECTRONIC & OTHER ELECTRIC EQUIP					
<b>Filename:</b>						
<b>Comments:</b>						

SIGNED A VOLUNTARY CLEANUP AGREEMENT WITH THE CITY OF SANTA CLARA FOR OVERSIGHT/APPROVAL OF A REMOVAL ACTION WORKPLAN AND IT IMPLEMENTATION. THE REMOVAL ACTION WILL ALLOW THE CITY TO CONSTRUCT A NEW POLICE STATION AT THE SITE. CONSTRUCTION OF THE STATION IS SCHEDULED TO BEGIN IN FEBRUARY 1998.

Approved Removal Action Workplan which proposes to consolidate soils contaminated with polynuclear aromatic hydrocarbons from operation of a town gas plant. Soils will be consolidated under asphalt parking area. A notice of exemption was filed for the project.

#### Background:

The Site is identified by Assessor's Parcel Number 230-6-0. The site is a flat, open field of approximately 4.7 acres, bounded on two sides by roadways, one side by a railroad yard, and one side by a flat open field of approximately 4.5 acres. The site contains 5 old buildings (of approximately 3900, 2800, 1200, 1100, and 400 square feet, respectively) which are scheduled for demolition by the end of 1997.

The site was used by the City of Santa Clara as a Utility Yard from approximately 1890 through the 1960's. From the 1890's through the 1930's coal gas was generated at this site, first to power gas street lights and later to generate electricity for the electric street light system. The on-site structures were used for the City for storage since the 1960's.

Reports, containing the results of environmental media sampling conducted at the Site, indicate that the soil is contaminated with hazardous substances, including Polynuclear Aromatic Hydrocarbons (PNAs) and lead.

<a href="#">34</a>	1 of 1	NNW	0.38 / 1,990.25	73.33 / -2	Santa Clara University Parking Garage 3205 The Alameda Santa Clara CA	LOP SANTA CLARA
<b>SCVWD ID:</b>	07S1W02K03f					
<b>Closure Date:</b>	05/20/2014					
<b>Link:</b>	<a href="http://lustop.sccgov.org/files/07S1W02K03f/">http://lustop.sccgov.org/files/07S1W02K03f/</a>					

<a href="#">35</a>	1 of 1	NNW	0.38 / 1,997.34	73.72 / -1	SANTA CLARA UN. PARKING GARAGE 3205 THE ALAMEDA SANTA CLARA CA 95050	LUST
<b>Global ID:</b>	T10000004298			<b>County:</b> SANTA CLARA		
<b>Status:</b>	COMPLETED - CASE CLOSED			<b>Latitude:</b>		
<b>Status Date:</b>				<b>Longitude:</b>		
<b>Case Type:</b>	LUST CLEANUP SITE					
<b>Date Source:</b>	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download					

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>RB Case No:</b>	14-827				<b>Potential COC:</b>	Benzene, Total Petroleum Hydrocarbons (TPH)
<b>Local Case No:</b>	07S1W02K03f				<b>How Discovered:</b>	Other Means
<b>Begin Date:</b>	9/29/1982				<b>Stop Method:</b>	Close and Remove Tank
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP				<b>Stop Description:</b>	Remove USTs and station
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP				<b>Case Worker:</b>	GOR
<b>CUF Case:</b>	NO				<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Aquifer used for drinking water supply, Soil  
**How Discovered Description:** excavation for creation of bioswale  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 46-50%  
**Site History:**

Location of a historical gas station. The USTs were removed in 1982. Report of UST removal not supplied to us. After demolition, the site was a paved parking lot. Excavation began to create a bioswale adjacent to a planned parking garage when contamination was encountered.

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

**Action Type:** RESPONSE  
**Date :** 6/6/2014  
**Action:** Well Destruction Report

**Action Type:** ENFORCEMENT  
**Date :** 5/20/2014  
**Action:** Closure/No Further Action Letter

**Action Type:** ENFORCEMENT  
**Date :** 4/4/2014  
**Action:** Staff Letter

**Action Type:** ENFORCEMENT  
**Date :** 1/16/2014  
**Action:** Notification - Public Notice of Case Closure

**Action Type:** ENFORCEMENT  
**Date :** 9/17/2013  
**Action:** Staff Letter

**Action Type:** RESPONSE  
**Date :** 7/31/2013  
**Action:** Well Installation Report - Regulator Responded

**Action Type:** RESPONSE  
**Date :** 7/24/2013  
**Action:** Request for Closure - Regulator Responded

**Action Type:** RESPONSE  
**Date :** 7/22/2013  
**Action:** Other Report / Document

**Action Type:** RESPONSE  
**Date :** 5/28/2013  
**Action:** Well Installation Report

**Action Type:** ENFORCEMENT  
**Date :** 4/30/2013  
**Action:** Staff Letter

**Action Type:** RESPONSE  
**Date :** 4/11/2013  
**Action:** Soil and Water Investigation Report

**Action Type:** RESPONSE  
**Date :** 4/5/2013  
**Action:** Soil and Water Investigation Workplan - Regulator Responded

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		2/8/2013				
<b>Action:</b>		Staff Letter				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		12/21/2012				
<b>Action:</b>		Final Remedial Action Report / Corrective Action Report				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		12/8/2012				
<b>Action:</b>		Other Workplan				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		10/23/2012				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		10/19/2012				
<b>Action:</b>		Notice of Responsibility				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		10/19/2012				
<b>Action:</b>		Staff Letter				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		9/28/2012				
<b>Action:</b>		Other Report				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		9/28/2012				
<b>Action:</b>		Notice of Responsibility				
<b>Action Type:</b>		Other				
<b>Date :</b>		9/17/2012				
<b>Action:</b>		Leak Reported				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		9/17/2012				
<b>Action:</b>		Preliminary Site Assessment Report				
<b>Action Type:</b>		Other				
<b>Date :</b>		9/7/2012				
<b>Action:</b>		Leak Discovery				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		1/1/2012				
<b>Action:</b>		Correspondence				
<b>Action Type:</b>		Other				
<b>Date :</b>		9/29/1982				
<b>Action:</b>		Leak Stopped				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 BERGER DRIVE STE 300
<b>Contact Name:</b>	Gerald O'Regan	<b>Email:</b>	gerald.o'regan@deh.sccgov.org
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	5/20/2014
<b>Status:</b>	Open - Eligible for Closure
<b>Status Date:</b>	5/19/2014

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Status: Open - Site Assessment  
 Status Date: 9/27/2012

Status: Open - Case Begin Date  
 Status Date: 9/29/1982

**LUST Sites from GeoTracker Search - Regulatory Profile**

**Site Facility Name:** SANTA CLARA UN. PARKING GARAGE **Potential COC:** BENZENE, TOTAL PETROLEUM HYDROCARBONS (TPH)

**Site Facility Type:** LUST CLEANUP SITE **Facility Type:**

**Cleanup Status:** COMPLETED - CASE CLOSED **Composting Method:**

**Project Status:** **Address:** 3205 THE ALAMEDA

**WDR Place Type:** **City:** SANTA CLARA

**WDR File:** **Zip:** 95050

**WDR Order:** **County:** SANTA CLARA

**CUF Priority Assig:** **CUF Claim:**

**CUF Amount Paid:**

**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE

**Designated Beneficial Use:** MUN, AGR, IND, PROC

**Project Oversight Agencies:**

**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T10000004298](https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000004298)

**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 5/20/2014

**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T10000004298&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000004298&tabname=regulatoryhistory)

**Potential Media of Concern:** AQUIFER USED FOR DRINKING WATER SUPPLY, SOIL

**User Defined Beneficial Use:**

**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)

**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)

**Post Closure Site Management:**

**Future Land Use:**

**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD) - CASE #: 07S1W02K03f  
 CASEWORKER: Gerald O'Regan  
 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 14-827  
 CASEWORKER: Regional Water Board

**Gndwater Monitoring Freque:**

**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply

**Site History:**

Location of a historical gas station. The USTs were removed in 1982. Report of UST removal not supplied to us. After demolition, the site was a paved parking lot. Excavation began to create a bioswale adjacent to a planned parking garage when contamination was encountered.

**LUST Sites from GeoTracker Search - Cleanup Status History**

Status: Completed - Case Closed  
 Date : 5/20/2014

Status: Open - Eligible for Closure  
 Date : 5/19/2014

Status: Open - Site Assessment  
 Date : 9/27/2012

Status: Open - Case Begin Date  
 Date : 9/29/1982

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Reports

**Action Date:** 6/6/2014

**Received Issue Date:** 5/5/2014

**Action:** Well Destruction Report

**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5801471](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5801471)

**Title Description Comments:**

- concur

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/20/2014  
**Received Issue Date:** 5/20/2014  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6204038&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6204038&temptable=ENFORCEMENT)

**Title Description Comments:**

Case Closure Letter/Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/4/2014  
**Received Issue Date:** 4/4/2014  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6198291&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6198291&temptable=ENFORCEMENT)

**Title Description Comments:**

Well Destruction

**Action Type:** Notices  
**Action Date:** 1/16/2014  
**Received Issue Date:** 1/16/2014  
**Action:** Notification - Public Notice of Case Closure  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6189442&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6189442&temptable=ENFORCEMENT)

**Title Description Comments:**

Intent to Close Letter, Fact Sheet, and Contact List

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/17/2013  
**Received Issue Date:** 9/17/2013  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6175802&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6175802&temptable=ENFORCEMENT)

**Title Description Comments:**

No Further Action

**Action Type:** Response Requested - Reports  
**Action Date:** 7/31/2013  
**Received Issue Date:** 7/22/2013  
**Action:** Well Installation Report - Regulator Responded  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5769667](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5769667)

**Title Description Comments:**

Soil Excavation and Groundwater Well Installation Report - Issued NFA.

**Action Type:** Response Requested - Other  
**Action Date:** 7/24/2013  
**Received Issue Date:** 7/24/2013  
**Action:** Request for Closure - Regulator Responded  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5797889](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5797889)

**Title Description Comments:**

Contaminated Soil Removal-Backfill Report - refer to 9/17/2013 staff letter

**Action Type:** Response Requested - Other  
**Action Date:** 7/22/2013

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Received Issue Date:** 7/22/2013  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5927387](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927387)  
**Title Description Comments:**

Soil Disposal Report 07/22/2013

**Action Type:** Response Requested - Reports  
**Action Date:** 5/28/2013  
**Received Issue Date:** 5/28/2013  
**Action:** Well Installation Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5927390](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927390)  
**Title Description Comments:**

Well Construction Application 05/28/2013

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/30/2013  
**Received Issue Date:** 4/30/2013  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6157478&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6157478&temptable=ENFORCEMENT)  
**Title Description Comments:**

Soil Excavation and Groundwater Well Installation Report

**Action Type:** Response Requested - Reports  
**Action Date:** 4/11/2013  
**Received Issue Date:** 4/11/2013  
**Action:** Soil and Water Investigation Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5927389](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927389)  
**Title Description Comments:**

Soil & Water Investigation Report 04/11/2013

**Action Type:** Response Requested - Workplans  
**Action Date:** 4/5/2013  
**Received Issue Date:** 4/1/2013  
**Action:** Soil and Water Investigation Workplan - Regulator Responded  
**Doc Link:**  
**Title Description Comments:**

Workplan, Additional Site Assessment

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/8/2013  
**Received Issue Date:** 2/8/2013  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6148962&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6148962&temptable=ENFORCEMENT)  
**Title Description Comments:**

Workplan, Additional Site Assessment

**Action Type:** Response Requested - Workplans  
**Action Date:** 12/8/2012  
**Received Issue Date:** 12/8/2012  
**Action:** Other Workplan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000004298&doc\\_id=5927391](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927391)  
**Title Description Comments:**

Work Plan 12/08/2012

**Action Type:** Response Requested - Other

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Date:</b>			10/23/2012			
<b>Received Issue Date:</b>			10/23/2012			
<b>Action:</b>			Other Report / Document			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927388			
<b>Title Description Comments:</b>			State Information 10/23/2012			
<b>Action Type:</b>			Other Regulatory Actions			
<b>Action Date:</b>			10/19/2012			
<b>Received Issue Date:</b>			10/19/2012			
<b>Action:</b>			Staff Letter			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6140640&temptable=ENFORCEMENT			
<b>Title Description Comments:</b>			REemial Action Plan			
<b>Action Type:</b>			Notices			
<b>Action Date:</b>			10/19/2012			
<b>Received Issue Date:</b>			10/19/2012			
<b>Action:</b>			Notice of Responsibility			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6140916&temptable=ENFORCEMENT			
<b>Title Description Comments:</b>						
<b>Action Type:</b>			Notices			
<b>Action Date:</b>			9/28/2012			
<b>Received Issue Date:</b>			9/28/2012			
<b>Action:</b>			Notice of Responsibility			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6139003&temptable=ENFORCEMENT			
<b>Title Description Comments:</b>			Notice of Responsibility Letter			
<b>Action Type:</b>			Reports			
<b>Action Date:</b>			9/28/2012			
<b>Received Issue Date:</b>			9/28/2012			
<b>Action:</b>			Other Report			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6324299&temptable=ENFORCEMENT			
<b>Title Description Comments:</b>			Map & Metroscan Information 09/28/2012			
<b>Action Type:</b>			Response Requested - Reports			
<b>Action Date:</b>			9/17/2012			
<b>Received Issue Date:</b>			9/17/2012			
<b>Action:</b>			Preliminary Site Assessment Report			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927386			
<b>Title Description Comments:</b>			Preliminary Site Assessment Report 09/17/2012			
<b>Action Type:</b>			Response Requested - Other			
<b>Action Date:</b>			1/1/2012			
<b>Received Issue Date:</b>			1/1/2012			
<b>Action:</b>			Correspondence			
<b>Doc Link:</b>			https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000004298&doc_id=5927385			
<b>Title Description Comments:</b>			Correspondence 2012			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		12/21/2012				
<b>Received Issue Date:</b>						
<b>Action:</b>		Final Remedial Action Report / Corrective Action Report				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Remedial Action Plan				
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		9/17/2012				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		9/7/2012				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Discovery				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		9/29/1982				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Stopped				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b><u>LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)</u></b>						
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	5/20/2014			<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)	
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER			<b>Submitted:</b>		
<b>Title:</b>	CASE CLOSURE LETTER/REPORT					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6204038					
<b>Document Type:</b>	Site Documents			<b>Size :</b>	14,272 KB	
<b>Document Date:</b>	5/5/2014			<b>Submitted By:</b>	ALEX KASSAI (AUTH_RP)	
<b>Type:</b>	REQUEST FOR CLOSURE			<b>Submitted:</b>		
<b>Title:</b>	MONITORING WELL DESTRUCTION					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4281694531/T10000004298.PDF					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	4/4/2014			<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)	
<b>Type:</b>	STAFF LETTER			<b>Submitted:</b>		
<b>Title:</b>	WELL DESTRUCTION					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6198291					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/16/2014			<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)	
<b>Type:</b>	NOTIFICATION - PUBLIC NOTICE OF CASE CLOSURE			<b>Submitted:</b>		
<b>Title:</b>	INTENT TO CLOSE LETTER, FACT SHEET, AND CONTACT LIST					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6189442					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	9/17/2013			<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)	
<b>Type:</b>	STAFF LETTER			<b>Submitted:</b>		
<b>Title:</b>	NO FURTHER ACTION					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6175802					
<b>Document Type:</b>	Site Documents			<b>Size :</b>	2,400 KB	
<b>Document Date:</b>	7/24/2013			<b>Submitted By:</b>	ALEX KASSAI (AUTH_RP)	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Type:</b>	REQUEST FOR CLOSURE				<b>Submitted:</b>	
<b>Title:</b>	CONTAMINATED SOIL REMOVAL-BACKFILL REPORT					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2494652926/T1000004298.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	7/22/2013				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT				<b>Submitted:</b>	
<b>Title:</b>	SOIL DISPOSAL REPORT 07/22/2013					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&document_id=5927387					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	12,073 KB
<b>Document Date:</b>	6/14/2013*				<b>Submitted By:</b>	ALEX KASSAI (AUTH_RP)
<b>Type:</b>	WELL INSTALLATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	MONITORING WELL INSTALLATION REPORT					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4319756686/T1000004298.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	5/28/2013				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	WELL INSTALLATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	WELL CONSTRUCTION APPLICATION 05/28/2013					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&document_id=5927390					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	4,465 KB
<b>Document Date:</b>	5/15/2013*				<b>Submitted By:</b>	ALEX KASSAI (AUTH_RP)
<b>Type:</b>	SITE ASSESSMENT REPORT				<b>Submitted:</b>	
<b>Title:</b>	ADDITIONAL SOIL INVESTIGATION / ANALYSIS					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4760135710/T1000004298.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	4/30/2013				<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)
<b>Type:</b>	STAFF LETTER				<b>Submitted:</b>	
<b>Title:</b>	SOIL EXCAVATION AND GROUNDWATER WELL INSTALLATION REPORT					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&enforcement_id=6157478					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	4/11/2013				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	SOIL & WATER INVESTIGATION REPORT 04/11/2013					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&document_id=5927389					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	2/8/2013				<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)
<b>Type:</b>	STAFF LETTER				<b>Submitted:</b>	
<b>Title:</b>	WORKPLAN, ADDITIONAL SITE ASSESSMENT					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&enforcement_id=6148962					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	12/8/2012				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER WORKPLAN				<b>Submitted:</b>	
<b>Title:</b>	WORK PLAN 12/08/2012					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&document_id=5927391					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	10/23/2012				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT				<b>Submitted:</b>	
<b>Title:</b>	STATE INFORMATION 10/23/2012					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&document_id=5927388					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	10/19/2012				<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)
<b>Type:</b>	NOTICE OF RESPONSIBILITY				<b>Submitted:</b>	
<b>Title:</b>	UNKNOWN					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000004298&enforcement_id=6140916					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	10/19/2012				<b>Submitted By:</b>	CHRIS WIDMANN (REGULATOR)
<b>Type:</b>	STAFF LETTER				<b>Submitted:</b>	
<b>Title:</b>	REEMIAL ACTION PLAN					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6140640](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6140640)

**Document Type:** Site Documents **Size :**  
**Document Date:** 9/28/2012 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT **Submitted:**  
**Title:** MAP & METROSCAN INFORMATION 09/28/2012  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6324299](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6324299)

**Document Type:** Site Documents **Size :**  
**Document Date:** 9/28/2012 **Submitted By:** CHRIS WIDMANN (REGULATOR)  
**Type:** NOTICE OF RESPONSIBILITY **Submitted:**  
**Title:** NOTICE OF RESPONSIBILITY LETTER  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&enforcement\\_id=6139003](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&enforcement_id=6139003)

**Document Type:** Site Documents **Size :**  
**Document Date:** 9/17/2012 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** PRELIMINARY SITE ASSESSMENT REPORT **Submitted:**  
**Title:** PRELIMINARY SITE ASSESSMENT REPORT 09/17/2012  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&document\\_id=5927386](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&document_id=5927386)

**Document Type:** Site Documents **Size :**  
**Document Date:** 1/1/2012 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** CORRESPONDENCE **Submitted:**  
**Title:** CORRESPONDENCE 2012  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000004298&document\\_id=5927385](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000004298&document_id=5927385)

<a href="#">36</a>	1 of 1	E	0.39 / 2,083.08	67.33 / -8	OWENS ILLINOIS GLASS CO. 1185 CAMPBELL AVENUE SANTA CLARA CA 95050	ENVIROSTOR
--------------------	--------	---	--------------------	---------------	--	------------

<b>Estor/EPA ID:</b> 43320024	<b>Assembly District:</b> 25
<b>Site Code:</b>	<b>Senate District:</b> 10
<b>Nat Priority List:</b> NO	<b>Permit Renewal Lead:</b>
<b>APN:</b> 230-13-011	<b>Public Partici Spclst:</b>
<b>Census Tract:</b> 6085505203	<b>Project Manager:</b>
<b>Site Type:</b> * HISTORICAL	<b>County:</b> SANTA CLARA
<b>Address Description:</b> 1185 CAMPBELL AVENUE	<b>Latitude:</b> 37.3467908346523
<b>Office:</b> CLEANUP BERKELEY	<b>Longitude:</b> -121.929831504822
<b>Special Program:</b>	<b>Acres:</b> NONE SPECIFIED
<b>Funding:</b>	<b>Supervisor:</b>
<b>Cleanup Status:</b> REFER: RWQCB AS OF 6/8/1994	
<b>Cleanup Oversight Agencies:</b> NONE SPECIFIED	
<b>School District:</b>	
<b>Past Use that Caused Contam:</b> NONE SPECIFIED	
<b>Potential Media Affected:</b> NONE SPECIFIED	
<b>Potential Contamin of Concern:</b>	

NONE SPECIFIED

**Site History:**

**Status:** REFER: RWQCB  
**Program Type:** HISTORICAL  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=43320024](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43320024)

**Completed Activities**

**Title:** Discovery  
**Title Link:**  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** \* Discovery  
**Date Completed:** 9/24/1981

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Comments:</b>		FACILITY IDENTIFIED ACTIVE SITE ID'D FROM SUPERFUND				
<b>Title:</b>		Discovery				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		* Discovery				
<b>Date Completed:</b>		9/14/1981				
<b>Comments:</b>		FACILITY IDENTIFIED INACTIVE SITE: POLK DIR.				
<b>Title:</b>		Site Screening				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Screening				
<b>Date Completed:</b>		4/24/1987				
<b>Comments:</b>		SITE SCREENING DONE NO FILE FOUND.				

[37](#) 1 of 1 E 0.39 / 2,085.10 67.29 / -8 OWENS ILLINOIS GLASS CO. 1185 CAMPBELL AVENUE SANTA CLARA CA 95050 CALSITES

<b>ID No:</b>	43320024	<b>Assembly:</b>	
<b>Status Date:</b>	06/08/1994	<b>Senate:</b>	
<b>NPL:</b>		<b>Region:</b>	2
<b>Tier:</b>		<b>Region Name:</b>	BERKELEY
<b>Fund:</b>		<b>County Co:</b>	43
<b>Access :</b>		<b>Facility County:</b>	SANTA CLARA
<b>Access Code:</b>	NOT REPORTED	<b>Lat Deg:</b>	0
<b>Cortese:</b>		<b>Lat Min:</b>	0
<b>Hrscore:</b>		<b>Lat Sec:</b>	0
<b>Hrsdate:</b>		<b>Lat Dir:</b>	
<b>Groundwater Contam:</b>		<b>Long Deg:</b>	0
<b>GW Code:</b>	NOT REPORTED	<b>Long Min:</b>	0
<b>No Sources:</b>	0	<b>Long Sec:</b>	0
<b>RWQCB Name:</b>	SAN FRANCISCO BAY	<b>Long Dir:</b>	
<b>Branch Name:</b>	NORTH COAST	<b>LImethod:</b>	
<b>Staff:</b>		<b>LIdesc:</b>	
<b>Senior:</b>			
<b>Status Name:</b>	PROPERTY/SITE REFERRED TO RWQCB		
<b>Type Name:</b>	N/A		
<b>Lead Name:</b>	N/A		
<b>SIC Name:</b>	MANU - STONE, CLAY & GLASS PRODUCTS		
<b>Filename:</b>			
<b>Comments:</b>			

FACILITY IDENTIFIED INACTIVE SITE: POLK DIR. FACILITY IDENTIFIED ACTIVE SITE ID'D FROM SUPERFUND FACILITY DRIVE-BY ACTIVE SITE. OWENS ILLINOIS CLOSURE DIV. NO PROBLEMS NOTED QUESTIONNAIRE SENT QUESTIONNAIRE REC'D FINAL STRATEGY SITE REFERRED: TO RWQCB RWQCB PERMIT/SUPERVISION SITE SCREENING DONE NO FILE FOUND.

**Background:**

[38](#) 1 of 4 NNW 0.41 / 2,171.34 72.79 / -2 Old Simas Service Station 3290 The Alameda Santa Clara CA LOP SANTA CLARA

**SCVWD ID:** 07S1W02K01f  
**Closure Date:** 10/23/2000  
**Link:** <http://lustop.sccgov.org/files/07S1W02K01f/>

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<a href="#">38</a>	2 of 4	NNW	0.41 / 2,171.34	72.79 / -2	Santa Clara Un Property 3290 The Alameda Santa Clara CA	LOP SANTA CLARA

SCVWD ID: 07S1W02K02f  
 Closure Date: 04/29/2010  
 Link: <http://lustop.sccgov.org/files/07S1W02K02f/>

<a href="#">38</a>	3 of 4	NNW	0.41 / 2,171.34	72.79 / -2	OLD SIMAS SERVICE STATION 3290 THE ALAMEDA SANTA CLARA CA 95050	LUST
--------------------	--------	-----	--------------------	---------------	---	------

Global ID: T0608500247 County: SANTA CLARA  
 Status: COMPLETED - CASE CLOSED Latitude:  
 Status Date: Longitude:  
 Case Type: LUST CLEANUP SITE  
 Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: Potential COC: Gasoline  
 Local Case No: How Discovered:  
 Begin Date: 4/7/1986 Stop Method:  
 Lead Agency: SANTA CLARA COUNTY LOP Stop Description:  
 Local Agency: SANTA CLARA COUNTY LOP Case Worker: UST  
 CUF Case: YES File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media of Concern: Other Groundwater (uses other than drinking water)  
 How Discovered Description:  
 Calwater Watershed Name: Santa Clara - Palo Alto (205.50)  
 DWR GW Subbasin Name: Santa Clara Valley - Santa Clara (2-009.02)  
 Disadvantaged Community:  
 Calenviroscreen Score: 46-50%  
 Site History:

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: RESPONSE  
 Date : 6/3/2005  
 Action: Other Report / Document

Action Type: RESPONSE  
 Date : 10/6/1999  
 Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT  
 Date : 9/29/1999  
 Action: Staff Letter - #23339

Action Type: RESPONSE  
 Date : 2/25/1999  
 Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT  
 Date : 12/18/1998  
 Action: Staff Letter - #23337

Action Type: RESPONSE  
 Date : 12/5/1996  
 Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT  
 Date : 10/11/1996

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action:</b>		Staff Letter - #23335				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		8/12/1996				
<b>Action:</b>		Notice of Responsibility - #39704				
<b>Action Type:</b>		Other				
<b>Date :</b>		1/1/1992				
<b>Action:</b>		Leak Reported				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	10/23/2000
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	3/17/2000
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	4/7/1986
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	4/7/1986

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	OLD SIMAS SERVICE STATION	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	3290 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>	B	<b>CUF Claim:</b>	15196
<b>CUF Amount Paid:</b>	\$63,538		
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500247">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500247</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 10/23/2000		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500247&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500247&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02K01f		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Desc:**  
**Site History:**

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 10/23/2000

**Status:** Open - Site Assessment  
**Date :** 3/17/2000

**Status:** Open - Case Begin Date  
**Date :** 4/7/1986

**Status:** Open - Site Assessment  
**Date :** 4/7/1986

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500247&doc\\_id=5927372](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500247&doc_id=5927372)  
**Title Description Comments:**

Microfiche Scans - See Read Me First - 06/03/2005

**Action Type:** Response Requested - Workplans  
**Action Date:** 10/6/1999  
**Received Issue Date:** 10/6/1999  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/29/1999  
**Received Issue Date:** 9/29/1999  
**Action:** Staff Letter - #23339  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/18/1998  
**Received Issue Date:** 12/18/1998  
**Action:** Staff Letter - #23337  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/11/1996  
**Received Issue Date:** 10/11/1996  
**Action:** Staff Letter - #23335  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 8/12/1996

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Received Issue Date:** 8/12/1996  
**Action:** Notice of Responsibility - #39704  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Workplans  
**Action Date:** 2/25/1999  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Response Requested - Workplans  
**Action Date:** 12/5/1996  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Leak Action  
**Action Date:** 1/1/1992  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :** 772 KB  
**Document Date:** 10/5/2007 **Submitted By:** CYNTHIA MANA-AY (REGULATOR)  
**Type:** LETTER **Submitted:**  
**Title:** CLOSURE LETTER & SITE CLOSURE SUMMARY  
**Title Link:** [https://geotracker.waterboards.ca.gov/site\\_documents/9217289566/CLOS%5FL%5F2000%2D10%2D23%2Epdf](https://geotracker.waterboards.ca.gov/site_documents/9217289566/CLOS%5FL%5F2000%2D10%2D23%2Epdf)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** MICROFICHE SCANS - SEE READ ME FIRST - 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500247&document\\_id=5927372](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500247&document_id=5927372)

<a href="#">38</a>	4 of 4	NNW	0.41 / 2,171.34	72.79 / -2	SANTA CLARA UN PROPERTY 3290 THE ALAMEDA SANTA CLARA CA 95050	LUST
--------------------	--------	-----	--------------------	---------------	---	------

**Global ID:** T0608510936 **County:** SANTA CLARA  
**Status:** COMPLETED - CASE CLOSED **Latitude:**  
**Status Date:** **Longitude:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Potential COC:** Gasoline  
**Local Case No:** 07S1W02K02f **How Discovered:** Tank Closure  
**Begin Date:** 5/20/2003 **Stop Method:** Close and Remove Tank  
**Lead Agency:** SANTA CLARA COUNTY LOP **Stop Description:**  
**Local Agency:** **Case Worker:**  
**CUF Case:** NO **File Location:** All Files are on GeoTracker or in the Local

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 46-50%  
**Site History:**

A previous Fuel Leak Case (07S1W02K01f) was opened at this site. This case was associated with the removal of 4 underground storage tanks (USTs) at a former gasoline retail station in 1986 and 1994. The case was closed on 10/23/00. At the time of closure, residual contamination remained in soil (4,700 parts per million (ppm) Total Petroleum Hydrocarbons as Gasoline (TPHg), 3.5 ppm Benzene, 50 ppm Toluene, 25 ppm Ethylbenzene, and 260 ppm Xylenes) and groundwater (1,200 parts per billion (ppb) TPHg, 24 ppb Benzene, 3.3 ppb Toluene, 38 ppb Ethylbenzene, and 99 ppb Xylenes) at the site. 2003 – In May, a 1,000-gallon UST was found onsite and removed. 4 soil samples (P-1 through P-4) were collected from the excavation; 2 from each end at 6-inches and 2 feet below the bottom of the UST. The soil samples were analyzed for TPHg, TPH as Diesel (TPHd), TPH as Motor Oil (TPHmo), Oil and Grease (O&G), Pesticides, Polychlorinated Biphenyls (PCBs), LUFT Metals, Volatile Organic Compounds (VOCs) and Semi-Volatile Organic Compounds (SVOCs). The maximum concentrations reported were 5,900 ppm TPHg, 1,400 ppm TPHd, 81 ppm Ethylbenzene, 32 ppm Toluene, 44 ppm Naphthalene, 500 ppm Trichlorofluoromethane, 390 ppm 1,2,4-Trimethylbenzene, 120 ppm 1,3,5 trimethylbenzene, 46 ppm n-Propylbenzene, 3.7 ppm p-isopropyl benzene, 22 ppm 2 Methylnaphthalene, 1.6 ppm Cadmium, 38 ppm Chromium, 67 ppm Lead, 60 ppm Nickel, and 37 ppm Zinc. All other constituents were not reported to be present above the laboratory reporting limits. In June, 6 hand auger borings (B1 through B6) were advanced between 13 and 16 feet below the ground surface (ft bgs). Two soil samples were collected from each boring at varying depths and were analyzed for TPHg, TPHd, TPHmo, VOCs, SVOCs and LUFT Metals. Maximum concentrations reported were 11,000 ppm TPHg, 1,200 ppm TPHd, 55 ppm Ethylbenzene, 48 ppm Naphthalene, 510 ppm 1,2,4-Trimethylbenzene, 170 ppm 1,3,5-Trimethylbenzene, 45 ppm n-Butyl Benzene, 76 ppm n-Propyl Benzene, 26 ppm p-Isopropyl Benzene, 0.34 ppm Tert-butyl Benzene, and 4.7 ppm 2-Methylnaphthalene. Metals were detected at similar levels to the previous soil samples. All other constituents were not reported to be present above the laboratory reporting limits. Groundwater was encountered in the borings and grab groundwater samples were collected from each open boring and analyzed for TPHg, TPHd, TPHmo, VOCs, SVOCs, and LUFT Metals. The maximum concentrations reported were 38,000 ppb TPHg, 13,000 ppb TPHd, 3,500 ppb Benzene, 4,200 ppb Ethylbenzene, 450 ppb Toluene, 11,000 ppb Xylenes, 580 ppb n Butylbenzene, 760 ppb Isopropylbenzene, 540 ppb p-Isopropylbenzene, 720 ppb Naphthalene, 1,500 ppb n-Propylbenzene, 9,100 ppb 1,2,4-Trimethylbenzene, 2,700 ppb 1,3,5 Trimethylbenzene, 51 ppb 2-Methylnaphthalene, 22 ppb Benzoic Acid, 210 ppb Cadmium, 2,600 ppb Chromium, 730 ppb Lead, 3,900 ppb Nickel, and 3,500 ppb Zinc. All other constituents were not reported to be present above the laboratory reporting limits. 2004 – In July, 4 groundwater monitoring wells (MW-1 through MW-4) were installed onsite. 5 soil samples were collected from each boring at various depths. Soil samples were reported to have up to 150 ppm TPHg, 21 ppm TPHd, 0.3 ppm Benzene, 1.9 ppm Ethylbenzene, 32 ppm Toluene, 1.6 ppm Naphthalene, 8.9 ppm Trichlorofluoromethane, 0.26 ppm Isopropylbenzene, 7.6 ppm 1,2,4-Trimethylbenzene, 2.1 ppm 1,3,5-Trimethylbenzene, 0.8 ppm n-Propylbenzene, 0.26 ppm p-Isopropyl Benzene. Metals were reported at similar concentrations as previous soil samples. All other constituents were not reported to be present above the laboratory reporting limits. Quarterly groundwater monitoring began at this site in July 2004 and continued through February 2006. In July, the maximum concentrations reported in groundwater were 2,000 ppb TPHg, 480 ppb TPHd, 11 ppb Benzene, 54 ppb Ethylbenzene, 96 ppb Xylenes, 0.71 ppb 1,2-Dichloroethane (DCA), 8.6 ppb sec-Butylbenzene, 13 ppb Isopropylbenzene, and 17 ppb n-Propylbenzene. 2006 – In February, groundwater samples collected at the site during the last groundwater monitoring event were reported to have up to 700 ppb TPHg, 190 ppb TPHd, 2.2 ppb Benzene, 14 ppb Ethylbenzene, 6.9 ppb Xylenes, 1 ppb DCA, 4.4 ppb sec-Butylbenzene, 4.7 ppb Isopropylbenzene, and 3.7 ppb n-Propylbenzene. 2007 – In October, a soil vapor study was completed and the groundwater monitoring wells were sampled. Maximum concentrations reported for groundwater were 930 ppb TPHg, 260 ppb TPHd, 260 ppb Benzene, 52 ppb Ethylbenzene, 5.9 ppb Toluene, 0.71 ppb DCA, 5 ppb sec-Butylbenzene, 6.5 ppb Isopropylbenzene, and 1.8 ppb n-Propylbenzene. The constituents detected in the soil gas did not exceed the Environmental Screening Levels.

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

**Action Type:** ENFORCEMENT  
**Date :** 4/29/2010  
**Action:** Closure/No Further Action Letter

**Action Type:** ENFORCEMENT  
**Date :** 12/21/2009  
**Action:** Staff Letter

**Action Type:** ENFORCEMENT  
**Date :** 7/15/2009  
**Action:** Staff Letter

**Action Type:** RESPONSE  
**Date :** 1/30/2009  
**Action:** Monitoring Report - Quarterly

**Action Type:** RESPONSE  
**Date :** 10/30/2008  
**Action:** Monitoring Report - Quarterly

**Action Type:** ENFORCEMENT

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date :</b>						
<b>Action:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>					Staff Letter - #42831	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					12/12/2003	
<b>Action:</b>					Other Report / Document	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					12/10/2003	
<b>Action:</b>					Well Installation Report	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date :</b>					11/13/2003	
<b>Action:</b>					Staff Letter - #42593	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date :</b>					11/13/2003	
<b>Action:</b>					Notice of Responsibility - #42592	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					10/3/2003	
<b>Action:</b>					Other Report / Document	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					10/3/2003	
<b>Action:</b>					Unauthorized Release Form	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					8/26/2003	
<b>Action:</b>					Tank Removal Report / UST Sampling Report	
<b>Action Type:</b>					Other	
<b>Date :</b>					6/11/2003	
<b>Action:</b>					Leak Reported	
<b>Action Type:</b>					Other	
<b>Date :</b>					5/17/2003	
<b>Action:</b>					Leak Stopped	
<b>Action Type:</b>					Other	
<b>Date :</b>					5/17/2003	
<b>Action:</b>					Leak Discovery	
<b>Action Type:</b>					REMEDIATION	
<b>Date :</b>					5/7/2003	
<b>Action:</b>					Excavation	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					1/1/2003	
<b>Action:</b>					Correspondence	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					6/10/2002	
<b>Action:</b>					Other Workplan	

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	4/29/2010
<b>Status:</b>	Open - Case Begin Date

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Status Date:** 5/20/2003  
**Status:** Open - Site Assessment  
**Status Date:** 5/20/2003

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	SANTA CLARA UN PROPERTY	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	3290 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608510936">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608510936</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 4/29/2010		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608510936&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608510936&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>	NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL NOTIFY PRIOR TO CHANGE IN LAND USE NOTIFY PRIOR TO DEVELOPMENT		
<b>Future Land Use:</b>	COMMERCIAL		
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) - CASE #: 07S1W02K02f SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board # OF WELLS MONITORED - OTHER : 4		
<b>Gndwater Monitoring Freque:</b>	# OF WELLS MONITORED - OTHER : 4		
<b>Designated Beneficial Use Desc:</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Site History:</b>			

A previous Fuel Leak Case (07S1W02K01f) was opened at this site. This case was associated with the removal of 4 underground storage tanks (USTs) at a former gasoline retail station in 1986 and 1994. The case was closed on 10/23/00. At the time of closure, residual contamination remained in soil (4,700 parts per million (ppm) Total Petroleum Hydrocarbons as Gasoline (TPHg), 3.5 ppm Benzene, 50 ppm Toluene, 25 ppm Ethylbenzene, and 260 ppm Xylenes) and groundwater (1,200 parts per billion (ppb) TPHg, 24 ppb Benzene, 3.3 ppb Toluene, 38 ppb Ethylbenzene, and 99 ppb Xylenes) at the site.

2003 – In May, a 1,000-gallon UST was found onsite and removed. 4 soil samples (P-1 through P-4) were collected from the excavation; 2 from each end at 6-inches and 2 feet below the bottom of the UST. The soil samples were analyzed for TPHg, TPH as Diesel (TPHd), TPH as Motor Oil (TPHmo), Oil and Grease (O&G), Pesticides, Polychlorinated Biphenyls (PCBs), LUFT Metals, Volatile Organic Compounds (VOCs) and Semi-Volatile Organic Compounds (SVOCs). The maximum concentrations reported were 5,900 ppm TPHg, 1,400 ppm TPHd, 81 ppm Ethylbenzene, 32 ppm Toluene, 44 ppm Naphthalene, 500 ppm Trichlorofluoromethane, 390 ppm 1,2,4-Trimethylbenzene, 120 ppm 1,3,5 trimethylbenzene, 46 ppm n-Propylbenzene, 3.7 ppm p-isopropyl benzene, 22 ppm 2 Methyl-naphthalene, 1.6 ppm Cadmium, 38 ppm Chromium, 67 ppm Lead, 60 ppm Nickel, and 37 ppm Zinc. All other constituents were not reported to be present above the laboratory reporting limits.

In June, 6 hand auger borings (B1 through B6) were advanced between 13 and 16 feet below the ground surface (ft bgs). Two soil samples were collected from each boring at varying depths and were analyzed for TPHg, TPHd, TPHmo, VOCs, SVOCs and LUFT Metals. Maximum concentrations reported were 11,000 ppm TPHg, 1,200 ppm TPHd, 55 ppm Ethylbenzene, 48 ppm Naphthalene, 510 ppm 1,2,4-Trimethylbenzene, 170 ppm 1,3,5-Trimethylbenzene, 45 ppm n-Butyl Benzene, 76 ppm n-Propyl Benzene, 26 ppm p-Isopropyl Benzene, 0.34 ppm Tert-butyl Benzene, and 4.7 ppm 2-Methylnaphthalene. Metals were detected at similar levels to the previous soil samples. All other constituents were not reported to be present above the laboratory reporting limits.

Groundwater was encountered in the borings and grab groundwater samples were collected from each open boring and analyzed for TPHg, TPHd, TPHmo, VOCs, SVOCs, and LUFT Metals. The maximum concentrations reported were 38,000 ppb TPHg, 13,000 ppb TPHd, 3,500 ppb Benzene, 4,200 ppb Ethylbenzene, 450 ppb Toluene, 11,000 ppb Xylenes, 580 ppb n Butylbenzene, 760 ppb Isopropylbenzene, 540 ppb p-Isopropylbenzene, 720 ppb Naphthalene, 1,500 ppb n-Propylbenzene, 9,100 ppb 1,2,4-Trimethylbenzene, 2,700 ppb 1,3,5 Trimethylbenzene, 51 ppb 2-Methylnaphthalene, 22 ppb Benzoic Acid, 210 ppb Cadmium, 2,600 ppb Chromium, 730 ppb Lead, 3,900 ppb Nickel, and 3,500 ppb Zinc. All other constituents were not reported to be present above the laboratory reporting limits.

2004 – In July, 4 groundwater monitoring wells (MW-1 through MW-4) were installed onsite. 5 soil samples were collected from each boring at various depths. Soil samples were reported to have up to 150 ppm TPHg, 21 ppm TPHd, 0.3 ppm Benzene, 1.9 ppm Ethylbenzene, 32 ppm Toluene, 1.6 ppm Naphthalene, 8.9 ppm Trichlorofluoromethane, 0.26 ppm Isopropylbenzene, 7.6 ppm 1,2,4-Trimethylbenzene, 2.1 ppm 1,3,5-Trimethylbenzene, 0.8 ppm

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

n-Propylbenzene, 0.26 ppm p-Isopropyl Benzene. Metals were reported at similar concentrations as previous soil samples. All other constituents were not reported to be present above the laboratory reporting limits.

Quarterly groundwater monitoring began at this site in July 2004 and continued through February 2006. In July, the maximum concentrations reported in groundwater were 2,000 ppb TPHg, 480 ppb TPHd, 11 ppb Benzene, 54 ppb Ethylbenzene, 96 ppb Xylenes, 0.71 ppb 1,2-Dichloroethane (DCA), 8.6 ppb sec-Butylbenzene, 13 ppb Isopropylbenzene, and 17 ppb n-Propylbenzene.

2006 – In February, groundwater samples collected at the site during the last groundwater monitoring event were reported to have up to 700 ppb TPHg, 190 ppb TPHd, 2.2 ppb Benzene, 14 ppb Ethylbenzene, 6.9 ppb Xylenes, 1 ppb DCA, 4.4 ppb sec-Butylbenzene, 4.7 ppb Isopropylbenzene, and 3.7 ppb n-Propylbenzene.

2007 – In October, a soil vapor study was completed and the groundwater monitoring wells were sampled. Maximum concentrations reported for groundwater were 930 ppb TPHg, 260 ppb TPHd, 260 ppb Benzene, 52 ppb Ethylbenzene, 5.9 ppb Toluene, 0.71 ppb DCA, 5 ppb sec-Butylbenzene, 6.5 ppb Isopropylbenzene, and 1.8 ppb n-Propylbenzene. The constituents detected in the soil gas did not exceed the Environmental Screening Levels.

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 4/29/2010

**Status:** Open - Site Assessment  
**Date :** 5/20/2003

**Status:** Open - Case Begin Date  
**Date :** 5/20/2003

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** EXCAVATION  
**Phase:** Soil  
**Contaminant Mass Removed:**  
**Description:**

**Begin Date:** 5/7/2003  
**End Date:** 5/20/2003

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/29/2010  
**Received Issue Date:** 4/29/2010  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608510936&enforcement\\_id=6049915&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&enforcement_id=6049915&temptable=ENFORCEMENT)

**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/21/2009  
**Received Issue Date:** 12/21/2009  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608510936&enforcement\\_id=6038648&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&enforcement_id=6038648&temptable=ENFORCEMENT)

**Title Description Comments:**

destroy wells for closure

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/15/2009  
**Received Issue Date:** 7/15/2009  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608510936&enforcement\\_id=6020877&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&enforcement_id=6020877&temptable=ENFORCEMENT)

**Title Description Comments:**

nfa pending file review for closure - awaiting 6/09 sampling results.

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		1/30/2009				
<b>Received Issue Date:</b>		2/26/2009				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5618971">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5618971</a>				
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		10/30/2008				
<b>Received Issue Date:</b>		8/27/2008				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5618970">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5618970</a>				
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		5/30/2008				
<b>Received Issue Date:</b>		5/30/2008				
<b>Action:</b>		Staff Letter - #800350				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		Geotracker upload noncompliance				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		5/28/2008				
<b>Received Issue Date:</b>		5/28/2008				
<b>Action:</b>		Staff Letter - #808250				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		gwm required				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		8/15/2007				
<b>Received Issue Date:</b>		2/22/2008				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5593128">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5593128</a>				
<b>Title Description Comments:</b>						
		Other Type of Submission by RP - Soil gas investigation				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		4/11/2007				
<b>Received Issue Date:</b>		4/11/2007				
<b>Action:</b>		Staff Letter - #701140				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		app soil gas wp				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		4/9/2007				
<b>Received Issue Date:</b>		4/9/2007				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5592183">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5592183</a>				
<b>Title Description Comments:</b>						
		Other Type of Submission by RP - Soil gas investigation work plan for downgradient				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		2/22/2007				
<b>Received Issue Date:</b>		2/22/2007				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>		Staff Letter - #70222				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		req soil gas inv.				
<b>Action Type:</b>		Enforcement - Other				
<b>Action Date:</b>		2/9/2007				
<b>Received Issue Date:</b>		2/9/2007				
<b>Action:</b>		* No Action - #7092				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		NFA pending closure review				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/22/2005				
<b>Received Issue Date:</b>		6/22/2005				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		GWM reporting and questionable gw results				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		6/22/2005				
<b>Received Issue Date:</b>		6/22/2005				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927377">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927377</a>				
<b>Title Description Comments:</b>						
		Phone Log 06/22/2005				
<b>Action Type:</b>		Reports				
<b>Action Date:</b>		6/3/2005				
<b>Received Issue Date:</b>		6/3/2005				
<b>Action:</b>		Other Report				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6324297&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6324297&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
		Map & Metroscan Information 06/03/2005				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		6/3/2005				
<b>Received Issue Date:</b>		6/3/2005				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927379">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927379</a>				
<b>Title Description Comments:</b>						
		State Information 06/03/2005				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		1/28/2005				
<b>Received Issue Date:</b>		6/21/2005				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
		Monitoring Report - Quarterly				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		1/12/2005				
<b>Received Issue Date:</b>		1/12/2005				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927376">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927376</a>				
<b>Title Description Comments:</b>		GW Monitoring Report 01/12/2005 - 09/15/2009				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		10/19/2004				
<b>Received Issue Date:</b>		10/19/2004				
<b>Action:</b>		Staff Letter - #44950				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		10/12/2004				
<b>Received Issue Date:</b>		10/12/2004				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927380">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927380</a>				
<b>Title Description Comments:</b>		Soil & Water Investigation Report 10/12/2004 - 02/14/2008				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		3/31/2004				
<b>Received Issue Date:</b>		10/18/2004				
<b>Action:</b>		Soil and Water Investigation Report				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Soil and Water Investigation Report				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		12/31/2003				
<b>Received Issue Date:</b>		12/22/2003				
<b>Action:</b>		Soil and Water Investigation Workplan				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>		Soil and Water Investigation Workplan				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		12/24/2003				
<b>Received Issue Date:</b>		12/24/2003				
<b>Action:</b>		Staff Letter - #42831				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		12/12/2003				
<b>Received Issue Date:</b>		12/12/2003				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927378">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927378</a>				
<b>Title Description Comments:</b>		Soil Disposal Report 12/12/2003				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		12/10/2003				
<b>Received Issue Date:</b>		12/10/2003				
<b>Action:</b>		Well Installation Report				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927383">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&amp;doc_id=5927383</a>				
<b>Title Description Comments:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

Well Construction Application 12/10/2003

**Action Type:** Notices  
**Action Date:** 11/13/2003  
**Received Issue Date:** 11/13/2003  
**Action:** Notice of Responsibility - #42592  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 11/13/2003  
**Received Issue Date:** 11/13/2003  
**Action:** Staff Letter - #42593  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 10/3/2003  
**Received Issue Date:** 10/3/2003  
**Action:** Unauthorized Release Form  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608510936&doc\\_id=5927382](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&doc_id=5927382)  
**Title Description Comments:**

Unauthorized Release Form 10/03/2003

**Action Type:** Response Requested - Other  
**Action Date:** 10/3/2003  
**Received Issue Date:** 10/3/2003  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608510936&doc\\_id=5927375](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&doc_id=5927375)  
**Title Description Comments:**

Geotracker Info 10/03/2003

**Action Type:** Response Requested - Reports  
**Action Date:** 8/26/2003  
**Received Issue Date:** 8/26/2003  
**Action:** Tank Removal Report / UST Sampling Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608510936&doc\\_id=5927381](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&doc_id=5927381)  
**Title Description Comments:**

Tank Removal Report 08/26/2003

**Action Type:** Response Requested - Other  
**Action Date:** 1/1/2003  
**Received Issue Date:** 1/1/2003  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608510936&doc\\_id=5927374](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&doc_id=5927374)  
**Title Description Comments:**

Correspondence 2003

**Action Type:** Response Requested - Workplans  
**Action Date:** 6/10/2002  
**Received Issue Date:** 6/10/2002  
**Action:** Other Workplan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608510936&doc\\_id=5927384](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608510936&doc_id=5927384)  
**Title Description Comments:**

Work Plan 06/10/2002 - 04/08/2007

**Action Type:** Leak Action  
**Action Date:** 6/11/2003

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		5/17/2003				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Discovery				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		5/17/2003				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Stopped				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		5/7/2003				
<b>Received Issue Date:</b>						
<b>Action:</b>		Excavation				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						

**LUST Sites from GeoTracker Search - Site Maps (as of Sep 15, 2021)**

<b>Title:</b>	GEO_MAP
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/5162000894/T0608510936.pdf">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/5162000894/T0608510936.pdf</a>
<b>Size :</b>	3,234 KB
<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Submitted:</b>	6/6/2008
<b>Title:</b>	GEO_MAP
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8657259881/T0608510936.pdf">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8657259881/T0608510936.pdf</a>
<b>Size :</b>	3,602 KB
<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Submitted:</b>	6/6/2008
<b>Title:</b>	GEO_MAP
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6758671641/T0608510936.pdf">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6758671641/T0608510936.pdf</a>
<b>Size :</b>	3,700 KB
<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Submitted:</b>	6/6/2008
<b>Title:</b>	GEO_MAP
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8563353598/T0608510936.pdf">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8563353598/T0608510936.pdf</a>
<b>Size :</b>	2,966 KB
<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Submitted:</b>	6/6/2008
<b>Title:</b>	GEO_MAP
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/2333830893/T0608510936.pdf">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/2333830893/T0608510936.pdf</a>
<b>Size :</b>	3,643 KB
<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Submitted:</b>	6/6/2008
<b>Title:</b>	GEO_MAP
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7990508854/T0608510936.pdf">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7990508854/T0608510936.pdf</a>
<b>Size :</b>	1,643 KB
<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Submitted:</b>	6/6/2008

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>			GEO_MAP			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7843447625/T0608510936.pdf			
<b>Size :</b>			4,691 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_MAP			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6007109701/T0608510936.pdf			
<b>Size :</b>			1,852 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_MAP			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/5725544810/T0608510936.pdf			
<b>Size :</b>			328 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_BORE (MW-1)			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9269610345/T0608510936.pdf			
<b>Size :</b>			165 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_MAP			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/1262623667/T0608510936.pdf			
<b>Size :</b>			2,688 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_BORE (MW-2)			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1614886224/T0608510936.pdf			
<b>Size :</b>			163 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_MAP			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6965666830/T0608510936.pdf			
<b>Size :</b>			752 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_BORE (MW-4)			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3228352427/T0608510936.pdf			
<b>Size :</b>			168 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			
<b>Title:</b>			GEO_BORE (MW-3)			
<b>Link:</b>			https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8426409661/T0608510936.pdf			
<b>Size :</b>			165 KB			
<b>Submitted By:</b>			SHERWOOD LOVEJOY, JR. (AUTH_RP)			
<b>Submitted:</b>			6/6/2008			

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	4/29/2010	<b>Submitted By:</b>	KRISTI CONG (REGULATOR)
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER	<b>Submitted:</b>	
<b>Title:</b>	UNKNOWN		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&enforcement_id=6049915		
<b>Document Type:</b>	Site Documents	<b>Size :</b>	1,028 KB
<b>Document Date:</b>	4/27/2010	<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	WELL DESTRUCTION REPORT	<b>Submitted:</b>	
<b>Title:</b>	WELL DESTRUCTION DWRS		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5131394743/T0608510936.PDF		

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	12/21/2009				<b>Submitted By:</b>	KRISTI CONG (REGULATOR)
<b>Type:</b>	STAFF LETTER				<b>Submitted:</b>	
<b>Title:</b>	DESTROY WELLS FOR CLOSURE					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6038648">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6038648</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	3,238 KB
<b>Document Date:</b>	9/22/2009				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	JUNE09-GWM REPORT					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7175970792/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7175970792/T0608510936.PDF</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	7/15/2009				<b>Submitted By:</b>	KRISTI CONG (REGULATOR)
<b>Type:</b>	STAFF LETTER				<b>Submitted:</b>	
<b>Title:</b>	NFA PENDING FILE REVIEW FOR CLOSURE - AWAITING 6/09 SAMPLING RESULTS.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6020877">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6020877</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	2,041 KB
<b>Document Date:</b>	6/30/2009				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GWMR-MAR09					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1753719508/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1753719508/T0608510936.PDF</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	2,156 KB
<b>Document Date:</b>	2/24/2009				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	080117-GWM-TR(DEC08).PDF					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5520382106/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5520382106/T0608510936.PDF</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	3,010 KB
<b>Document Date:</b>	8/27/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	080117-GWM-TR(JULY08).PDF					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3910248279/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3910248279/T0608510936.PDF</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	1,481 KB
<b>Document Date:</b>	6/14/2008				<b>Submitted By:</b>	CYNTHIA MANA-AY (REGULATOR)
<b>Type:</b>	LETTER				<b>Submitted:</b>	
<b>Title:</b>	CORRESPONDENCE					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/site_documents/6328709244/CORRES%5F2003%2D%2Epdf">https://geotracker.waterboards.ca.gov/site_documents/6328709244/CORRES%5F2003%2D%2Epdf</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	93 KB
<b>Document Date:</b>	6/7/2008				<b>Submitted By:</b>	CYNTHIA MANA-AY (REGULATOR)
<b>Type:</b>	LETTER				<b>Submitted:</b>	
<b>Title:</b>	DIRECTIVE					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/site_documents/9997985661/CORRES%5F2003%2D%2Epdf">https://geotracker.waterboards.ca.gov/site_documents/9997985661/CORRES%5F2003%2D%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	6,437 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	040122-GWM-TR					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4532562077/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4532562077/T0608510936.PDF</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	3,883 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	TANK REMOVAL REPORT / UST SAMPLING REPORT				<b>Submitted:</b>	
<b>Title:</b>	REMOVAL LETTER					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7296740472/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7296740472/T0608510936.PDF</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	11,229 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	TANK REMOVAL REPORT / UST SAMPLING REPORT				<b>Submitted:</b>	
<b>Title:</b>	040103-TR					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7261215686/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7261215686/T0608510936.PDF</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	4,037 KB

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	050103-GWM(APR05)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2111357748/T0608510936.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	1,812 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	030129-GWMW-WP					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3690890252/T0608510936.PDF					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	1,111 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	070108-GWM(OCT07)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1284728825/T0608510936.PDF					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	5,816 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	050103-GWM(OCT05)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5216231405/T0608510936.PDF					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	5,697 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	060102-GWM(FEB06)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5901188731/T0608510936.PDF					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	4,265 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	050103-GWM(JUL05)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9156217277/T0608510936.PDF					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	5,260 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	050103-GWM(JAN05)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2010283529/T0608510936.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	5,743 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	OTHER REPORT / DOCUMENT				<b>Submitted:</b>	
<b>Title:</b>	070108-SOIL VAPOR STUDY(NOV07)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8453587412/T0608510936.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	1,717 KB
<b>Document Date:</b>	3/4/2008				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	OTHER WORKPLAN				<b>Submitted:</b>	
<b>Title:</b>	070108-SV WP(APR07)					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9885792613/T0608510936.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	6,517 KB
<b>Document Date:</b>	9/17/2007				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	TECHNICALREPORT.PDF					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3974638998/T0608510936.PDF					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	779 KB
<b>Document Date:</b>	9/17/2007				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	030116.CHARACTERIZATION					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7949177622/T0608510936.PDF					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	5,697 KB

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Date:</b>	5/22/2007				<b>Submitted By:</b>	SHERWOOD LOVEJOY, JR. (AUTH_RP)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GWMR-FEB2006					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8224439859/T0608510936.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8224439859/T0608510936.PDF</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	6/22/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT				<b>Submitted:</b>	
<b>Title:</b>	PHONE LOG 06/22/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927377">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927377</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	6/3/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER REPORT				<b>Submitted:</b>	
<b>Title:</b>	MAP & METROSCAN INFORMATION 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6324297">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;enforcement_id=6324297</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	6/3/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT				<b>Submitted:</b>	
<b>Title:</b>	STATE INFORMATION 06/03/2005					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927379">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927379</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	2,270 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2009%2D02%2D19%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2009%2D02%2D19%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	4,967 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2006%2D03%2D28%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2006%2D03%2D28%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	3,122 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2008%2D08%2D12%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2008%2D08%2D12%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	1,334 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2007%2D12%2D13%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2007%2D12%2D13%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	2,453 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D01%2D12%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D01%2D12%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	2,411 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2009%2D09%2D15%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2009%2D09%2D15%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	4,769 KB
<b>Document Date:</b>	1/12/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D05%2D23%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D05%2D23%2Epdf</a>	
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	3,910 KB	
<b>Document Date:</b>	1/12/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D07%2D31%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D07%2D31%2Epdf</a>	
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	4,769 KB	
<b>Document Date:</b>	1/12/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D05%2D22%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D05%2D22%2Epdf</a>	
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	5,843 KB	
<b>Document Date:</b>	1/12/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2007%2D01%2D10%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2007%2D01%2D10%2Epdf</a>	
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	4,370 KB	
<b>Document Date:</b>	1/12/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D10%2D10%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2005%2D10%2D10%2Epdf</a>	
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	2,139 KB	
<b>Document Date:</b>	1/12/2005			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 01/12/2005 - 09/15/2009 -					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2009%2D06%2D29%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5095670938/GWM%5FR%5F2009%2D06%2D29%2Epdf</a>	
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	10/12/2004			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	SOIL & WATER INVESTIGATION REPORT 10/12/2004 - 02/14/2008					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927380">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927380</a>	
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/12/2003			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	SOIL DISPOSAL REPORT 12/12/2003					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927378">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927378</a>	
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/10/2003			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	WELL INSTALLATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	WELL CONSTRUCTION APPLICATION 12/10/2003					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927383">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927383</a>	
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	10/3/2003			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	GEOTRACKER INFO 10/03/2003					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927375">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927375</a>	
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	10/3/2003			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	UNAUTHORIZED RELEASE FORM			<b>Submitted:</b>		
<b>Title:</b>	UNAUTHORIZED RELEASE FORM 10/03/2003					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927382">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&amp;document_id=5927382</a>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	8/26/2003				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	TANK REMOVAL REPORT / UST SAMPLING REPORT				<b>Submitted:</b>	
<b>Title:</b>	TANK REMOVAL REPORT 08/26/2003					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&document_id=5927381					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	1/1/2003				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	CORRESPONDENCE				<b>Submitted:</b>	
<b>Title:</b>	CORRESPONDENCE 2003					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&document_id=5927374					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	6/10/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER WORKPLAN				<b>Submitted:</b>	
<b>Title:</b>	WORK PLAN 06/10/2002 - 04/08/2007					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608510936&document_id=5927384					

<a href="#">39</a>	1 of 2	<b>NNE</b>	<b>0.41 / 2,182.63</b>	<b>67.87 / -7</b>	<b>Mayfair Packing-Site #2 475 El Camino Real Santa Clara CA</b>	<b>LOP SANTA CLARA</b>
--------------------	--------	------------	------------------------	-------------------	--	----------------------------

**SCVWD ID:** 07S1W02J02f  
**Closure Date:** 9/12/1991  
**Link:** http://lustop.sccgov.org/files/07S1W02J02f/

<a href="#">39</a>	2 of 2	<b>NNE</b>	<b>0.41 / 2,182.63</b>	<b>67.87 / -7</b>	<b>MAYFAIR PACKING-SITE #2 475 EL CAMINO REAL SANTA CLARA CA 95050</b>	<b>LUST</b>
--------------------	--------	------------	------------------------	-------------------	--	-------------

**Global ID:** T0608502098  
**Status:** COMPLETED - CASE CLOSED  
**Status Date:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

<b>RB Case No:</b>		<b>Potential COC:</b>	Gasoline
<b>Local Case No:</b>		<b>How Discovered:</b>	
<b>Begin Date:</b>	5/3/1991	<b>Stop Method:</b>	
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP	<b>Stop Description:</b>	
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP	<b>Case Worker:</b>	UST
<b>CUF Case:</b>	NO	<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)

**How Discovered Description:**

**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)

**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)

**Disadvantaged Community:**

**Calenviroscreen Score:** 41-45%

**Site History:**

#### LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

**Action Type:** ENFORCEMENT  
**Date :** 9/12/1999  
**Action:** Closure/No Further Action Letter

**Action Type:** ENFORCEMENT  
**Date :** 8/6/1991

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action:</b>		Notice of Responsibility - #39702				
<b>Action Type:</b>		Other				
<b>Date :</b>		7/23/1991				
<b>Action:</b>		Leak Reported				
<b>Action Type:</b>		REMEDIATION				
<b>Date :</b>		5/3/1991				
<b>Action:</b>		Excavation				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		5/2/1989				
<b>Action:</b>		Other Report / Document				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		
<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	9/12/1991
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	5/3/1991
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	5/3/1991

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	MAYFAIR PACKING-SITE #2	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	475 EL CAMINO REAL
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502098">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502098</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 9/12/1991		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502098&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502098&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02J02f		

**Gndwater Monitoring Freque:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Designated Beneficial Use Desc:**  
**Site History:**  
 Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
 No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 9/12/1991  
**Status:** Open - Site Assessment  
**Date :** 5/3/1991  
**Status:** Open - Case Begin Date  
**Date :** 5/3/1991

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** EXCAVATION  
**Phase:**  
**Contaminant Mass Removed:**  
**Description:**  
**Begin Date:** 5/3/1991  
**End Date:** 5/3/1991

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/12/1999  
**Received Issue Date:** 9/12/1999  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502098&enforcement\\_id=6087424&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502098&enforcement_id=6087424&temptable=ENFORCEMENT)  
**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 8/6/1991  
**Received Issue Date:** 8/6/1991  
**Action:** Notice of Responsibility - #39702  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 5/2/1989  
**Received Issue Date:** 5/2/1989  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502098&doc\\_id=5713714](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502098&doc_id=5713714)  
**Title Description Comments:**

SCVWD ELECTRONIC FILES

**Action Type:** Leak Action  
**Action Date:** 7/23/1991  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Cleanup Action  
**Action Date:** 5/3/1991  
**Received Issue Date:**  
**Action:** Excavation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Doc Link:  
Title Description Comments:

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :**  
**Document Date:** 9/12/1999 **Submitted By:** (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER **Submitted:**  
**Title:** UNKNOWN  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502098&enforcement\\_id=6087424](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502098&enforcement_id=6087424)

**Document Type:** Site Documents **Size :**  
**Document Date:** 5/2/1989 **Submitted By:** (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** SCVWD ELECTRONIC FILES - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502098&document\\_id=5713714](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502098&document_id=5713714)

<a href="#">40</a>	1 of 4	ENE	0.42 / 2,195.83	65.69 / -9	T.W. Smith 1200 Campbell Ave San Jose CA	LOP SANTA CLARA
--------------------	--------	-----	--------------------	---------------	--	--------------------

**SCVWD ID:** 07S1W01N01f  
**Closure Date:** 12/29/1995  
**Link:** <http://lustop.sccgov.org/files/07S1W01N01f/>

<a href="#">40</a>	2 of 4	ENE	0.42 / 2,195.83	65.69 / -9	T.W. Smith 1200 Campbell Ave San Jose CA	LOP SANTA CLARA
--------------------	--------	-----	--------------------	---------------	--	--------------------

**SCVWD ID:** 07S1W01M02f  
**Closure Date:** 4/16/2001  
**Link:** <http://lustop.sccgov.org/files/07S1W01M02f/>

<a href="#">40</a>	3 of 4	ENE	0.42 / 2,195.83	65.69 / -9	T.W. SMITH 1200 CAMPBELL AVE SAN JOSE CA 95126	LUST
--------------------	--------	-----	--------------------	---------------	--	------

**Global ID:** T0608501403 **County:** SANTA CLARA  
**Status:** COMPLETED - CASE CLOSED **Latitude:**  
**Status Date:** **Longitude:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Potential COC:** Gasoline  
**Local Case No:** **How Discovered:**  
**Begin Date:** 11/29/1995 **Stop Method:**  
**Lead Agency:** SANTA CLARA COUNTY LOP **Stop Description:**  
**Local Agency:** SANTA CLARA COUNTY LOP **Case Worker:** UST  
**CUF Case:** NO **File Location:** All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Soil  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 41-45%  
**Site History:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

**Action Type:** ENFORCEMENT  
**Date :** 12/29/1995  
**Action:** Closure/No Further Action Letter

**Action Type:** RESPONSE  
**Date :** 12/29/1995  
**Action:** Other Report / Document

**Action Type:** Other  
**Date :** 11/29/1995  
**Action:** Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Local Agency Caseworker  
**Contact Name:** UST CASE WORKER  
**City:** SAN JOSE  
**Organization Name:** SANTA CLARA COUNTY LOP  
**Address:** 1555 Berger Drive, Suite 300  
**Email:**  
**Phone No:** 4089183400

**Contact Type:** Regional Board Caseworker  
**Contact Name:** Regional Water Board  
**City:** OAKLAND  
**Organization Name:** SAN FRANCISCO BAY RWQCB (REGION 2)  
**Address:** 1515 CLAY ST SUITE 1400  
**Email:**  
**Phone No:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 12/29/1995

**Status:** Open - Case Begin Date  
**Status Date:** 11/29/1995

**LUST Sites from GeoTracker Search - Regulatory Profile**

**Site Facility Name:** T.W. SMITH  
**Site Facility Type:** LUST CLEANUP SITE  
**Cleanup Status:** COMPLETED - CASE CLOSED  
**Project Status:**  
**WDR Place Type:**  
**WDR File:**  
**WDR Order:**  
**CUF Priority Assig:**  
**CUF Amount Paid:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T0608501403](https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608501403)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 12/29/1995  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608501403&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608501403&tabname=regulatoryhistory)  
**Potential Media of Concern:** SOIL  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W01N01f

**Gndwater Monitoring Freque:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Site History:**  
 No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 12/29/1995  
**Status:** Open - Case Begin Date  
**Date :** 11/29/1995

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/29/1995  
**Received Issue Date:** 12/29/1995  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501403&enforcement\\_id=6232319&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501403&enforcement_id=6232319&temptable=ENFORCEMENT)  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 12/29/1995  
**Received Issue Date:** 12/29/1995  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501403&doc\\_id=5825223](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501403&doc_id=5825223)  
**Title Description Comments:**  
 SCVWD Electronic Files

**Action Type:** Leak Action  
**Action Date:** 11/29/1995  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	12/29/1995	<b>Submitted By:</b>	COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT	<b>Submitted:</b>	
<b>Title:</b>	SCVWD ELECTRONIC FILES		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501403&amp;document_id=5825223">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501403&amp;document_id=5825223</a>		
<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	12/29/1995	<b>Submitted By:</b>	COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER	<b>Submitted:</b>	
<b>Title:</b>	UNKNOWN		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501403&amp;enforcement_id=6232319">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501403&amp;enforcement_id=6232319</a>		

<a href="#">40</a>	4 of 4	ENE	0.42 / 2,195.83	65.69 / -9	T.W. SMITH 1200 CAMPBELL AVE SAN JOSE CA 95126	LUST
--------------------	--------	-----	-----------------	------------	--	------

**Global ID:** T0608502441 **County:** SANTA CLARA  
**Status:** COMPLETED - CASE CLOSED **Latitude:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Status Date:** \_\_\_\_\_ **Longitude:** \_\_\_\_\_  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>		<b>Potential COC:</b>	Gasoline
<b>Local Case No:</b>		<b>How Discovered:</b>	
<b>Begin Date:</b>	9/20/1999	<b>Stop Method:</b>	
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP	<b>Stop Description:</b>	
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP	<b>Case Worker:</b>	UST
<b>CUF Case:</b>	NO	<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)

**How Discovered Description:**

**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)

**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)

**Disadvantaged Community:**

**Calenviroscreen Score:** 41-45%

**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	RESPONSE
<b>Date :</b>	10/31/2005
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	7/30/2003
<b>Action:</b>	NPDES / WDR Reports
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	11/27/2002
<b>Action:</b>	Well Destruction Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/7/2000
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	7/27/2000
<b>Action:</b>	Other Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	7/12/2000
<b>Action:</b>	Staff Letter - #23507
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	7/12/2000
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/15/2000
<b>Action:</b>	Soil and Water Investigation Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	1/10/2000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action:** Staff Letter - #23505  
**Action Type:** RESPONSE  
**Date :** 1/1/2000  
**Action:** Correspondence  
**Action Type:** RESPONSE  
**Date :** 10/22/1999  
**Action:** Tank Removal Report / UST Sampling Report  
**Action Type:** RESPONSE  
**Date :** 9/20/1999  
**Action:** Unauthorized Release Form  
**Action Type:** Other  
**Date :** 9/20/1999  
**Action:** Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 4/16/2001  
**Status:** Open - Site Assessment  
**Status Date:** 10/22/1999  
**Status:** Open - Site Assessment  
**Status Date:** 9/20/1999  
**Status:** Open - Case Begin Date  
**Status Date:** 9/20/1999

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	T.W. SMITH	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	1200 CAMPBELL AVE
<b>WDR Place Type:</b>		<b>City:</b>	SAN JOSE
<b>WDR File:</b>		<b>Zip:</b>	95126
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502441">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502441</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 4/16/2001		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502441&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502441&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Post Closure Site Management:**

**Future Land Use:**

**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W01M02f

**Gndwater Monitoring Freque:**

**Designated Beneficial Use**

Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply

**Desc:**

**Site History:**

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 4/16/2001

**Status:** Open - Site Assessment  
**Date :** 10/22/1999

**Status:** Open - Case Begin Date  
**Date :** 9/20/1999

**Status:** Open - Site Assessment  
**Date :** 9/20/1999

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 10/31/2005  
**Received Issue Date:** 10/31/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927301](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927301)  
**Title Description Comments:**

Miscellaneous Report 10/31/2005

**Action Type:** Reports  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502441&enforcement\\_id=6324271&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&enforcement_id=6324271&temptable=ENFORCEMENT)

**Title Description Comments:**

Map & Metroscan Information 06/03/2005

**Action Type:** Response Requested - Other  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927305](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927305)  
**Title Description Comments:**

State Information 06/03/2005

**Action Type:** Response Requested - Other  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927304](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927304)  
**Title Description Comments:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

Phone Log 06/03/2005

**Action Type:** Response Requested - Reports  
**Action Date:** 7/30/2003  
**Received Issue Date:** 7/30/2003  
**Action:** NPDES / WDR Reports  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927303](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927303)  
**Title Description Comments:**

NPDES Miscellaneous Reports 07/30/2003

**Action Type:** Response Requested - Reports  
**Action Date:** 11/27/2002  
**Received Issue Date:** 11/27/2002  
**Action:** Well Destruction Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927309](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927309)  
**Title Description Comments:**

Well Abandonment/Destruction 11/27/2002

**Action Type:** Response Requested - Reports  
**Action Date:** 8/7/2000  
**Received Issue Date:** 8/7/2000  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Response Requested - Workplans  
**Action Date:** 7/27/2000  
**Received Issue Date:** 7/27/2000  
**Action:** Other Workplan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927310](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927310)  
**Title Description Comments:**

Work Plan 07/27/2000

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/12/2000  
**Received Issue Date:** 7/12/2000  
**Action:** Staff Letter - #23507  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 7/12/2000  
**Received Issue Date:** 7/12/2000  
**Action:** Soil and Water Investigation Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927306](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927306)  
**Title Description Comments:**

Soil & Water Investigation Report 07/12/2000

**Action Type:** Response Requested - Workplans  
**Action Date:** 3/15/2000  
**Received Issue Date:** 3/15/2000  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Other Regulatory Actions  
**Action Date:** 1/10/2000  
**Received Issue Date:** 1/10/2000  
**Action:** Staff Letter - #23505  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 1/1/2000  
**Received Issue Date:** 1/1/2000  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927300](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927300)  
**Title Description Comments:**

Correspondence 2000

**Action Type:** Response Requested - Reports  
**Action Date:** 10/22/1999  
**Received Issue Date:** 10/22/1999  
**Action:** Tank Removal Report / UST Sampling Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927307](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927307)  
**Title Description Comments:**

Tank Removal Report 10/22/1999

**Action Type:** Response Requested - Other  
**Action Date:** 9/20/1999  
**Received Issue Date:** 9/20/1999  
**Action:** Unauthorized Release Form  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502441&doc\\_id=5927308](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502441&doc_id=5927308)  
**Title Description Comments:**

Unauthorized Release Form 09/20/1999

**Action Type:** Leak Action  
**Action Date:** 9/20/1999  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :** 486 KB  
**Document Date:** 10/5/2007 **Submitted By:** CYNTHIA MANA-AY (REGULATOR)  
**Type:** LETTER **Submitted:**  
**Title:** CLOSURE LETTER & SITE CLOSURE SUMMARY  
**Title Link:** [https://geotracker.waterboards.ca.gov/site\\_documents/7237827897/CLOS%5FL%2D2001%2D04%2D16%2Epdf](https://geotracker.waterboards.ca.gov/site_documents/7237827897/CLOS%5FL%2D2001%2D04%2D16%2Epdf)

**Document Type:** Site Documents **Size :**  
**Document Date:** 10/31/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** MISCELLANEOUS REPORT 10/31/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502441&document\\_id=5927301](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927301)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** PHONE LOG 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502441&document\\_id=5927304](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927304)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Type:</b>	OTHER REPORT / DOCUMENT				<b>Submitted:</b>	
<b>Title:</b>	STATE INFORMATION 06/03/2005					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927305					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	6/3/2005				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER REPORT				<b>Submitted:</b>	
<b>Title:</b>	MAP & METROSCAN INFORMATION 06/03/2005					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&enforcement_id=6324271					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	7/30/2003				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	NPDES / WDR REPORTS				<b>Submitted:</b>	
<b>Title:</b>	NPDES MISCELLANEOUS REPORTS 07/30/2003					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927303					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	11/27/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	WELL DESTRUCTION REPORT				<b>Submitted:</b>	
<b>Title:</b>	WELL ABANDONMENT/DESTRUCTION 11/27/2002					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927309					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	7/27/2000				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	OTHER WORKPLAN				<b>Submitted:</b>	
<b>Title:</b>	WORK PLAN 07/27/2000					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927310					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	7/12/2000				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT				<b>Submitted:</b>	
<b>Title:</b>	SOIL & WATER INVESTIGATION REPORT 07/12/2000					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927306					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	1/1/2000				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	CORRESPONDENCE				<b>Submitted:</b>	
<b>Title:</b>	CORRESPONDENCE 2000					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927300					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	10/22/1999				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	TANK REMOVAL REPORT / UST SAMPLING REPORT				<b>Submitted:</b>	
<b>Title:</b>	TANK REMOVAL REPORT 10/22/1999					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927307					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	9/20/1999				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	UNAUTHORIZED RELEASE FORM				<b>Submitted:</b>	
<b>Title:</b>	UNAUTHORIZED RELEASE FORM 09/20/1999					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502441&document_id=5927308					

[41](#)

1 of 3

**ENE**

0.43 /  
2,276.24

66.37 /  
-9

**CUSTOM FOOD MACHINERY**  
**1180 - 1184 CAMPBELL AVENUE**  
**SAN JOSE CA 95126**

**VCP**

**Estor/EPA ID:** 43200021  
**Site Code:** 201590  
**Nat Priority List:** NO  
**Acres:** 7.8 ACRES  
**Special Program:** VOLUNTARY CLEANUP PROGRAM  
**Funding:** SITE PROPONENT  
**Assembly District:** 28  
**Senate District:** 10  
**School District:**  
**APN:** 230-14-07

**Permit Renewal Lead:**  
**Project Manager:** CLAUDE JEMISON  
**Supervisor:** CHERYL PROWELL  
**Public Partici Splst:**  
**Census Tract:** 6085505203  
**County:** SANTA CLARA  
**Latitude:** 37.349463  
**Longitude:** -121.93035

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Cleanup Status:** CERTIFIED / OPERATION & MAINTENANCE AS OF 3/26/2009  
**Cleanup Oversight Agencies:** DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY US EPA  
**Site Type:** VOLUNTARY CLEANUP  
**Office:** CLEANUP BERKELEY  
**Past Use that Caused Contam:** MANUFACTURING - INDUSTRIAL MACHINERY, TRANSFORMER REPAIR  
**Potential Media Affected:** OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL  
**Site History:**

Structural drawings indicate that the buildings located on the Site were constructed around 1953 to 1954. The facility located on 1180 Campbell was operated by the Stokely Van Camp for the production and storage of frozen food until the mid-1980's. In 1982, the site was purchased by Custom Food Machinery (CFM). CFM's operation involved refurbishing and rebuilding food processing machinery and equipment for resale. CFM operated a machine shop and parts storage area in Building 3 and where hazardous materials were stored. CFM operated the facility until December 1991. The facility appeared to be vacated in 1993 when it was leased to MMAD. MMAD Partnership purchased the Site in 1995. Tenants in the buildings include: HA Distributing Corp, Odyssey Enterprises Inc; Primo Packagaing Co. and Paper Materials Co. at 1180 Campbell from 1996 to 2000; Dale's Trucking Company at 1184 Campbell from 1996 to present; AIT Freight Company at 1184 Campbell in 2000. Presently, building 1 (1180 Campbell) and Building 2 (1182 Campbell) are a single structure currently occupied by CPS'Odyssey Complete Packaging Solutions (Odyssey). The buildings are currently used for packaging, crating and warehousing. Building 3 (1184 Campbell), the smallest of the three buildings, is located at the rear of the property. The current owner operated the facility as a trucking business until July 1999. It is currently leased by On Time Transport and Ryan's Express Freight. The owner still uses some portions of the property for snowmobile and jet-ski repair, restoration of classic automobiles, and material storage. The property is surrounded by mixed uses including commercial and residential.

**Potential Contamin of Concern:**

1,2,4-TRICHLOROBENZENE POLYCHLORINATED BIPHENYLS (PCBS) TETRACHLOROETHYLENE (PCE)

**Status:** CERTIFIED / OPERATION & MAINTENANCE - LAND USE RESTRICTIONS  
**Program Type:** VOLUNTARY CLEANUP  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=43200021](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43200021)

**Land Use Restrictions**

**Site Management Requirements:** NO EXCAVATION OF CONTAMINATED SOILS WITHOUT AGENCY REVIEW AND APPROVAL  
 NOTIFY AFTER CHANGE OF PROPERTY OWNER  
 NOTIFY PRIOR TO DEVELOPMENT  
 NOTIFY PRIOR TO SUBSURFACE WORK  
**Title:** Revised Deed Restriction  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/deliverable\\_documents/3214771866/Revised%20deed%20restriction%20Epdf](https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/3214771866/Revised%20deed%20restriction%20Epdf)  
**Date Recorded:** 6/1/2007

**Site Management Requirements:** LAND USE COVENANT  
 NOTIFY AFTER CHANGE OF PROPERTY OWNER  
 NOTIFY PRIOR TO CHANGE IN LAND USE  
**Title:** Deed Restriction  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?cmd=radocuments&global\\_id=43200021&enforcement\\_id=6007951](https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&global_id=43200021&enforcement_id=6007951)  
**Date Recorded:** 10/18/2006

**Currently Scheduled Activities**

**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** 5 Year Review Reports  
**Due Date:** 3/20/2022  
**Revised Date:**

**Completed Activities**

**Title:** Phase I Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&doc\\_id=6014777](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6014777)  
**Area Name:**  
**Area Link:**  
**Sub Area:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Phase 1				
<b>Date Completed:</b>		2/28/2007				
<b>Comments:</b>		DTSC approved Phase 1 and 2 Environmental Assessment Report.				
<b>Title:</b>		Annual Oversight Cost Estimate letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60413018">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60413018</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/14/2016				
<b>Comments:</b>						
<b>Title:</b>		Annual Oversight Cost Estimate Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60337135">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60337135</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		10/18/2013				
<b>Comments:</b>		DTSC letter with oversight cost estimate for fiscal year 2013/2014.				
<b>Title:</b>		Deed Restriction Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6019117">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6019117</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Other Report				
<b>Date Completed:</b>		5/6/2008				
<b>Comments:</b>		The letter indicates that the site is in accordance with the requirements of the deed restriction.				
<b>Title:</b>		CLRRA Agreement				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010601">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010601</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		California Land Reuse and Revitalization Agreement				
<b>Date Completed:</b>		9/20/2007				
<b>Comments:</b>		A CLRRA agreement was entered into between DTSC and Robson Homes. The Agreement calls for review of documents according to the schedule described in the Agreement.				
<b>Title:</b>		Financial Assurance Mechanism				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60290147">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60290147</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Financial Assurance Documentation				
<b>Date Completed:</b>		6/29/2012				
<b>Comments:</b>		Revised financial assurance mechanism approved and in place.				
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254222">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254222</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		3/17/2014				
<b>Comments:</b>						
<b>Title:</b>		Amendment to Operation and Maintenance Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60287513">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60287513</a>				
<b>Area Name:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operations and Maintenance Plan Amendment	
<b>Date Completed:</b>					2/15/2012	
<b>Comments:</b>					Operations and Maintenance Plan amended to reduce groundwater sampling to an annual frequency.	
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012663">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012663</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/12/2011	
<b>Comments:</b>					Monitoring report approved. Request to cease monitoring not approved because remedial goals have not been met.	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254221">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254221</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					2/28/2013	
<b>Comments:</b>						
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60397306">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60397306</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/20/2015	
<b>Comments:</b>						
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012659">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012659</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/7/2009	
<b>Comments:</b>					Contaminants in groundwater are within historic ranges. Increase in Tetrachloroethylene in MW3A needs to be reviewed during next reporting period.	
<b>Title:</b>					Annual Oversight Cost Estimate	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448811">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448811</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/6/2020	
<b>Comments:</b>					Emailed annual cost estimate letter on 10/6/2020. -EC	
<b>Title:</b>					Annual cost estimate 2010	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60256126">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60256126</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/5/2010	
<b>Comments:</b>					.	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336206">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336206</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	
<b>Date Completed:</b>					3/15/2017	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336205">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336205</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	
<b>Date Completed:</b>					3/14/2016	
<b>Comments:</b>						
<b>Title:</b>					Financial Assurance	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60393491">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60393491</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Financial Assurance Documentation	
<b>Date Completed:</b>					6/25/2015	
<b>Comments:</b>						
<b>Title:</b>					Operation and Maintenance Plan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012653">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012653</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Plan	
<b>Date Completed:</b>					11/27/2006	
<b>Comments:</b>					Report approved.	
<b>Title:</b>					Operation and Maintenance Agreement	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6009661">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6009661</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation & Maintenance Order/Agreement	
<b>Date Completed:</b>					2/19/2009	
<b>Comments:</b>					The Agreement is entered into between Robson Homes, LLC and DTSC. The Agreement includes implementing the O&M Plan (groundwater monitoring) and submittal of groundwater monitoring reports.	
<b>Title:</b>					Quarterly GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012654">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012654</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/6/2007	
<b>Comments:</b>					Report documents that biodegradation is occurring on site.	
<b>Title:</b>					Cost Estimate Letter 2014-2015	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60376196">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60376196</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/15/2014	

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Comments:</b>					DTSC letter with oversight cost estimate for fiscal year 2014/2015.	
<b>Title:</b>					Removal Action Completion Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016993">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016993</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Removal Action Completion Report	
<b>Date Completed:</b>					8/11/2006	
<b>Comments:</b>					Completion report approved. During implementation of the final remedy, additional PCB contaminated soil was encountered at another area on the site. Excavation of this PCB impacted soil occurred to the top of the groundwater table (approximately 9 feet below ground surface). Confirmation sampling verified that the PCB cleanup goal in this area was achieved in the upper 10 feet, but PCBs remain below 10 feet. A deed restriction will be required. The groundwater cleanup goal established in the RAW has not been met. Ongoing groundwater monitoring will be required until cleanup goals have been achieved.	
<b>Title:</b>					Revised Deed Restriction	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010643">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010643</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction	
<b>Date Completed:</b>					6/1/2007	
<b>Comments:</b>					The deed restriction was revised to include notification to EPA and include a a compliance letter snd replaced the original deed restriction..	
<b>Title:</b>					Groundwater Monitoring Well Destruction Implementation	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					2/28/2015	
<b>Comments:</b>					The destruction of monitoring wells on the Site was completed in accordance with the Work Plan for Well Decommissioning approved by DTSC on 11/5/2014.	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254220">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254220</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					3/16/2012	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254219">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254219</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					6/1/2011	
<b>Comments:</b>					The Encanto Homeowner's Association submitted a letter to DTSC to verify compliance with the land use restrictions that are included in a deed restriction that is in place for the site. DTSC had no comments and approved the compliance letter.	
<b>Title:</b>					Annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286813">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286813</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/25/2012	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Comments:</b>						
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012660">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012660</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					8/12/2009	
<b>Comments:</b>					Groundwater concentrations are within historic ranges.	
<b>Title:</b>					Quarterly Groundwater Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014104">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014104</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					1/23/2008	
<b>Comments:</b>					Data is consistent with previous findings.	
<b>Title:</b>					Annual Oversight Cost Estimate	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448809">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448809</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/13/2018	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction 2009 Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6027171">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6027171</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					6/29/2010	
<b>Comments:</b>					compliance letter acknowledgement sent	
<b>Title:</b>					Quarterly GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012656">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012656</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					7/23/2007	
<b>Comments:</b>					VOC concentrations are generally decreasing.	
<b>Title:</b>					Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60460564">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60460564</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	
<b>Date Completed:</b>					5/20/2019	
<b>Comments:</b>						
<b>Title:</b>					Community Profile	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014202">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014202</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Community Profile	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date Completed:</b>		10/10/2006				
<b>Comments:</b>		Community Profile completed in October 10, 2006				
<b>Title:</b>		Semi-annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012658">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012658</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		9/26/2008				
<b>Comments:</b>		The data is within the historical trend.				
<b>Title:</b>		Public Notice for Draft RAW				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011288">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011288</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Public Notice				
<b>Date Completed:</b>		6/23/2005				
<b>Comments:</b>		Public Notice for Draft RAW				
<b>Title:</b>		Deed Restriction				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6007951">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6007951</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Land Use Restriction				
<b>Date Completed:</b>		10/18/2006				
<b>Comments:</b>						
<b>Title:</b>		First 5-Year Review and Annual Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6023015">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6023015</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		5 Year Review Reports				
<b>Date Completed:</b>		6/27/2014				
<b>Comments:</b>		Five-Year Review Report was performed to evaluate the protectiveness of the remedy. The Report determined that the site remedy is still protective of human health and the environment. It also recommended ceasing the groundwater monitoring of the Site, which was approved by DTSC.				
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012657">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012657</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		12/14/2007				
<b>Comments:</b>		VOC concentrations generally decreasing but still above Remedial Goals..				
<b>Title:</b>		Annual Oversight Cost Estimate Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60433034">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60433034</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/15/2017				
<b>Comments:</b>						
<b>Title:</b>		Groundwater Monitoring Well Destruction Workplan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60376197">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60376197</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Technical Workplan				
<b>Date Completed:</b>		11/5/2014				
<b>Comments:</b>						
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336204">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336204</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		3/20/2015				
<b>Comments:</b>						
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014105">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014105</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/25/2008				
<b>Comments:</b>		DTSC letter requires that semi-annual sampling for two wells should be continued.				
<b>Title:</b>		Inject ORC & monitor for 6 months				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Fieldwork				
<b>Date Completed:</b>		5/11/2006				
<b>Comments:</b>		The final groundwater sampling was conducted on May 11, 2006 to verify Hydrogen Release (HRC's) effectiveness. Previous sampling results indicate HRC is reducing concentrations on chemicals of concern including, perchloroethylene and trichloroethylene. However, the trichlorobenzenes concentrations have stayed the same. The breakdown of these contaminants can also take longer.				
<b>Title:</b>		Annual Cost Estimate 2011-2012				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60287490">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60287490</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		12/14/2011				
<b>Comments:</b>						
<b>Title:</b>		Semi-annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012661">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012661</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		2/16/2010				
<b>Comments:</b>						
<b>Title:</b>		Certification				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016994">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016994</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Certification				
<b>Date Completed:</b>		3/26/2009				
<b>Comments:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012662">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012662</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					7/12/2010	
<b>Comments:</b>					approval letter sent with memo from GSU. Recommendation for change in sampling methodology.	
<b>Title:</b>					Annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286814">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286814</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/30/2013	
<b>Comments:</b>					The report presents the result of annual groundwater monitoring performed in December 2012. Groundwater levels were measured in six monitoring wells and monitoring well MW-4A was sampled. 1,2,4-Trichlorobenzene was detected in MW-4A at a concentration of 110 micrograms per liter and the concentration is showing a decreasing trend with time.	
<b>Title:</b>					Removal Action Workplan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016992">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016992</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Removal Action Workplan	
<b>Date Completed:</b>					7/29/2005	
<b>Comments:</b>					The RAW requires a deed restriction preventing digging in the area where PCBs are at depth and treatment of contaminated groundwater with HRC and Bio-Innoculum. No comments were received during the public comment period.	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336207">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336207</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	
<b>Date Completed:</b>					3/7/2018	
<b>Comments:</b>						
<b>Title:</b>					Fact Sheet for Draft RAW	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011287">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011287</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fact Sheets	
<b>Date Completed:</b>					6/23/2005	
<b>Comments:</b>					Fact Sheet for Draft RAW	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/12/2021	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction 2008 Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6022388">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6022388</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Sub Area:**

**Sub Area Link:**

**Document Type:** Other Report

**Date Completed:** 3/5/2009

**Comments:** The report indicates no soil work conducted in the restricted areas.

**Title:** VCA

**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&enforcement\\_id=5016991](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&enforcement_id=5016991)

**Area Name:**

**Area Link:**

**Sub Area:**

**Sub Area Link:**

**Document Type:** Standard Voluntary Agreement

**Date Completed:** 4/22/2005

**Comments:** VCA signed with the developer, Robson Homes.

**Title:** Groundwater Monitoring Well Destruction Report

**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&doc\\_id=60381104](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=60381104)

**Area Name:**

**Area Link:**

**Sub Area:**

**Sub Area Link:**

**Document Type:** Technical Report

**Date Completed:** 4/21/2015

**Comments:** The Well Decommissioning Completion Report documents the destruction of the six groundwater monitoring wells on the site. All site groundwater monitoring wells were destroyed in accordance with the Santa Clara Valley Water District's standards and requirements and the workplan approved by DTSC on November 5, 2014.

<a href="#">41</a>	2 of 3	ENE	0.43 / 2,276.24	66.37 / -9	<b>CUSTOM FOOD MACHINERY 1180 - 1184 CAMPBELL AVENUE SAN JOSE CA 95126</b>	LUR
--------------------	--------	-----	--------------------	---------------	--	-----

**Estor/EPA ID:** 43200021

**Site Code:** 201590

**Nat Priority List:** NO

**Acres:** 7.8 ACRES

**Special Program:** VOLUNTARY CLEANUP PROGRAM

**Funding:** SITE PROPONENT

**Assembly District:** 28

**Senate District:** 10

**School District:**

**APN:** 230-14-07

**Cleanup Status:** CERTIFIED / OPERATION & MAINTENANCE AS OF 3/26/2009

**Cleanup Oversight Agencies:** DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY US EPA

**Site Type:** VOLUNTARY CLEANUP

**Office:** CLEANUP BERKELEY

**Past Use that Caused Contam:** MANUFACTURING - INDUSTRIAL MACHINERY, TRANSFORMER REPAIR

**Potential Media Affected:** OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL

**Potential Contamin of Concern:**

1,2,4-TRICHLOROBENZENE POLYCHLORINATED BIPHENYLS (PCBS) TETRACHLOROETHYLENE (PCE)

**Site History:**

Structural drawings indicate that the buildings located on the Site were constructed around 1953 to 1954. The facility located on 1180 Campbell was operated by the Stokely Van Camp for the production and storage of frozen food until the mid-1980's. In 1982, the site was purchased by Custom Food Machinery (CFM). CFM's operation involved refurbishing and rebuilding food processing machinery and equipment for resale. CFM operated a machine shop and parts storage area in Building 3 and where hazardous materials were stored. CFM operated the facility until December 1991. The facility appeared to be vacated in 1993 when it was leased to MMAD. MMAD Partnership purchased the Site in 1995. Tenants in the buildings include: HA Distributing Corp, Odyssey Enterprises Inc; Primo Packaging Co. and Paper Materials Co. at 1180 Campbell from 1996 to 2000; Dale's Trucking Company at 1184 Campbell from 1996 to present; AIT Freight Company at 1184 Campbell in 2000. Presently, building 1 (1180 Campbell) and Building 2 (1182 Campbell) are a single structure currently occupied by CPS'Odyssey Complete Packaging Solutions (Odyssey). The buildings are currently used for packaging, crating and warehousing. Building 3 (1184 Campbell), the smallest of the three buildings, is located at the rear of the property. The current owner operated the facility as a trucking business until July 1999. It is currently leased by On Time Transport and Ryan's Express Freight. The owner still uses some portions of the property for snowmobile and jet-ski repair, restoration of classic automobiles, and material storage. The property is surrounded by mixed uses including commercial and residential.

**Status:** CERTIFIED / OPERATION & MAINTENANCE - LAND USE RESTRICTIONS

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Program Type:</b>		VOLUNTARY CLEANUP				
<b>CalEnviroScreen Score:</b>		56-60%				
<b>Summary Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43200021">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43200021</a>				
<b><u>Land Use Restrictions</u></b>						
<b>Site Management Requirements:</b>		LAND USE COVENANT NOTIFY AFTER CHANGE OF PROPERTY OWNER NOTIFY PRIOR TO CHANGE IN LAND USE				
<b>Title:</b>		Deed Restriction				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&amp;global_id=43200021&amp;enforcement_id=6007951">https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&amp;global_id=43200021&amp;enforcement_id=6007951</a>				
<b>Date Recorded:</b>		10/18/2006				
<b>Site Management Requirements:</b>		NO EXCAVATION OF CONTAMINATED SOILS WITHOUT AGENCY REVIEW AND APPROVAL NOTIFY AFTER CHANGE OF PROPERTY OWNER NOTIFY PRIOR TO DEVELOPMENT NOTIFY PRIOR TO SUBSURFACE WORK				
<b>Title:</b>		Revised Deed Restriction				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/3214771866/RevisedI%20deed%20restriction%20Epdf">https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/3214771866/RevisedI%20deed%20restriction%20Epdf</a>				
<b>Date Recorded:</b>		6/1/2007				
<b><u>Currently Scheduled Activities</u></b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		5 Year Review Reports				
<b>Due Date:</b>		3/20/2022				
<b>Revised Date:</b>						
<b><u>Completed Activities</u></b>						
<b>Title:</b>		Certification				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016994">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016994</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Certification				
<b>Date Completed:</b>		3/26/2009				
<b>Comments:</b>						
<b>Title:</b>		Quarterly Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014104">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014104</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		1/23/2008				
<b>Comments:</b>		Data is consistent with previous findings.				
<b>Title:</b>		Operation and Maintenance Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012653">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012653</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Plan				
<b>Date Completed:</b>		11/27/2006				
<b>Comments:</b>		Report approved.				
<b>Title:</b>		Semi-annual GWM Report				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6012660	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					8/12/2009	
<b>Comments:</b>					Groundwater concentrations are within historic ranges.	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=60336204	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					3/20/2015	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=60336205	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	
<b>Date Completed:</b>					3/14/2016	
<b>Comments:</b>						
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6012659	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/7/2009	
<b>Comments:</b>					Contaminants in groundwater are within historic ranges. Increase in Tetrachloroethylene in MW3A needs to be reviewed during next reporting period.	
<b>Title:</b>					Quarterly GWM Report	
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6012657	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					12/14/2007	
<b>Comments:</b>					VOC concentrations generally decreasing but still above Remedial Goals..	
<b>Title:</b>					First 5-Year Review and Annual Groundwater Monitoring Report	
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6023015	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					5 Year Review Reports	
<b>Date Completed:</b>					6/27/2014	
<b>Comments:</b>					Five-Year Review Report was performed to evaluate the protectiveness of the remedy. The Report determined that the site remedy is still protective of human health and the environment. It also recommended ceasing the groundwater monitoring of the Site, which was approved by DTSC.	
<b>Title:</b>					Annual Cost Estimate 2011-2012	
<b>Title Link:</b>					https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&enforcement_id=60287490	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date Completed:</b>		12/14/2011				
<b>Comments:</b>						
<b>Title:</b>		Annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286814">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286814</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		4/30/2013				
<b>Comments:</b>		The report presents the result of annual groundwater monitoring performed in December 2012. Groundwater levels were measured in six monitoring wells and monitoring well MW-4A was sampled. 1,2,4-Trichlorobenzene was detected in MW-4A at a concentration of 110 micrograms per liter and the concentration is showing a decreasing trend with time.				
<b>Title:</b>		Annual Oversight Cost Estimate				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448811">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448811</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		10/6/2020				
<b>Comments:</b>		Emailed annual cost estimate letter on 10/6/2020. -EC				
<b>Title:</b>		Deed Restriction 2008 Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6022388">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6022388</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Other Report				
<b>Date Completed:</b>		3/5/2009				
<b>Comments:</b>		The report indicates no soil work conducted in the restricted areas.				
<b>Title:</b>		Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60460564">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60460564</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Land Use Restriction Monitoring Report				
<b>Date Completed:</b>		5/20/2019				
<b>Comments:</b>						
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012654">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012654</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		4/6/2007				
<b>Comments:</b>		Report documents that biodegradation is occurring on site.				
<b>Title:</b>		Deed Restriction 2009 Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6027171">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6027171</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		6/29/2010				
<b>Comments:</b>		compliance letter acknowledgement sent				
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336206">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336206</a>				
<b>Area Name:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	
<b>Date Completed:</b>					3/15/2017	
<b>Comments:</b>						
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60397306">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60397306</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/20/2015	
<b>Comments:</b>						
<b>Title:</b>					Inject ORC & monitor for 6 months	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					5/11/2006	
<b>Comments:</b>					The final groundwater sampling was conducted on May 11, 2006 to verify Hydrogen Release (HRC's) effectiveness. Previous sampling results indicate HRC is reducing concentrations on chemicals of concern including, perchloroethylene and trichloroethylene. However, the trichlorobenzenes concentrations have stayed the same. The breakdown of these contaminants can also take longer.	
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012661">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012661</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					2/16/2010	
<b>Comments:</b>						
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60337135">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60337135</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/18/2013	
<b>Comments:</b>					DTSC letter with oversight cost estimate for fiscal year 2013/2014.	
<b>Title:</b>					Community Profile	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014202">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014202</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Community Profile	
<b>Date Completed:</b>					10/10/2006	
<b>Comments:</b>					Community Profile completed in October 10, 2006	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254221">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254221</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					2/28/2013	
<b>Comments:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Amendment to Operation and Maintenance Plan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60287513">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60287513</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operations and Maintenance Plan Amendment	
<b>Date Completed:</b>					2/15/2012	
<b>Comments:</b>					Operations and Maintenance Plan amended to reduce groundwater sampling to an annual frequency.	
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012658">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012658</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					9/26/2008	
<b>Comments:</b>					The data is within the historical trend.	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254222">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254222</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					3/17/2014	
<b>Comments:</b>						
<b>Title:</b>					CLRRA Agreement	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010601">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010601</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					California Land Reuse and Revitalization Agreement	
<b>Date Completed:</b>					9/20/2007	
<b>Comments:</b>					A CLRRA agreement was entered into between DTSC and Robson Homes. The Agreement calls for review of documents according to the schedule described in the Agreement.	
<b>Title:</b>					Deed Restriction Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6019117">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6019117</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Other Report	
<b>Date Completed:</b>					5/6/2008	
<b>Comments:</b>					The letter indicates that the site is in accordance with the requirements of the deed restriction.	
<b>Title:</b>					Groundwater Monitoring Well Destruction Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60381104">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60381104</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Technical Report	
<b>Date Completed:</b>					4/21/2015	
<b>Comments:</b>					The Well Decommissioning Completion Report documents the destruction of the six groundwater monitoring wells on the site. All site groundwater monitoring wells were destroyed in accordance with the Santa Clara Valley Water District's standards and requirements and the workplan approved by DTSC on November 5, 2014.	
<b>Title:</b>					Public Notice for Draft RAW	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011288">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011288</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Public Notice				
<b>Date Completed:</b>		6/23/2005				
<b>Comments:</b>		Public Notice for Draft RAW				
<b>Title:</b>		Removal Action Completion Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016993">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016993</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Removal Action Completion Report				
<b>Date Completed:</b>		8/11/2006				
<b>Comments:</b>		Completion report approved. During implementation of the final remedy, additional PCB contaminated soil was encountered at another area on the site. Excavation of this PCB impacted soil occurred to the top of the groundwater table (approximately 9 feet below ground surface). Confirmation sampling verified that the PCB cleanup goal in this area was achieved in the upper 10 feet, but PCBs remain below 10 feet. A deed restriction will be required. The groundwater cleanup goal established in the RAW has not been met. Ongoing groundwater monitoring will be required until cleanup goals have been achieved.				
<b>Title:</b>		Groundwater Monitoring Well Destruction Workplan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60376197">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60376197</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Technical Workplan				
<b>Date Completed:</b>		11/5/2014				
<b>Comments:</b>						
<b>Title:</b>		Financial Assurance				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60393491">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60393491</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Financial Assurance Documentation				
<b>Date Completed:</b>		6/25/2015				
<b>Comments:</b>						
<b>Title:</b>		Deed Restriction				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6007951">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6007951</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Land Use Restriction				
<b>Date Completed:</b>		10/18/2006				
<b>Comments:</b>						
<b>Title:</b>		Annual Oversight Cost Estimate Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60433034">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60433034</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/15/2017				
<b>Comments:</b>						
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014105">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014105</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/25/2008				
<b>Comments:</b>		DTSC letter requires that semi-annual sampling for two wells should be continued.				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Phase I Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014777">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014777</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Phase 1	
<b>Date Completed:</b>					2/28/2007	
<b>Comments:</b>					DTSC approved Phase 1 and 2 Environmental Assessment Report.	
<b>Title:</b>					VCA	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016991">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016991</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Standard Voluntary Agreement	
<b>Date Completed:</b>					4/22/2005	
<b>Comments:</b>					VCA signed with the developer, Robson Homes.	
<b>Title:</b>					Revised Deed Restriction	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010643">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010643</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction	
<b>Date Completed:</b>					6/1/2007	
<b>Comments:</b>					The deed restriction was revised to include notification to EPA and include a a compliance letter snd replaced the original deed restriction..	
<b>Title:</b>					Cost Estimate Letter 2014-2015	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60376196">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60376196</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/15/2014	
<b>Comments:</b>					DTSC letter with oversight cost estimate for fiscal year 2014/2015.	
<b>Title:</b>					Annual Oversight Cost Estimate letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60413018">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60413018</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/14/2016	
<b>Comments:</b>						
<b>Title:</b>					Fact Sheet for Draft RAW	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011287">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011287</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fact Sheets	
<b>Date Completed:</b>					6/23/2005	
<b>Comments:</b>					Fact Sheet for Draft RAW	
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336207">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336207</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction Monitoring Report	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date Completed:</b>		3/7/2018				
<b>Comments:</b>						
<b>Title:</b>		Semi-annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012663">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012663</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		4/12/2011				
<b>Comments:</b>		Monitoring report approved. Request to cease monitoring not approved because remedial goals have not been met.				
<b>Title:</b>		Financial Assurance Mechanism				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60290147">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60290147</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Financial Assurance Documentation				
<b>Date Completed:</b>		6/29/2012				
<b>Comments:</b>		Revised financial assurance mechanism approved and in place.				
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254220">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254220</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		3/16/2012				
<b>Comments:</b>						
<b>Title:</b>		Operation and Maintenance Agreement				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6009661">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6009661</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation & Maintenance Order/Agreement				
<b>Date Completed:</b>		2/19/2009				
<b>Comments:</b>		The Agreement is entered into between Robson Homes, LLC and DTSC. The Agreement includes implementing the O&M Plan (groundwater monitoring) and submittal of groundwater monitoring reports.				
<b>Title:</b>		Annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286813">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286813</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		4/25/2012				
<b>Comments:</b>						
<b>Title:</b>		Annual Oversight Cost Estimate Letter				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		10/12/2021				
<b>Comments:</b>						
<b>Title:</b>		Groundwater Monitoring Well Destruction Implementation				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			2/28/2015			
<b>Comments:</b>			The destruction of monitoring wells on the Site was completed in accordance with the Work Plan for Well Decommissioning approved by DTSC on 11/5/2014.			
<b>Title:</b>			Deed Restriction Annual Compliance Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254219">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254219</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			6/1/2011			
<b>Comments:</b>			The Encanto Homeowner's Association submitted a letter to DTSC to verify compliance with the land use restrictions that are included in a deed restriction that is in place for the site. DTSC had no comments and approved the compliance letter.			
<b>Title:</b>			Quarterly GWM Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012656">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012656</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			7/23/2007			
<b>Comments:</b>			VOC concentrations are generally decreasing.			
<b>Title:</b>			Annual cost estimate 2010			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60256126">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60256126</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			10/5/2010			
<b>Comments:</b>			.			
<b>Title:</b>			Removal Action Workplan			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016992">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016992</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Removal Action Workplan			
<b>Date Completed:</b>			7/29/2005			
<b>Comments:</b>			The RAW requires a deed restriction preventing digging in the area where PCBs are at depth and treatment of contaminated groundwater with HRC and Bio-Innoculum. No comments were received during the public comment period.			
<b>Title:</b>			Annual Oversight Cost Estimate			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448809">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448809</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			9/13/2018			
<b>Comments:</b>						
<b>Title:</b>			Semi-annual GWM Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012662">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012662</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			7/12/2010			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Comments:</b>		approval letter sent with memo from GSU. Recommendation for change in sampling methodology.				

<a href="#">41</a>	3 of 3	ENE	0.43 / 2,276.24	66.37 / -9	CUSTOM FOOD MACHINERY 1180 - 1184 CAMPBELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	-----	--------------------	---------------	---	------------

<b>Estor/EPA ID:</b>	43200021	<b>Assembly District:</b>	28
<b>Site Code:</b>	201590	<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-14-07	<b>Public Partici Splst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	CLAUDE JEMISON
<b>Site Type:</b>	VOLUNTARY CLEANUP	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1180 - 1184 CAMPBELL AVENUE	<b>Latitude:</b>	37.349463
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.93035
<b>Special Program:</b>	VOLUNTARY CLEANUP PROGRAM	<b>Acres:</b>	7.8 ACRES
<b>Funding:</b>	SITE PROPONENT	<b>Supervisor:</b>	CHERYL PROWELL
<b>Cleanup Status:</b>	CERTIFIED / OPERATION & MAINTENANCE AS OF 3/26/2009		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY US EPA		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	MANUFACTURING - INDUSTRIAL MACHINERY, TRANSFORMER REPAIR		
<b>Potential Media Affected:</b>	OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL		
<b>Potential Contamin of Concern:</b>			

1,2,4-TRICHLOROBENZENE POLYCHLORINATED BIPHENYLS (PCBS) TETRACHLOROETHYLENE (PCE)

#### Site History:

Structural drawings indicate that the buildings located on the Site were constructed around 1953 to 1954. The facility located on 1180 Campbell was operated by the Stokely Van Camp for the production and storage of frozen food until the mid-1980's. In 1982, the site was purchased by Custom Food Machinery (CFM). CFM's operation involved refurbishing and rebuilding food processing machinery and equipment for resale. CFM operated a machine shop and parts storage area in Building 3 and where hazardous materials were stored. CFM operated the facility until December 1991. The facility appeared to be vacated in 1993 when it was leased to MMAD. MMAD Partnership purchased the Site in 1995. Tenants in the buildings include: HA Distributing Corp, Odyssey Enterprises Inc; Primo Packagaing Co. and Paper Materials Co. at 1180 Campbell from 1996 to 2000; Dale's Trucking Company at 1184 Campbell from 1996 to present; AIT Freight Company at 1184 Campbell in 2000. Presently, building 1 (1180 Campbell) and Building 2 (1182 Campbell) are a single structure currently occupied by CPS/Odyssey Complete Packaging Solutions (Odyssey). The buildings are currently used for packaging, crating and warehousing. Building 3 (1184 Campbell), the smallest of the three buildings, is located at the rear of the property. The current owner operated the facility as a trucking business until July 1999. It is currently leased by On Time Transport and Ryan's Express Freight. The owner still uses some portions of the property for snowmobile and jet-ski repair, restoration of classic automobiles, and material storage. The property is surrounded by mixed uses including commercial and residential.

<b>Status:</b>	CERTIFIED / OPERATION & MAINTENANCE - LAND USE RESTRICTIONS
<b>Program Type:</b>	VOLUNTARY CLEANUP
<b>CalEnviroScreen Score:</b>	56-60%
<b>Summary Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43200021">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43200021</a>

#### Land Use Restrictions

<b>Site Management Requirements:</b>	NO EXCAVATION OF CONTAMINATED SOILS WITHOUT AGENCY REVIEW AND APPROVAL NOTIFY AFTER CHANGE OF PROPERTY OWNER NOTIFY PRIOR TO DEVELOPMENT NOTIFY PRIOR TO SUBSURFACE WORK
<b>Title:</b>	Revised Deed Restriction
<b>Title Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/3214771866/Revised%20deed%20restriction%20Epdf">https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/3214771866/Revised%20deed%20restriction%20Epdf</a>
<b>Date Recorded:</b>	6/1/2007
<b>Site Management Requirements:</b>	LAND USE COVENANT NOTIFY AFTER CHANGE OF PROPERTY OWNER NOTIFY PRIOR TO CHANGE IN LAND USE
<b>Title:</b>	Deed Restriction
<b>Title Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&amp;global_id=43200021&amp;enforcement_id=6007951">https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&amp;global_id=43200021&amp;enforcement_id=6007951</a>
<b>Date Recorded:</b>	10/18/2006

#### Currently Scheduled Activities

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		5 Year Review Reports				
<b>Due Date:</b>		3/20/2022				
<b>Revised Date:</b>						
<b><u>Completed Activities</u></b>						
<b>Title:</b>		Annual cost estimate 2010				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60256126">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60256126</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		10/5/2010				
<b>Comments:</b>						
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254222">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254222</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		3/17/2014				
<b>Comments:</b>						
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336206">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336206</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Land Use Restriction Monitoring Report				
<b>Date Completed:</b>		3/15/2017				
<b>Comments:</b>						
<b>Title:</b>		Financial Assurance Mechanism				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60290147">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60290147</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Financial Assurance Documentation				
<b>Date Completed:</b>		6/29/2012				
<b>Comments:</b>						
Revised financial assurance mechanism approved and in place.						
<b>Title:</b>		Operation and Maintenance Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012653">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012653</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Plan				
<b>Date Completed:</b>		11/27/2006				
<b>Comments:</b>						
Report approved.						
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014105">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014105</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/25/2008				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Comments:</b>					DTSC letter requires that semi-annual sampling for two wells should be continued.	
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012663">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012663</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/12/2011	
<b>Comments:</b>					Monitoring report approved. Request to cease monitoring not approved because remedial goals have not been met.	
<b>Title:</b>					Annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286813">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286813</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/25/2012	
<b>Comments:</b>						
<b>Title:</b>					Annual Oversight Cost Estimate	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448811">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448811</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/6/2020	
<b>Comments:</b>					Emailed annual cost estimate letter on 10/6/2020. -EC	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/12/2021	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction 2008 Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6022388">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6022388</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Other Report	
<b>Date Completed:</b>					3/5/2009	
<b>Comments:</b>					The report indicates no soil work conducted in the restricted areas.	
<b>Title:</b>					Groundwater Monitoring Well Destruction Implementation	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					2/28/2015	
<b>Comments:</b>					The destruction of monitoring wells on the Site was completed in accordance with the Work Plan for Well Decommissioning approved by DTSC on 11/5/2014.	
<b>Title:</b>					Phase I Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014777">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014777</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Phase 1				
<b>Date Completed:</b>		2/28/2007				
<b>Comments:</b>		DTSC approved Phase 1 and 2 Environmental Assessment Report.				
<b>Title:</b>		Quarterly Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014104">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6014104</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		1/23/2008				
<b>Comments:</b>		Data is consistent with previous findings.				
<b>Title:</b>		VCA				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016991">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016991</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Standard Voluntary Agreement				
<b>Date Completed:</b>		4/22/2005				
<b>Comments:</b>		VCA signed with the developer, Robson Homes.				
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012654">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012654</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		4/6/2007				
<b>Comments:</b>		Report documents that biodegradation is occurring on site.				
<b>Title:</b>		Quarterly GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012656">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012656</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/23/2007				
<b>Comments:</b>		VOC concentrations are generally decreasing.				
<b>Title:</b>		Semi-annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012658">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012658</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		9/26/2008				
<b>Comments:</b>		The data is within the historical trend.				
<b>Title:</b>		Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60460564">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60460564</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Land Use Restriction Monitoring Report				
<b>Date Completed:</b>		5/20/2019				
<b>Comments:</b>						
<b>Title:</b>		Annual Oversight Cost Estimate				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448809">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60448809</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			9/13/2018			
<b>Comments:</b>						
<b>Title:</b>			CLRRRA Agreement			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010601">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010601</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			California Land Reuse and Revitalization Agreement			
<b>Date Completed:</b>			9/20/2007			
<b>Comments:</b>			A CLRRRA agreement was entered into between DTSC and Robson Homes. The Agreement calls for review of documents according to the schedule described in the Agreement.			
<b>Title:</b>			Deed Restriction 2009 Annual Compliance Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6027171">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6027171</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			6/29/2010			
<b>Comments:</b>			compliance letter acknowledgement sent			
<b>Title:</b>			Deed Restriction Annual Compliance Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254219">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254219</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			6/1/2011			
<b>Comments:</b>			The Encanto Homeowner's Association submitted a letter to DTSC to verify compliance with the land use restrictions that are included in a deed restriction that is in place for the site. DTSC had no comments and approved the compliance letter.			
<b>Title:</b>			Deed Restriction Compliance Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6019117">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6019117</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Other Report			
<b>Date Completed:</b>			5/6/2008			
<b>Comments:</b>			The letter indicates that the site is in accordance with the requirements of the deed restriction.			
<b>Title:</b>			Inject ORC & monitor for 6 months			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			5/11/2006			
<b>Comments:</b>			The final groundwater sampling was conducted on May 11, 2006 to verify Hydrogen Release (HRC's) effectiveness. Previous sampling results indicate HRC is reducing concentrations on chemicals of concern including, perchloroethylene and trichloroethylene. However, the trichlorobenzenes concentrations have stayed the same. The breakdown of these contaminants can also take longer.			
<b>Title:</b>			Semi-annual GWM Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012661">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012661</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date Completed:</b>		2/16/2010				
<b>Comments:</b>						
<b>Title:</b>		Semi-annual GWM Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012662">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012662</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/12/2010				
<b>Comments:</b>		approval letter sent with memo from GSU. Recommendation for change in sampling methodology.				
<b>Title:</b>		Amendment to Operation and Maintenance Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60287513">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60287513</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operations and Maintenance Plan Amendment				
<b>Date Completed:</b>		2/15/2012				
<b>Comments:</b>		Operations and Maintenance Plan amended to reduce groundwater sampling to an annual frequency.				
<b>Title:</b>		Cost Estimate Letter 2014-2015				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60376196">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60376196</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		10/15/2014				
<b>Comments:</b>		DTSC letter with oversight cost estimate for fiscal year 2014/2015.				
<b>Title:</b>		Deed Restriction Annual Compliance Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336207">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336207</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Land Use Restriction Monitoring Report				
<b>Date Completed:</b>		3/7/2018				
<b>Comments:</b>						
<b>Title:</b>		Financial Assurance				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60393491">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60393491</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Financial Assurance Documentation				
<b>Date Completed:</b>		6/25/2015				
<b>Comments:</b>						
<b>Title:</b>		First 5-Year Review and Annual Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6023015">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6023015</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		5 Year Review Reports				
<b>Date Completed:</b>		6/27/2014				
<b>Comments:</b>		Five-Year Review Report was performed to evaluate the protectiveness of the remedy. The Report determined that the site remedy is still protective of human health and the environment. It also recommended ceasing the groundwater monitoring of the Site, which was approved by DTSC.				
<b>Title:</b>		Annual Oversight Cost Estimate letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60413018">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60413018</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			9/14/2016			
<b>Comments:</b>						
<b>Title:</b>			Deed Restriction Annual Compliance Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254220">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60254220</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			3/16/2012			
<b>Comments:</b>						
<b>Title:</b>			Deed Restriction Annual Compliance Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336205">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336205</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Land Use Restriction Monitoring Report			
<b>Date Completed:</b>			3/14/2016			
<b>Comments:</b>						
<b>Title:</b>			Groundwater Monitoring Well Destruction Workplan			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60376197">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60376197</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Technical Workplan			
<b>Date Completed:</b>			11/5/2014			
<b>Comments:</b>						
<b>Title:</b>			Removal Action Workplan			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016992">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016992</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Removal Action Workplan			
<b>Date Completed:</b>			7/29/2005			
<b>Comments:</b>			The RAW requires a deed restriction preventing digging in the area where PCBs are at depth and treatment of contaminated groundwater with HRC and Bio-Innoculum. No comments were received during the public comment period.			
<b>Title:</b>			Revised Deed Restriction			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010643">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6010643</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Land Use Restriction			
<b>Date Completed:</b>			6/1/2007			
<b>Comments:</b>			The deed restriction was revised to include notification to EPA and include a a compliance letter snd replaced the original deed restriction..			
<b>Title:</b>			Semi-annual GWM Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012660">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012660</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			8/12/2009			
<b>Comments:</b>			Groundwater concentrations are within historic ranges.			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Quarterly GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012657">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012657</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					12/14/2007	
<b>Comments:</b>					VOC concentrations generally decreasing but still above Remedial Goals..	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60397306">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60397306</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/20/2015	
<b>Comments:</b>						
<b>Title:</b>					Certification	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016994">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=5016994</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Certification	
<b>Date Completed:</b>					3/26/2009	
<b>Comments:</b>						
<b>Title:</b>					Removal Action Completion Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016993">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=5016993</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Removal Action Completion Report	
<b>Date Completed:</b>					8/11/2006	
<b>Comments:</b>					Completion report approved. During implementation of the final remedy, additional PCB contaminated soil was encountered at another area on the site. Excavation of this PCB impacted soil occurred to the top of the groundwater table (approximately 9 feet below ground surface). Confirmation sampling verified that the PCB cleanup goal in this area was achieved in the upper 10 feet, but PCBs remain below 10 feet. A deed restriction will be required. The groundwater cleanup goal established in the RAW has not been met. Ongoing groundwater monitoring will be required until cleanup goals have been achieved.	
<b>Title:</b>					Semi-annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012659">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6012659</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/7/2009	
<b>Comments:</b>					Contaminants in groundwater are within historic ranges. Increase in Tetrachloroethylene in MW3A needs to be reviewed during next reporting period.	
<b>Title:</b>					Deed Restriction	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6007951">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6007951</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction	
<b>Date Completed:</b>					10/18/2006	
<b>Comments:</b>						
<b>Title:</b>					Deed Restriction Annual Compliance Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336204">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60336204</a>	
<b>Area Name:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					3/20/2015	
<b>Comments:</b>						
<b>Title:</b>					Fact Sheet for Draft RAW	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011287">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=6011287</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fact Sheets	
<b>Date Completed:</b>					6/23/2005	
<b>Comments:</b>					Fact Sheet for Draft RAW	
<b>Title:</b>					Operation and Maintenance Agreement	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6009661">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=6009661</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation & Maintenance Order/Agreement	
<b>Date Completed:</b>					2/19/2009	
<b>Comments:</b>					The Agreement is entered into between Robson Homes, LLC and DTSC. The Agreement includes implementing the O&M Plan (groundwater monitoring) and submittal of groundwater monitoring reports.	
<b>Title:</b>					Annual Cost Estimate 2011-2012	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60287490">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60287490</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					12/14/2011	
<b>Comments:</b>						
<b>Title:</b>					Annual GWM Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286814">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;doc_id=60286814</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					4/30/2013	
<b>Comments:</b>					The report presents the result of annual groundwater monitoring performed in December 2012. Groundwater levels were measured in six monitoring wells and monitoring well MW-4A was sampled. 1,2,4-Trichlorobenzene was detected in MW-4A at a concentration of 110 micrograms per liter and the concentration is showing a decreasing trend with time.	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60337135">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60337135</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/18/2013	
<b>Comments:</b>					DTSC letter with oversight cost estimate for fiscal year 2013/2014.	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60433034">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&amp;enforcement_id=60433034</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/15/2017	

**Comments:**

**Title:** Community Profile  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&doc\\_id=6014202](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6014202)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Community Profile  
**Date Completed:** 10/10/2006  
**Comments:** Community Profile completed in October 10, 2006

**Title:** Deed Restriction Annual Compliance Letter  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&doc\\_id=60254221](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=60254221)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Operation and Maintenance Report  
**Date Completed:** 2/28/2013  
**Comments:**

**Title:** Groundwater Monitoring Well Destruction Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&doc\\_id=60381104](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=60381104)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Technical Report  
**Date Completed:** 4/21/2015  
**Comments:** The Well Decommissioning Completion Report documents the destruction of the six groundwater monitoring wells on the site. All site groundwater monitoring wells were destroyed in accordance with the Santa Clara Valley Water District's standards and requirements and the workplan approved by DTSC on November 5, 2014.

**Title:** Public Notice for Draft RAW  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43200021&doc\\_id=6011288](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43200021&doc_id=6011288)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Public Notice  
**Date Completed:** 6/23/2005  
**Comments:** Public Notice for Draft RAW

<a href="#">42</a>	1 of 1	ENE	0.44 / 2,327.92	67.24 / -8	TW SMITH PLUMBING SUPPLY 1200 CAMPBELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	-----	--------------------	---------------	---	------------

<b>Estor/EPA ID:</b>	70000010	<b>Assembly District:</b>	28
<b>Site Code:</b>		<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-14-004, 23014004	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	EVALUATION	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1200 CAMPBELL AVENUE	<b>Latitude:</b>	37.3491684503095
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.929924149132
<b>Special Program:</b>		<b>Acres:</b>	2.28 ACRES
<b>Funding:</b>	NOT APPLICABLE	<b>Supervisor:</b>	
<b>Cleanup Status:</b>	REFER: OTHER AGENCY AS OF 10/21/2005		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	NONE SPECIFIED		
<b>Potential Media Affected:</b>	AQUIFER USED FOR DRINKING WATER SUPPLY AFFECTED		
<b>Potential Contamin of Concern:</b>			

TPH-DIESEL

**Site History:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

The site is located at 1200-1202 Campbell Avenue, San Jose, Santa Clara County, California 95126. The site has two single-story warehouse type buildings, which are 20,727square feet in The building at the front is used as sales office and showroom. The concrete building at the back is used for storage. A temporary/make shift storage shed is attached to the building at the back. There is paved parking area at the front of the site. The paved area at the back is used both as parking and storage for of various plumbing materials. The site is fenced and surrounded by drive-ways all around the buildings. There are two gates on both sides of the front building restricting access to the back of the site. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of primarily industrial/commercial businesses. Adjacent to the northeast boundary of the property is the Southern Pacific Railroad Newhall Yard. Beyond the Railroad to the northeast are the FMC Corporation Facility and San Jose International Airport. To the south across Campbell Avenue is Sanmina Corporation. To the southeast are Odyssey Complete Packaging Solutions, On Time Transport, and Ryan's Express Freight. The site is referred to Santa Clara Valley Water District because of several leaking underground storage tanks.

**Status:** REFER: OTHER AGENCY  
**Program Type:** EVALUATION  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000010](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000010)

**Completed Activities**

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000010&doc\\_id=6008114](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000010&doc_id=6008114)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 10/20/2005  
**Comments:** In house site screening report has been signed off.

<a href="#">43</a>	1 of 2	NW	0.44 / 2,342.17	72.71 / -2	Guerrera's Automotive 3305 The Alameda Santa Clara CA	LOP SANTA CLARA
--------------------	--------	----	--------------------	---------------	---	--------------------

**SCVWD ID:** 07S1W02L01f  
**Closure Date:** 3/2/2000  
**Link:** <http://lustop.sccgov.org/files/07S1W02L01f/>

<a href="#">43</a>	2 of 2	NW	0.44 / 2,342.17	72.71 / -2	GUERRERA'S AUTOMOTIVE 3305 THE ALAMEDA SANTA CLARA CA 95050	LUST
--------------------	--------	----	--------------------	---------------	---	------

**Global ID:** T0608500701  
**Status:** COMPLETED - CASE CLOSED  
**Status Date:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download  
**County:** SANTA CLARA  
**Latitude:**  
**Longitude:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:**  
**Local Case No:**  
**Begin Date:** 1/7/1987  
**Lead Agency:** SANTA CLARA COUNTY LOP  
**Local Agency:** SANTA CLARA COUNTY LOP  
**CUF Case:** NO  
**Potential COC:** Gasoline  
**How Discovered:**  
**Stop Method:**  
**Stop Description:**  
**Case Worker:** UST  
**File Location:** All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 46-50%

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	7/19/1999
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	5/11/1999
<b>Action:</b>	Staff Letter - #23354
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	2/25/1999
<b>Action:</b>	Soil and Water Investigation Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	12/18/1998
<b>Action:</b>	Staff Letter - #23351
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	11/17/1997
<b>Action:</b>	Warning Letter - #23350
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	8/29/1997
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	5/30/1997
<b>Action:</b>	Staff Letter - #23348
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	7/10/1996
<b>Action:</b>	Notice of Responsibility - #39705
<b>Action Type:</b>	Other
<b>Date :</b>	1/9/1987
<b>Action:</b>	Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	3/2/2000
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	1/7/1987
<b>Status:</b>	Open - Case Begin Date

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Status Date: 1/7/1987

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	GUERRERA'S AUTOMOTIVE	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	3305 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500701">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500701</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 3/2/2000		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500701&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500701&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02L01f		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Desc:</b>			
<b>Site History:</b>			

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

<b>Status:</b>	Completed - Case Closed
<b>Date :</b>	3/2/2000
<b>Status:</b>	Open - Site Assessment
<b>Date :</b>	1/7/1987
<b>Status:</b>	Open - Case Begin Date
<b>Date :</b>	1/7/1987

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

<b>Action Type:</b>	Response Requested - Other
<b>Action Date:</b>	6/3/2005
<b>Received Issue Date:</b>	6/3/2005
<b>Action:</b>	Other Report / Document
<b>Doc Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500701&amp;doc_id=5927392">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500701&amp;doc_id=5927392</a>
<b>Title Description Comments:</b>	

Microfiche Scans - See Read Me First 06/03/2005

<b>Action Type:</b>	Other Regulatory Actions
<b>Action Date:</b>	5/11/1999
<b>Received Issue Date:</b>	5/11/1999
<b>Action:</b>	Staff Letter - #23354
<b>Doc Link:</b>	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/18/1998  
**Received Issue Date:** 12/18/1998  
**Action:** Staff Letter - #23351  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Enforcement/Orders  
**Action Date:** 11/17/1997  
**Received Issue Date:** 11/17/1997  
**Action:** Warning Letter - #23350  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/30/1997  
**Received Issue Date:** 5/30/1997  
**Action:** Staff Letter - #23348  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 7/10/1996  
**Received Issue Date:** 7/10/1996  
**Action:** Notice of Responsibility - #39705  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 7/19/1999  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Response Requested - Workplans  
**Action Date:** 2/25/1999  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Response Requested - Reports  
**Action Date:** 8/29/1997  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Leak Action  
**Action Date:** 1/9/1987  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Title Description Comments:

LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)

**Document Type:** Site Documents **Size :** 396 KB  
**Document Date:** 10/5/2007 **Submitted By:** CYNTHIA MANA-AY (REGULATOR)  
**Type:** LETTER **Submitted:**  
**Title:** CLOSURE LETTER & SITE CLOSURE SUMMARY  
**Title Link:** [https://geotracker.waterboards.ca.gov/site\\_documents/7460850358/CLOS%5FL%5F2000%2D03%2D02%2Epdf](https://geotracker.waterboards.ca.gov/site_documents/7460850358/CLOS%5FL%5F2000%2D03%2D02%2Epdf)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** MICROFICHE SCANS - SEE READ ME FIRST 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500701&document\\_id=5927392](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500701&document_id=5927392)

<a href="#">44</a>	1 of 1	W	0.45 / 2,356.52	86.03 / 11	FAGUNDES, FATIMA 1246 SANTA CLARA STREET SANTA CLARA CA 95050	RCRA TSD
--------------------	--------	---	--------------------	---------------	---	----------

**EPA Handler ID:** CAC003019390  
**Gen Status Universe:** No Report  
**Contact Name:** FAGUNDES, FATIMA  
**Contact Address:** 1246 SANTA CLARA STREET , , SANTA CLARA , CA, 95050 ,  
**Contact Phone No and Ext:** 408-316-6845  
**Contact Email:** MICKIEL@PWSEI.COM  
**Contact Country:**  
**Land Type:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Receive Date:** 20190612  
**Location Latitude:** 37.345917  
**Location Longitude:** -121.945826

Violation/Evaluation Summary

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Smelting, Melting and Refining:** No  
**Underground Injection Control:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No  
**Used Oil Burner:** No  
**Used Oil Market Burner:** No  
**Used Oil Spec Marketer:** No

Hazardous Waste Handler Details

**Sequence No:** 1  
**Receive Date:** 20190612  
**Handler Name:** FAGUNDES, FATIMA  
**Federal Waste Generator Code:** N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Generator Code Description: Not a Generator, Verified  
 Source Type: Implementer

**Owner/Operator Details**

<b>Owner/Operator Ind:</b>	Current Owner	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	1246 SANTA CLARA STREET
<b>Name:</b>	FAGUNDES, FATIMA	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	408-316-6845	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95050

<b>Owner/Operator Ind:</b>	Current Operator	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	1246 SANTA CLARA STREET
<b>Name:</b>	FAGUNDES, FATIMA	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	408-316-6845	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95050

<a href="#">45</a>	1 of 1	NW	0.45 / 2,374.75	74.75 / 0	SANTA CLARA UNIVERSITY 870 BENTON ST. SANTA CLARA CA 95050	RCRA TSD
--------------------	--------	----	--------------------	--------------	--	----------

**EPA Handler ID:** CAC003006852  
**Gen Status Universe:** No Report  
**Contact Name:** SANTA CLARA UNIVERSITY  
**Contact Address:** 500 EL CAMINO REAL , , SANTA CLARA , CA, 95053 ,  
**Contact Phone No and Ext:** 408-554-4736  
**Contact Email:** LILIAN.RAMOS@SYNERGYCOMPANIES.ORG  
**Contact Country:**  
**Land Type:**  
**County Name:** SANTA CLARA  
**EPA Region:** 09  
**Receive Date:** 20190322  
**Location Latitude:** 37.351271  
**Location Longitude:** -121.943404

**Violation/Evaluation Summary**

**Note:** NO RECORDS: As of Nov 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

**Handler Summary**

**Importer Activity:** No  
**Mixed Waste Generator:** No  
**Transporter Activity:** No  
**Transfer Facility:** No  
**Onsite Burner Exemption:** No  
**Smelting, Melting and Refining:** No  
**Underground Injection Control:** No  
**Commercial TSD:** No  
**Used Oil Transporter:** No  
**Used Oil Transfer Facility:** No  
**Used Oil Processor:** No  
**Used Oil Refiner:** No  
**Used Oil Burner:** No  
**Used Oil Market Burner:** No  
**Used Oil Spec Marketer:** No

**Hazardous Waste Handler Details**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Sequence No:** 1  
**Receive Date:** 20190322  
**Handler Name:** SANTA CLARA UNIVERSITY  
**Federal Waste Generator Code:** N  
**Generator Code Description:** Not a Generator, Verified  
**Source Type:** Implementer

**Owner/Operator Details**

<b>Owner/Operator Ind:</b>	Current Owner	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	500 EL CAMINO REAL
<b>Name:</b>	SANTA CLARA UNIVERSITY	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	408-554-4736	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95053

<b>Owner/Operator Ind:</b>	Current Operator	<b>Street No:</b>	
<b>Type:</b>	Other	<b>Street 1:</b>	500 EL CAMINO REAL
<b>Name:</b>	SANTA CLARA UNIVERSITY	<b>Street 2:</b>	
<b>Date Became Current:</b>		<b>City:</b>	SANTA CLARA
<b>Date Ended Current:</b>		<b>State:</b>	CA
<b>Phone:</b>	408-554-4736	<b>Country:</b>	
<b>Source Type:</b>	Implementer	<b>Zip Code:</b>	95053

<a href="#">46</a>	1 of 3	E	0.45 / 2,390.68	67.34 / -8	<b>BLUE'S ROOFING COMPANY</b> 1181 CAMPBELL AVENUE SAN JOSE CA 95126	VCP
--------------------	--------	---	--------------------	---------------	--	-----

<b>Estor/EPA ID:</b>	70000013	<b>Permit Renewal Lead:</b>	
<b>Site Code:</b>	201740, 201751	<b>Project Manager:</b>	
<b>Nat Priority List:</b>	NO	<b>Supervisor:</b>	KAREN TOTH
<b>Acres:</b>	2.67 ACRES	<b>Public Partici Spclst:</b>	
<b>Special Program:</b>	VOLUNTARY CLEANUP PROGRAM	<b>Census Tract:</b>	6085505203
<b>Funding:</b>	NOT APPLICABLE	<b>County:</b>	SANTA CLARA
<b>Assembly District:</b>	28	<b>Latitude:</b>	37.3464420872453
<b>Senate District:</b>	10	<b>Longitude:</b>	-121.928730956897
<b>School District:</b>			
<b>APN:</b>	230-56-029, 23013012		
<b>Cleanup Status:</b>	NO FURTHER ACTION AS OF 10/19/2007		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>Site Type:</b>	VOLUNTARY CLEANUP		
<b>Office:</b>	CLEANUP BERKELEY		
<b>Past Use that Caused Contam:</b>	FUEL - VEHICLE STORAGE/ REFUELING		
<b>Potential Media Affected:</b>	NO MEDIA AFFECTED		
<b>Potential Contamin of Concern:</b>			

NO CONTAMINANTS FOUND

**Site History:**

The site has one single-story warehouse type building, which is 23,480 square feet in size. The building is split into three tenant areas. The front of the property is fenced off and used as a storage area for scaffolding material. There is a small landscaped area and a parking lot at the front of the building. A drive-way on the northwest side of the site leads to the back of the building to a paved area which is used as a storage yard and has one aboveground propane tank and a fueling station. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of mixed commercial/industrial and residential developments. Adjacent to the northwest boundary of the property is Sanmina Corporation. Beyond Sanmina Corporation to the northwest is Stephen Schott Stadium. To the northeast across Campbell Avenue are Silicon Valley Microelectronics, Precision Specialties, Variety Metal Finishing and Southern Pacific Railroad Newhall Yard. Beyond the Railroad to the northeast is the former FMC Corporation Facility and San Jose International Airport. Adjacent to the southeast boundary of the property are A.J. Commercial Laundry and ALL Chem Supply and to the southwest are residential buildings. Prior to 1981, it was a vacant lot owned by Owens Illinois. In 1981, South Bay Construction started developing the property. Cobalt Associates has been the owner of the property since 1986. Blue's Roofing Company (Blue's) occupied the building at 1181 Campbell Avenue since 1981. Blue's specializes in commercial roofing and waterproofing. Past tenants include a towing company (Ray's Towing Service), a general contractor and an RV repair service.

**Status:** NO FURTHER ACTION  
**Program Type:** VOLUNTARY CLEANUP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

CalEnviroScreen Score: 56-60%  
 Summary Link: [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000013](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000013)

**Completed Activities**

**Title:** Phase I and II Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000013&doc\\_id=6016136](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000013&doc_id=6016136)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Phase 1  
**Date Completed:** 10/19/2007  
**Comments:** The Phase I and II Report was approved meeting the AAI Requirements. An NFA determination was also made.

**Title:** Consultative Agreement  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000013&enforcement\\_id=6010845](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000013&enforcement_id=6010845)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Consultative Service Agreement  
**Date Completed:** 10/11/2007  
**Comments:** This is an Agreement between Robson Homes and DTSC to review a Phase I and II Report according to the schedule outlined in the Agreement.

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000013&doc\\_id=6007983](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000013&doc_id=6007983)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 10/3/2005  
**Comments:**

<a href="#">46</a>	2 of 3	E	0.45 / 2,390.68	67.34 / -8	<b>KILMAN SALES 1179 CAMPBELL AVENUE SAN JOSE CA 95126</b>	<b>ENVIROSTOR</b>
--------------------	--------	---	--------------------	---------------	--	-------------------

<b>Estor/EPA ID:</b>	70000011	<b>Assembly District:</b>	28
<b>Site Code:</b>		<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	23013012	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	EVALUATION	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1179 CAMPBELL AVENUE	<b>Latitude:</b>	37.3464420872453
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.928730956897
<b>Special Program:</b>		<b>Acres:</b>	2.67 ACRES
<b>Funding:</b>	NOT APPLICABLE	<b>Supervisor:</b>	KAREN TOTH
<b>Cleanup Status:</b>	NO ACTION REQUIRED AS OF 10/21/2005		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	NONE		
<b>Potential Media Affected:</b>	NO MEDIA AFFECTED		
<b>Site History:</b>			

The site is located at 1179 Campbell Avenue, San Jose, Santa Clara County, California 95126. The site has one single-story warehouse type building, which is 23,480 square feet in size. The building is split into three tenant areas. The front of the property is fenced off and used as a storage area for scaffolding material. There is a small landscaped area and a parking lot at the front of the building. A drive-way on the northwest side of the site leads to the back of the building to a paved area which is used as a storage yard and has one aboveground propane tank and a fueling station. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of mixed commercial/industrial and residential developments. Adjacent to the northwest boundary of the property is Sanmina Corporation. Beyond Sanmina Corporation to the northwest is Stephen Schott Stadium. To the northeast across Campbell Avenue are Silicon Valley Microelectronics, Precision Specialties, Variety Metal Finishing and Southern Pacific Railroad Newhall Yard. Beyond the Railroad to the northeast is the former FMC Corporation Facility and San Jose International Airport. Adjacent to the southeast boundary of the property are A.J. Commercial Laundry and ALL Chem Supply and to the southwest are residential buildings. Prior to 1981, it was a vacant lot owned by Owens Illinois. In 1981, South Bay Construction started developing

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

the property. Cobalt Associates has been the owner of the property since 1986. In 1981, a metal working company occupied the building at 1179 Campbell Avenue. In 1985, A & J Repair – a RV repair company occupied the site. From 1991 to August 2000, Leon Frank, dba GTC Enterprises, a machinist occupied the site. Since February 2001, Kilman Sales, Inc. has been occupying the Site. It is a plumbing supplies company and uses this facility only as a warehouse.

**Potential Contamin of Concern:**

NO CONTAMINANTS FOUND

**Status:** NO ACTION REQUIRED  
**Program Type:** EVALUATION  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000011](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000011)

**Completed Activities**

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000011&doc\\_id=6008575](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000011&doc_id=6008575)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 10/20/2005  
**Comments:** Report written by in-house DTSC staff

<a href="#">46</a>	3 of 3	E	0.45 / 2,390.68	67.34 / -8	BLUE'S ROOFING COMPANY 1181 CAMPBELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	---	-----------------	------------	---	------------

<b>Estor/EPA ID:</b>	70000013	<b>Assembly District:</b>	28
<b>Site Code:</b>	201740, 201751	<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-56-029, 23013012	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	VOLUNTARY CLEANUP	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1181 CAMPBELL AVENUE	<b>Latitude:</b>	37.3464420872453
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.928730956897
<b>Special Program:</b>	VOLUNTARY CLEANUP PROGRAM	<b>Acres:</b>	2.67 ACRES
<b>Funding:</b>	NOT APPLICABLE	<b>Supervisor:</b>	KAREN TOTH
<b>Cleanup Status:</b>	NO FURTHER ACTION AS OF 10/19/2007		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	FUEL - VEHICLE STORAGE/ REFUELING		
<b>Potential Media Affected:</b>	NO MEDIA AFFECTED		
<b>Potential Contamin of Concern:</b>			

NO CONTAMINANTS FOUND

**Site History:**

The site has one single-story warehouse type building, which is 23,480 square feet in size. The building is split into three tenant areas. The front of the property is fenced off and used as a storage area for scaffolding material. There is a small landscaped area and a parking lot at the front of the building. A drive-way on the northwest side of the site leads to the back of the building to a paved area which is used as a storage yard and has one aboveground propane tank and a fueling station. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of mixed commercial/industrial and residential developments. Adjacent to the northwest boundary of the property is Sanmina Corporation. Beyond Sanmina Corporation to the northwest is Stephen Schott Stadium. To the northeast across Campbell Avenue are Silicon Valley Microelectronics, Precision Specialties, Variety Metal Finishing and Southern Pacific Railroad Newhall Yard. Beyond the Railroad to the northeast is the former FMC Corporation Facility and San Jose International Airport. Adjacent to the southeast boundary of the property are A.J. Commercial Laundry and ALL Chem Supply and to the southwest are residential buildings. Prior to 1981, it was a vacant lot owned by Owens Illinois. In 1981, South Bay Construction started developing the property. Cobalt Associates has been the owner of the property since 1986. Blue's Roofing Company (Blue's) occupied the building at 1181 Campbell Avenue since 1981. Blue's specializes in commercial roofing and waterproofing. Past tenants include a towing company (Ray's Towing Service), a general contractor and an RV repair service.

**Status:** NO FURTHER ACTION  
**Program Type:** VOLUNTARY CLEANUP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

CalEnviroScreen Score: 56-60%  
 Summary Link: [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000013](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000013)

**Completed Activities**

**Title:** Consultative Agreement  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000013&enforcement\\_id=6010845](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000013&enforcement_id=6010845)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Consultative Service Agreement  
**Date Completed:** 10/11/2007  
**Comments:** This is an Agreement between Robson Homes and DTSC to review a Phase I and II Report according to the schedule outlined in the Agreement.

**Title:** Phase I and II Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000013&doc\\_id=6016136](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000013&doc_id=6016136)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Phase 1  
**Date Completed:** 10/19/2007  
**Comments:** The Phase I and II Report was approved meeting the AAI Requirements. An NFA determination was also made.

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000013&doc\\_id=6007983](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000013&doc_id=6007983)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 10/3/2005  
**Comments:**

<a href="#">47</a>	1 of 1	NNW	0.46 / 2,412.25	70.64 / -4	REILING AUTOMOTIVE SERVICE 3340 THE ALAMEDA SANTA CLARA CA 95050	DELISTED HAZ
--------------------	--------	-----	--------------------	---------------	--	-----------------

**Siteid:** 61194  
**Latitude:** 37.352555  
**Longitude:** -121.941000  
**Original Source:** CHAZ  
**Record Date:** 09-JUL-2018

<a href="#">48</a>	1 of 1	NNW	0.46 / 2,435.94	71.49 / -4	MISSION TOWN CENTER 575 - 675 BENTON STREET SANTA CLARA CA 95050	CLEANUP SITES
--------------------	--------	-----	--------------------	---------------	--	------------------

**Global ID:** T10000008392  
**Status:** OPEN - REMEDIATION  
**Status Date:** 8/7/2019  
**Site Facility Type:** CLEANUP PROGRAM SITE  
**Data Source:** Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

**Latitude:** 37.35292  
**Longitude:** -121.93953  
**County:** SANTA CLARA

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** 43S1197  
**Local Case No:**  
**Begin Date:** 1/1/1997  
**File Location:** All Files are on GeoTracker or in the Local Agency Database  
**Lead Agency:** SAN FRANCISCO BAY RWQCB (REGION 2)  
**Local Agency:** SANTA CLARA, CITY OF

**Stop Method:**  
**CUF Case:** NO  
**Case Worker:** MBR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Potential COC:</b>		Tetrachloroethylene (PCE), Trichloroethylene (TCE), Diesel, Gasoline, Heating Oil / Fuel Oil				
<b>Potential Media of Concern:</b>		Indoor Air, Other Groundwater (uses other than drinking water), Soil, Soil Vapor				
<b>How Discovered:</b>						
<b>How Discovered Description:</b>						
<b>Stop Description:</b>						
<b>CalWater Watershed Name:</b>		Santa Clara - Palo Alto (205.50)				
<b>DWR GW Subbasin Name:</b>		Santa Clara Valley - Santa Clara (2-009.02)				
<b>Disadvantaged Community:</b>						
<b>CalEnviroScreen Score:</b>		41-45%				
<b>Site History:</b>						

The Irvine Company's Mission Town Center is currently on hold and inactive. The proposed project is located on an approximately 5.7-acre project site at the intersection of Benton Street and El Camino Real in the southeastern portion of the City of Santa Clara. The site is presently occupied by a mix of land uses, including light industrial uses such as a self-storage complex and auto repair shop, single and multifamily residential uses, office, and a restaurant. The applicant proposed to demolish the existing buildings on the project site and construct a mixed-use residential development project that would consist of 385 apartment units, approximately 10,000 square feet of conditioned amenity and leasing space, three distinct private open space areas, and about 27,000 square feet of ground floor retail. Parking would be provided in a 6 story parking structure, with one story below grade. The residential building would be slab-on-grade construction, while the commercial building would be podium construction with wood framing above. The project included a General Plan Amendment (to Santa Clara Station Very High Density Residential), a rezoning to Planned Development, and vacation of two streets (Sherman and Fremont). The project Environmental Impact Report was scheduled to be distributed for review in mid November 2015 with approval obtained in early January 2016. The project would then go to Planning Commission in early February 2016 with City Council approval scheduled for February 23, 2016. Project construction was scheduled to begin demolition on August 1, 2016 with project completion in February 2019. The project includes improvements to off-site utilities, including construction of 12 and 24-inch water mains in The Alameda and Harrison Street; rerouting a storm drain around the project site to the east along Benton Street and then to the north along El Camino Real. The new segment of storm drain would be upsized as part of the proposed project to 72 inches to maintain prior capacity. Finally, the project would extend the 8 inch recycled water main approximately 500 linear feet within Fremont Street from the intersection of Fremont and Alviso Street to the project frontage on the east side of the intersection of The Alameda and Fremont Street.

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2021-09-09 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2021-07-26 00:00:00
<b>Action:</b>	Annual Estimation Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2021-02-17 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-06-30 00:00:00
<b>Action:</b>	Annual Estimation Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-06-26 00:00:00
<b>Action:</b>	Notification - Public Participation Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-04-22 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-03-20 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-03-12 00:00:00
<b>Action:</b>	Email Correspondence
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-02-14 00:00:00
<b>Action:</b>	Email Correspondence
<b>Action Type:</b>	ENFORCEMENT

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						
<i>Action Type:</i>		ENFORCEMENT				
<i>Date:</i>						
<i>Action:</i>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>					Staff Letter	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-10-09 00:00:00	
<b>Action:</b>					Interim Remedial Action Plan	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-10-09 00:00:00	
<b>Action:</b>					Well Destruction Workplan	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-10-09 00:00:00	
<b>Action:</b>					Site Investigation Workplan	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-09-18 00:00:00	
<b>Action:</b>					Preliminary Site Assessment Report	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-09-18 00:00:00	
<b>Action:</b>					Email Correspondence	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2018-06-29 00:00:00	
<b>Action:</b>					Annual Estimation Letter	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2018-05-08 00:00:00	
<b>Action:</b>					Technical Correspondence / Assistance / Other	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-05-07 00:00:00	
<b>Action:</b>					Soil Vapor Intrusion Investigation Workplan	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2018-05-03 00:00:00	
<b>Action:</b>					Site Investigation Workplan	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2018-05-03 00:00:00	
<b>Action:</b>					Technical Correspondence / Assistance / Other	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2018-04-30 00:00:00	
<b>Action:</b>					Meeting	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2017-06-30 00:00:00	
<b>Action:</b>					Annual Estimation Letter	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2017-06-28 00:00:00	
<b>Action:</b>					Staff Letter	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2016-10-06 00:00:00	
<b>Action:</b>					Staff Letter	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2016-09-07 00:00:00	
<b>Action:</b>					Correspondence	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2016-08-29 00:00:00	
<b>Action:</b>					Staff Letter	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2016-08-23 00:00:00	
<b>Action:</b>					Interim Remedial Action Plan	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action Type:</b>		RESPONSE				
<b>Date:</b>		2016-05-26 00:00:00				
<b>Action:</b>		Correspondence				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2016-02-11 00:00:00				
<b>Action:</b>		Meeting				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2016-01-15 00:00:00				
<b>Action:</b>		Cost Recovery Agreement / N. of Reimbursement				
<b>Action Type:</b>		Other				
<b>Date:</b>		2015-11-12 00:00:00				
<b>Action:</b>		Leak Reported				
<b>Action Type:</b>		Other				
<b>Date:</b>		1997-01-01 00:00:00				
<b>Action:</b>		Leak Began				
<b>Action Type:</b>		Other				
<b>Date:</b>		1997-01-01 00:00:00				
<b>Action:</b>		Leak Discovery				

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Open - Remediation
<b>Status Date:</b>	2019-08-07 00:00:00
<b>Status:</b>	Open - Remediation
<b>Status Date:</b>	2018-10-09 00:00:00
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	2018-01-09 00:00:00
<b>Status:</b>	Open - Assessment & Interim Remedial Action
<b>Status Date:</b>	2017-01-09 00:00:00
<b>Status:</b>	Open - Inactive
<b>Status Date:</b>	2016-06-06 00:00:00
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	2016-01-28 00:00:00
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	1997-01-01 00:00:00

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY STREET, SUITE 1400
<b>Contact Name:</b>	MICHAEL ROCHETTE	<b>City:</b>	OAKLAND
<b>Phone No:</b>			
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Email:</b>	michael.rochette@waterboards.ca.gov		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	SANTA CLARA FIRE DEPARTMENT - FIRE PREVENTION AND HAZARDOUS MATERIALS DIVISION
<b>Contact Name:</b>	FREDERICK CHUN	<b>City:</b>	SANTA CLARA
<b>Phone No:</b>			
<b>Organization Name:</b>	SANTA CLARA, CITY OF		
<b>Email:</b>	fchun@santaclaraca.gov		

**Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of Sep 15, 2021)**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Project Status:**  
**Cuf Claim No:**  
**CUF Priority Assign:**  
**CUF Amount Paid:**  
**Composting Method:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**User Defined Beneficial Use:**  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T10000008392](https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000008392)  
**Cleanup Status Detail:** OPEN - REMEDIATION AS OF 8/7/2019  
**Potential COC:** DIESEL, GASOLINE, HEATING OIL / FUEL OIL, TETRACHLOROETHYLENE (PCE), TRICHLOROETHYLENE (TCE)  
**Potential Media of Concern:** INDOOR AIR, OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER), SOIL, SOIL VAPOR  
**Groundwater Monitoring Frequen:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SAN FRANCISCO BAY RWQCB (REGION 2) (LEAD) - CASE #: 43S1197  
CASEWORKER: MICHAEL ROCHETTE  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T10000008392&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000008392&tabname=regulatoryhistory)  
**Site History:**

The Irvine Company's Mission Town Center is currently on hold and inactive. The proposed project is located on an approximately 5.7-acre project site at the intersection of Benton Street and El Camino Real in the southeastern portion of the City of Santa Clara. The site is presently occupied by a mix of land uses, including light industrial uses such as a self-storage complex and auto repair shop, single and multifamily residential uses, office, and a restaurant.

The applicant proposed to demolish the existing buildings on the project site and construct a mixed-use residential development project that would consist of 385 apartment units, approximately 10,000 square feet of conditioned amenity and leasing space, three distinct private open space areas, and about 27,000 square feet of ground floor retail. Parking would be provided in a 6 story parking structure, with one story below grade. The residential building would be slab-on-grade construction, while the commercial building would be podium construction with wood framing above.

The project included a General Plan Amendment (to Santa Clara Station Very High Density Residential), a rezoning to Planned Development, and vacation of two streets (Sherman and Fremont). The project Environmental Impact Report was scheduled to be distributed for review in mid November 2015 with approval obtained in early January 2016. The project would then go to Planning Commission in early February 2016 with City Council approval scheduled for February 23, 2016. Project construction was scheduled to begin demolition on August 1, 2016 with project completion in February 2019.

The project includes improvements to off-site utilities, including construction of 12 and 24-inch water mains in The Alameda and Harrison Street; rerouting a storm drain around the project site to the east along Benton Street and then to the north along El Camino Real. The new segment of storm drain would be upsized as part of the proposed project to 72 inches to maintain prior capacity. Finally, the project would extend the 8 inch recycled water main approximately 500 linear feet within Fremont Street from the intersection of Fremont and Alviso Street to the project frontage on the east side of the intersection of The Alameda and Fremont Street.

**Sites from GeoTracker Search - Regulatory Activities (as of Sep 15, 2021)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/9/2021  
**Received Issue Date:** 9/9/2021  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6475644&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6475644&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Risk Management Plan, Mission Town Center, Santa Clara

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/26/2021  
**Received Issue Date:** 7/26/2021  
**Action:** Annual Estimation Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6471969&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6471969&temptable=ENFORCEMENT)

**Title Description Comments:**

Annual Estimate Letter FY 2021/2022

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/17/2021  
**Received Issue Date:** 2/17/2021  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6457819&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6457819&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of the 2020 Site Completion Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/30/2020  
**Received Issue Date:** 6/30/2020  
**Action:** Annual Estimation Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6440875&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6440875&temptable=ENFORCEMENT)

**Title Description Comments:**

Annual Estimate Letter FY 2020/2021

**Action Type:** Notices  
**Action Date:** 6/26/2020  
**Received Issue Date:** 6/26/2020  
**Action:** Notification - Public Participation Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6439569&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6439569&temptable=ENFORCEMENT)

**Title Description Comments:**

Fact Sheet 1250 Sherman Street, Mission Town Center

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/22/2020  
**Received Issue Date:** 4/22/2020  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6433206&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6433206&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval letter for the March 20, 2020, Soil Vapor Testing Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/20/2020  
**Received Issue Date:** 3/20/2020  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6430633&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6430633&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Focused Feasibility Study and Request for Fact Sheet. Addresses elevated lead concentrations at 1250 Sherman Street within the Mission Town Center redevelopment

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/12/2020  
**Received Issue Date:** 3/12/2020  
**Action:** Email Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6430137&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6430137&temptable=ENFORCEMENT)

**Title Description Comments:**

Response to Email Regarding Review of Focused Feasibility Study Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/14/2020

**Received Issue Date:** 2/14/2020  
**Action:** Email Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6427413&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6427413&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Soil Gas Sampling Locations for Oxygen Concentrations

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/11/2020  
**Received Issue Date:** 2/11/2020  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6427011&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6427011&temptable=ENFORCEMENT)

**Title Description Comments:**

Response to Proposed Soil Capping in 1250 Sherman Street Area and VIMS in Former UST Area. Approval of the proposed option 1 if a focused feasibility study is submitted.

**Action Type:** Other Regulatory Actions  
**Action Date:** 1/29/2020  
**Received Issue Date:** 1/29/2020  
**Action:** Email Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6426129&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6426129&temptable=ENFORCEMENT)

**Title Description Comments:**

Email response to request for a meeting with the Water Board

**Action Type:** Other Regulatory Actions  
**Action Date:** 11/25/2019  
**Received Issue Date:** 11/25/2019  
**Action:** Meeting  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6418279&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6418279&temptable=ENFORCEMENT)

**Title Description Comments:**

Project Management Meeting with property developer and consultants to discuss soil sampling results and onsite reuse following the approved soil management plan.

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/23/2019  
**Received Issue Date:** 10/23/2019  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6418279&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6418279&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of workplan for soil stockpile sampling procedure for onsite soil reuse.

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/5/2019  
**Received Issue Date:** 9/5/2019  
**Action:** Email Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6414026&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6414026&temptable=ENFORCEMENT)

**Title Description Comments:**

Email approval of request for a time extension to submit the vapor intrusion investigation completion report from September 30, 2019, to November 15, 2019

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/26/2019  
**Received Issue Date:** 7/26/2019  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6414026&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6414026&temptable=ENFORCEMENT)

global\_id=T10000008392&enforcement\_id=6410009&temptable=ENFORCEMENT

**Title Description Comments:**

Approval of July 15, 2019, Proposed Work Plan for Vapor Intrusion Investigation for the former Viso property and requests for a completion report by September 30, 2019

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/25/2019  
**Received Issue Date:** 7/25/2019  
**Action:** Annual Estimation Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6409915&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6409915&temptable=ENFORCEMENT)

**Title Description Comments:**

Annual Estimate Letter FY 2019/2020

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/25/2019  
**Received Issue Date:** 6/25/2019  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6407086&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6407086&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of the Soil Vapor Testing Report and Request for a Vapor Intrusion Investigation Workplan by August 30, 2019.

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/3/2019  
**Received Issue Date:** 6/3/2019  
**Action:** Email Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6403931&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6403931&temptable=ENFORCEMENT)

**Title Description Comments:**

Denial of Request to Use 2016 ESLs

**Action Type:** Enforcement/Orders  
**Action Date:** 5/7/2019  
**Received Issue Date:** 5/7/2019  
**Action:** Deadline Extension  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6401309&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6401309&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of time extension for the submittal of the Soil Vapor Sampling Completion Report to June 17, 2019.

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/27/2019  
**Received Issue Date:** 3/27/2019  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6397466&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6397466&temptable=ENFORCEMENT)

**Title Description Comments:**

Conditional Approval of Proposed Soil Vapor Sampling Workplan - with revised sampling locations.

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/18/2019  
**Received Issue Date:** 3/18/2019  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6388367&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6388367&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of the February 28, 2019, Soil Management Plan Addendum

**Action Type:** Enforcement/Orders  
**Action Date:** 1/31/2019  
**Received Issue Date:** 1/31/2019  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6384279&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6384279&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Soil Management Plan and (13267) Requirement for Reports

**Action Type:** Enforcement/Orders  
**Action Date:** 11/8/2018  
**Received Issue Date:** 11/8/2018  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6375275&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6375275&temptable=ENFORCEMENT)

**Title Description Comments:**

Rejection of Soil Management Plan and Requirement for Revised SMP (Due Jan. 18, 2019)

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/18/2018  
**Received Issue Date:** 10/18/2018  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6372866&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6372866&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Work Plan for Destruction of Monitoring Wells and requests for a completion report (Due November 30, 2018)

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/18/2018  
**Received Issue Date:** 10/18/2018  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6372860&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6372860&temptable=ENFORCEMENT)

**Title Description Comments:**

Conditionally approval of Proposed Work Plan for Soil Vapor and Groundwater Testing, and request for a completion report (Due November 30, 2018)

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/16/2018  
**Received Issue Date:** 10/16/2018  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6372506&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6372506&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Remedial Effectiveness Evaluation Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/15/2018  
**Received Issue Date:** 10/15/2018  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6372362&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6372362&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Soil Vapor Investigation Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/11/2018  
**Received Issue Date:** 10/11/2018

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6371972&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Approval of the Further Characterization of Soil Quality Report (Lampblack Area)				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		10/9/2018				
<b>Received Issue Date:</b>		10/9/2018				
<b>Action:</b>		Interim Remedial Action Plan				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5977147				
<b>Title Description Comments:</b>		Interim Work Plan for Soil Remediation				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		10/9/2018				
<b>Received Issue Date:</b>		10/9/2018				
<b>Action:</b>		Site Investigation Workplan				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5977146				
<b>Title Description Comments:</b>		Proposed Work Plan for Soil Vapor and Groundwater Testing				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		10/9/2018				
<b>Received Issue Date:</b>		10/9/2018				
<b>Action:</b>		Well Destruction Workplan				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5977148				
<b>Title Description Comments:</b>		Workplan for Destruction of Monitoring Wells				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		9/18/2018				
<b>Received Issue Date:</b>		9/18/2018				
<b>Action:</b>		Preliminary Site Assessment Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5975224				
<b>Title Description Comments:</b>		Phase II Environmental Assessment				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		9/18/2018				
<b>Received Issue Date:</b>		9/18/2018				
<b>Action:</b>		Preliminary Site Assessment Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5975225				
<b>Title Description Comments:</b>		Supplemental Phase II Environmental Assessment				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		9/18/2018				
<b>Received Issue Date:</b>		9/18/2018				
<b>Action:</b>		Email Correspondence				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5975226				
<b>Title Description Comments:</b>		Maps of Proposed Redevelopment and Isoconcentrations				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/29/2018				
<b>Received Issue Date:</b>		6/29/2018				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action:</b>		Annual Estimation Letter				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6366007&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6366007&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
Annual Estimate Letter FY 2018-2019						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		5/8/2018				
<b>Received Issue Date:</b>		5/8/2018				
<b>Action:</b>		Technical Correspondence / Assistance / Other				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6357284&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6357284&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
Approval of Proposed Work Plan for Soil Vapor Testing Work and Request for completion report.						
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		5/7/2018				
<b>Received Issue Date:</b>		5/7/2018				
<b>Action:</b>		Soil Vapor Intrusion Investigation Workplan				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&amp;doc_id=5964097">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&amp;doc_id=5964097</a>				
<b>Title Description Comments:</b>						
Proposed Work Plan for Soil Vapor Testing						
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		5/3/2018				
<b>Received Issue Date:</b>		5/3/2018				
<b>Action:</b>		Site Investigation Workplan				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&amp;doc_id=5964103">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&amp;doc_id=5964103</a>				
<b>Title Description Comments:</b>						
Proposed Work Plan for Further Characterization of Lampblack Area, 575 Benton Street, Santa Clara						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		5/3/2018				
<b>Received Issue Date:</b>		5/3/2018				
<b>Action:</b>		Technical Correspondence / Assistance / Other				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6356831&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6356831&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
Conditional Approval of Lampblack Investigation Workplan and Request for Completion Report by June 15, 2018						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		4/30/2018				
<b>Received Issue Date:</b>		4/30/2018				
<b>Action:</b>		Meeting				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6356605&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6356605&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
Telephone meeting to discuss Lampblack Investigation Workplan scope of investigation and additional information showing areas to be sampled.						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/30/2017				
<b>Received Issue Date:</b>		6/30/2017				
<b>Action:</b>		Annual Estimation Letter				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6325243&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6325243&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
Annual Estimate Letter FY 2017-2018						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/28/2017  
**Received Issue Date:** 6/28/2017  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6324780&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6324780&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Work Plan Addendum - Mission Town Center - Viso Property, Santa Clara. Approval of additional ORC treatment, monitoring, and revised submittal date completion report to March 1, 2018.

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/6/2016  
**Received Issue Date:** 10/6/2016  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6300329&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6300329&temptable=ENFORCEMENT)

**Title Description Comments:**

Conditional Approval of Interim Remedial Measures – Former Tank Area (Workplan)

**Action Type:** Response Requested - Other  
**Action Date:** 9/7/2016  
**Received Issue Date:** 9/7/2016  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000008392&doc\\_id=5900920](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5900920)

**Title Description Comments:**

Signed copy of the cost recovery agreement by Prometheus Real Estate Group, Inc.

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/29/2016  
**Received Issue Date:** 8/29/2016  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6296507&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6296507&temptable=ENFORCEMENT)

**Title Description Comments:**

Site Cleanup Program Cost Recovery Letter

**Action Type:** Response Requested - Workplans  
**Action Date:** 8/23/2016  
**Received Issue Date:** 8/23/2016  
**Action:** Interim Remedial Action Plan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000008392&doc\\_id=5902176](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5902176)

**Title Description Comments:**

Interim Remedial Measures - Former Tank Area

**Action Type:** Response Requested - Other  
**Action Date:** 5/26/2016  
**Received Issue Date:** 5/26/2016  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000008392&doc\\_id=5893496](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000008392&doc_id=5893496)

**Title Description Comments:**

Notification of project cancellation and request for cost recovery termination.

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/11/2016  
**Received Issue Date:** 2/11/2016  
**Action:** Meeting  
**Doc Link:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Title Description Comments:**

Initial project management meeting to discuss proposed project and time schedule.

**Action Type:** Agreements  
**Action Date:** 1/15/2016  
**Received Issue Date:** 1/15/2016  
**Action:** Cost Recovery Agreement / N. of Reimbursement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6275042&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6275042&temptable=ENFORCEMENT)

**Title Description Comments:**

Site Cleanup Program cost recovery letter with signed Acknowledgment Letter (Attachment3)

**Action Type:** Leak Action  
**Action Date:** 11/12/2015  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**

**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 1/1/1997  
**Received Issue Date:**  
**Action:** Leak Began  
**Doc Link:**

**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 1/1/1997  
**Received Issue Date:**  
**Action:** Leak Discovery  
**Doc Link:**

**Title Description Comments:**

**Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents  
**Document Date:** 9/9/2021  
**Submitted:** MICHAEL ROCHETTE (REGULATOR)  
**Submitted By:**  
**Size :**  
**Title:** APPROVAL OF RISK MANAGEMENT PLAN, MISSION TOWN CENTER, SANTA CLARA \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6475644](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6475644)  
**Type:** STAFF LETTER

**Document Type:** Site Documents  
**Document Date:** 7/26/2021  
**Submitted:** MICHAEL ROCHETTE (REGULATOR)  
**Submitted By:**  
**Size :**  
**Title:** ANNUAL ESTIMATE LETTER FY 2021/2022 \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6471969](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6471969)  
**Type:** ANNUAL ESTIMATION LETTER

**Document Type:** Site Documents  
**Document Date:** 6/17/2021  
**Submitted:** AUSTIN CLOWDUS (AUTH\_RP)  
**Submitted By:**  
**Size :** 1,300 KB  
**Title:** RISK MANAGEMENT PLAN \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/9885353803/T10000008392.PDF](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9885353803/T10000008392.PDF)  
**Type:** OTHER REPORT / DOCUMENT

**Document Type:** Site Documents  
**Document Date:** 2/17/2021  
**Submitted:** MICHAEL ROCHETTE (REGULATOR)  
**Submitted By:**  
**Size :**  
**Title:** APPROVAL OF THE 2020 SITE COMPLETION REPORT \*\*Note: Many records provided by the department have

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>					a truncated [Title] field.	
<b>Type:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6457819">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6457819</a>	
					STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	10/30/2020				<b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Size :</b>	50,003 KB					
<b>Title:</b>	2020 SITE COMPLETION REPORT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1806071400/T10000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1806071400/T10000008392.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/30/2020				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	ANNUAL ESTIMATE LETTER FY 2020/2021 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6440875">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6440875</a>					
<b>Type:</b>	ANNUAL ESTIMATION LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/26/2020				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	FACT SHEET 1250 SHERMAN STREET, MISSION TOWN CENTER **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6439569">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6439569</a>					
<b>Type:</b>	NOTIFICATION - PUBLIC PARTICIPATION DOCUMENT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	4/22/2020				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL LETTER FOR THE MARCH 20, 2020, SOIL VAPOR TESTING REPORT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6433206">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6433206</a>					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/20/2020				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL OF FOCUSED FEASIBILITY STUDY AND REQUEST FOR FACT SHEET. ADDRESSES ELEVATED LEAD CONCENTRATIONS AT 1250 SHERMAN STREET WITHIN THE MISSION TOWN CENTER REDEVELOPMENT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6430633">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6430633</a>					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/20/2020				<b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Size :</b>	4,453 KB					
<b>Title:</b>	2020 SOIL VAPOR TESTING REPORT - FORMER VISO PROPERTY, SANTA CLARA **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1426219105/T10000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1426219105/T10000008392.PDF</a>					
<b>Type:</b>	SOIL VAPOR INTRUSION INVESTIGATION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/12/2020				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	RESPONSE TO EMAIL REGARDING REVIEW OF FOCUSED FEASIBILITY STUDY REPORT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6430137">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6430137</a>					
<b>Type:</b>	EMAIL CORRESPONDENCE					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/6/2020				<b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Size :</b>	8,745 KB					
<b>Title:</b>	FOCUSED FEASIBILITY STUDY REPORT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5516191959/T10000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5516191959/T10000008392.PDF</a>					
<b>Type:</b>	FEASIBILITY STUDY (FS)					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 2/14/2020				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF SOIL GAS SAMPLING LOCATIONS FOR OXYGEN CONCENTRATIONS **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6427413">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6427413</a> EMAIL CORRESPONDENCE					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 2/11/2020				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	RESPONSE TO PROPOSED SOIL CAPPING IN 1250 SHERMAN STREET AREA AND VIMS IN FORMER UST AREA. APPROVAL OF THE PROPOSED OPTION 1 IF A FOCUSED FEASIBILITY STUDY IS SUBMITTED. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6427011">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6427011</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 1/29/2020				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	EMAIL RESPONSE TO REQUEST FOR A MEETING WITH THE WATER BOARD **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6426129">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6426129</a> EMAIL CORRESPONDENCE					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/23/2019				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF WORKPLAN FOR SOIL STOCKPILE SAMPLING PROCEDURE FOR ONSITE SOIL REUSE. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6418279">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6418279</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 9/5/2019				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	EMAIL APPROVAL OF REQUEST FOR A TIME EXTENSION TO SUBMIT THE VAPOR INTRUSION INVESTIGATION COMPLETION REPORT FROM SEPTEMBER 30, 2019, TO NOVEMBER 15, 2019 **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6414026">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6414026</a> EMAIL CORRESPONDENCE					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 7/26/2019				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF JULY 15, 2019, PROPOSED WORK PLAN FOR VAPOR INTRUSION INVESTIGATION FOR THE FORMER VISO PROPERTY AND REQUESTS FOR A COMPLETION REPORT BY SEPTEMBER 30, 2019 **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6410009">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6410009</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 7/26/2019* 655 KB				<b>Submitted:</b> <b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Title Link:</b> <b>Type:</b>	PROPOSED WORK PLAN FOR VAPOR INTRUSION INVESTIGATION **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4285583734/T1000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4285583734/T1000008392.PDF</a> SOIL VAPOR INTRUSION INVESTIGATION WORKPLAN					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 7/25/2019				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Title Link:</b> <b>Type:</b>	ANNUAL ESTIMATE LETTER FY 2019/2020 **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6409915">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&amp;enforcement_id=6409915</a> ANNUAL ESTIMATION LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 6/25/2019				<b>Submitted:</b> <b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
APPROVAL OF THE SOIL VAPOR TESTING REPORT AND REQUEST FOR A VAPOR INTRUSION						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>					INVESTIGATION WORKPLAN BY AUGUST 30, 2019.	
<b>Type:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6407086 STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/25/2019				<b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Size :</b>	2,880 KB					
<b>Title:</b>	2019 SOIL VAPOR TESTING REPORT - VISO PROPERTY **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6039022624/T10000008392.PDF					
<b>Type:</b>	SPECIAL STUDIES AND INVESTIGATIONS					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/3/2019				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	DENIAL OF REQUEST TO USE 2016 ESLS **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6403931					
<b>Type:</b>	EMAIL CORRESPONDENCE					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/7/2019				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL OF TIME EXTENSION FOR THE SUBMITTAL OF THE SOIL VAPOR SAMPLING COMPLETION REPORT TO JUNE 17, 2019.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6401309					
<b>Type:</b>	DEADLINE EXTENSION					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/27/2019				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	CONDITIONAL APPROVAL OF PROPOSED SOIL VAPOR SAMPLING WORKPLAN - WITH REVISED SAMPLING LOCATIONS.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6397466					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/18/2019				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL OF THE FEBRUARY 28, 2019, SOIL MANAGEMENT PLAN ADDENDUM **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6388367					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/18/2019				<b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Size :</b>	1,579 KB					
<b>Title:</b>	PROPOSED WORK PLAN FOR ADDITIONAL SOIL VAPOR TESTING **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8551766455/T10000008392.PDF					
<b>Type:</b>	SOIL VAPOR INTRUSION INVESTIGATION WORKPLAN					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	2/28/2019				<b>Submitted By:</b>	AUSTIN CLOWDUS (AUTH_RP)
<b>Size :</b>	2,325 KB					
<b>Title:</b>	SOIL MANAGEMENT PLAN ADDENDUM, PROMETHEUS REDEVELOPMENT PROJECT, FEBRUARY 2019 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6141039371/T10000008392.PDF					
<b>Type:</b>	OTHER REPORT / DOCUMENT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	1/31/2019				<b>Submitted By:</b>	MICHAEL ROCHETTE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL OF SOIL MANAGEMENT PLAN AND (13267) REQUIREMENT FOR REPORTS **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6384279					
<b>Type:</b>	13267 REQUIREMENT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Date:</b> <b>Size :</b> <b>Title:</b>	1/10/2019 2,749 KB				<b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>	SOIL MANAGEMENT PLAN, PROMETHEUS REDEVELOPMENT PROJECT, JANUARY 2018 **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3747061610/T10000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3747061610/T10000008392.PDF</a> PROPOSED PLAN					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 11/30/2018 3,918 KB				<b>Submitted:</b> <b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>	FURTHER CHARACTERIZATION OF SV AND GW - FORMER VISO PROPERTY **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3958191156/T10000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3958191156/T10000008392.PDF</a> SITE INVESTIGATION					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 11/30/2018 302 KB				<b>Submitted:</b> <b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>	WELL DESTRUCTION REPORT - FORMER VISO PROPERTY **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3111062109/T10000008392.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3111062109/T10000008392.PDF</a> WELL DESTRUCTION REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 11/8/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	REJECTION OF SOIL MANAGEMENT PLAN AND REQUIREMENT FOR REVISED SMP (DUE JAN. 18, 2019) **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6375275">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6375275</a> 13267 REQUIREMENT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/18/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF WORK PLAN FOR DESTRUCTION OF MONITORING WELLS AND REQUESTS FOR A COMPLETION REPORT (DUE NOVEMBER 30, 2018) **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372866">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372866</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/18/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	CONDITIONALLY APPROVAL OF PROPOSED WORK PLAN FOR SOIL VAPOR AND GROUNDWATER TESTING, AND REQUEST FOR A COMPLETION REPORT (DUE NOVEMBER 30, 2018) **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372860">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372860</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/16/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF REMEDIAL EFFECTIVENESS EVALUATION REPORT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372506">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372506</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/15/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF SOIL VAPOR INVESTIGATION REPORT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372362">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&amp;enforcement_id=6372362</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/11/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF THE FURTHER CHARACTERIZATION OF SOIL QUALITY REPORT (LAMPBLACK AREA) **Note: Many records provided by the department have a truncated [Title] field.					

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b> <b>Type:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&enforcement_id=6371972 STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/9/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					PROPOSED WORK PLAN FOR SOIL VAPOR AND GROUNDWATER TESTING **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&document_id=5977146 SITE INVESTIGATION WORKPLAN	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/9/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					WORKPLAN FOR DESTRUCTION OF MONITORING WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&document_id=5977148 WELL DESTRUCTION WORKPLAN	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/9/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					INTERIM WORK PLAN FOR SOIL REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&document_id=5977147 INTERIM REMEDIAL ACTION PLAN	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 9/18/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					PHASE II ENVIRONMENTAL ASSESSMENT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&document_id=5975224 PRELIMINARY SITE ASSESSMENT REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 9/18/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					MAPS OF PROPOSED REDEVELOPMENT AND ISOCONCENTRATIONS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&document_id=5975226 EMAIL CORRESPONDENCE	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 9/18/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					SUPPLEMENTAL PHASE II ENVIRONMENTAL ASSESSMENT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000008392&document_id=5975225 PRELIMINARY SITE ASSESSMENT REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/23/2018 1,914 KB				<b>Submitted:</b> <b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>					2018 SOIL VAPOR INVESTIGATION REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5254660487/T1000008392.PDF SOIL VAPOR INTRUSION INVESTIGATION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/23/2018 5,411 KB				<b>Submitted:</b> <b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>					SOIL MANAGEMENT PLAN, PROMETHEUS REDEVELOPMENT PROJECT, JULY 2018 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3849428653/T1000008392.PDF OTHER WORKPLAN	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 8/23/2018				<b>Submitted:</b> <b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Size :</b> <b>Title:</b>	2,760 KB					
<b>Title Link:</b> <b>Type:</b>	FURTHER CHARACTERIZATION OF SOIL QUALITY **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6988641560/T10000008392.PDF SITE INVESTIGATION					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/23/2018 902 KB				<b>Submitted:</b> <b>Submitted By:</b> AUSTIN CLOWDUS (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>	REMEDIAL EFFECTIVENESS EVALUATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1691259980/T10000008392.PDF REMEDIAL PROGRESS REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 6/29/2018				<b>Submitted:</b> <b>Submitted By:</b> MADELEINE LITTLE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	ANNUAL ESTIMATE LETTER FY 2018-2019 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6366007 ANNUAL ESTIMATION LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/8/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF PROPOSED WORK PLAN FOR SOIL VAPOR TESTING WORK AND REQUEST FOR COMPLETION REPORT. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6357284 TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/7/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	PROPOSED WORK PLAN FOR SOIL VAPOR TESTING **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&document_id=5964097 SOIL VAPOR INTRUSION INVESTIGATION WORKPLAN					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/3/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	PROPOSED WORK PLAN FOR FURTHER CHARACTERIZATION OF LAMPBLACK AREA, 575 BENTON STREET, SANTA CLARA **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&document_id=5964103 SITE INVESTIGATION WORKPLAN					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/3/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	CONDITIONAL APPROVAL OF LAMPBLACK INVESTIGATION WORKPLAN AND REQUEST FOR COMPLETION REPORT BY JUNE 15, 2018 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6356831 TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 4/30/2018				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL ROCHETTE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	TELEPHONE MEETING TO DISCUSS LAMPBLACK INVESTIGATION WORKPLAN SCOPE OF INVESTIGATION AND ADDITIONAL INFORMATION SHOWING AREAS TO BE SAMPLED. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6356605 MEETING					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 6/30/2017				<b>Submitted:</b> <b>Submitted By:</b> SUNNY GRUNLOH (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	ANNUAL ESTIMATE LETTER FY 2017-2018 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6325243 ANNUAL ESTIMATION LETTER					

**Document Type:** Site Documents  
**Document Date:** 6/29/2017\*  
**Size :** 190 KB  
**Title:** ADDENDUM FOR INTERIM REMEDIAL MEASURES - FORMER TANK AREA \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/3455736160/T10000008392.PDF](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3455736160/T10000008392.PDF)  
**Type:** CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN - ADDENDUM

**Document Type:** Site Documents  
**Document Date:** 6/28/2017  
**Size :**  
**Title:** APPROVAL OF WORK PLAN ADDENDUM - MISSION TOWN CENTER - VISO PROPERTY, SANTA CLARA. APPROVAL OF ADDITIONAL ORC TREATMENT, MONITORING, AND REVISED SUBMITTAL DATE COMPLETION REPORT TO MARCH 1, 2018.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6324780](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6324780)  
**Type:** STAFF LETTER

**Document Type:** Site Documents  
**Document Date:** 10/6/2016  
**Size :**  
**Title:** CONDITIONAL APPROVAL OF INTERIM REMEDIAL MEASURES – FORMER TANK AREA (WORKPLAN) \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6300329](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6300329)  
**Type:** STAFF LETTER

**Document Type:** Site Documents  
**Document Date:** 9/7/2016  
**Size :**  
**Title:** SIGNED COPY OF THE COST RECOVERY AGREEMENT BY PROMETHEUS REAL ESTATE GROUP, INC.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&document\\_id=5900920](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&document_id=5900920)  
**Type:** CORRESPONDENCE

**Document Type:** Site Documents  
**Document Date:** 8/29/2016  
**Size :**  
**Title:** SITE CLEANUP PROGRAM COST RECOVERY LETTER \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6296507](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6296507)  
**Type:** STAFF LETTER

**Document Type:** Site Documents  
**Document Date:** 8/23/2016  
**Size :**  
**Title:** INTERIM REMIDAL MEASURES - FORMER TANK AREA \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&document\\_id=5902176](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&document_id=5902176)  
**Type:** INTERIM REMEDIAL ACTION PLAN

**Document Type:** Site Documents  
**Document Date:** 5/26/2016  
**Size :**  
**Title:** NOTIFICATION OF PROJECT CANCELLATION AND REQUEST FOR COST RECOVERY TERMINATION.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&document\\_id=5893496](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&document_id=5893496)  
**Type:** CORRESPONDENCE

**Document Type:** Site Documents  
**Document Date:** 1/15/2016  
**Size :**  
**Title:** SITE CLEANUP PROGRAM COST RECOVERY LETTER WITH SIGNED ACKNOWLEDGMENT LETTER (ATTACHMENT3) \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000008392&enforcement\\_id=6275042](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000008392&enforcement_id=6275042)  
**Type:** COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT

**Sites from GeoTracker Search - Cleanup Status History (as of Sep 15, 2021)**

**Status:** Open - Remediation  
**Date:** 8/7/2019

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Status:</b>		Open - Remediation				
<b>Date:</b>		10/9/2018				
<b>Status:</b>		Open - Site Assessment				
<b>Date:</b>		1/9/2018				
<b>Status:</b>		Open - Assessment & Interim Remedial Action				
<b>Date:</b>		1/9/2017				
<b>Status:</b>		Open - Inactive				
<b>Date:</b>		6/6/2016				
<b>Status:</b>		Open - Site Assessment				
<b>Date:</b>		1/28/2016				
<b>Status:</b>		Open - Case Begin Date				
<b>Date:</b>		1/1/1997				

<a href="#">49</a>	1 of 1	E	0.47 / 2,490.31	65.27 / -10	ZAZZLE.COM INC 1185 CAMPBELL AV SAN JOSE CA 95126	DELISTED HAZ
--------------------	--------	---	--------------------	----------------	---	-----------------

**Siteid:** 172836  
**Latitude:** 37.346900  
**Longitude:** -121.929770  
**Original Source:** CHAZ  
**Record Date:** 30-MAY-2017

<a href="#">50</a>	1 of 2	E	0.47 / 2,504.19	66.66 / -8	AJ COMMERCIAL LAUNDRY/ALL CHEM SUPPLY 1173-1175 CAMPBELL AVENUE SAN JOSE CA 95126	RESPONSE
--------------------	--------	---	--------------------	---------------	--	----------

<b>Estor/EPA ID:</b>	60000133	<b>Permit Renewal Lead:</b>	
<b>Site Code:</b>	201631	<b>Project Manager:</b>	NICOLE YUEN
<b>Nat Priority List:</b>	NO	<b>Supervisor:</b>	JOHN KARACHEWSKI
<b>Acres:</b>	2 ACRES	<b>Public Partici Spclst:</b>	
<b>Special Program:</b>		<b>Census Tract:</b>	6085505203
<b>Funding:</b>	RESPONSIBLE PARTY	<b>County:</b>	SANTA CLARA
<b>Assembly District:</b>	28	<b>Latitude:</b>	37.3462716038083
<b>Senate District:</b>	10	<b>Longitude:</b>	-121.928331537851
<b>School District:</b>			
<b>APN:</b>	230-13-008, 230-13-009, 23013008, 23013009		
<b>Cleanup Status:</b>	ACTIVE AS OF 4/19/2005		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>Site Type:</b>	STATE RESPONSE OR NPL		
<b>Office:</b>	CLEANUP BERKELEY		
<b>Past Use that Caused Contam:</b>	LAUNDRY SERVICES		
<b>Potential Media Affected:</b>	OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER)		
<b>Potential Contamin of Concern:</b>			

1,2-DICHLOROETHYLENE (CIS) TPH-GAS TETRACHLOROETHYLENE (PCE) TRICHLOROETHYLENE (TCE) VINYL CHLORIDE

**Site History:**

The property has two parcels, each approximately 1.0 acre. 1175 Campbell Avenue is identified by Santa Clara County Assessor's Parcel Number 23013008. It has 2 warehouse type buildings, which are 19,000 square feet in size. 1173 Campbell Avenue is identified by Santa Clara County Assessor's Parcel Number 23013009. It has 3 warehouse type buildings, which are 19,000 square feet in size. The buildings on the site were built in 1956/1957. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of mixed commercial/ industrial and residential developments. DTSC issued an Imminent and Substantial Endangerment Order for the Site on June 27, 2006 after a Site investigation in May 2005 revealed elevated levels of petroleum compounds, metals, and chlorinated volatile organic compounds in the groundwater. In January 2010, a dual-phase extraction system was operated for 9 months, removing contaminated groundwater and soil vapor. In May 2015, another round of extraction started and ran for approximately one year. Groundwater, soil vapor, and soil samples have been collected from the Site at various times since 2005. Further investigation is planned at the Site to evaluate potential off-Site impacts, but work has been paused due to lack of funding. 9/2021, NY

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Status:** ACTIVE  
**Program Type:** STATE RESPONSE  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=60000133](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60000133)

**Completed Activities**

**Title:** Notice of Exemption  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=60000133&enforcement\\_id=6013460](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&enforcement_id=6013460)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** CEQA - Notice of Exemption  
**Date Completed:** 1/13/2010  
**Comments:** CEQA Notice of Exemption for Interim Dual Phase Extraction System signed by DTSC.

**Title:** Groundwater Sampling  
**Title Link:**  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Fieldwork  
**Date Completed:** 11/27/2018  
**Comments:** Groundwater sampling was conducted at the Site on November 26 and 27, 2018.

**Title:** Fieldwork for Rebound Study  
**Title Link:**  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Fieldwork  
**Date Completed:** 10/27/2012  
**Comments:** First rebound study sampling event completed.

**Title:** Order Amendment for PDF Files  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=60000133&enforcement\\_id=6010564](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&enforcement_id=6010564)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Amendment - Order/Agreement  
**Date Completed:** 2/21/2007  
**Comments:** Order amendment was done for PDF submittal of documents.

**Title:** Investigation Workplan (Onsite)  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=60000133&doc\\_id=6016553](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&doc_id=6016553)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Remedial Investigation Workplan  
**Date Completed:** 2/7/2008  
**Comments:** Onsite sampling investigations include soil and groundwater and indoor air survey.

**Title:** Remedial Investigation Workplan  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=60000133&doc\\_id=6013221](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&doc_id=6013221)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Remedial Investigation Workplan  
**Date Completed:** 11/17/2006  
**Comments:** Workplan approved requiring groundwater monitoring wells installation, soil, and soil gas sampling.

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Groundwater Monitoring Report: Second Semi-Annual 2015	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60405336">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60405336</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Monitoring Report	
<b>Date Completed:</b>					4/27/2016	
<b>Comments:</b>					The Groundwater Monitoring Report - Second Semi-Annual 2015 summarizes groundwater monitoring activities completed in November and December 2015 and provides a progress report for the dual-phase extraction system. Due to recent rains, shallower wells that were previously dry were sampled.	
<b>Title:</b>					Historical Research and Environmental Sampling Work Plan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60444199">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60444199</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Workplan	
<b>Date Completed:</b>					5/31/2018	
<b>Comments:</b>						
<b>Title:</b>					1st 2018 Semi-Annual Groundwater and Soil Vapor Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60446859">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60446859</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					8/22/2018	
<b>Comments:</b>						
<b>Title:</b>					I&SE Order	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6008184">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6008184</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Unilateral Order (I/SE, RAO, CAO, EPA AO)	
<b>Date Completed:</b>					6/27/2006	
<b>Comments:</b>						
<b>Title:</b>					Sumps Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60385177">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60385177</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Correspondence	
<b>Date Completed:</b>					11/7/2014	
<b>Comments:</b>					Georestation, Inc. submitted a letter informing DTSC of the current property owners intent to fill sumps located in the southwestern portion of the site with clean, small pieces of concrete mixed with base rock and then placing inches of concrete to grade above the fill. The identified purpose of filling the sumps was to eliminate a physical hazard. DTSC provided approval to proceed in its response letter.	
<b>Title:</b>					Soil Gas Sampling	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					7/1/2016	
<b>Comments:</b>					Additional soil gas wells were installed and soil gas sampling to determine remediation progress was completed.	
<b>Title:</b>					Com. Profile & Mailing List	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6016559">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6016559</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Community Profile						
<b>Date Completed:</b> 2/1/2008						
<b>Comments:</b> The key contacts for the site has been updated.						
<b>Title:</b> Interim Removal Action Workplan						
<b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022198">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022198</a>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Removal Action Workplan						
<b>Date Completed:</b> 1/13/2010						
<b>Comments:</b> RAW approved for installation of an Interim Dual Phase Extraction System with one revision to page 18 of the Health and Safety Plan.						
<b>Title:</b> Soil Gas and Groundwater Sampling						
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Fieldwork						
<b>Date Completed:</b> 5/22/2015						
<b>Comments:</b> The soil gas and groundwater sampling activities outlined in the Workplan for Soil Gas and Groundwater Sampling approved by DTSC on May 13, 2015 was completed.						
<b>Title:</b> Annual Oversight Cost Estimate Letter						
<b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60397302">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60397302</a>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Annual Oversight Cost Estimate						
<b>Date Completed:</b> 9/21/2015						
<b>Comments:</b>						
<b>Title:</b> DTSC Response to Project Schedule Update Letter						
<b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60408510">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60408510</a>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Correspondence						
<b>Date Completed:</b> 5/2/2016						
<b>Comments:</b> DTSC sent a letter to 1175 Campbell Avenue, LLC, the responsible party, that approved the updated project schedule outlined in a February 10, 2016 letter from GeoRestoration, Inc. DTSC agreed that the dual-phase extraction system should run until the Bay Area Air Quality District permit expired at the end of May 2016. After system shutdown, soil sampling would be performed after a one-month period to provide data to assess the progress of remediation.						
<b>Title:</b> Groundwater Monitoring Report, 1st Semi Annual 2017						
<b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60431210">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60431210</a>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Site Characterization Report						
<b>Date Completed:</b> 12/12/2017						
<b>Comments:</b>						
<b>Title:</b> Fact Sheet						
<b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022572">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022572</a>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b> Fact Sheets						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date Completed:</b>		10/21/2009				
<b>Comments:</b>		Fact sheet for Draft RAW				
<b>Title:</b>		Amendment to I&SE Order				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60358646">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60358646</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Amendment - Order/Agreement				
<b>Date Completed:</b>		1/7/2015				
<b>Comments:</b>		DTSC issued an Amendment to Imminent and Substantial Endangerment Order and Remedial Action Order, Docket No. I&SE 05/06-012, which was issued in 2006. The Amendment added 1175 Campbell Avenue, LLC, the new Site owner, and the Estate of Jonnie Lindsell as responsible parties.				
<b>Title:</b>		Cost Estimate 2011-2012				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60287488">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60287488</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		12/14/2011				
<b>Comments:</b>						
<b>Title:</b>		Rebound Study: Preliminary Data				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60327782">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60327782</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Technical Report				
<b>Date Completed:</b>		6/27/2013				
<b>Comments:</b>		Raw lab data from rebound study sampling.				
<b>Title:</b>		Off-Site Characterization Workplan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60258775">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60258775</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Workplan				
<b>Date Completed:</b>		11/8/2011				
<b>Comments:</b>		Report approved.				
<b>Title:</b>		Annual Oversight Cost Estimate for FY20-21				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60483066">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60483066</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/9/2020				
<b>Comments:</b>		DTSC's annual estimate of oversight costs for the 2020-2021 fiscal year.				
<b>Title:</b>		3rd Quarter 2019 Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60472209">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60472209</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Report				
<b>Date Completed:</b>		3/5/2020				
<b>Comments:</b>						
<b>Title:</b>		Groundwater Monitoring Report - 1st Semi-Annual 2016				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396471">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396471</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Technical Report			
<b>Date Completed:</b>			3/14/2017			
<b>Comments:</b>						
<b>Title:</b>			Public Notice			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022573">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022573</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Public Notice			
<b>Date Completed:</b>			10/21/2009			
<b>Comments:</b>			Public Notice for Draft RAW			
<b>Title:</b>			Field Investigation			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			2/15/2013			
<b>Comments:</b>			On-site groundwater sampled as part of ongoing rebound study.			
<b>Title:</b>			Cost Estimate 2012-2013			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60325163">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60325163</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			11/1/2012			
<b>Comments:</b>			Annual DTSC oversight cost estimate sent to responsible party.			
<b>Title:</b>			Work Plan for Off-Site Investigation			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60482061">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60482061</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Workplan			
<b>Date Completed:</b>			8/21/2020			
<b>Comments:</b>			Off-Site investigation workplan proposes installing soil vapor wells along the site boundary, grab groundwater samples near a previous historical sample that contained chlorinated volatile organic compounds, and decommissioning previously-approved groundwater monitoring wells.			
<b>Title:</b>			Site Investigation Report -- Offsite Groundwater Sampling			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60475552">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60475552</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Report			
<b>Date Completed:</b>			9/27/2013			
<b>Comments:</b>			Report summarizes the results of offsite groundwater sampling.			
<b>Title:</b>			2012 2nd Quarter Semi-Annual Groundwater Monitoring Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60445385">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60445385</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Report			
<b>Date Completed:</b>			8/2/2012			
<b>Comments:</b>			The semi-annual groundwater monitoring report summarizes the groundwater monitoring activities conducted at the Site during the second quarter of 2012 by SGI.			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Work Notice	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60194464">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60194464</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Public Notice	
<b>Date Completed:</b>					1/25/2010	
<b>Comments:</b>						
<b>Title:</b>					Soil and Groundwater Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6015456">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6015456</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					9/20/2007	
<b>Comments:</b>					Additional investigation is required which includes defining the lateral and vertical extent of groundwater contamination, and investigating the source of TPH contamination around MW-3.	
<b>Title:</b>					Annual Oversight Cost Estimate	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60414599">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60414599</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/23/2016	
<b>Comments:</b>					DTSC letter with oversight cost estimate for fiscal year 2016/2017	
<b>Title:</b>					Project Schedule Update Letter	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Correspondence	
<b>Date Completed:</b>					2/10/2016	
<b>Comments:</b>					Letter from GeoRestoration details the proposed schedule for shutdown of the dual phase extraction system and soil gas and groundwater sampling and reporting.	
<b>Title:</b>					Amendment to Ground Water Monitoring Schedule	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60459438">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60459438</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Workplan	
<b>Date Completed:</b>					3/5/2020	
<b>Comments:</b>						
<b>Title:</b>					Sampling Report (Onsite)	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018177">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018177</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Remedial Investigation Report	
<b>Date Completed:</b>					8/15/2008	
<b>Comments:</b>					Indoor air survey results indicate VOC levels are elevated and above the screening levels. An Expedited Removal Action and additional offsite groundwater investigation are recommended for the site.	
<b>Title:</b>					Site Investigation Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60460194">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60460194</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Type:</b>		Site Characterization Report				
<b>Date Completed:</b>		5/27/2020				
<b>Comments:</b>						
<b>Title:</b>		Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386221">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386221</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Technical Report				
<b>Date Completed:</b>		11/5/2015				
<b>Comments:</b>		The Groundwater Monitoring Report, First Semi-Annual 2015 summarizes groundwater monitoring activities completed in May 2015. Select monitoring wells in areas with remaining elevated volatile organic compounds were sampled to evaluate current groundwater conditions and to provide a baseline to track progress for the remediation that was restarted in May 2015. Wells with a total depth of 20 feet or less were dry or had small amounts of groundwater and were not sampled.				
<b>Title:</b>		Letter from RP to Lt. Governor				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60276737">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60276737</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		*Correspondence - Received				
<b>Date Completed:</b>		9/2/2011				
<b>Comments:</b>		The Site owner sent a letter to Lt. Governor Gavin Newsom regarding the investigation and cleanup of the Site.				
<b>Title:</b>		Annual Oversight Cost Estimate Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60447311">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60447311</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/25/2018				
<b>Comments:</b>		Annual cost estimate letter estimating DTSC's oversight costs for the 2018 to 2019 fiscal year.				
<b>Title:</b>		Proposed Determination of Non Compliance				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6009681">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6009681</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Proposed Determination of non-compliance				
<b>Date Completed:</b>		8/2/2006				
<b>Comments:</b>		Proposed Determination of Non Compliance issued. Respondent's request for a 12 month extension denied. Extension to comply granted through August 31, 2006.				
<b>Title:</b>		Soil Gas & Groundwater Sampling Work Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386209">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386209</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Technical Workplan				
<b>Date Completed:</b>		5/13/2015				
<b>Comments:</b>						
<b>Title:</b>		2nd 2018 Semi-Annual Groundwater Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60448422">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60448422</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Report				
<b>Date Completed:</b>		3/5/2020				
<b>Comments:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Resumption of Dual-Phase Extraction / RAW Implementation	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			6/1/2015			
<b>Comments:</b>			Dual-phase extraction was restarted on the site.			
<b>Title:</b>					Rebound Study Workplan: Groundwater Monitoring and Soil Vapor Sampling	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Workplan			
<b>Date Completed:</b>			11/2/2012			
<b>Comments:</b>			The Workplan outlines groundwater and soil vapor sampling to determine current subsurface conditions at the site following cessation of dual phase extraction and soil vapor extraction in December 2011.			
<b>Title:</b>					Soil Gas Survey Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6013284">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6013284</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Report			
<b>Date Completed:</b>			9/20/2007			
<b>Comments:</b>			Additional investigation is required which includes onsite indoor air sampling.			
<b>Title:</b>					Fieldwork (Interim RAW)	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			5/26/2010			
<b>Comments:</b>			inspection completed			
<b>Title:</b>					Annual Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60255699">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60255699</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			9/29/2010			
<b>Comments:</b>						
<b>Title:</b>					Preliminary Groundwater Sampling and Testing Investigation Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447051">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447051</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Report			
<b>Date Completed:</b>			8/15/2005			
<b>Comments:</b>			The report presents the results of preliminary groundwater sampling at the site and was submitted to the California Office of Emergency Services who referred it to the Emergency Response Division at DTSC. This report was completed prior to the issuance of an order for the site and not performed under DTSC's oversight.			
<b>Title:</b>					Report for Site Investigation, Well Installation, and Remediation Progress	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60261873">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60261873</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Type:</b>					Removal Action Completion Report	
<b>Date Completed:</b>					1/26/2012	
<b>Comments:</b>						
<b>Title:</b>					Geophysical Investigation Results and Work Plan for Additional Investigation	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447784">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447784</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Workplan	
<b>Date Completed:</b>					9/21/2018	
<b>Comments:</b>						
<b>Title:</b>					Fieldwork	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					2/29/2008	
<b>Comments:</b>					Fieldwork included soil and groundwater investigations, and indoor soil gas survey.	
<b>Title:</b>					Site Screening	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6007946">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6007946</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Screening	
<b>Date Completed:</b>					10/20/2005	
<b>Comments:</b>					In-house site screening report approved which determined that further action is needed.	
<b>Title:</b>					Soil Gas Sampling Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396473">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396473</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Technical Report	
<b>Date Completed:</b>					3/13/2017	
<b>Comments:</b>						
<b>Title:</b>					Offsite Investigation Workplan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018181">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018181</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Remedial Investigation Workplan	
<b>Date Completed:</b>					3/15/2010	
<b>Comments:</b>					approved	
<b>Title:</b>					On-Site Soilgas and Groundwater Sampling	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					1/8/2007	
<b>Comments:</b>					Fieldwork is complete which included soil gas survey, drilling and sampling six groundwater monitoring wells. Soil sampling will be implemented after reviewing the analytical results from soil gas and groundwater data.	
<b>Title:</b>					Soil Gas and Groundwater Workplan Modification	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60395478">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60395478</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Correspondence  
**Date Completed:** 5/14/2015  
**Comments:** Email from GeoRestoration outlining proposed groundwater sampling location changes due to dry shallow wells caused by a lower than expected water table.

**Title:** Letter from Roger Dokter Regarding Future Actions at the Site  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=60000133&enforcement\\_id=60418344](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&enforcement_id=60418344)

**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Correspondence  
**Date Completed:** 10/4/2016  
**Comments:** Letter from GeoRestoration to DTSC proposing conceptual approach for final site remedy

<a href="#">50</a>	2 of 2	E	0.47 / 2,504.19	66.66 / -8	AJ COMMERCIAL LAUNDRY/ALL CHEM SUPPLY 1173-1175 CAMPBELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	---	--------------------	---------------	--	------------

<b>Estor/EPA ID:</b>	60000133	<b>Assembly District:</b>	28
<b>Site Code:</b>	201631	<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-13-008, 230-13-009, 23013008, 23013009	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	NICOLE YUEN
<b>Site Type:</b>	STATE RESPONSE OR NPL	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1173-1175 CAMPBELL AVENUE	<b>Latitude:</b>	37.3462716038083
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.928331537851
<b>Special Program:</b>		<b>Acres:</b>	2 ACRES
<b>Funding:</b>	RESPONSIBLE PARTY	<b>Supervisor:</b>	JOHN KARACHEWSKI
<b>Cleanup Status:</b>	ACTIVE AS OF 4/19/2005		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	LAUNDRY SERVICES		
<b>Potential Media Affected:</b>	OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER)		
<b>Site History:</b>			

The property has two parcels, each approximately 1.0 acre. 1175 Campbell Avenue is identified by Santa Clara County Assessor's Parcel Number 23013008. It has 2 warehouse type buildings, which are 19,000 square feet in size. 1173 Campbell Avenue is identified by Santa Clara County Assessor's Parcel Number 23013009. It has 3 warehouse type buildings, which are 19,000 square feet in size. The buildings on the site were built in 1956/1957. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of mixed commercial/ industrial and residential developments. DTSC issued an Imminent and Substantial Endangerment Order for the Site on June 27, 2006 after a Site investigation in May 2005 revealed elevated levels of petroleum compounds, metals, and chlorinated volatile organic compounds in the groundwater. In January 2010, a dual-phase extraction system was operated for 9 months, removing contaminated groundwater and soil vapor. In May 2015, another round of extraction started and ran for approximately one year. Groundwater, soil vapor, and soil samples have been collected from the Site at various times since 2005. Further investigation is planned at the Site to evaluate potential off-Site impacts, but work has been paused due to lack of funding. 9/2021, NY

**Potential Contaminant of Concern:**

1,2-DICHLOROETHYLENE (CIS) TPH-GAS TETRACHLOROETHYLENE (PCE) TRICHLOROETHYLENE (TCE) VINYL CHLORIDE

**Status:** ACTIVE  
**Program Type:** STATE RESPONSE  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=60000133](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60000133)

**Completed Activities**

**Title:** 2012 2nd Quarter Semi-Annual Groundwater Monitoring Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=60000133&doc\\_id=60445385](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&doc_id=60445385)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					8/2/2012	
<b>Comments:</b>					The semi-annual groundwater monitoring report summarizes the groundwater monitoring activities conducted at the Site during the second quarter of 2012 by SGI.	
<b>Title:</b>					Groundwater Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386221">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386221</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Technical Report	
<b>Date Completed:</b>					11/5/2015	
<b>Comments:</b>					The Groundwater Monitoring Report, First Semi-Annual 2015 summarizes groundwater monitoring activities completed in May 2015. Select monitoring wells in areas with remaining elevated volatile organic compounds were sampled to evaluate current groundwater conditions and to provide a baseline to track progress for the remediation that was restarted in May 2015. Wells with a total depth of 20 feet or less were dry or had small amounts of groundwater and were not sampled.	
<b>Title:</b>					Groundwater Monitoring Report: Second Semi-Annual 2015	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60405336">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60405336</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Monitoring Report	
<b>Date Completed:</b>					4/27/2016	
<b>Comments:</b>					The Groundwater Monitoring Report - Second Semi-Annual 2015 summarizes groundwater monitoring activities completed in November and December 2015 and provides a progress report for the dual-phase extraction system. Due to recent rains, shallower wells that were previously dry were sampled.	
<b>Title:</b>					Notice of Exemption	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6013460">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6013460</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					CEQA - Notice of Exemption	
<b>Date Completed:</b>					1/13/2010	
<b>Comments:</b>					CEQA Notice of Exemption for Interim Dual Phase Extraction System signed by DTSC.	
<b>Title:</b>					1st 2018 Semi-Annual Groundwater and Soil Vapor Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60446859">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60446859</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					8/22/2018	
<b>Comments:</b>						
<b>Title:</b>					Com. Profile & Mailing List	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6016559">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6016559</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Community Profile	
<b>Date Completed:</b>					2/1/2008	
<b>Comments:</b>					The key contacts for the site has been updated.	
<b>Title:</b>					Order Amendment for PDF Files	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6010564">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6010564</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Amendment - Order/Agreement	
<b>Date Completed:</b>					2/21/2007	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Comments:</b>					Order amendment was done for PDF submittal of documents.	
<b>Title:</b>					Proposed Determination of Non Compliance	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6009681">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6009681</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Proposed Determination of non-compliance	
<b>Date Completed:</b>					8/2/2006	
<b>Comments:</b>					Proposed Determination of Non Compliance issued. Respondent's request for a 12 month extension denied. Extension to comply granted through August 31, 2006.	
<b>Title:</b>					Public Notice	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022573">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022573</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Public Notice	
<b>Date Completed:</b>					10/21/2009	
<b>Comments:</b>					Public Notice for Draft RAW	
<b>Title:</b>					Soil Gas and Groundwater Workplan Modification	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60395478">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60395478</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Correspondence	
<b>Date Completed:</b>					5/14/2015	
<b>Comments:</b>					Email from GeoRestoration outlining proposed groundwater sampling location changes due to dry shallow wells caused by a lower than expected water table.	
<b>Title:</b>					3rd Quarter 2019 Groundwater Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60472209">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60472209</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					3/5/2020	
<b>Comments:</b>						
<b>Title:</b>					Amendment to I&SE Order	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60358646">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60358646</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Amendment - Order/Agreement	
<b>Date Completed:</b>					1/7/2015	
<b>Comments:</b>					DTSC issued an Amendment to Imminent and Substantial Endangerment Order and Remedial Action Order, Docket No. I&SE 05/06-012, which was issued in 2006. The Amendment added 1175 Campbell Avenue, LLC, the new Site owner, and the Estate of Jonnie Lindsell as responsible parties.	
<b>Title:</b>					Annual Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60255699">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60255699</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/29/2010	
<b>Comments:</b>						
<b>Title:</b>					Fact Sheet	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022572">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022572</a>	
<b>Area Name:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fact Sheets			
<b>Date Completed:</b>			10/21/2009			
<b>Comments:</b>			Fact sheet for Draft RAW			
<b>Title:</b>			Groundwater Monitoring Report - 1st Semi-Annual 2016			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396471">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396471</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Technical Report			
<b>Date Completed:</b>			3/14/2017			
<b>Comments:</b>						
<b>Title:</b>			Groundwater Sampling			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			11/27/2018			
<b>Comments:</b>			Groundwater sampling was conducted at the Site on November 26 and 27, 2018.			
<b>Title:</b>			Off-Site Characterization Workplan			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60258775">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60258775</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Characterization Workplan			
<b>Date Completed:</b>			11/8/2011			
<b>Comments:</b>			Report approved.			
<b>Title:</b>			Offsite Investigation Workplan			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018181">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018181</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Remedial Investigation Workplan			
<b>Date Completed:</b>			3/15/2010			
<b>Comments:</b>			approved			
<b>Title:</b>			Project Schedule Update Letter			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Correspondence			
<b>Date Completed:</b>			2/10/2016			
<b>Comments:</b>			Letter from GeoRestoration details the proposed schedule for shutdown of the dual phase extraction system and soil gas and groundwater sampling and reporting.			
<b>Title:</b>			Site Screening			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6007946">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6007946</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Site Screening			
<b>Date Completed:</b>			10/20/2005			
<b>Comments:</b>			In-house site screening report approved which determined that further action is needed.			
<b>Title:</b>			Soil Gas Survey Report			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6013284">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6013284</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					9/20/2007	
<b>Comments:</b>					Additional investigation is required which includes onsite indoor air sampling.	
<b>Title:</b>					2nd 2018 Semi-Annual Groundwater Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60448422">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60448422</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					3/5/2020	
<b>Comments:</b>						
<b>Title:</b>					Fieldwork (Interim RAW)	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fieldwork	
<b>Date Completed:</b>					5/26/2010	
<b>Comments:</b>					inspection completed	
<b>Title:</b>					Groundwater Monitoring Report, 1st Semi Annual 2017	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60431210">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60431210</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					12/12/2017	
<b>Comments:</b>						
<b>Title:</b>					Interim Removal Action Workplan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022198">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6022198</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Removal Action Workplan	
<b>Date Completed:</b>					1/13/2010	
<b>Comments:</b>					RAW approved for installation of an Interim Dual Phase Extraction System with one revision to page 18 of the Health and Safety Plan.	
<b>Title:</b>					Letter from RP to Lt. Governor	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60276737">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60276737</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					*Correspondence - Received	
<b>Date Completed:</b>					9/2/2011	
<b>Comments:</b>					The Site owner sent a letter to Lt. Governor Gavin Newsom regarding the investigation and cleanup of the Site.	
<b>Title:</b>					Remedial Investigation Workplan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6013221">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6013221</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Remedial Investigation Workplan	
<b>Date Completed:</b>					11/17/2006	
<b>Comments:</b>					Workplan approved requiring groundwater monitoring wells installation, soil, and soil gas sampling.	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Site Investigation Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60460194">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60460194</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					5/27/2020	
<b>Comments:</b>						
<b>Title:</b>					Amendment to Ground Water Monitoring Schedule	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60459438">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60459438</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Workplan	
<b>Date Completed:</b>					3/5/2020	
<b>Comments:</b>						
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60447311">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60447311</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/25/2018	
<b>Comments:</b>					Annual cost estimate letter estimating DTSC's oversight costs for the 2018 to 2019 fiscal year.	
<b>Title:</b>					Annual Oversight Cost Estimate for FY20-21	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60483066">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60483066</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					9/9/2020	
<b>Comments:</b>					DTSC's annual estimate of oversight costs for the 2020-2021 fiscal year.	
<b>Title:</b>					Report for Site Investigation, Well Installation, and Remediation Progress	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60261873">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60261873</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Removal Action Completion Report	
<b>Date Completed:</b>					1/26/2012	
<b>Comments:</b>						
<b>Title:</b>					Sampling Report (Onsite)	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018177">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6018177</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Remedial Investigation Report	
<b>Date Completed:</b>					8/15/2008	
<b>Comments:</b>					Indoor air survey results indicate VOC levels are elevated and above the screening levels. An Expedited Removal Action and additional offsite groundwater investigation are recommended for the site.	
<b>Title:</b>					Soil Gas Sampling Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396473">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60396473</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Technical Report	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date Completed:</b>		3/13/2017				
<b>Comments:</b>						
<b>Title:</b>		Soil and Groundwater Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6015456">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6015456</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Report				
<b>Date Completed:</b>		9/20/2007				
<b>Comments:</b>		Additional investigation is required which includes defining the lateral and vertical extent of groundwater contamination, and investigating the source of TPH contamination around MW-3.				
<b>Title:</b>		Annual Oversight Cost Estimate Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60397302">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60397302</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/21/2015				
<b>Comments:</b>						
<b>Title:</b>		Cost Estimate 2012-2013				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60325163">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60325163</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		11/1/2012				
<b>Comments:</b>		Annual DTSC oversight cost estimate sent to responsible party.				
<b>Title:</b>		DTSC Response to Project Schedule Update Letter				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60408510">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60408510</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Correspondence				
<b>Date Completed:</b>		5/2/2016				
<b>Comments:</b>		DTSC sent a letter to 1175 Campbell Avenue, LLC, the responsible party, that approved the updated project schedule outlined in a February 10, 2016 letter from GeoRestoration, Inc. DTSC agreed that the dual-phase extraction system should run until the Bay Area Air Quality District permit expired at the end of May 2016. After system shutdown, soil sampling would be performed after a one-month period to provide data to assess the progress of remediation.				
<b>Title:</b>		Investigation Workplan (Onsite)				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6016553">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=6016553</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Remedial Investigation Workplan				
<b>Date Completed:</b>		2/7/2008				
<b>Comments:</b>		Onsite sampling investigations include soil and groundwater and indoor air survey.				
<b>Title:</b>		Letter from Roger Dokter Regarding Future Actions at the Site				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60418344">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60418344</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Correspondence				
<b>Date Completed:</b>		10/4/2016				
<b>Comments:</b>		Letter from GeoRestoration to DTSC proposing conceptual approach for final site remedy				
<b>Title:</b>		On-Site Soilgas and Groundwater Sampling				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			1/8/2007			
<b>Comments:</b>			Fieldwork is complete which included soil gas survey, drilling and sampling six groundwater monitoring wells. Soil sampling will be implemented after reviewing the analytical results from soil gas and groundwater data.			
<b>Title:</b>			Resumption of Dual-Phase Extraction / RAW Implementation			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			6/1/2015			
<b>Comments:</b>			Dual-phase extraction was restarted on the site.			
<b>Title:</b>			Soil Gas Sampling			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			7/1/2016			
<b>Comments:</b>			Additional soil gas wells were installed and soil gas sampling to determine remediation progress was completed.			
<b>Title:</b>			Soil Gas and Groundwater Sampling			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			5/22/2015			
<b>Comments:</b>			The soil gas and groundwater sampling activities outlined in the Workplan for Soil Gas and Groundwater Sampling approved by DTSC on May 13, 2015 was completed.			
<b>Title:</b>			Annual Oversight Cost Estimate			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60414599">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60414599</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			9/23/2016			
<b>Comments:</b>			DTSC letter with oversight cost estimate for fiscal year 2016/2017			
<b>Title:</b>			Field Investigation			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			2/15/2013			
<b>Comments:</b>			On-site groundwater sampled as part of ongoing rebound study.			
<b>Title:</b>			Fieldwork for Rebound Study			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Fieldwork			
<b>Date Completed:</b>			10/27/2012			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Comments:</b>					First rebound study sampling event completed.	
<b>Title:</b>					Geophysical Investigation Results and Work Plan for Additional Investigation	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447784">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447784</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Workplan	
<b>Date Completed:</b>					9/21/2018	
<b>Comments:</b>						
<b>Title:</b>					I&SE Order	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6008184">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=6008184</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Unilateral Order (I/SE, RAO, CAO, EPA AO)	
<b>Date Completed:</b>					6/27/2006	
<b>Comments:</b>						
<b>Title:</b>					Preliminary Groundwater Sampling and Testing Investigation Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447051">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60447051</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					8/15/2005	
<b>Comments:</b>					The report presents the results of preliminary groundwater sampling at the site and was submitted to the California Office of Emergency Services who referred it to the Emergency Response Division at DTSC. This report was completed prior to the issuance of an order for the site and not performed under DTSC's oversight.	
<b>Title:</b>					Rebound Study: Preliminary Data	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60327782">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60327782</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Technical Report	
<b>Date Completed:</b>					6/27/2013	
<b>Comments:</b>					Raw lab data from rebound study sampling.	
<b>Title:</b>					Site Investigation Report -- Offsite Groundwater Sampling	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60475552">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60475552</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Site Characterization Report	
<b>Date Completed:</b>					9/27/2013	
<b>Comments:</b>					Report summarizes the results of offsite groundwater sampling.	
<b>Title:</b>					Soil Gas & Groundwater Sampling Work Plan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386209">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60386209</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Technical Workplan	
<b>Date Completed:</b>					5/13/2015	
<b>Comments:</b>						
<b>Title:</b>					Sumps Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60385177">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60385177</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Correspondence				
<b>Date Completed:</b>		11/7/2014				
<b>Comments:</b>		Georestation, Inc. submitted a letter informing DTSC of the current property owners intent to fill sumps located in the southwestern portion of the site with clean, small pieces of concrete mixed with base rock and then placing inches of concrete to grade above the fill. The identified purpose of filling the sumps was to eliminate a physical hazard. DTSC provided approval to proceed in its response letter.				
<b>Title:</b>		Work Notice				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60194464">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60194464</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Public Notice				
<b>Date Completed:</b>		1/25/2010				
<b>Comments:</b>						
<b>Title:</b>		Cost Estimate 2011-2012				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60287488">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;enforcement_id=60287488</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		12/14/2011				
<b>Comments:</b>						
<b>Title:</b>		Fieldwork				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Fieldwork				
<b>Date Completed:</b>		2/29/2008				
<b>Comments:</b>		Fieldwork included soil and groundwater investigations, and indoor soil gas survey.				
<b>Title:</b>		Historical Research and Environmental Sampling Work Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60444199">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60444199</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Workplan				
<b>Date Completed:</b>		5/31/2018				
<b>Comments:</b>						
<b>Title:</b>		Rebound Study Workplan: Groundwater Monitoring and Soil Vapor Sampling				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Workplan				
<b>Date Completed:</b>		11/2/2012				
<b>Comments:</b>		The Workplan outlines groundwater and soil vapor sampling to determine current subsurface conditions at the site following cessation of dual phase extraction and soil vapor extraction in December 2011.				
<b>Title:</b>		Work Plan for Off-Site Investigation				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60482061">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60000133&amp;doc_id=60482061</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Site Characterization Workplan				
<b>Date Completed:</b>		8/21/2020				
<b>Comments:</b>		Off-Site investigation workplan proposes installing soil vapor wells along the site boundary, grab groundwater samples near a previous historical sample that contained chlorinated volatile organic compounds, and				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

decommissioning previously-approved groundwater monitoring wells.

<a href="#">51</a>	1 of 1	S	0.48 / 2,522.52	88.44 / 13	FORMER NELSON CLEANERS 53 WASHINGTON STREET SANTA CLARA CA 95050	CLEANUP SITES
--------------------	--------	---	--------------------	---------------	--	---------------

**Global ID:** T10000006410 **Latitude:** 37.3392496852702  
**Status:** OPEN - SITE ASSESSMENT **Longitude:** -121.938311657314  
**Status Date:** 1/8/2015 **County:** SANTA CLARA  
**Site Facility Type:** CLEANUP PROGRAM SITE  
**Data Source:** Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Stop Method:**  
**Local Case No:** 07S1W11G03s **CUF Case:** NO  
**Begin Date:** 1/6/2011 **Case Worker:** GOR  
**File Location:** All Files are on GeoTracker or in the Local Agency Database  
**Lead Agency:** SANTA CLARA COUNTY LOP  
**Local Agency:** SANTA CLARA COUNTY LOP  
**Potential COC:** Tetrachloroethylene (PCE)  
**Potential Media of Concern:** Other Groundwater (uses other than drinking water), Soil, Soil Vapor  
**How Discovered:** Site Assessment/Site Investigation  
**How Discovered Description:** facility closure sampling in 2011  
**Stop Description:** Discontinued use of solvent and business closed  
**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**CalEnviroScreen Score:** 36-40%  
**Site History:**

Dry cleaning operations for 60 years and discontinued in 2013. The dry cleaner was located centrally within a strip mall. In 2011 when the PCE dry cleaning machine was removed, the SCD required soil sampling as part of the facility closure activity. Shallow soil samples were collected and reported to contain PCE. Additionally, grab groundwater samples were collected at that time from wells present within the facility.

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

**Action Type:** RESPONSE  
**Date:** 2021-11-30 00:00:00  
**Action:** Soil Vapor Intrusion Investigation Report  
  
**Action Type:** RESPONSE  
**Date:** 2021-08-30 00:00:00  
**Action:** Other Report / Document  
  
**Action Type:** ENFORCEMENT  
**Date:** 2021-08-18 00:00:00  
**Action:** Staff Letter  
  
**Action Type:** RESPONSE  
**Date:** 2021-07-30 00:00:00  
**Action:** Monitoring Report - Other  
  
**Action Type:** ENFORCEMENT  
**Date:** 2021-05-28 00:00:00  
**Action:** Staff Letter  
  
**Action Type:** ENFORCEMENT  
**Date:** 2021-03-29 00:00:00  
**Action:** Staff Letter  
  
**Action Type:** RESPONSE  
**Date:** 2020-12-15 00:00:00  
**Action:** Site Assessment Report - Regulator Responded

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date:</b>			2015-03-06 00:00:00			
<b>Action:</b>			Email Correspondence			
<b>Action Type:</b>			RESPONSE			
<b>Date:</b>			2015-01-16 00:00:00			
<b>Action:</b>			Email Correspondence			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date:</b>			2015-01-09 00:00:00			
<b>Action:</b>			Staff Letter			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date:</b>			2015-01-02 00:00:00			
<b>Action:</b>			Cost Recovery Agreement / N. of Reimbursement			
<b>Action Type:</b>			ENFORCEMENT			
<b>Date:</b>			2014-12-22 00:00:00			
<b>Action:</b>			Letter - Notice			
<b>Action Type:</b>			RESPONSE			
<b>Date:</b>			2014-12-22 00:00:00			
<b>Action:</b>			Other Report / Document			
<b>Action Type:</b>			RESPONSE			
<b>Date:</b>			2014-12-19 00:00:00			
<b>Action:</b>			Correspondence			
<b>Action Type:</b>			RESPONSE			
<b>Date:</b>			2014-12-19 00:00:00			
<b>Action:</b>			Site Investigation Workplan - Regulator Responded			
<b>Action Type:</b>			Other			
<b>Date:</b>			2014-12-19 00:00:00			
<b>Action:</b>			Leak Reported			
<b>Action Type:</b>			Other			
<b>Date:</b>			2011-01-06 00:00:00			
<b>Action:</b>			Leak Stopped			
<b>Action Type:</b>			Other			
<b>Date:</b>			2011-01-06 00:00:00			
<b>Action:</b>			Leak Discovery			

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	2015-01-08 00:00:00
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	2011-01-06 00:00:00

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 BERGER DRIVE STE 300
<b>Contact Name:</b>	Gerald O'Regan	<b>City:</b>	SAN JOSE
<b>Phone No:</b>			
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		
<b>Email:</b>	gerald.o'regan@deh.sccgov.org		

**Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of Sep 15, 2021)**

<b>Project Status:</b>		<b>Facility Type:</b>	
<b>Cuf Claim No:</b>		<b>WDR Place Type:</b>	
<b>CUF Priority Assign:</b>		<b>Wdr File No:</b>	
<b>CUF Amount Paid:</b>		<b>Wdr Order No:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Composting Method:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**User Defined Beneficial Use:**  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T10000006410](https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000006410)  
**Cleanup Status Detail:** OPEN - SITE ASSESSMENT AS OF 1/8/2015  
**Potential COC:** TETRACHLOROETHYLENE (PCE)  
**Potential Media of Concern:** OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER), SOIL, SOIL VAPOR  
**Groundwater Monitoring Frequen:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD) - CASE #: 07S1W11G03s  
CASEWORKER: Gerald O'Regan  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T10000006410&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000006410&tabname=regulatoryhistory)  
**Site History:**

Dry cleaning operations for 60 years and discontinued in 2013. The dry cleaner was located centrally within a strip mall. In 2011 when the PCE dry cleaning machine was removed, the SCFD required soil sampling as part of the facility closure activity. Shallow soil samples were collected and reported to contain PCE. Additionally, grab groundwater samples were collected at that time from wells present within the facility.

**Sites from GeoTracker Search - Regulatory Activities (as of Sep 15, 2021)**

**Action Type:** Response Requested - Reports  
**Action Date:** \*11/30/2021  
**Received Issue Date:**  
**Action:** Soil Vapor Intrusion Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Vapor Intrusion Investigation Report - For extension approval see Directive Letter dated August 18, 2021.

**Action Type:** Response Requested - Other  
**Action Date:** 8/30/2021  
**Received Issue Date:**  
**Action:** Other Report / Document  
**Doc Link:**  
**Title Description Comments:**

Final Design

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/18/2021  
**Received Issue Date:** 8/18/2021  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000006410&enforcement\\_id=6474045&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6474045&temptable=ENFORCEMENT)  
**Title Description Comments:**

Extension Request Approved with Email Attachment

**Action Type:** Response Requested - Reports  
**Action Date:** 7/30/2021  
**Received Issue Date:**  
**Action:** Monitoring Report - Other  
**Doc Link:**  
**Title Description Comments:**

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

Groundwater Monitoring Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/28/2021  
**Received Issue Date:** 5/28/2021  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000006410&enforcement\\_id=6467866&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6467866&temptable=ENFORCEMENT)

**Title Description Comments:**

Final Design

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/29/2021  
**Received Issue Date:** 3/29/2021  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000006410&enforcement\\_id=6467795&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6467795&temptable=ENFORCEMENT)

**Title Description Comments:**

VI Investigation Report and GW Monitoring Report

**Action Type:** Response Requested - Other  
**Action Date:** \*12/15/2020  
**Received Issue Date:** 1/6/2021  
**Action:** Conceptual Site Model  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000006410&doc\\_id=6028244](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=6028244)

**Title Description Comments:**

Conceptual Site Model

**Action Type:** Response Requested - Reports  
**Action Date:** \*12/15/2020  
**Received Issue Date:** 12/15/2020  
**Action:** Site Assessment Report - Regulator Responded  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000006410&doc\\_id=6028243](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=6028243)

**Title Description Comments:**

Site Assessment Report

**Action Type:** Response Requested - Reports  
**Action Date:** \*12/15/2020  
**Received Issue Date:**  
**Action:** Feasibility Study Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000006410&doc\\_id=6028245](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=6028245)

**Title Description Comments:**

Feasibility Study and Remedial Action Plan

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/16/2020  
**Received Issue Date:** 10/16/2020  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000006410&enforcement\\_id=6449774&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6449774&temptable=ENFORCEMENT)

**Title Description Comments:**

Extension Request Approval with Attachment

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/27/2020  
**Received Issue Date:** 7/27/2020  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?](https://geotracker.waterboards.ca.gov/view_documents?)

global\_id=T10000006410&enforcement\_id=6442978&temptable=ENFORCEMENT

**Title Description Comments:**

Site Assessment Report, CSM and FSRAP

**Action Type:** Response Requested - Other  
**Action Date:** 9/6/2018  
**Received Issue Date:** 9/6/2018  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000006410&doc\\_id=5975389](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=5975389)  
**Title Description Comments:**

Email re RP Address

**Action Type:** Response Requested - Reports  
**Action Date:** \*9/16/2016  
**Received Issue Date:**  
**Action:** Site Assessment Report  
**Doc Link:**  
**Title Description Comments:**

- See Directive Letter dated May 16, 2016 granting second extension to September 16, 2016., See Directive Ltr dated March 8, 2016 granting first extension to June 13, 2016.

**Action Type:** Response Requested - Other  
**Action Date:** 5/23/2016  
**Received Issue Date:** 5/23/2016  
**Action:** Email Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000006410&doc\\_id=5889960](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=5889960)  
**Title Description Comments:**

EMAIL AND ATTACHMENTS

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/16/2016  
**Received Issue Date:** 5/16/2016  
**Action:** Staff Letter  
**Doc Link:**  
**Title Description Comments:**

Second Extension - Site Assessment Report Approval to extend due date to September 16, 2016.

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/8/2016  
**Received Issue Date:** 3/8/2016  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000006410&enforcement\\_id=6278165&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6278165&temptable=ENFORCEMENT)  
**Title Description Comments:**

Site Assessment Report Extension Granted

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/10/2016  
**Received Issue Date:** 2/10/2016  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000006410&enforcement\\_id=6275376&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6275376&temptable=ENFORCEMENT)  
**Title Description Comments:**

Well Completion Report Info

**Action Type:** Response Requested - Other  
**Action Date:** 2/1/2016

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Received Issue Date:</b>		2/1/2016				
<b>Action:</b>		Correspondence				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=5878600				
<b>Title Description Comments:</b>		CORRESPONDENCE				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		11/3/2015				
<b>Received Issue Date:</b>		11/3/2015				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6266234&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Site Assessment Report				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		9/24/2015				
<b>Received Issue Date:</b>		8/4/2015				
<b>Action:</b>		Site Investigation Workplan - Regulator Responded				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=5851585				
<b>Title Description Comments:</b>		- concur				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		8/10/2015				
<b>Received Issue Date:</b>		8/10/2015				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6255785&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		concur with recommendation to conduct additional investigation; request work plan				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		*7/31/2015				
<b>Received Issue Date:</b>		8/4/2015				
<b>Action:</b>		Preliminary Site Assessment Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006410&doc_id=5825724				
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		5/6/2015				
<b>Received Issue Date:</b>		5/6/2015				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6243901&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		email requesting extension and email response granting extension				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		4/9/2015				
<b>Received Issue Date:</b>		4/9/2015				
<b>Action:</b>		Email Correspondence				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&enforcement_id=6249875&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		email from consultant with results of investigation and recommendation to additional indoor air testing prior to submittal of report; email response from DEH concurring				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		3/6/2015				
<b>Received Issue Date:</b>		3/6/2015				
<b>Action:</b>		Email Correspondence				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&amp;doc_id=5845773">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&amp;doc_id=5845773</a>				
<b>Title Description Comments:</b>		email weber hayes with results of PSA and recommendation for indoor air sampling				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		1/16/2015				
<b>Received Issue Date:</b>		1/16/2015				
<b>Action:</b>		Email Correspondence				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&amp;doc_id=5826677">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&amp;doc_id=5826677</a>				
<b>Title Description Comments:</b>		email notification of planned field work and modification to scope of work				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		1/9/2015				
<b>Received Issue Date:</b>		1/9/2015				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232781&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232781&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		concurrence with work plan. Suggest installing permanent vapor sampling points for long term monitoring and request destruction of existing unknown wells within the tenant space.				
<b>Action Type:</b>		Agreements				
<b>Action Date:</b>		1/2/2015				
<b>Received Issue Date:</b>		1/2/2015				
<b>Action:</b>		Cost Recovery Agreement / N. of Reimbursement				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232645&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232645&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Notices				
<b>Action Date:</b>		12/22/2014				
<b>Received Issue Date:</b>		12/22/2014				
<b>Action:</b>		Letter - Notice				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232644&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232644&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		notification to of request to provide regulatory oversight				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		12/22/2014				
<b>Received Issue Date:</b>		12/22/2014				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&amp;doc_id=5825580">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&amp;doc_id=5825580</a>				
<b>Title Description Comments:</b>		real property report				
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		12/19/2014				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Response Requested - Workplans				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action Date:** 12/19/2014  
**Received Issue Date:** 12/19/2014  
**Action:** Site Investigation Workplan - Regulator Responded  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T1000006410&doc\\_id=5825581](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&doc_id=5825581)  
**Title Description Comments:**

Preliminary Site Assessment Work Plan - See 1/9/15 staff letter

**Action Type:** Response Requested - Other  
**Action Date:** 12/19/2014  
**Received Issue Date:** 12/19/2014  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T1000006410&doc\\_id=5825579](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000006410&doc_id=5825579)  
**Title Description Comments:**

VCP Application

**Action Type:** Leak Action  
**Action Date:** 1/6/2011  
**Received Issue Date:**  
**Action:** Leak Discovery  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 1/6/2011  
**Received Issue Date:**  
**Action:** Leak Stopped  
**Doc Link:**  
**Title Description Comments:**

**Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	8/18/2021	<b>Submitted By:</b>	GERALD O'REGAN (REGULATOR)
<b>Size :</b>			
<b>Title:</b>	EXTENSION REQUEST APPROVED WITH EMAIL ATTACHMENT **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6474045">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6474045</a>		
<b>Type:</b>	STAFF LETTER		

<b>Document Type:</b>	Monitoring Reports	<b>Submitted:</b>	
<b>Document Date:</b>	6/22/2021	<b>Submitted By:</b>	WEBER-HAYES (AUTH_RP)
<b>Size :</b>	17,941 KB		
<b>Title:</b>	GROUNDWATER MONITORING REPORT **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3287387311/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3287387311/T1000006410.PDF</a>		
<b>Type:</b>	MONITORING REPORT - OTHER		

<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	5/28/2021	<b>Submitted By:</b>	GERALD O'REGAN (REGULATOR)
<b>Size :</b>			
<b>Title:</b>	FINAL DESIGN **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6467866">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6467866</a>		
<b>Type:</b>	STAFF LETTER		

<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	3/29/2021	<b>Submitted By:</b>	GERALD O'REGAN (REGULATOR)
<b>Size :</b>			
<b>Title:</b>	VI INVESTIGATION REPORT AND GW MONITOTING REPORT **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6467795">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6467795</a>		
<b>Type:</b>	STAFF LETTER		

<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
-----------------------	----------------	-------------------	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Date:</b> <b>Size :</b> <b>Title:</b>	3/24/2021* 14,489 KB				<b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	
<b>Title Link:</b> <b>Type:</b>	FEASIBILITY STUDY & CORRECTIVE ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6861926496/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6861926496/T1000006410.PDF</a> CAP/RAP - FEASIBILITY STUDY REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 1/5/2021 17,576 KB				<b>Submitted:</b> <b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	
CONCEPTUAL SITE MODEL **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7943340599/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7943340599/T1000006410.PDF</a> CONCEPTUAL SITE MODEL						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 12/15/2020 21,190 KB				<b>Submitted:</b> <b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	
SITE ASSESSMENT REPORT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5067986249/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5067986249/T1000006410.PDF</a> SITE ASSESSMENT REPORT						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 10/16/2020				<b>Submitted:</b> <b>Submitted By:</b> GERALD O'REGAN (REGULATOR)	
EXTENSION REQUEST APPROVAL WITH ATTACHMENT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6449774">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6449774</a> STAFF LETTER						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 7/27/2020				<b>Submitted:</b> <b>Submitted By:</b> GERALD O'REGAN (REGULATOR)	
SITE ASSESSMENT REPORT, CSM AND FSRAP **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6442978">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6442978</a> STAFF LETTER						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 6/22/2020 40,845 KB				<b>Submitted:</b> <b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	
ADDITIONAL SITE ASSESSMENT REPORT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8183004558/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8183004558/T1000006410.PDF</a> WELL INSTALLATION WORKPLAN						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 9/6/2018				<b>Submitted:</b> <b>Submitted By:</b> GERALD O'REGAN (REGULATOR)	
EMAIL RE RP ADDRESS **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5975389">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5975389</a> CORRESPONDENCE						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 5/23/2016				<b>Submitted:</b> <b>Submitted By:</b> CANDACE GARCIA (REGULATOR)	
EMAIL AND ATTACHMENTS **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5889960">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5889960</a> EMAIL CORRESPONDENCE						
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	Site Documents 3/8/2016				<b>Submitted:</b> <b>Submitted By:</b> CANDACE GARCIA (REGULATOR)	
SITE ASSESSMENT REPORT EXTENSION GRANTED **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6278165">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6278165</a> STAFF LETTER						
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 2/10/2016				<b>Submitted:</b> <b>Submitted By:</b> CANDACE GARCIA (REGULATOR)	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Size :</b> <b>Title:</b>					WELL COMPLETION REPORT INFO **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b> <b>Type:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6275376">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6275376</a> STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 2/1/2016				<b>Submitted:</b> <b>Submitted By:</b> CANDACE GARCIA (REGULATOR)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>					CORRESPONDENCE **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;document_id=5878600">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;document_id=5878600</a> CORRESPONDENCE	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 11/3/2015				<b>Submitted:</b> <b>Submitted By:</b> CANDACE GARCIA (REGULATOR)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>					SITE ASSESSMENT REPORT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6266234">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6266234</a> STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 9/24/2015				<b>Submitted:</b> <b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	9,344 KB				ADDITIONAL SITE ASSESSMENT WORKPLAN **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2572150528/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2572150528/T10000006410.PDF</a> SITE INVESTIGATION WORKPLAN	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 8/10/2015				<b>Submitted:</b> <b>Submitted By:</b> LANI LEE (REGULATOR)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>					CONCUR WITH RECOMMENDATION TO CONDUCT ADDITIONAL INVESTIGATION; REQUEST WORK PLAN **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6255785">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6255785</a> STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 7/29/2015				<b>Submitted:</b> <b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>	28,159 KB				PRELIMINARY SITE ASSESSMENT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9659689366/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9659689366/T10000006410.PDF</a> PRELIMINARY SITE ASSESSMENT REPORT	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 5/6/2015				<b>Submitted:</b> <b>Submitted By:</b> LANI LEE (REGULATOR)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>					EMAIL REQUESTING EXTENSION AND EMAIL RESPONSE GRANTING EXTENSION **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6243901">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6243901</a> STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 4/9/2015				<b>Submitted:</b> <b>Submitted By:</b> LANI LEE (REGULATOR)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>					EMAIL FROM CONSULTANT WITH RESULTS OF INVESTIGATION AND RECOMMENDATION TO ADDITIONAL INDOOR AIR TESTING PRIOR TO SUBMITTAL OF REPORT; EMAIL RESPONSE FROM DEH CONCURRING **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6249875">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;enforcement_id=6249875</a> EMAIL CORRESPONDENCE	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 3/6/2015				<b>Submitted:</b> <b>Submitted By:</b> LANI LEE (REGULATOR)	
<b>Size :</b> <b>Title:</b> <b>Title Link:</b> <b>Type:</b>					EMAIL WEBER HAYES WITH RESULTS OF PSA AND RECOMMENDATION FOR INDOOR AIR SAMPLING **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;document_id=5845773">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006410&amp;document_id=5845773</a> EMAIL CORRESPONDENCE	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	1/16/2015				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	EMAIL NOTIFICATION OF PLANNED FIELD WORK AND MODIFICATION TO SCOPE OF WORK **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5826677">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5826677</a>					
<b>Type:</b>	EMAIL CORRESPONDENCE					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	1/9/2015				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	CONCURRENCE WITH WORK PLAN. SUGGEST INSTALLING PERMANENT VAPOR SAMPLING POINTS FOR LONG TERM MONITORING AND REQUEST DESTRUCTION OF EXISTING UNKNOWN WELLS WITHIN THE TENANT SPACE.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232781">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232781</a>					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	1/2/2015				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	UNKNOWN **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232645">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232645</a>					
<b>Type:</b>	COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/22/2014				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	REAL PROPERTY REPORT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5825580">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5825580</a>					
<b>Type:</b>	OTHER REPORT / DOCUMENT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/22/2014				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	NOTIFICATION TO OF REQUEST TO PROVIDE REGULATORY OVERSIGHT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232644">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;enforcement_id=6232644</a>					
<b>Type:</b>	LETTER - NOTICE					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/19/2014				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	PRELIMINARY SITE ASSESSMENT WORK PLAN **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5825581">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5825581</a>					
<b>Type:</b>	SITE INVESTIGATION WORKPLAN					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/19/2014				<b>Submitted By:</b>	LANI LEE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	VCP APPLICATION **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5825579">https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000006410&amp;document_id=5825579</a>					
<b>Type:</b>	CORRESPONDENCE					

**Sites from GeoTracker Search - Site Maps (as of Sep 15, 2021)**

<b>Title:</b>	GEO_MAP	<b>Submitted By:</b>	WEBER-HAYES (AUTH_RP)
<b>Size :</b>	752 KB	<b>Submitted:</b>	1/20/2021
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7529156029/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7529156029/T1000006410.PDF</a>		
<b>Title:</b>	2020 SITE ASSESSMENT REPORT (MW-1)	<b>Submitted By:</b>	WEBER-HAYES (AUTH_RP)
<b>Size :</b>	159 KB	<b>Submitted:</b>	12/15/2020
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8141971051/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8141971051/T1000006410.PDF</a>		
<b>Title:</b>	2020 SITE ASSESSMENT REPORT (MW-2)	<b>Submitted By:</b>	WEBER-HAYES (AUTH_RP)
<b>Size :</b>	198 KB	<b>Submitted:</b>	12/15/2020
<b>Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5168373823/T1000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5168373823/T1000006410.PDF</a>		

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b> <b>Size :</b> <b>Link:</b>	2020 SITE ASSESSMENT REPORT (MW-5) 171 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/15/2020	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7160040080/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7160040080/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	2020 SITE ASSESSMENT REPORT (MW-4) 168 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/15/2020	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9257305443/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9257305443/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	2020 SITE ASSESSMENT REPORT (SV-5) 172 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/15/2020	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5194117665/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5194117665/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	2020 SITE ASSESSMENT REPORT (MW-3) 197 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/15/2020	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7001442670/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7001442670/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	GEO_MAP 814 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8390108108/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8390108108/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SO-7 BORE LOG (SO-7) 239 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9104559540/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9104559540/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SV-5 BORE LOG (SV-5) 130 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6816833734/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6816833734/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SL-1 BORE LOG (SL-1) 247 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2706534028/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2706534028/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	CB-1 BORE LOG (CB-1) 179 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6701849579/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6701849579/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SB-1 BORE LOG (SB-1) 281 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3162927448/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3162927448/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	CB-4 BORE LOG (CB-4) 179 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4362634479/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4362634479/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SL-4 BORE LOG (SL-4) 239 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2489076614/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2489076614/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	GEO_MAP 624 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/4877069294/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/4877069294/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	CB-3 BORE LOG (CB-3) 180 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9810067951/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9810067951/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	GEO_MAP 721 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7374389886/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7374389886/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SO-3 BORE LOG (SO-3) 239 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1406027436/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1406027436/T10000006410.PDF</a>	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	SO-5 BORE LOG (SO-5) 240 KB				<b>Submitted By:</b> <b>Submitted:</b> WEBER-HAYES (AUTH_RP) 12/5/2017	
					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7690931856/T10000006410.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7690931856/T10000006410.PDF</a>	
<b>Title:</b>	CB-2 BORE LOG (CB-2)				<b>Submitted By:</b> WEBER-HAYES (AUTH_RP)	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Size :</b> <b>Link:</b>	180 KB				<b>Submitted:</b> 12/5/2017 https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6826240241/T1000006410.PDF	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	PRELIMINARY SITE ASSESSMENT SB-1 (SB-1) 281 KB				<b>Submitted By:</b> WEBER-HAYES (AUTH_RP) <b>Submitted:</b> 7/31/2015 https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4778463780/T1000006410.PDF	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	PRELIMINARY SITE ASSESSMENT SV-1 (SV-1) 175 KB				<b>Submitted By:</b> WEBER-HAYES (AUTH_RP) <b>Submitted:</b> 7/31/2015 https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2000162482/T1000006410.PDF	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	PRELIMINARY SITE ASSESSMENT SB-2 (SB-2) 252 KB				<b>Submitted By:</b> WEBER-HAYES (AUTH_RP) <b>Submitted:</b> 7/31/2015 https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8907530367/T1000006410.PDF	
<b>Title:</b> <b>Size :</b> <b>Link:</b>	PRELIMINARY SITE ASSESSMENT SB-3 (SB-3) 428 KB				<b>Submitted By:</b> WEBER-HAYES (AUTH_RP) <b>Submitted:</b> 7/31/2015 https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3154151260/T1000006410.PDF	

**Sites from GeoTracker Search - Cleanup Status History (as of Sep 15, 2021)**

**Status:** Open - Site Assessment  
**Date:** 1/8/2015

**Status:** Open - Case Begin Date  
**Date:** 1/6/2011

<a href="#">52</a>	1 of 2	ESE	0.48 / 2,522.84	72.56 / -3	Kumar Property 2106 The Alameda San Jose CA	LOP SANTA CLARA
<b>SCVWD ID:</b>	07S1W12D01f					
<b>Closure Date:</b>	12/3/2004					
<b>Link:</b>	http://lustop.sccgov.org/files/07S1W12D01f/					

<a href="#">52</a>	2 of 2	ESE	0.48 / 2,522.84	72.56 / -3	KUMAR PROPERTY 2106 THE ALAMEDA SAN JOSE CA 95126	LUST
<b>Global ID:</b>	T0608501565				<b>County:</b> SANTA CLARA	
<b>Status:</b>	COMPLETED - CASE CLOSED				<b>Latitude:</b>	
<b>Status Date:</b>					<b>Longitude:</b>	
<b>Case Type:</b>	LUST CLEANUP SITE					
<b>Date Source:</b>	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download					

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>		<b>Potential COC:</b>	Gasoline
<b>Local Case No:</b>		<b>How Discovered:</b>	
<b>Begin Date:</b>	7/12/1985	<b>Stop Method:</b>	
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP	<b>Stop Description:</b>	
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP	<b>Case Worker:</b>	UST
<b>CUF Case:</b>	NO	<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)

**How Discovered Description:**

**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)

**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)

**Disadvantaged Community:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Calenviroscreen Score:</b>		41-45%				
<b>Site History:</b>						

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	11/15/2004
<b>Action:</b>	Well Destruction Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	1/27/2003
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	10/31/2002
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	10/8/2002
<b>Action:</b>	Staff Letter - #38690
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/7/2001
<b>Action:</b>	Soil and Water Investigation Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	2/7/2001
<b>Action:</b>	Staff Letter - #22467
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	7/24/2000
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	5/19/2000
<b>Action:</b>	Warning Letter - #22446
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	10/20/1999
<b>Action:</b>	Staff Letter - #22444
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	10/16/1998
<b>Action:</b>	Other Workplan
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	9/25/1998
<b>Action:</b>	Soil and Water Investigation Workplan
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	8/11/1998
<b>Action:</b>	Staff Letter - #22440
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	3/4/1997
<b>Action:</b>	Notice of Responsibility - #39651
<b>Action Type:</b>	Other
<b>Date :</b>	12/26/1985

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action:</b>					Leak Reported	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					12/26/1985	
<b>Action:</b>					Unauthorized Release Form	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					12/21/1985	
<b>Action:</b>					Soil and Water Investigation Report	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					11/27/1985	
<b>Action:</b>					Preliminary Site Assessment Report	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					10/30/1985	
<b>Action:</b>					Remedial Progress Report	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					6/5/1985	
<b>Action:</b>					Other Report / Document	
<b>Action Type:</b>					RESPONSE	
<b>Date :</b>					1/1/1985	
<b>Action:</b>					Correspondence	

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	12/3/2004
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	5/15/2000
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	7/12/1985
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	7/12/1985

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	KUMAR PROPERTY	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	2106 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SAN JOSE
<b>WDR File:</b>		<b>Zip:</b>	95126
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Project Oversight Agencies:**

**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T0608501565](https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608501565)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 12/3/2004  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608501565&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608501565&tabname=regulatoryhistory)  
**Potential Media of Concern:** OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W12D01f

**Gndwater Monitoring Freque:**

**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Site History:**

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 12/3/2004

**Status:** Open - Site Assessment  
**Date :** 5/15/2000

**Status:** Open - Site Assessment  
**Date :** 7/12/1985

**Status:** Open - Case Begin Date  
**Date :** 7/12/1985

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927529](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927529)  
**Title Description Comments:**

State Information 06/03/2005

**Action Type:** Response Requested - Other  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927527](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927527)  
**Title Description Comments:**

Phone Log 06/03/2005

**Action Type:** Reports  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501565&enforcement\\_id=6324348&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&enforcement_id=6324348&temptable=ENFORCEMENT)  
**Title Description Comments:**

Map & Metrosan Information 06/03/2005

**Action Type:** Response Requested - Reports  
**Action Date:** 11/15/2004  
**Received Issue Date:** 11/15/2004  
**Action:** Well Destruction Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927535](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927535)  
**Title Description Comments:**

Well Abandonment/Destruction 11/15/2004

**Action Type:** Response Requested - Reports  
**Action Date:** 1/27/2003  
**Received Issue Date:** 2/3/2003  
**Action:** Monitoring Report - Quarterly  
**Doc Link:**  
**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Response Requested - Reports  
**Action Date:** 10/31/2002  
**Received Issue Date:** 10/31/2002  
**Action:** Monitoring Report - Quarterly  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927525](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927525)  
**Title Description Comments:**

GW Monitoring Report 10/31/2002 - 10/26/2004

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/8/2002  
**Received Issue Date:** 10/8/2002  
**Action:** Staff Letter - #38690  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 2/7/2001  
**Received Issue Date:** 2/7/2001  
**Action:** Staff Letter - #22467  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 7/24/2000  
**Received Issue Date:** 7/24/2000  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927522](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927522)  
**Title Description Comments:**

Additional Information Report 07/24/2000

**Action Type:** Enforcement/Orders  
**Action Date:** 5/19/2000  
**Received Issue Date:** 5/19/2000  
**Action:** Warning Letter - #22446  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/20/1999  
**Received Issue Date:** 10/20/1999  
**Action:** Staff Letter - #22444

**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Workplans  
**Action Date:** 10/16/1998  
**Received Issue Date:** 10/16/1998  
**Action:** Other Workplan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927536](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927536)  
**Title Description Comments:**

Work Plan 10/16/1998 - 09/04/2002

**Action Type:** Response Requested - Workplans  
**Action Date:** 9/25/1998  
**Received Issue Date:** 4/30/1999  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/11/1998  
**Received Issue Date:** 8/11/1998  
**Action:** Staff Letter - #22440  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 3/4/1997  
**Received Issue Date:** 3/4/1997  
**Action:** Notice of Responsibility - #39651  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 12/26/1985  
**Received Issue Date:** 12/26/1985  
**Action:** Unauthorized Release Form  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927534](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927534)  
**Title Description Comments:**

Unauthorized Release Form 12/26/1985

**Action Type:** Response Requested - Reports  
**Action Date:** 12/21/1985  
**Received Issue Date:** 12/21/1985  
**Action:** Soil and Water Investigation Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927533](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927533)  
**Title Description Comments:**

Soil & Water Investigation Report 12/21/1985 - 10/01/2002

**Action Type:** Response Requested - Reports  
**Action Date:** 11/27/1985  
**Received Issue Date:** 11/27/1985  
**Action:** Preliminary Site Assessment Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927531](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927531)  
**Title Description Comments:**

Preliminary Site Assessment Report 11/27/1985 - 06/26/2000

**Action Type:** Response Requested - Reports

**Action Date:** 10/30/1985  
**Received Issue Date:** 10/30/1985  
**Action:** Remedial Progress Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927532](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927532)  
**Title Description Comments:**

Remediation Progress Report 10/30/1985

**Action Type:** Response Requested - Other  
**Action Date:** 6/5/1985  
**Received Issue Date:** 6/5/1985  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927526](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927526)  
**Title Description Comments:**

Miscellaneous Sample Results 06/05/1985 - 10/10/1985

**Action Type:** Response Requested - Other  
**Action Date:** 1/1/1985  
**Received Issue Date:** 1/1/1985  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608501565&doc\\_id=5927523](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608501565&doc_id=5927523)  
**Title Description Comments:**

Correspondence 1985

**Action Type:** Response Requested - Workplans  
**Action Date:** 3/7/2001  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Workplan  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Workplan

**Action Type:** Leak Action  
**Action Date:** 12/26/1985  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :** 620 KB  
**Document Date:** 8/30/2007 **Submitted By:** CYNTHIA MANA-AY (REGULATOR)  
**Type:** LETTER **Submitted:**  
**Title:** CASE CLOSURE LETTER & SUMMARY FORM  
**Title Link:** [https://geotracker.waterboards.ca.gov/site\\_documents/9469288468/CLOS%5FL%5F2004%2D12%2D03%2Epdf](https://geotracker.waterboards.ca.gov/site_documents/9469288468/CLOS%5FL%5F2004%2D12%2D03%2Epdf)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** STATE INFORMATION 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501565&document\\_id=5927529](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&document_id=5927529)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** PHONE LOG 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608501565&document\\_id=5927527](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&document_id=5927527)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Type:</b>	OTHER REPORT				<b>Submitted:</b>	
<b>Title:</b>	MAP & METROSCAN INFORMATION				06/03/2005	
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;enforcement_id=6324348">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;enforcement_id=6324348</a>					
<b>Document Type:</b>	Site Documents				<b>Size :</b>	
<b>Document Date:</b>	11/15/2004				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	WELL DESTRUCTION REPORT				<b>Submitted:</b>	
<b>Title:</b>	WELL ABANDONMENT/DESTRUCTION				11/15/2004	
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927535">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927535</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	762 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D04%2D24%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D04%2D24%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	724 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D07%2D30%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D07%2D30%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	760 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D07%2D20%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D07%2D20%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	766 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D10%2D28%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D10%2D28%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	783 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2002%2D10%2D31%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2002%2D10%2D31%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	715 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D10%2D26%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D10%2D26%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	773 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D01%2D27%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D01%2D27%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	681 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	
<b>Title:</b>	GW MONITORING REPORT 10/31/2002 - 10/26/2004 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D04%2D30%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2004%2D04%2D30%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports				<b>Size :</b>	737 KB
<b>Document Date:</b>	10/31/2002				<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)
<b>Type:</b>	MONITORING REPORT - QUARTERLY				<b>Submitted:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title:</b>		GW MONITORING REPORT 10/31/2002 - 10/26/2004 -				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D01%2D15%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5823775351/GWM%5FR%5F2003%2D01%2D15%2Epdf</a>				
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	7/24/2000			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	ADDITIONAL INFORMATION REPORT 07/24/2000					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927522">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927522</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	10/16/1998			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER WORKPLAN			<b>Submitted:</b>		
<b>Title:</b>	WORK PLAN 10/16/1998 - 09/04/2002					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927536">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927536</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/26/1985			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	UNAUTHORIZED RELEASE FORM			<b>Submitted:</b>		
<b>Title:</b>	UNAUTHORIZED RELEASE FORM 12/26/1985					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927534">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927534</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	12/21/1985			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	SOIL & WATER INVESTIGATION REPORT 12/21/1985 - 10/01/2002					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927533">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927533</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	11/27/1985			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	PRELIMINARY SITE ASSESSMENT REPORT			<b>Submitted:</b>		
<b>Title:</b>	PRELIMINARY SITE ASSESSMENT REPORT 11/27/1985 - 06/26/2000					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927531">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927531</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	10/30/1985			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	REMEDIAL PROGRESS REPORT			<b>Submitted:</b>		
<b>Title:</b>	REMEDIAL PROGRESS REPORT 10/30/1985					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927532">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927532</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/5/1985			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER REPORT / DOCUMENT			<b>Submitted:</b>		
<b>Title:</b>	MISCELLANEOUS SAMPLE RESULTS 06/05/1985 - 10/10/1985					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927526">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927526</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/1/1985			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	CORRESPONDENCE			<b>Submitted:</b>		
<b>Title:</b>	CORRESPONDENCE 1985					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927523">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608501565&amp;document_id=5927523</a>					

53

1 of 2

ENE

0.48 /  
2,528.6865.00 /  
-10

**BART SYSTEM SILICON VALLEY  
BERRYESSA EXTENSION  
PROJECT  
VARIOUS LOCATIONS ALONG A  
16.3 MILE LINE, BETWEEN  
MILPITAS AND SANTA CLARA  
VARIOUS CA**

CLEANUP  
SITES

<b>Global ID:</b>	SL0608596091	<b>Latitude:</b>	37.3505777004892
<b>Status:</b>	OPEN - REMEDIATION	<b>Longitude:</b>	-121.930303573608
<b>Status Date:</b>	12/15/2020	<b>County:</b>	SANTA CLARA
<b>Site Facility Type:</b>	CLEANUP PROGRAM SITE		
<b>Data Source:</b>	Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>	43S1073	<b>Stop Method:</b>	Change Operating Procedures
<b>Local Case No:</b>		<b>CUF Case:</b>	NO
<b>Begin Date:</b>	2/1/2006	<b>Case Worker:</b>	EHD
<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database		
<b>Lead Agency:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Local Agency:</b>			
<b>Potential COC:</b>	Other Solvent or Non-Petroleum Hydrocarbon, * Solvents, Arsenic		
<b>Potential Media of Concern:</b>	Under Investigation		
<b>How Discovered:</b>	* Other Means, Site Assessment/Site Investigation		
<b>How Discovered Description:</b>			
<b>Stop Description:</b>			
<b>CalWater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>DWR GW Subbasin Name:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Disadvantaged Community:</b>	Severely Disadvantaged Community		
<b>CalEnviroScreen Score:</b>	66-70%		
<b>Site History:</b>			

The case includes oversight during the Santa Clara Valley Transportation Authority's (VTA) Silicon Valley Rapid Transit (SVRT) project that will extend the existing BART system from Fremont to Milpitas, San Jose and Santa Clara. In 2020, Phase I is complete through Berryessa in San Jose. Phase 2 will start from Berryessa to Santa Clara. The design includes plans for a new BART maintenance facility and a Santa Clara Station to be built on the former UPRR yard. VTA purchased the Site from UPRR and is now the current owner. The Site is approximately 47.5 acres of land that straddles the city limits of San Jose and Santa Clara. The Site is more than one mile in length and is bounded on the north by Brokaw Road and on the south by Newhall Street (see Site Location Map). The Site formerly had numerous sets of rails on the western side, which were removed. Land use in the surrounding area is a mix of residential, commercial, and industrial use. In 2002, 2003, and 2007, the Authority conducted soil and groundwater investigations on the Site. Soils on the Site, generally within the upper 3 feet, were found to contain petroleum hydrocarbons and certain heavy metals, including arsenic, lead, and mercury. The concentrations of these chemicals of potential concern (COPCs) in shallow soil generally exceed environmental regulatory screening levels (ESLs). Below approximately 3 feet across the Site, the levels are generally below their ESLs. Shallow groundwater at the Site was found to be impacted by volatile organic compounds from an off-site source. Shallow groundwater beneath the Site is not currently used as a source of drinking water. The San Jose Water Company supplies drinking water to the area. Construction activities at the Project will likely expose contaminated soils, groundwater, and/or other hazardous materials where they could be a potential concern to human health and the environment; therefore, management plans and/or remedial action plans have been prepared and completion reports will be submitted. The Regional Water Board's August 12, 2013, February 2, 2012, July 26, 2011, and October 21, 2008, letters (Letters) approved the remediation activities during the Project. The letters require a completion report. The February 2, 2012, letter also required a deed restriction to ensure that future workers and others are aware of post-construction conditions. Phase I BART extension completed in 2017 for Fremont, Milpitas and Berryessa/San Jose (aka C700 project). In 2018, a completion report documenting the excavation areas, and soil encapsulated areas was submitted and is under review by the Regional Water Board. Two deed restrictions have been recorded in Alameda and Santa Clara County. One deed restriction is pending. Case closure letter will be issued after all deed restrictions are recorded. Future BART extension construction will have a site management plan and remedial action plan. The remedial action plan was implemented during construction. Phase II BART extension is underway, and a remedial action plan and contaminant management plan have been approved by the Regional Water Board. A fact sheet was issued to the general public, which received no comments.

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2021-08-04 00:00:00
<b>Action:</b>	13267 Requirement
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2021-07-28 00:00:00
<b>Action:</b>	Annual Estimation Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2020-12-23 00:00:00
<b>Action:</b>	Annual Estimation Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2019-12-19 00:00:00
<b>Action:</b>	Deed Restriction / Land Use Restriction / Covenant - #2019260443
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2019-12-16 00:00:00
<b>Action:</b>	Deed Restriction / Land Use Restriction / Covenant - #24358198
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2019-12-16 00:00:00
<b>Action:</b>	Deed Restriction / Land Use Restriction / Covenant - #2019260443

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2019-11-19 00:00:00				
<b>Action:</b>		13267 Requirement				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2019-06-04 00:00:00				
<b>Action:</b>		Annual Estimation Letter				
<b>Action Type:</b>		RESPONSE				
<b>Date:</b>		2019-04-25 00:00:00				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2018-08-17 00:00:00				
<b>Action:</b>		Staff Letter				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2018-07-05 00:00:00				
<b>Action:</b>		Annual Estimation Letter				
<b>Action Type:</b>		RESPONSE				
<b>Date:</b>		2018-05-04 00:00:00				
<b>Action:</b>		Final Remedial Action Report / Corrective Action Report				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2017-06-30 00:00:00				
<b>Action:</b>		Annual Estimation Letter				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2016-06-30 00:00:00				
<b>Action:</b>		Annual Estimation Letter				
<b>Action Type:</b>		RESPONSE				
<b>Date:</b>		2015-07-27 00:00:00				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2015-07-21 00:00:00				
<b>Action:</b>		Annual Estimation Letter - #43S1073				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2015-03-18 00:00:00				
<b>Action:</b>		Letter - Notice - #43S1073				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2014-12-19 00:00:00				
<b>Action:</b>		Technical Correspondence / Assistance / Other				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2014-11-05 00:00:00				
<b>Action:</b>		Staff Letter				
<b>Action Type:</b>		RESPONSE				
<b>Date:</b>		2014-08-29 00:00:00				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2014-08-01 00:00:00				
<b>Action:</b>		Cost Recovery Agreement / N. of Reimbursement - #43S1073				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date:</b>		2014-05-21 00:00:00				
<b>Action:</b>		Staff Letter				
<b>Action Type:</b>		RESPONSE				
<b>Date:</b>		2014-03-26 00:00:00				
<b>Action:</b>		Other Report / Document				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						
<b>Action Type:</b>						
<b>Date:</b>						
<b>Action:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Date:</b>						
<b>Action:</b>					2011-10-20 00:00:00 Site Investigation	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2011-10-04 00:00:00	
<b>Action:</b>					Technical Correspondence / Assistance / Other	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2011-08-31 00:00:00	
<b>Action:</b>					CAP/RAP - Other Report	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2011-08-31 00:00:00	
<b>Action:</b>					Other Report / Document	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2011-08-30 00:00:00	
<b>Action:</b>					Corrective Action Plan / Remedial Action Plan	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2011-08-01 00:00:00	
<b>Action:</b>					Corrective Action Plan / Remedial Action Plan	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2011-07-26 00:00:00	
<b>Action:</b>					13267 Requirement	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2011-05-26 00:00:00	
<b>Action:</b>					Correspondence	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2008-10-21 00:00:00	
<b>Action:</b>					Technical Correspondence / Assistance / Other	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2008-04-21 00:00:00	
<b>Action:</b>					13267 Requirement	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2008-04-01 00:00:00	
<b>Action:</b>					CAP/RAP - Other Report	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2007-08-15 00:00:00	
<b>Action:</b>					13267 Requirement	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2007-06-21 00:00:00	
<b>Action:</b>					* No Action	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2007-06-21 00:00:00	
<b>Action:</b>					Technical Correspondence / Assistance / Other	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2006-11-03 00:00:00	
<b>Action:</b>					13267 Requirement	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2006-10-02 00:00:00	
<b>Action:</b>					Conceptual Site Model	
<b>Action Type:</b>					RESPONSE	
<b>Date:</b>					2006-03-23 00:00:00	
<b>Action:</b>					Corrective Action Plan / Remedial Action Plan	
<b>Action Type:</b>					ENFORCEMENT	
<b>Date:</b>					2006-03-20 00:00:00	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action:** Cost Recovery Agreement / N. of Reimbursement

**Action Type:** RESPONSE  
**Date:** 2006-03-20 00:00:00  
**Action:** Correspondence

**Action Type:** REMEDIATION  
**Date:** 2006-02-07 00:00:00  
**Action:** Other (Use Description Field)

**Action Type:** Other  
**Date:** 2006-02-01 00:00:00  
**Action:** Leak Discovery

**Action Type:** Other  
**Date:** 2006-02-01 00:00:00  
**Action:** Leak Reported

**Action Type:** ENFORCEMENT  
**Date:** 2006-02-01 00:00:00  
**Action:** Referral to Regional Board

**Action Type:** RESPONSE  
**Date:** 2005-12-01 00:00:00  
**Action:** Correspondence

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Open - Remediation  
**Status Date:** 2020-12-15 00:00:00

**Status:** Open - Eligible for Closure  
**Status Date:** 2020-01-02 00:00:00

**Status:** Open - Remediation  
**Status Date:** 2018-06-11 00:00:00

**Status:** Open - Remediation  
**Status Date:** 2017-07-14 00:00:00

**Status:** Open - Assessment & Interim Remedial Action  
**Status Date:** 2014-05-21 00:00:00

**Status:** Open - Site Assessment  
**Status Date:** 2006-02-10 00:00:00

**Status:** Open - Case Begin Date  
**Status Date:** 2006-02-01 00:00:00

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	EMMA HOFFMAN-DAVIES	<b>City:</b>	OAKLAND
<b>Phone No:</b>	5106222313		
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Email:</b>	emma.hoffman-davies@waterboards.ca.gov		

**Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of Sep 15, 2021)**

<b>Project Status:</b>	<b>Facility Type:</b>
<b>Cuf Claim No:</b>	<b>WDR Place Type:</b>
<b>CUF Priority Assign:</b>	<b>Wdr File No:</b>
<b>CUF Amount Paid:</b>	<b>Wdr Order No:</b>
<b>Composting Method:</b>	
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**User Defined Beneficial Use:**

**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply

**Project Oversight Agencies:**

**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=SL0608596091](https://geotracker.waterboards.ca.gov/profile_report?global_id=SL0608596091)

**Cleanup Status Detail:** OPEN - REMEDIATION AS OF 12/15/2020

**Potential COC:** ARSENIC, OTHER SOLVENT OR NON-PETROLEUM HYDROCARBON, SOLVENTS

**Potential Media of Concern:** UNDER INVESTIGATION

**Groundwater Monitoring**

**Frequen:**

**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)

**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)

**Post Closure Site Management:** DAY CARE CENTER PROHIBITED  
 ELDER CARE CENTER PROHIBITED  
 HOSPITAL USE PROHIBITED  
 LAND USE COVENANT  
 NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL  
 PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED  
 REQUIRES SURFACE COVERS  
 RESIDENCE USE PROHIBITED

**Future Land Use:**

**Cleanup Oversight Agencies:** SAN FRANCISCO BAY RWQCB (REGION 2) (LEAD) - CASE #: 43S1073  
 CASEWORKER: EMMA HOFFMAN-DAVIES  
 SANTA CLARA COUNTY

**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=SL0608596091&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=SL0608596091&tabname=regulatoryhistory)

**Site History:**

The case includes oversight during the Santa Clara Valley Transportation Authority's (VTA) Silicon Valley Rapid Transit (SVRT) project that will extend the existing BART system from Fremont to Milpitas, San Jose and Santa Clara. In 2020, Phase I is complete through Berryessa in San Jose. Phase 2 will start from Berryessa to Santa Clara.

The design includes plans for a new BART maintenance facility and a Santa Clara Station to be built on the former UPRR yard. VTA purchased the Site from UPRR and is now the current owner. The Site is approximately 47.5 acres of land that straddles the city limits of San Jose and Santa Clara. The Site is more than one mile in length and is bounded on the north by Brokaw Road and on the south by Newhall Street (see Site Location Map). The Site formerly had numerous sets of rails on the western side, which were removed. Land use in the surrounding area is a mix of residential, commercial, and industrial use.

In 2002, 2003, and 2007, the Authority conducted soil and groundwater investigations on the Site. Soils on the Site, generally within the upper 3 feet, were found to contain petroleum hydrocarbons and certain heavy metals, including arsenic, lead, and mercury. The concentrations of these chemicals of potential concern (COPCs) in shallow soil generally exceed environmental regulatory screening levels (ESLs). Below approximately 3 feet across the Site, the levels are generally below their ESLs. Shallow groundwater at the Site was found to be impacted by volatile organic compounds from an off-site source. Shallow groundwater beneath the Site is not currently used as a source of drinking water. The San Jose Water Company supplies drinking water to the area.

Construction activities at the Project will likely expose contaminated soils, groundwater, and/or other hazardous materials where they could be a potential concern to human health and the environment; therefore, management plans and/or remedial action plans have been prepared and completion reports will be submitted. The Regional Water Board's August 12, 2013, February 2, 2012, July 26, 2011, and October 21, 2008, letters (Letters) approved the remediation activities during the Project. The letters require a completion report. The February 2, 2012, letter also required a deed restriction to ensure that future workers and others are aware of post-construction conditions.

Phase I BART extension completed in 2017 for Fremont, Milpitas and Berryessa/San Jose (aka C700 project). In 2018, a completion report documenting the excavation areas, and soil encapsulated areas was submitted and is under review by the Regional Water Board. Two deed restrictions have been recorded in Alameda and Santa Clara County. One deed restriction is pending. Case closure letter will be issued after all deed restrictions are recorded. Future BART extension construction will have a site management plan and remedial action plan. The remedial action plan was implemented during construction.

Phase II BART extension is underway, and a remedial action plan and contaminant management plan have been approved by the Regional Water Board. A fact sheet was issued to the general public, which received no comments.

**Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

<b>Action Type:</b>	OTHER (USE DESCRIPTION FIELD)	<b>Begin Date:</b>	2/7/2006
<b>Phase:</b>		<b>End Date:</b>	
<b>Description:</b>			
<b>Contaminant Mass Removed:</b>			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Sites from GeoTracker Search - Regulatory Activities (as of Sep 15, 2021)**

**Action Type:** Enforcement/Orders  
**Action Date:** 8/4/2021  
**Received Issue Date:** 8/4/2021  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6472757&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6472757&temptable=ENFORCEMENT)

**Title Description Comments:**  
Approval Letter for RAP and CMP

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/28/2021  
**Received Issue Date:** 7/28/2021  
**Action:** Annual Estimation Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6472198&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6472198&temptable=ENFORCEMENT)

**Title Description Comments:**  
Annual Estimate Letter FY 21/22

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/23/2020  
**Received Issue Date:** 12/23/2020  
**Action:** Annual Estimation Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6454243&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6454243&temptable=ENFORCEMENT)

**Title Description Comments:**  
Annual Estimate Letter FY 20-21

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/19/2019  
**Received Issue Date:** 12/19/2019  
**Action:** Deed Restriction / Land Use Restriction / Covenant - #2019260443  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6424058&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6424058&temptable=ENFORCEMENT)

**Title Description Comments:**  
COVENANT AND ENVIRONMENTAL RESTRICTION, ALAMEDA COUNTY, FREMONT, MILPITAS, SAN JOSE AND 1735 S. MILPITAS BLVD., MILPITAS

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/16/2019  
**Received Issue Date:** 12/16/2019  
**Action:** Deed Restriction / Land Use Restriction / Covenant - #24358198  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6424023&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6424023&temptable=ENFORCEMENT)

**Title Description Comments:**  
Covenant and Environmental Restriction, Santa Clara County, Fremont, Milpitas, San Jose and 1735 S. Milpitas Blvd., Milpitas

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/16/2019  
**Received Issue Date:** 12/16/2019  
**Action:** Deed Restriction / Land Use Restriction / Covenant - #2019260443  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6424023&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6424023&temptable=ENFORCEMENT)

**Title Description Comments:**  
COVENANT AND ENVIRONMENTAL RESTRICTION, SANTA CLARA COUNTY, FREMONT, MILPITAS, SAN JOSE AND 1735 S. MILPITAS BLVD., MILPITAS

**Action Type:** Enforcement/Orders

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Date:</b>		11/19/2019				
<b>Received Issue Date:</b>		11/19/2019				
<b>Action:</b>		13267 Requirement				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6420990&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Approval Remediation Completion Report and Soil Management Plan				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/4/2019				
<b>Received Issue Date:</b>		6/4/2019				
<b>Action:</b>		Annual Estimation Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6404069&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Annual Estimate Letter FY 19/20				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		4/25/2019				
<b>Received Issue Date:</b>		4/25/2019				
<b>Action:</b>		Other Report / Document				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5994674				
<b>Title Description Comments:</b>		Fact Sheets on VTA BART Silicon Valley Phase II Extension (VTA Public Meeting)				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		8/17/2018				
<b>Received Issue Date:</b>		8/17/2018				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6375865&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		VTA Comfort Letter (UPRR APN 086-32-19)				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		7/5/2018				
<b>Received Issue Date:</b>		7/5/2018				
<b>Action:</b>		Annual Estimation Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6363274&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>		Annual Estimate for FY 2018/2019				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		5/4/2018				
<b>Received Issue Date:</b>		5/4/2018				
<b>Action:</b>		Final Remedial Action Report / Corrective Action Report				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5964648				
<b>Title Description Comments:</b>		Remediation Completion Report (C700) - replaced all figures and Table 2 in completion report text per Dan Pernel				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		6/30/2017				
<b>Received Issue Date:</b>		6/30/2017				
<b>Action:</b>		Annual Estimation Letter				
<b>Doc Link:</b>		https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6325170&temptable=ENFORCEMENT				
<b>Title Description Comments:</b>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Annual Estimate for SCP Cost Recovery Oversight

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/30/2016  
**Received Issue Date:** 6/30/2016  
**Action:** Annual Estimation Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6292148&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6292148&temptable=ENFORCEMENT)

**Title Description Comments:**

Annual Estimate for SCP Cost Recovery Oversight

**Action Type:** Response Requested - Other  
**Action Date:** 7/27/2015  
**Received Issue Date:** 7/27/2015  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982838](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982838)

**Title Description Comments:**

JC Manufacturing Documents, 1490 Gladding Ct, Milpitas

**Action Type:** Other Regulatory Actions  
**Action Date:** 7/21/2015  
**Received Issue Date:** 7/21/2015  
**Action:** Annual Estimation Letter - #43S1073  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6254039&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6254039&temptable=ENFORCEMENT)

**Title Description Comments:**

ANNUAL ESTIMATE FOR SCP COST RECOVERY OVERSIGHT - SAN JOSE BART EXTENSION PROJECT, SANTA CLARA COUNTY

**Action Type:** Notices  
**Action Date:** 3/18/2015  
**Received Issue Date:** 3/18/2015  
**Action:** Letter - Notice - #43S1073  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6240639&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6240639&temptable=ENFORCEMENT)

**Title Description Comments:**

Courtesy Notice - Requirement for Electronic Reporting in GeoTracker

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/19/2014  
**Received Issue Date:** 12/19/2014  
**Action:** Technical Correspondence / Assistance / Other  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6233045&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6233045&temptable=ENFORCEMENT)

**Title Description Comments:**

Confirmation of RWQCB Position on Request to Dispose of Class 2 Soils to Non-State Permitted Landfill

**Action Type:** Other Regulatory Actions  
**Action Date:** 11/5/2014  
**Received Issue Date:** 11/5/2014  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6227066&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6227066&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Ballast Encapsulation Pilot Test Report for Mix 2 and Mix 3, BART System Silicon Valley Berryessa Extension

**Action Type:** Response Requested - Other  
**Action Date:** 8/29/2014  
**Received Issue Date:** 8/29/2014

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982830](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982830)  
**Title Description Comments:**

Ballast Encapsulation Pilot Test Results

**Action Type:** Agreements  
**Action Date:** 8/1/2014  
**Received Issue Date:** 8/1/2014  
**Action:** Cost Recovery Agreement / N. of Reimbursement - #43S1073  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6216700&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6216700&temptable=ENFORCEMENT)

**Title Description Comments:**  
 ANNUAL ESTIMATE FOR SCP COST RECOVERY OVERSIGHT - SAN JOSE BART EXTENSION PROJECT, SANTA CLARA COUNTY

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/21/2014  
**Received Issue Date:** 5/21/2014  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6204447&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6204447&temptable=ENFORCEMENT)

**Title Description Comments:**  
 approval of Ballast Encapsulation Pilot Test Report for BART SVBX project

**Action Type:** Response Requested - Other  
**Action Date:** 3/26/2014  
**Received Issue Date:** 3/26/2014  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982829](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982829)  
**Title Description Comments:**

Ballast Encapsulation Pilot Test Results

**Action Type:** Response Requested - Reports  
**Action Date:** 2/13/2014  
**Received Issue Date:** 2/13/2014  
**Action:** Pilot Study/ Treatability Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5800546](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5800546)  
**Title Description Comments:**

Ballast Encapsulation Pilot Test, Silicon Valley Berryessa Extension

**Action Type:** Response Requested - Reports  
**Action Date:** 12/31/2013  
**Received Issue Date:**  
**Action:** Pilot Study/ Treatability Report  
**Doc Link:**  
**Title Description Comments:**

report on the results of pilot testing and confirmation sampling

**Action Type:** Other Regulatory Actions  
**Action Date:** 11/25/2013  
**Received Issue Date:** 11/25/2013  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6183782&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6183782&temptable=ENFORCEMENT)

**Title Description Comments:**  
 approval of Ballast Slurry Mixture Solubility Testing Procedure SVBX project

**Action Type:** Response Requested - Workplans

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Date:</b>		11/21/2013				
<b>Received Issue Date:</b>		11/21/2013				
<b>Action:</b>		Pilot Study / Treatability Workplan				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5790764">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5790764</a>				
<b>Title Description Comments:</b>		Ballast Slurry Mixture Solubility Testing Procedure SVBX project				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		8/12/2013				
<b>Received Issue Date:</b>		8/12/2013				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6171268&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6171268&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		Approval of Appendix E to CMP e-mail approval of Appendix E.				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		8/9/2013				
<b>Received Issue Date:</b>		8/9/2013				
<b>Action:</b>		CAP/RAP - Other Report				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982836">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982836</a>				
<b>Title Description Comments:</b>		In-Process Soil Transportation and Management Plan; Amendment to App E of CMP				
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		7/31/2013				
<b>Received Issue Date:</b>		7/31/2013				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6170808&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6170808&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		approval of site investigation report for Sierra and Lundy site, SJ e-mail approval				
<b>Action Type:</b>		Agreements				
<b>Action Date:</b>		7/9/2013				
<b>Received Issue Date:</b>		7/9/2013				
<b>Action:</b>		Cost Recovery Agreement / N. of Reimbursement				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6167414&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6167414&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		Annual Estimate Letter for Cost Recovery				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		5/13/2013				
<b>Received Issue Date:</b>		5/13/2013				
<b>Action:</b>		Site Investigation				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5973400">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5973400</a>				
<b>Title Description Comments:</b>		Phase II Soil and Groundwater Quality Investigation				
<b>Action Type:</b>		Response Requested - Reports				
<b>Action Date:</b>		4/10/2013				
<b>Received Issue Date:</b>		4/10/2013				
<b>Action:</b>		Site Investigation				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5976062">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5976062</a>				
<b>Title Description Comments:</b>		Site Investigation at Sierra Road & the Lundy Avenue Intersection				

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Action Type:</b>		Other Regulatory Actions				
<b>Action Date:</b>		1/22/2013				
<b>Received Issue Date:</b>		1/22/2013				
<b>Action:</b>		Staff Letter				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6148195&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6148195&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		approval of work plan for site investigation at Sierra-Lundy intersection site investigation work plan approval by email				
<b>Action Type:</b>		Response Requested - Workplans				
<b>Action Date:</b>		2/29/2012				
<b>Received Issue Date:</b>		2/29/2012				
<b>Action:</b>		Corrective Action Plan / Remedial Action Plan				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982875">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982875</a>				
<b>Title Description Comments:</b>		Contaminant Management Plan				
<b>Action Type:</b>		Enforcement/Orders				
<b>Action Date:</b>		2/2/2012				
<b>Received Issue Date:</b>		2/2/2012				
<b>Action:</b>		13267 Requirement				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6112522&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6112522&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		Approval of Remedial Action Plan and Request for Completion Report for Mission/Warren Project, Fremont, Alameda County				
<b>Action Type:</b>		Enforcement/Orders				
<b>Action Date:</b>		2/2/2012				
<b>Received Issue Date:</b>		2/2/2012				
<b>Action:</b>		13267 Requirement				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6112524&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6112524&amp;temptable=ENFORCEMENT</a>				
<b>Title Description Comments:</b>		Approval of the Remedial Action Plan and Request for Completion Report for Silicon Valley Berryessa Extension Project, Fremont, Milpitas, and San Jose, California				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		1/27/2012				
<b>Received Issue Date:</b>		1/27/2012				
<b>Action:</b>		Response to Comments				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982853">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982853</a>				
<b>Title Description Comments:</b>		VTA Response to Comments on RAP				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		1/13/2012				
<b>Received Issue Date:</b>		1/13/2012				
<b>Action:</b>		Correspondence				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982840">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982840</a>				
<b>Title Description Comments:</b>		Comments on Remedial Action Plan				
<b>Action Type:</b>		Response Requested - Other				
<b>Action Date:</b>		12/13/2011				
<b>Received Issue Date:</b>		12/13/2011				
<b>Action:</b>		Fact Sheets - Public Participation				
<b>Doc Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982843">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&amp;doc_id=5982843</a>				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Title Description Comments:**

Public Comments on Fact Sheet

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/6/2011  
**Received Issue Date:** 12/6/2011  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6108001&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6108001&temptable=ENFORCEMENT)

**Title Description Comments:**

Fact Sheet on Cleanup Plan for Portions of Silicon Valley Berryessa Extension Project in Fremont, Milpitas, and San Jose The Fact Sheet announces a proposed cleanup plan for the remediation of soils from portions of the former Union Pacific Railroad (Union Pacific) trackways from the cities of Fremont, Milpitas and San Jose. The cleanup actions consist of soil excavation and either on-site reuse or off-site disposal at an appropriately permitted disposal facility.

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/6/2011  
**Received Issue Date:** 12/6/2011  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6107999&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6107999&temptable=ENFORCEMENT)

**Title Description Comments:**

Fact Sheet on Cleanup Plan for Mission/Warren Improvement Project in Fremont The Fact Sheet announces a proposed cleanup plan for the remediation of soils from the former Union Pacific Railroad (Union Pacific) trackways at the Mission/Warren project in the city of Fremont. The cleanup actions consist of soil excavation and either on-Site reuse or off-Site disposal at an appropriately permitted disposal facility.

**Action Type:** Response Requested - Reports  
**Action Date:** 10/20/2011  
**Received Issue Date:** 10/20/2011  
**Action:** Site Investigation  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982824](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982824)

**Title Description Comments:**

555 E. Captol Ave Milpitas-Environmental Testing Results

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/4/2011  
**Received Issue Date:** 10/4/2011  
**Action:** Technical Correspondence / Assistance / Other  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6100110&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6100110&temptable=ENFORCEMENT)

**Title Description Comments:**

Approval of Arsenic Screening Level for Silicon Valley Rapid Transit Corridor along Piper Drive in Milpitas, Santa Clara County This letter responds to an August 31, 2011, e-mail requesting the use of a soil screening level of 12 parts per million (ppm) for Arsenic (As) for utility line relocations along Piper Drive in Milpitas.

**Action Type:** Response Requested - Other  
**Action Date:** 8/31/2011  
**Received Issue Date:** 8/31/2011  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5722317](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5722317)

**Title Description Comments:**

Contaminant management Plan for Silicon Valley Berryessa Extension Project

**Action Type:** Response Requested - Reports  
**Action Date:** 8/31/2011  
**Received Issue Date:** 8/31/2011  
**Action:** CAP/RAP - Other Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5722317](#)

**Title Description Comments:**

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

RAP for Silicon Valley Berryessa Extention Project

**Action Type:** Response Requested - Workplans  
**Action Date:** 8/30/2011  
**Received Issue Date:** 8/30/2011  
**Action:** Corrective Action Plan / Remedial Action Plan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5973342](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5973342)  
**Title Description Comments:**

Contaminant Management Plan (Milpitas to San Jose Ext)

**Action Type:** Response Requested - Workplans  
**Action Date:** 8/1/2011  
**Received Issue Date:** 8/1/2011  
**Action:** Corrective Action Plan / Remedial Action Plan  
**Doc Link:**  
**Title Description Comments:**

RAP Mission-Warren Fremont Area

**Action Type:** Enforcement/Orders  
**Action Date:** 7/26/2011  
**Received Issue Date:** 7/26/2011  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6093608&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6093608&temptable=ENFORCEMENT)  
**Title Description Comments:**

Approval of Addendum to Contaminant Management Plan for Silicon Valley Rapid Transit Corridor, Fremont, Milpitas, and San Jose, California

**Action Type:** Response Requested - Other  
**Action Date:** 5/26/2011  
**Received Issue Date:** 5/26/2011  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982846](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982846)  
**Title Description Comments:**

UPR Discontinue Trackage Rights and Abandon Freight Easemont

**Action Type:** Other Regulatory Actions  
**Action Date:** 10/21/2008  
**Received Issue Date:** 10/21/2008  
**Action:** Technical Correspondence / Assistance / Other  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6090755&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6090755&temptable=ENFORCEMENT)  
**Title Description Comments:**

Approval of the Contaminant Management Plan for the Bay Area Rapid Transit (BART) Extension Project to Milpitas, San Jose, and Santa Clara, Santa Clara County The CMP is intended for use during design and construction of the Project. The CMP describes how all potentially-contaminated materials associated with the Project will be characterized, evaluated, handled, transported, stored, and treated. It also provides criteria for material reuse, and contains a public participation plan.

**Action Type:** Enforcement/Orders  
**Action Date:** 4/21/2008  
**Received Issue Date:** 4/21/2008  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6379580&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6379580&temptable=ENFORCEMENT)  
**Title Description Comments:**

Approval of Remedial Action Plan Addendum for Former UPRR Newhall Yard Segment, San Jose and Santa Clara

**Action Type:** Response Requested - Reports

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Action Date:** 4/1/2008  
**Received Issue Date:** 4/1/2008  
**Action:** CAP/RAP - Other Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5981106](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5981106)  
**Title Description Comments:**

REMEDIAL ACTION PLAN ADDENDUM FOR FORMER UPRR NEWHALL YARD SEGMENT, SAN JOSE AND SANTA CLARA, PREPARED BY WEST

**Action Type:** Enforcement/Orders  
**Action Date:** 8/15/2007  
**Received Issue Date:** 8/15/2007  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6382545&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6382545&temptable=ENFORCEMENT)  
**Title Description Comments:**

Approval of RAP (UPRR Newhall Yard and Shops, San Jose and Santa Clara)

**Action Type:** Enforcement - Other  
**Action Date:** 6/21/2007  
**Received Issue Date:** 6/21/2007  
**Action:** \* No Action  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/21/2007  
**Received Issue Date:** 6/21/2007  
**Action:** Technical Correspondence / Assistance / Other  
**Doc Link:**  
**Title Description Comments:**

Fact Sheet on Remedial Action Plan for Former UPRR Newhall Yard, San Jose and Santa Clara, CA

**Action Type:** Enforcement/Orders  
**Action Date:** 11/3/2006  
**Received Issue Date:** 11/3/2006  
**Action:** 13267 Requirement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6382543&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6382543&temptable=ENFORCEMENT)  
**Title Description Comments:**

Approval of Appendix E, Public Participation Plan

**Action Type:** Response Requested - Other  
**Action Date:** 10/2/2006  
**Received Issue Date:** 10/2/2006  
**Action:** Conceptual Site Model  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982850](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982850)  
**Title Description Comments:**

VTA Response to Comments on Draft CMP

**Action Type:** Response Requested - Workplans  
**Action Date:** 3/23/2006  
**Received Issue Date:** 3/23/2006  
**Action:** Corrective Action Plan / Remedial Action Plan  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5973341](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5973341)  
**Title Description Comments:**

Draft Contaminant Mangement Plan

**Action Type:** Response Requested - Other

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

---

**Action Date:** 3/20/2006  
**Received Issue Date:** 3/20/2006  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982832](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982832)  
**Title Description Comments:**

Cost Recovery Agreement and Executed Agreement

**Action Type:** Agreements  
**Action Date:** 3/20/2006  
**Received Issue Date:** 3/20/2006  
**Action:** Cost Recovery Agreement / N. of Reimbursement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6366997&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6366997&temptable=ENFORCEMENT)  
**Title Description Comments:**

Executed Cost Recovery Agreement (2006)

**Action Type:** Cleanup Action  
**Action Date:** 2/7/2006  
**Received Issue Date:**  
**Action:** Other (Use Description Field)  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 2/1/2006  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Referral to Other Agency  
**Action Date:** 2/1/2006  
**Received Issue Date:** 2/1/2006  
**Action:** Referral to Regional Board  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6382549&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6382549&temptable=ENFORCEMENT)  
**Title Description Comments:**

Lead Agency Determination from Water Board

**Action Type:** Leak Action  
**Action Date:** 2/1/2006  
**Received Issue Date:**  
**Action:** Leak Discovery  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 12/1/2005  
**Received Issue Date:** 12/1/2005  
**Action:** Correspondence  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=SL0608596091&doc\\_id=5982844](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0608596091&doc_id=5982844)  
**Title Description Comments:**

Request for Agency Oversight Package

**Sites from GeoTracker Search - Deed Restrictions (as of Sep 15, 2021)**

**Date Recorded:** 12/19/2019  
**Site Management** DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED,

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Requirements:</b>					LAND USE COVENANT, NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, REQUIRES SURFACE COVERS, RESIDENCE USE PROHIBITED	
<b>Covenant Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1902172267/Certified%20Copy%20of%20Alameda%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation.pdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1902172267/Certified%20Copy%20of%20Alameda%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation.pdf</a>	
<b>Date Recorded:</b>					12/16/2019	
<b>Site Management Requirements:</b>					DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, REQUIRES SURFACE COVERS, RESIDENCE USE PROHIBITED	
<b>Covenant Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1713257312/Certified%20Copy%20of%20Santa%20Clara%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation%20Zone.pdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1713257312/Certified%20Copy%20of%20Santa%20Clara%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation%20Zone.pdf</a>	

**Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	8/4/2021	<b>Submitted By:</b>	EMMA HOFFMAN-DAVIES (REGULATOR)
<b>Size :</b>			
<b>Title:</b>	APPROVAL LETTER FOR RAP AND CMP **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=647275713267">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=647275713267</a>		
<b>Type:</b>	13267 REQUIREMENT		
<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	7/28/2021	<b>Submitted By:</b>	EMMA HOFFMAN-DAVIES (REGULATOR)
<b>Size :</b>			
<b>Title:</b>	ANNUAL ESTIMATE LETTER FY 21/22 **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6472198">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6472198</a>		
<b>Type:</b>	ANNUAL ESTIMATION LETTER		
<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	7/26/2021	<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	3,885 KB		
<b>Title:</b>	FINAL FACT SHEET BSVII PROJECTWIDE CMP & RAP **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6507152855/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6507152855/SL0608596091.PDF</a>		
<b>Type:</b>	FACT SHEETS - PUBLIC PARTICIPATION		
<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	7/2/2021	<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	54,741 KB		
<b>Title:</b>	BSVII PROJECTWIDE CONTAMINANT MANAGEMENT PLAN ISSUED FOR USE **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3040744245/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3040744245/SL0608596091.PDF</a>		
<b>Type:</b>	OTHER REPORT / DOCUMENT		
<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	7/2/2021	<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	99,559 KB		
<b>Title:</b>	BSVII PROJECTWIDE REMEDIAL ACTION PLAN ISSUED FOR USE **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1820087015/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1820087015/SL0608596091.PDF</a>		
<b>Type:</b>	OTHER REPORT / DOCUMENT		
<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	2/18/2021	<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	53,964 KB		
<b>Title:</b>	BSVII PROJECTWIDE CONTAMINANT MANAGEMENT PLAN **Note: Many records provided by the department have a truncated [Title] field.		
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4365392863/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4365392863/SL0608596091.PDF</a>		
<b>Type:</b>	SOIL MANAGEMENT PLAN		
<b>Document Type:</b>	Site Documents	<b>Submitted:</b>	
<b>Document Date:</b>	2/18/2021	<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	66,851 KB		
<b>Title:</b>	BSVII PROJECTWIDE REMEDIAL ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field.		

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b> <b>Type:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9132790327/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9132790327/SL0608596091.PDF</a> SOIL MANAGEMENT PLAN	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 12/23/2020				<b>Submitted:</b> <b>Submitted By:</b> EMMA HOFFMAN-DAVIES (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					ANNUAL ESTIMATE LETTER FY 20-21 **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6454243">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6454243</a> ANNUAL ESTIMATION LETTER	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 12/19/2019				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					COVENANT AND ENVIRONMENTAL RESTRICTION, ALAMEDA COUNTY, FREMONT, MILPITAS, SAN JOSE AND 1735 S. MILPITAS BLVD., MILPITAS **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6424058">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6424058</a> DEED RESTRICTION / LAND USE RESTRICTION / COVENANT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 12/16/2019				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					COVENANT AND ENVIRONMENTAL RESTRICTION, SANTA CLARA COUNTY, FREMONT, MILPITAS, SAN JOSE AND 1735 S. MILPITAS BLVD., MILPITAS **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6424023">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6424023</a> DEED RESTRICTION / LAND USE RESTRICTION / COVENANT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 11/19/2019				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					APPROVAL REMEDIATION COMPLETION REPORT AND SOIL MANAGEMENT PLAN **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6420990">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6420990</a> 13267 REQUIREMENT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 9/12/2019 78,325 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					SVBX SOIL MANAGEMENT PLAN FOR ENCAPSULATION ZONES **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2334274530/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2334274530/SL0608596091.PDF</a> REQUEST FOR CLOSURE	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 6/26/2019 19,739 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					WELL ABANDONMENT COMPLETION REPORT AT INTERSECTION OF SIERRA/LUNDY **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4685213565/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4685213565/SL0608596091.PDF</a> REQUEST FOR CLOSURE	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 6/4/2019				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					ANNUAL ESTIMATE LETTER FY 19/20 **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6404069">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6404069</a> ANNUAL ESTIMATION LETTER	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 4/25/2019				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					FACT SHEETS ON VTA BART SILICON VALLEY PHASE II EXTENSION (VTA PUBLIC MEETING) **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5994674">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5994674</a> OTHER REPORT / DOCUMENT	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/17/2018				<b>Submitted By:</b>	JEFFREY WHITE (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	VTA COMFORT LETTER (UPRR APN 086-32-19) **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6375865">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6375865</a>					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	7/5/2018				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	ANNUAL ESTIMATE FOR FY 2018/2019 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6363274">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6363274</a>					
<b>Type:</b>	ANNUAL ESTIMATION LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	294,851 KB					
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 19 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5818451166/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5818451166/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	258,056 KB					
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 5 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5431210458/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5431210458/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	279,228 KB					
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) APPENDIX I - 2016 THROUGH 2018 IDR **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7820709466/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7820709466/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	156,972 KB					
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) APPENDIX I - 2014 IDR **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3544486701/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3544486701/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018				<b>Submitted By:</b>	JOHN SEAL (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5964648">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5964648</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	146,286 KB					
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 20 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7424652338/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7424652338/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	381,627 KB					
<b>Title:</b>	REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 16 **Note: Many records provided by the department have a truncated [Title] field.					

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b> <b>Type:</b>					https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7944864094/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 347,686 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 9 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1991510212/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 378,630 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 8 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5658805549/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 337,463 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 10 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9665451288/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 323,403 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX I - 2013 IDR - PART 2 OF 2 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8010360956/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 303,832 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 6 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2875968635/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 371,867 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 7 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7352838337/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 369,796 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX G - PART 15 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7998852670/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/4/2018* 284,696 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>					REMEDATION COMPLETION REPORT (C700) APPENDIX I - 2013 IDR - PART 1 OF 2 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5671591639/SL0608596091.PDF FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT	
<b>Document Type:</b> <b>Document Date:</b>	Site Documents 5/4/2018*				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Size :</b>	343,505 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX I - 2015 IDR **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1142404377/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1142404377/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	367,182 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 12 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3817428827/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3817428827/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	381,103 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 18 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7662927448/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7662927448/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	323,413 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 4 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7064584553/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7064584553/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	353,640 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 13 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7701809823/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7701809823/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	337,040 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 14 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8229538202/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8229538202/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	339,151 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 17 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6129707038/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6129707038/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	260,613 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 3 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5477325677/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5477325677/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	147,344 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX I - 2012 IDR **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4093542933/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4093542933/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	15,112 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 21 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5649545490/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5649545490/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	391,038 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 2 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4189384162/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4189384162/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5964648">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5964648</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	348,166 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 11 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3251000463/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3251000463/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2018*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	324,876 KB					
<b>Title:</b>	REMEDIATION COMPLETION REPORT (C700) APPENDIX G - PART 1 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3555914521/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3555914521/SL0608596091.PDF</a>					
<b>Type:</b>	FINAL REMEDIAL ACTION REPORT / CORRECTIVE ACTION REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/30/2017				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	ANNUAL ESTIMATE FOR SCP COST RECOVERY OVERSIGHT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6325170">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6325170</a>					
<b>Type:</b>	ANNUAL ESTIMATION LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/12/2016				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	7,038 KB					
<b>Title:</b>	NOTICE OF POTENTIAL EXPOSURE TO CLASS 1 SOIL - BERRYESSA STATION SITE 1600 BERRYESSA ROAD, SAN JOSE **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2970804035/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2970804035/SL0608596091.PDF</a>					
<b>Type:</b>	RISK ASSESSMENT REPORT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/30/2016				<b>Submitted By:</b>	ASHA TURMAN (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	ANNUAL ESTIMATE FOR SCP COST RECOVERY OVERSIGHT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6292148">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6292148</a>					
<b>Type:</b>	ANNUAL ESTIMATION LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/31/2015*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	44,373 KB					
<b>Title:</b>	SITE SPECIFIC REMEDIAL ACTION PLAN FOR 555 E. CAPITOL AVENUE, MILPITAS, CA **Note: Many records					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>					provided by the department have a truncated [Title] field.	
<b>Type:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7858621954/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7858621954/SL0608596091.PDF</a>	
					CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/4/2015				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	822 KB					
<b>Title:</b>	BART SYSTEM SILICON VALLEY BERRYESSA EXTENSION PROJECT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2442350924/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2442350924/SL0608596091.PDF</a>	
<b>Type:</b>					INTERIM REMEDIAL ACTION REPORT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	7/27/2015				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	JC MANUFACTURING DOCUMENTS, 1490 GLADDING CT, MILPITAS **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982838">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982838</a>	
<b>Type:</b>					OTHER REPORT / DOCUMENT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	7/21/2015				<b>Submitted By:</b>	ASHA TURMAN (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	ANNUAL ESTIMATE FOR SCP COST RECOVERY OVERSIGHT - SAN JOSE BART EXTENSION PROJECT, SANTA CLARA COUNTY **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6254039">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6254039</a>	
<b>Type:</b>					ANNUAL ESTIMATION LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/18/2015				<b>Submitted By:</b>	ASHA TURMAN (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	COURTESY NOTICE - REQUIREMENT FOR ELECTRONIC REPORTING IN GEOTRACKER **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6240639">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6240639</a>	
<b>Type:</b>					LETTER - NOTICE	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/19/2014				<b>Submitted By:</b>	MAX SHAHBAZIAN (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	CONFIRMATION OF RWQCB POSITION ON REQUEST TO DISPOSE OF CLASS 2 SOILS TO NON-STATE PERMITTED LANDFILL **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6233045">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6233045</a>	
<b>Type:</b>					TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	11/17/2014				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	34,785 KB					
<b>Title:</b>	SVBX CONTAMINANT MANAGEMENT PLAN ISSUED FOR USE NOVEMBER 2014 **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7836458325/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7836458325/SL0608596091.PDF</a>	
<b>Type:</b>					OTHER WORKPLAN	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	11/5/2014				<b>Submitted By:</b>	MAX SHAHBAZIAN (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL OF BALLAST ENCAPSULATION PILOT TEST REPORT FOR MIX 2 AND MIX 3, BART SYSTEM SILICON VALLEY BERRYESSA EXTENSION **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6227066">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6227066</a>	
<b>Type:</b>					STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/29/2014				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	BALLAST ENCAPSULATION PILOT TEST RESULTS **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982830">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982830</a>	
<b>Type:</b>					OTHER REPORT / DOCUMENT	

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/1/2014				<b>Submitted:</b> <b>Submitted By:</b> ASHA TURMAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	ANNUAL ESTIMATE FOR SCP COST RECOVERY OVERSIGHT - SAN JOSE BART EXTENSION PROJECT, SANTA CLARA COUNTY **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6216700">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6216700</a> COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/21/2014				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF BALLAST ENCAPSULATION PILOT TEST REPORT FOR BART SVBX PROJECT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6204447">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6204447</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 3/26/2014				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	BALLAST ENCAPSULATION PILOT TEST RESULTS **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982829">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982829</a> OTHER REPORT / DOCUMENT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 2/13/2014				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	BALLAST ENCAPSULATION PILOT TEST, SILICON VALLEY BERRYESSA EXTENSION **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5800546">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5800546</a> PILOT STUDY/ TREATABILITY REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 11/25/2013				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF BALLAST SLURRY MIXTURE SOLUBILITY TESTING PROCEDURE SVBX PROJECT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6183782">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6183782</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 11/21/2013				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	BALLAST SLURRY MIXTURE SOLUBILITY TESTING PROCEDURE SVBX PROJECT **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5790764">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5790764</a> PILOT STUDY / TREATABILITY WORKPLAN					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/12/2013				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF APPENDIX E TO CMP **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6171268">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6171268</a> STAFF LETTER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/9/2013				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	IN-PROCESS SOIL TRANSPORTATION AND MANAGEMENT PLAN; AMENDMENT TO APP E OF CMP **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982836">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982836</a> CAP/RAP - OTHER REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 7/31/2013				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF SITE INVESTIGATION REPORT FOR SIERRA AND LUNDY SITE, SJ **Note: Many records provided by the department have a truncated [Title] field.					

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title Link:</b> <b>Type:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6170808 STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 7/9/2013				<b>Submitted:</b> <b>Submitted By:</b> MICHAEL WRIGLEY (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					ANNUAL ESTIMATE LETTER FOR COST RECOVERY **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6167414 COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/13/2013				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					PHASE II SOIL AND GROUNDWATER QUALITY INVESTIGATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5973400 SITE INVESTIGATION	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 4/10/2013				<b>Submitted:</b> <b>Submitted By:</b> MADELEINE LITTLE (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					SITE INVESTIGATION AT SIERRA ROAD & THE LUNDY AVENUE INTERSECTION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5976062 SITE INVESTIGATION	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 1/22/2013				<b>Submitted:</b> <b>Submitted By:</b> MAX SHAHBAZIAN (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					APPROVAL OF WORK PLAN FOR SITE INVESTIGATION AT SIERRA-LUNDY INTERSECTION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6148195 STAFF LETTER	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 2/29/2012				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					CONTAMINANT MANAGEMENT PLAN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5982875 CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 2/2/2012				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					APPROVAL OF REMEDIAL ACTION PLAN AND REQUEST FOR COMPLETION REPORT FOR MISSION/WARREN PROJECT, FREMONT, ALAMEDA COUNTY **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6112522 13267 REQUIREMENT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 2/2/2012				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					APPROVAL OF THE REMEDIAL ACTION PLAN AND REQUEST FOR COMPLETION REPORT FOR SILICON VALLEY BERRYESSA EXTENSION PROJECT, FREMONT, MILPITAS, AND SAN JOSE, CALIFORNIA **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6112524 13267 REQUIREMENT	
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 1/27/2012				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>					VTA RESPONSE TO COMMENTS ON RAP **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5982853 RESPONSE TO COMMENTS	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	1/13/2012				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	COMMENTS ON REMEDIAL ACTION PLAN - REGULATOR RESPONSE **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982840">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982840</a>					
<b>Type:</b>	CORRESPONDENCE					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/13/2011				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	PUBLIC COMMENTS ON FACT SHEET - REGULATOR RESPONSE **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982843">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982843</a>					
<b>Type:</b>	FACT SHEETS - PUBLIC PARTICIPATION					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/6/2011				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	FACT SHEET ON CLEANUP PLAN FOR MISSION/WARREN IMPROVEMENT PROJECT IN FREMONT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6107999">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6107999</a>					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/6/2011				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>	199 KB					
<b>Title:</b>	FACT SHEET ON CLEANUP PLAN FOR MISSION/WARREN IMPROVEMENT PROJECT IN FREMONT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/community_involvement/8662107169/Fact%20Sheet%20MW%20Dec%202011%2Epdf">https://geotracker.waterboards.ca.gov/community_involvement/8662107169/Fact%20Sheet%20MW%20Dec%202011%2Epdf</a>					
<b>Type:</b>	UPDATES AND INFORMATION - FACT SHEET					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/6/2011				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	FACT SHEET ON CLEANUP PLAN FOR PORTIONS OF SILICON VALLEY BERRYESSA EXTENSION PROJECT IN FREMONT, MILPITAS, AND SAN JOSE **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6108001">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6108001</a>					
<b>Type:</b>	STAFF LETTER					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/6/2011				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>	2,954 KB					
<b>Title:</b>	FACT SHEET ON CLEANUP PLAN FOR PORTIONS OF SILICON VALLEY BERRYESSA EXTENSION PROJECT - FREMONT, MILPITAS SAN JOSE **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/community_involvement/2105329215/Fact%20Sheet%20SVBX%20%20Dec%202011%2Epdf">https://geotracker.waterboards.ca.gov/community_involvement/2105329215/Fact%20Sheet%20SVBX%20%20Dec%202011%2Epdf</a>					
<b>Type:</b>	UPDATES AND INFORMATION - FACT SHEET					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	10/20/2011				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	555 E. CAPTOL AVE MILPITAS-ENVIRONMENTAL TESTING RESULTS **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982824">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982824</a>					
<b>Type:</b>	SITE INVESTIGATION					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	10/4/2011				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>						
<b>Title:</b>	APPROVAL OF ARSENIC SCREENING LEVEL FOR SILICON VALLEY RAPID TRANSIT CORRIDOR ALONG					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					PIPER DRIVE IN MILPITAS, SANTA CLARA COUNTY **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6100110">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6100110</a>	
<b>Type:</b>					TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/31/2011				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					CONTAMINANT MANAGEMENT PLAN FOR SILICON VALLEY BERRYESSA EXTENSION PROJECT - REGULATOR RESPONSE **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5722317">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5722317</a>	
<b>Type:</b>					OTHER REPORT / DOCUMENT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/30/2011				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					CONTAMINANT MANAGEMENT PLAN (MILPITAS TO SAN JOSE EXT) **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5973342">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5973342</a>	
<b>Type:</b>					CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/1/2011*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	19,471 KB					
<b>Title:</b>					SVBX REMEDIAL ACTION PLAN AUGUST 2011 PART II **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6775756776/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6775756776/SL0608596091.PDF</a>	
<b>Type:</b>					CAP/RAP - OTHER REPORT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/1/2011*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	16,589 KB					
<b>Title:</b>					MISSION-WARREN REMEDIAL ACTION PLAN AUGUST 2011 PART II **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6990918755/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6990918755/SL0608596091.PDF</a>	
<b>Type:</b>					CAP/RAP - OTHER REPORT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/1/2011*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	29,481 KB					
<b>Title:</b>					SVBX REMEDIAL ACTION PLAN AUGUST 2011 PART I **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7767789483/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7767789483/SL0608596091.PDF</a>	
<b>Type:</b>					CAP/RAP - OTHER REPORT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/1/2011*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	17,021 KB					
<b>Title:</b>					MISSION-WARREN REMEDIAL ACTION PLAN AUGUST 2011 PART I **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4684172868/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4684172868/SL0608596091.PDF</a>	
<b>Type:</b>					CAP/RAP - OTHER REPORT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/1/2011*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	2,436 KB					
<b>Title:</b>					MISSION-WARREN REMEDIAL ACTION PLAN AUGUST 2011 PART V **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5198911309/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5198911309/SL0608596091.PDF</a>	
<b>Type:</b>					CAP/RAP - OTHER REPORT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/1/2011*				<b>Submitted By:</b>	DAN PORNEL (RP)
<b>Size :</b>	24,094 KB					
<b>Title:</b>					MISSION-WARREN REMEDIAL ACTION PLAN AUGUST 2011 PART IV **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9252288103/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9252288103/SL0608596091.PDF</a>	
<b>Type:</b>					CAP/RAP - OTHER REPORT	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 8/1/2011* 23,980 KB				<b>Submitted:</b> <b>Submitted By:</b> DAN PORNEL (RP)	
<b>Title Link:</b> <b>Type:</b>	MISSION-WARREN REMEDIAL ACTION PLAN AUGUST 2011 PART III **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6152735412/SL0608596091.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6152735412/SL0608596091.PDF</a> CAP/RAP - OTHER REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 7/26/2011				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF ADDENDUM TO CONTAMINANT MANAGEMENT PLAN FOR SILICON VALLEY RAPID TRANSIT CORRIDOR, FREMONT, MILPITAS, AND SAN JOSE, CALIFORNIA **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=609360813267">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=609360813267</a> REQUIREMENT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/26/2011				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	UPR DISCONTINUE TRACKAGE RIGHTS AND ABANDON FREIGHT EASEMONT - REGULATOR RESPONSE **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982846">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982846</a> CORRESPONDENCE					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 5/12/2009				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	172 KB FACT SHEET FOR DIRIDON STATION IN SAN JOSE **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/community_involvement/6046949088/Fact%20Sheet%20June%202007%20Epdf">https://geotracker.waterboards.ca.gov/community_involvement/6046949088/Fact%20Sheet%20June%202007%20Epdf</a> UPDATES AND INFORMATION - FACT SHEET					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 10/21/2008				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF THE CONTAMINANT MANAGEMENT PLAN FOR THE BAY AREA RAPID TRANSIT (BART) EXTENSION PROJECT TO MILPITAS, SAN JOSE, AND SANTA CLARA, SANTA CLARA COUNTY **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6090755">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6090755</a> TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 4/21/2008				<b>Submitted:</b> <b>Submitted By:</b> CELINA HERNANDEZ (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	APPROVAL OF REMEDIAL ACTION PLAN ADDENDUM FOR FORMER UPRR NEWHALL YARD SEGMENT, SAN JOSE AND SANTA CLARA **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6379580">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=6379580</a> 13267 REQUIREMENT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 4/16/2008				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b> <b>Type:</b>	63 KB ARSENIC CONCENTRATION BACKGROUND CONCENTRATION EVALUATION **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/site_documents/9635299503/PSEC%2EVCA%20Statistical%20Analysis%20of%20Arsenic%20Background%20Epdf">https://geotracker.waterboards.ca.gov/site_documents/9635299503/PSEC%2EVCA%20Statistical%20Analysis%20of%20Arsenic%20Background%20Epdf</a> REPORT					
<b>Document Type:</b> <b>Document Date:</b> <b>Size :</b> <b>Title:</b>	Site Documents 4/16/2008				<b>Submitted:</b> <b>Submitted By:</b> ADRIANA CONSTANTINESCU (REGULATOR)	
<b>Title Link:</b>	69 KB RAP APPROVAL LETTER **Note: Many records provided by the department have a truncated [Title] field. <a href="https://geotracker.waterboards.ca.gov/site_documents/6026016056/RAP%20Approval%2008%2D15%2D07%">https://geotracker.waterboards.ca.gov/site_documents/6026016056/RAP%20Approval%2008%2D15%2D07%</a>					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Type:</b>		2Epdf LETTER				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	4/1/2008				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>		REMEDIAL ACTION PLAN ADDENDUM FOR FORMER UPRR NEWHALL YARD SEGMENT, SAN JOSE AND SANTA CLARA, PREPARED BY WEST **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5981106">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5981106</a>				
<b>Type:</b>		CAP/RAP - OTHER REPORT				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/15/2007				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>		APPROVAL OF RAP (UPRR NEWHALL YARD AND SHOPS, SAN JOSE AND SANTA CLARA) **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=638254513267">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=638254513267</a>				
<b>Type:</b>		13267 REQUIREMENT				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/28/2007				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>	172 KB					
<b>Title:</b>		FACT SHEET ON REMEDIAL ACTION PLAN FOR FORMER UPRR - NEWHALL YARD, BART EXTENSION PROJECTS **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/site_documents/4749149918/Fact%20Sheet%20June%202007%2Epdf">https://geotracker.waterboards.ca.gov/site_documents/4749149918/Fact%20Sheet%20June%202007%2Epdf</a>				
<b>Type:</b>		FACT SHEET				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/21/2007				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>	42,420 KB					
<b>Title:</b>		REMEDIAL ACTION PLAN FOR FORMER UPRR NEWHALL YARD, SAN JOSE AND SANTA CLARA, CA **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/site_documents/8289906144/Newhall%20Yard%20RAP%20June%202007%2Epdf">https://geotracker.waterboards.ca.gov/site_documents/8289906144/Newhall%20Yard%20RAP%20June%202007%2Epdf</a>				
<b>Type:</b>		REPORT				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/21/2007				<b>Submitted By:</b>	ADRIANA CONSTANTINESCU (REGULATOR)
<b>Size :</b>	151 KB					
<b>Title:</b>		APPROVAL OF APPENDIX E - PUBLIC PARTICIPATION PLAN OF THE DRAFT CONTAMINANT MANAGEMENT PLAN (CMP) FOR THE BART EXTENTION PROJECT TO SAN JOSE **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/site_documents/3307194352/BART%20extension%20%2D%20PP%20notification%2Epdf">https://geotracker.waterboards.ca.gov/site_documents/3307194352/BART%20extension%20%2D%20PP%20notification%2Epdf</a>				
<b>Type:</b>		OTHER				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	11/3/2006				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>		APPROVAL OF APPENDIX E, PUBLIC PARTICIPATION PLAN **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=638254313267">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;enforcement_id=638254313267</a>				
<b>Type:</b>		13267 REQUIREMENT				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	10/2/2006				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>		VTA RESPONSE TO COMMENTS ON DRAFT CMP **Note: Many records provided by the department have a truncated [Title] field.				
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982850">https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&amp;document_id=5982850</a>				
<b>Type:</b>		CONCEPTUAL SITE MODEL				
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	7/28/2006				<b>Submitted By:</b>	(REGULATOR)
<b>Size :</b>	70 KB					
<b>Title:</b>		4-13-06 APPROVAL LETTER FOR THE DRAFT CONTAMINANT MANAGEMENT PLAN **Note: Many records				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>					provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/site_documents/4512806534/bart%201%2Epdf	
<b>Type:</b>					LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/23/2006				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					DRAFT CONTAMINANT MANGEMENT PLAN **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5973341	
<b>Type:</b>					CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/20/2006				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					EXECUTED COST RECOVERY AGREEMENT (2006) **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6366997	
<b>Type:</b>					COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/20/2006				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					COST RECOVERY AGREEMENT AND EXECUTED AGREEMENT **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5982832	
<b>Type:</b>					CORRESPONDENCE	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	2/1/2006				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					LEAD AGENCY DETERMINATION FROM WATER BOARD **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6382549	
<b>Type:</b>					REFERRAL TO REGIONAL BOARD	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	12/1/2005				<b>Submitted By:</b>	CELINA HERNANDEZ (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					REQUEST FOR AGENCY OVERSIGHT PACKAGE **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&document_id=5982844	
<b>Type:</b>					CORRESPONDENCE	

**Sites from GeoTracker Search - Cleanup Status History (as of Sep 15, 2021)**

<b>Status:</b>	Open - Remediation
<b>Date:</b>	12/15/2020
<b>Status:</b>	Open - Eligible for Closure
<b>Date:</b>	1/2/2020
<b>Status:</b>	Open - Remediation
<b>Date:</b>	6/11/2018
<b>Status:</b>	Open - Remediation
<b>Date:</b>	7/14/2017
<b>Status:</b>	Open - Assessment & Interim Remedial Action
<b>Date:</b>	5/21/2014
<b>Status:</b>	Open - Site Assessment
<b>Date:</b>	2/10/2006
<b>Status:</b>	Open - Case Begin Date
<b>Date:</b>	2/1/2006

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<a href="#">53</a>	2 of 2	ENE	0.48 / 2,528.68	65.00 / -10	BART System Silicon Valley Berryessa Extension Project VARIOUS LOCATIONS ALONG A 16.3 MILE LINE, BETWEEN MILPITAS AND SANTA CLARA VARIOUS CA	DEED

**Global ID:** SL0608596091  
**Site Type:** Cleanup Program Site  
**Status:** Open - Remediation  
**Status Date:** 12/15/2020  
**County:** Santa Clara  
**Latitude:** 37.3505777004892  
**Longitude:** -121.930303573608  
**Search URL:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=SL0608596091](https://geotracker.waterboards.ca.gov/profile_report?global_id=SL0608596091)

**Regulatory Activities GeoTracker Download**

**Action Type:** ENFORCEMENT  
**Action:** Deed Restriction / Land Use Restriction / Covenant - #2019260443  
**Action Date:** 12/19/2019

**Action Type:** ENFORCEMENT  
**Action:** Deed Restriction / Land Use Restriction / Covenant - #24358198  
**Action Date:** 12/16/2019

**Action Type:** ENFORCEMENT  
**Action:** Deed Restriction / Land Use Restriction / Covenant - #2019260443  
**Action Date:** 12/16/2019

**GeoTracker Search - Regulatory Activities (as of Oct 20, 2021)**

**Action:** Deed Restriction / Land Use Restriction / Covenant - #2019260443  
**Action Type:** Other Regulatory Actions  
**Action Date:** 12/19/2019  
**Received Issue Date:** 12/19/2019  
**Doclink:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6424058&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6424058&temptable=ENFORCEMENT)

**Title Description Comments:**

COVENANT AND ENVIRONMENTAL RESTRICTION, ALAMEDA COUNTY, FREMONT, MILPITAS, SAN JOSE AND 1735 S. MILPITAS BLVD., MILPITAS

**GeoTracker Search - Regulatory Activities (as of Oct 20, 2021)**

**Action:** Deed Restriction / Land Use Restriction / Covenant - #24358198  
**Action Type:** Other Regulatory Actions  
**Action Date:** 12/16/2019  
**Received Issue Date:** 12/16/2019  
**Doclink:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6424023&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6424023&temptable=ENFORCEMENT)

**Title Description Comments:**

Covenant and Environmental Restriction, Santa Clara County, Fremont, Milpitas, San Jose and 1735 S. Milpitas Blvd., Milpitas

**GeoTracker Search - Regulatory Activities (as of Oct 20, 2021)**

**Action:** Deed Restriction / Land Use Restriction / Covenant - #2019260443  
**Action Type:** Other Regulatory Actions  
**Action Date:** 12/16/2019  
**Received Issue Date:** 12/16/2019  
**Doclink:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=SL0608596091&enforcement\\_id=6424058&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0608596091&enforcement_id=6424058&temptable=ENFORCEMENT)

**Title Description Comments:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

COVENANT AND ENVIRONMENTAL RESTRICTION, SANTA CLARA COUNTY, FREMONT, MILPITAS, SAN JOSE AND 1735 S. MILPITAS BLVD., MILPITAS

**GeoTracker Search - Deed Restrictions (as of Oct 20, 2021)**

**Date Recorded:** 12/16/2019  
**Site Management Requirements:** DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, REQUIRES SURFACE COVERS, RESIDENCE USE PROHIBITED  
**Covenant Doc Link:** [https://geotracker.waterboards.ca.gov/regulators/deliverable\\_documents/1713257312/Certified%20Copy%20of%20Santa%20Clara%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation%20Zone.pdf](https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1713257312/Certified%20Copy%20of%20Santa%20Clara%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation%20Zone.pdf)

**Date Recorded:** 12/19/2019  
**Site Management Requirements:** DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, REQUIRES SURFACE COVERS, RESIDENCE USE PROHIBITED  
**Covenant Doc Link:** [https://geotracker.waterboards.ca.gov/regulators/deliverable\\_documents/1902172267/Certified%20Copy%20of%20Alameda%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation.pdf](https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1902172267/Certified%20Copy%20of%20Alameda%20County%20Recorded%20Deed%20Restriction%20for%20SVBX%20Encapsulation.pdf)

<a href="#">54</a>	1 of 3	N	0.48 / 2,550.88	65.62 / -9	PG&E GAS PLANT SANTA CLARA COR BENTON & RAILROAD AVE SANTA CLARA CA 95050	CERCLIS
--------------------	--------	---	-----------------	------------	---	---------

<b>Site ID:</b> 0902400	<b>RNPL Status Code:</b> N
<b>Site EPA ID:</b> CAD981416027	<b>NPL Status:</b> Not on the NPL
<b>Site Street Address 2:</b>	<b>RFED Facility Code:</b> N
<b>Site County Name:</b> SANTA CLARA	<b>RFED Facility Desc:</b> Not a Federal Facility
<b>Site FIPS Code:</b> 06085	<b>USGS Hydro Unit No.:</b> 18050003
<b>Region Code:</b> 09	<b>Site Cong. Dist. Code:</b> 13
<b>Site SMSA No.:</b> 7400	<b>ROT Desc:</b> Unknown
<b>Site Prim. Latitude:</b> 37D20M42S	<b>FR NPL Update No.:</b>
<b>Site Prim. Longitude:</b> 121D56M48S	<b>RFRA Code:</b>
<b>Lat Long Source:</b>	
<b>RNON NPL Status Desc:</b> NRAP-Site does not qualify for the NPL based on existing information	

**CERCLIS Assess History**

<b>OU ID:</b> 00	<b>RALT Short Name:</b>
<b>Act Code ID:</b>	<b>Act Start Date:</b>
<b>RAT Code:</b>	<b>Act Complete Date:</b>
<b>RAT Short Name:</b>	<b>AGT Order No.:</b> 0
<b>RAT Name:</b>	<b>SH OU:</b>
<b>RAT Hist. Only Flag:</b>	<b>SH Code:</b>
<b>RAT NSI Indicator:</b>	<b>SH Seq:</b>
<b>RAT Level:</b>	<b>SH Start Date:</b>
<b>RAT DEF OU:</b>	<b>SH Complete Date:</b>
<b>RFBS Code:</b>	<b>SH Lead:</b>
<b>SPA Code:</b>	
<b>RAT Def:</b>	
<b>Site Desc:</b> No description available	
<b>Site Alias:</b> No alias data available	

**CERCLIS Assess History**

<b>OU ID:</b> 00	<b>RALT Short Name:</b> EPA Fund
<b>Act Code ID:</b> 001	<b>Act Start Date:</b>
<b>RAT Code:</b> PA	<b>Act Complete Date:</b> 12/1/1987 00:00:00
<b>RAT Short Name:</b> PA	<b>AGT Order No.:</b> 130
<b>RAT Name:</b> PRELIMINARY ASSESSMENT	<b>SH OU:</b>
<b>RAT Hist. Only Flag:</b>	<b>SH Code:</b>

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAT NSI Indicator:	B				SH Seq:	
RAT Level:	1				SH Start Date:	
RAT DEF OU:	00				SH Complete Date:	
RFBS Code:	P				SH Lead:	
SPA Code:	13					
RAT Def:					Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.	
Site Desc:						
Site Alias:						

**CERCLIS Assess History**

OU ID:	00	RALT Short Name:	EPA In-House
Act Code ID:	001	Act Start Date:	
RAT Code:	VS	Act Complete Date:	12/1/1987 00:00:00
RAT Short Name:	ARCH SITE	AGT Order No.:	1500
RAT Name:	ARCHIVE SITE	SH OU:	
RAT Hist. Only Flag:		SH Code:	
RAT NSI Indicator:	B	SH Seq:	
RAT Level:	1	SH Start Date:	
RAT DEF OU:	00	SH Complete Date:	
RFBS Code:		SH Lead:	
SPA Code:	13		
RAT Def:		The decision is made that no further activity is planned at the site.	
Site Desc:			
Site Alias:			

**CERCLIS Assess History**

OU ID:	00	RALT Short Name:	Other
Act Code ID:	001	Act Start Date:	
RAT Code:	DS	Act Complete Date:	6/1/1986 00:00:00
RAT Short Name:	DISCVRY	AGT Order No.:	10
RAT Name:	DISCOVERY	SH OU:	
RAT Hist. Only Flag:		SH Code:	
RAT NSI Indicator:	B	SH Seq:	
RAT Level:	1	SH Start Date:	
RAT DEF OU:	00	SH Complete Date:	
RFBS Code:		SH Lead:	
SPA Code:	13		
RAT Def:		The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.	
Site Desc:			
Site Alias:			

[54](#)

2 of 3

N

0.48 /  
2,550.88

65.62 /  
-9

PG&E GAS PLANT SANTA CLARA  
COR BENTON & RAILROAD AVE  
SANTA CLARA CA 95050

CERCLIS  
NFRAP

Site ID:	902400	Site FIPS Code:	6085
Site EPA ID:	CAD981416027	Region Code:	9
Site Parent ID:		Site Cong. Dist. Code:	13
Site County Name:	SANTA CLARA	Federal Facility:	
Parent Site Name:			

**CERCLIS-NFRAP Assess History**

OU ID:	0	Act Start Date:	
Act Code ID:	1	Act Complete Date:	6/1/1986
RAT Code:	DS	AGT Order No.:	10
RAT Short Name:	DISCVRY	SH OU:	
RAT Name:	DISCOVERY	SH Code:	
RAT Hist. Only Flag:		SH Seq:	
RAT NSI Indicator:	B	SH Start Date:	
RAT Level:	1	SH Complete Date:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAT DEF OU:	00				SH Lead:	
RFBS Code:					SH Qual:	
SPA Code:	13				RAQ Act. Qual Short:	
RALT Short Name:	Other				RNPL Status Code:	N
RAT Def:	The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.					
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information					

**CERCLIS-NFRAP Assess History**

OU ID:	0				Act Start Date:	
Act Code ID:	1				Act Complete Date:	12/1/1987
RAT Code:	PA				AGT Order No.:	130
RAT Short Name:	PA				SH OU:	
RAT Name:	PRELIMINARY ASSESSMENT				SH Code:	
RAT Hist. Only Flag:					SH Seq:	
RAT NSI Indicator:	B				SH Start Date:	
RAT Level:	1				SH Complete Date:	
RAT DEF OU:	00				SH Lead:	
RFBS Code:	P				SH Qual:	
SPA Code:	13				RAQ Act. Qual Short:	NFRAP
RALT Short Name:	EPA Fund				RNPL Status Code:	N
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.					
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information					

**CERCLIS-NFRAP Assess History**

OU ID:	0				Act Start Date:	
Act Code ID:	1				Act Complete Date:	12/1/1987
RAT Code:	VS				AGT Order No.:	1500
RAT Short Name:	ARCH SITE				SH OU:	
RAT Name:	ARCHIVE SITE				SH Code:	
RAT Hist. Only Flag:					SH Seq:	
RAT NSI Indicator:	B				SH Start Date:	
RAT Level:	1				SH Complete Date:	
RAT DEF OU:	00				SH Lead:	
RFBS Code:					SH Qual:	
SPA Code:	13				RAQ Act. Qual Short:	
RALT Short Name:	EPA In-House				RNPL Status Code:	N
RAT Def:	The decision is made that no further activity is planned at the site.					
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information					

<a href="#">54</a>	3 of 3	N	0.48 / 2,550.88	65.62 / -9	PG&E GAS PLANT SANTA CLARA COR BENTON & RAILROAD AVE SANTA CLARA CA 95050	SEMS ARCHIVE
--------------------	--------	---	--------------------	---------------	---	-----------------

Site ID:	0902400				FIPS Code:	06085
EPA ID:	CAD981416027				Cong District:	13
Superfund Alt Agmt:	No				Region:	09
Federal Facility:	No				County:	SANTA CLARA
FF Docket:	No					
NPL:	Not on the NPL					
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information					

**Action Information**

Operable Units:	00				Start Actual:	
Action Code:	VS				Finish Actual:	12/01/1987
Action Name:	ARCH SITE				Qual:	
SEQ:	1				Curr Action Lead:	EPA Perf In-Hse
Operable Units:	00				Start Actual:	06/01/1986
Action Code:	DS				Finish Actual:	06/01/1986
Action Name:	DISCVRY				Qual:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
SEQ:	1				Curr Action Lead: Other	
Operable Units:	00				Start Actual:	
Action Code:	PA				Finish Actual:	12/01/1987
Action Name:	PA				Qual:	N
SEQ:	1				Curr Action Lead:	EPA Perf

<a href="#">55</a>	1 of 4	NNW	0.48 / 2,554.32	68.92 / -6	Joe Amaral Mechanical 3390 The Alameda Santa Clara CA	LOP SANTA CLARA
SCVWD ID:		07S1W02G01f				
Closure Date:		10/31/1995				
Link:		http://lustop.sccgov.org/files/07S1W02G01f/				

<a href="#">55</a>	2 of 4	NNW	0.48 / 2,554.32	68.92 / -6	Paragon Mechanical Inc. 3390 The Alameda Santa Clara CA	LOP SANTA CLARA
SCVWD ID:		07S1W02G02f				
Closure Date:		8/4/2000				
Link:		http://lustop.sccgov.org/files/07S1W02G02f/				

<a href="#">55</a>	3 of 4	NNW	0.48 / 2,554.32	68.92 / -6	PARAGON MECHANICAL INC. 3390 THE ALAMEDA SANTA CLARA CA 95050	LUST
Global ID:		T0608500533		County:	SANTA CLARA	
Status:		COMPLETED - CASE CLOSED		Latitude:		
Status Date:				Longitude:		
Case Type:		LUST CLEANUP SITE				
Date Source:		LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

RB Case No:		Potential COC:	Diesel
Local Case No:		How Discovered:	
Begin Date:	10/6/1986	Stop Method:	
Lead Agency:	SANTA CLARA COUNTY LOP	Stop Description:	
Local Agency:	SANTA CLARA COUNTY LOP	Case Worker:	UST
CUF Case:	NO	File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media of Concern:	Other Groundwater (uses other than drinking water)		
How Discovered Description:			
Calwater Watershed Name:	Santa Clara - Palo Alto (205.50)		
DWR GW Subbasin Name:	Santa Clara Valley - Santa Clara (2-009.02)		
Disadvantaged Community:			
Calenviroscreen Score:	46-50%		
Site History:			

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

Action Type:	ENFORCEMENT
Date :	8/4/2000
Action:	Closure/No Further Action Letter
Action Type:	RESPONSE
Date :	8/1/2000
Action:	Other Report / Document

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		10/15/1997				
<b>Action:</b>		Monitoring Report - Quarterly				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		8/12/1997				
<b>Action:</b>		Staff Letter - #23658				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		6/9/1997				
<b>Action:</b>		Notice of Responsibility - #39700				
<b>Action Type:</b>		Other				
<b>Date :</b>		12/11/1986				
<b>Action:</b>		Leak Reported				
<b>Action Type:</b>		REMEDICATION				
<b>Date :</b>		11/13/1986				
<b>Action:</b>		Free Product Removal				
<b>Action Type:</b>		REMEDICATION				
<b>Date :</b>		11/13/1986				
<b>Action:</b>		Excavation				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		
<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	8/4/2000
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	11/6/1986
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	10/6/1986
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	10/6/1986

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	PARAGON MECHANICAL INC.	<b>Potential COC:</b>	DIESEL
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	3390 THE ALAMEDA
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500533">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500533</a>		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 8/4/2000  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608500533&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500533&tabname=regulatoryhistory)  
**Potential Media of Concern:** OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02G02f  
**Gndwater Monitoring Freque:**  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Site History:**

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 8/4/2000  
  
**Status:** Open - Site Assessment  
**Date :** 11/6/1986  
  
**Status:** Open - Site Assessment  
**Date :** 10/6/1986  
  
**Status:** Open - Case Begin Date  
**Date :** 10/6/1986

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

<b>Action Type:</b>	EXCAVATION	<b>Begin Date:</b>	11/13/1986
<b>Phase:</b>		<b>End Date:</b>	12/31/1997
<b>Contaminant Mass Removed:</b>			
<b>Description:</b>			
<b>Action Type:</b>	FREE PRODUCT REMOVAL	<b>Begin Date:</b>	11/13/1986
<b>Phase:</b>		<b>End Date:</b>	12/31/1997
<b>Contaminant Mass Removed:</b>			
<b>Description:</b>			

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/4/2000  
**Received Issue Date:** 8/4/2000  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500533&enforcement\\_id=6260125&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500533&enforcement_id=6260125&temptable=ENFORCEMENT)  
**Title Description Comments:**  
  
**Action Type:** Response Requested - Other  
**Action Date:** 8/1/2000  
**Received Issue Date:** 8/1/2000  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500533&doc\\_id=5856882](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500533&doc_id=5856882)  
**Title Description Comments:**

SCVWD ELECTRONIC FILES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/12/1997  
**Received Issue Date:** 8/12/1997  
**Action:** Staff Letter - #23658  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 6/9/1997  
**Received Issue Date:** 6/9/1997  
**Action:** Notice of Responsibility - #39700  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 10/15/1997  
**Received Issue Date:**  
**Action:** Monitoring Report - Quarterly  
**Doc Link:**  
**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Leak Action  
**Action Date:** 12/11/1986  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Cleanup Action  
**Action Date:** 11/13/1986  
**Received Issue Date:**  
**Action:** Excavation  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Cleanup Action  
**Action Date:** 11/13/1986  
**Received Issue Date:**  
**Action:** Free Product Removal  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :**  
**Document Date:** 8/4/2000 **Submitted By:** CANDACE GARCIA (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER **Submitted:**  
**Title:** UNKNOWN  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500533&enforcement\\_id=6260125](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500533&enforcement_id=6260125)

**Document Type:** Site Documents **Size :**  
**Document Date:** 8/1/2000 **Submitted By:** CANDACE GARCIA (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** SCVWD ELECTRONIC FILES  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500533&document\\_id=5856882](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500533&document_id=5856882)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**SANTA CLARA CA 95050**

**Global ID:** T0608502285 **County:** SANTA CLARA  
**Status:** COMPLETED - CASE CLOSED **Latitude:**  
**Status Date:** **Longitude:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Potential COC:** Gasoline  
**Local Case No:** **How Discovered:**  
**Begin Date:** 1/1/1992 **Stop Method:**  
**Lead Agency:** SANTA CLARA COUNTY LOP **Stop Description:**  
**Local Agency:** SANTA CLARA COUNTY LOP **Case Worker:** UST  
**CUF Case:** NO **File Location:** All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Soil  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 46-50%  
**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

**Action Type:** ENFORCEMENT  
**Date :** 10/31/1995  
**Action:** Closure/No Further Action Letter  
  
**Action Type:** RESPONSE  
**Date :** 4/29/1993  
**Action:** Other Report / Document  
  
**Action Type:** Other  
**Date :** 1/1/1992  
**Action:** Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Local Agency Caseworker **Address:** 1555 Berger Drive, Suite 300  
**Contact Name:** UST CASE WORKER **Email:**  
**City:** SAN JOSE **Phone No:** 4089183400  
**Organization Name:** SANTA CLARA COUNTY LOP  
  
**Contact Type:** Regional Board Caseworker **Address:** 1515 CLAY ST SUITE 1400  
**Contact Name:** Regional Water Board **Email:**  
**City:** OAKLAND **Phone No:**  
**Organization Name:** SAN FRANCISCO BAY RWQCB (REGION 2)

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 10/31/1995  
  
**Status:** Open - Case Begin Date  
**Status Date:** 1/1/1992

**LUST Sites from GeoTracker Search - Regulatory Profile**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

<b>Site Facility Name:</b>	JOE AMARAL MECHANICAL	<b>Potential COC:</b>	GASOLINE			
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>				
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>				
<b>Project Status:</b>		<b>Address:</b>	3390 THE ALAMEDA			
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA			
<b>WDR File:</b>		<b>Zip:</b>	95050			
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA			
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>				
<b>CUF Amount Paid:</b>						
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE					
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC					
<b>Project Oversight Agencies:</b>						
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502285">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502285</a>					
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 10/31/1995					
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502285&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502285&amp;tabname=regulatoryhistory</a>					
<b>Potential Media of Concern:</b>	SOIL					
<b>User Defined Beneficial Use:</b>						
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)					
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)					
<b>Post Closure Site Management:</b>						
<b>Future Land Use:</b>						
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W02G01f					
<b>Gndwater Monitoring Freque:</b>						
<b>Designated Beneficial Use Desc:</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply					
<b>Site History:</b>						

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

<b>Status:</b>	Completed - Case Closed
<b>Date :</b>	10/31/1995
<b>Status:</b>	Open - Case Begin Date
<b>Date :</b>	1/1/1992

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

<b>Action Type:</b>	Other Regulatory Actions
<b>Action Date:</b>	10/31/1995
<b>Received Issue Date:</b>	10/31/1995
<b>Action:</b>	Closure/No Further Action Letter
<b>Doc Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502285&amp;enforcement_id=6146947&amp;temptable=ENFORCEMENT">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502285&amp;enforcement_id=6146947&amp;temptable=ENFORCEMENT</a>

**Title Description Comments:**

<b>Action Type:</b>	Response Requested - Other
<b>Action Date:</b>	4/29/1993
<b>Received Issue Date:</b>	4/29/1993
<b>Action:</b>	Other Report / Document
<b>Doc Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502285&amp;doc_id=5760313">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502285&amp;doc_id=5760313</a>

**Title Description Comments:**

SCVWD Electronic Files

<b>Action Type:</b>	Leak Action
<b>Action Date:</b>	1/1/1992
<b>Received Issue Date:</b>	
<b>Action:</b>	Leak Reported

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Doc Link:  
Title Description Comments:

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	10/31/1995	<b>Submitted By:</b>	COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER	<b>Submitted:</b>	
<b>Title:</b>	UNKNOWN		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502285&enforcement_id=6146947		
<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	4/29/1993	<b>Submitted By:</b>	COUNTY OF SANTA CLARA STUDENT INTERN (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT	<b>Submitted:</b>	
<b>Title:</b>	SCVWD ELECTRONIC FILES - REGULATOR RESPONSE		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502285&document_id=5760313		

<a href="#">56</a>	1 of 2	E	0.49 / 2,563.82	65.00 / -10	Custom Food Machinery 1180 Campbell Ave San Jose CA	LOP SANTA CLARA
--------------------	--------	---	--------------------	----------------	---	--------------------

SCVWD ID: 07S1W01P06f  
Closure Date: 8/13/1992  
Link: http://lustop.sccgov.org/files/07S1W01P06f/

<a href="#">56</a>	2 of 2	E	0.49 / 2,563.82	65.00 / -10	CUSTOM FOOD MACHINERY 1180 CAMPBELL AVE SAN JOSE CA 95126	LUST
--------------------	--------	---	--------------------	----------------	---	------

Global ID: T0608500482  
Status: COMPLETED - CASE CLOSED  
Status Date:  
Case Type: LUST CLEANUP SITE  
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

County: SANTA CLARA  
Latitude:  
Longitude:

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>		<b>Potential COC:</b>	Diesel
<b>Local Case No:</b>		<b>How Discovered:</b>	
<b>Begin Date:</b>	7/31/1991	<b>Stop Method:</b>	
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP	<b>Stop Description:</b>	
<b>Local Agency:</b>	SANTA CLARA COUNTY LOP	<b>Case Worker:</b>	UST
<b>CUF Case:</b>	NO	<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Soil  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 41-45%  
**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

**Action Type:** ENFORCEMENT  
**Date :** 9/9/1996  
**Action:** Staff Letter - #43-0432

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		5/25/1995				
<b>Action:</b>		Staff Letter - #0349				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		4/28/1995				
<b>Action:</b>		Clean Up Fund - Letter to RP - #0349				
<b>Action Type:</b>		RESPONSE				
<b>Date :</b>		8/13/1992				
<b>Action:</b>		Other Report / Document				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		8/13/1992				
<b>Action:</b>		Closure/No Further Action Letter				
<b>Action Type:</b>		ENFORCEMENT				
<b>Date :</b>		7/30/1992				
<b>Action:</b>		Notice of Responsibility - #39686				
<b>Action Type:</b>		REMEDIATION				
<b>Date :</b>		7/31/1991				
<b>Action:</b>		Excavation				
<b>Action Type:</b>		Other				
<b>Date :</b>		7/31/1991				
<b>Action:</b>		Leak Reported				

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		
<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

<b>Status:</b>	Completed - Case Closed
<b>Status Date:</b>	8/13/1992
<b>Status:</b>	Open - Site Assessment
<b>Status Date:</b>	7/31/1991
<b>Status:</b>	Open - Case Begin Date
<b>Status Date:</b>	7/31/1991

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	CUSTOM FOOD MACHINERY	<b>Potential COC:</b>	DIESEL
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	1180 CAMPBELL AVE
<b>WDR Place Type:</b>		<b>City:</b>	SAN JOSE
<b>WDR File:</b>		<b>Zip:</b>	95126
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T0608500482](https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500482)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 8/13/1992  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608500482&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500482&tabname=regulatoryhistory)  
**Potential Media of Concern:** SOIL  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W01P06f  
**Gndwater Monitoring Freque:**  
**Designated Beneficial Use** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Desc:**  
**Site History:**

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 8/13/1992  
  
**Status:** Open - Site Assessment  
**Date :** 7/31/1991  
  
**Status:** Open - Case Begin Date  
**Date :** 7/31/1991

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** EXCAVATION  
**Phase:**  
**Contaminant Mass Removed:**  
**Description:**  
  
**Begin Date:** 7/31/1991  
**End Date:** 9/7/1991

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 9/9/1996  
**Received Issue Date:** 9/9/1996  
**Action:** Staff Letter - #43-0432  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6264585&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6264585&temptable=ENFORCEMENT)  
**Title Description Comments:**

Site Investigations and Remedial Activities

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/25/1995  
**Received Issue Date:** 5/25/1995  
**Action:** Staff Letter - #0349  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6261149&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6261149&temptable=ENFORCEMENT)  
**Title Description Comments:**

Custom Food Machinery

**Action Type:** Other Regulatory Actions  
**Action Date:** 4/28/1995

**Received Issue Date:** 4/28/1995  
**Action:** Clean Up Fund - Letter to RP - #0349  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6261151&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6261151&temptable=ENFORCEMENT)

**Title Description Comments:**

Spill, Leaks, Investigations and Cleanups (SLIC) Program for Oversight Costs

**Action Type:** Response Requested - Other  
**Action Date:** 8/13/1992  
**Received Issue Date:** 8/13/1992  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500482&doc\\_id=5716591](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500482&doc_id=5716591)

**Title Description Comments:**

SCVWD MICROFICHE OF FILES

**Action Type:** Response Requested - Other  
**Action Date:** 8/13/1992  
**Received Issue Date:** 8/13/1992  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500482&doc\\_id=5716389](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500482&doc_id=5716389)

**Title Description Comments:**

SCVWD MICROFICHE OF FILES

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/13/1992  
**Received Issue Date:** 8/13/1992  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6091110&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6091110&temptable=ENFORCEMENT)

**Title Description Comments:**

**Action Type:** Notices  
**Action Date:** 7/30/1992  
**Received Issue Date:** 7/30/1992  
**Action:** Notice of Responsibility - #39686

**Title Description Comments:**

**Action Type:** Leak Action  
**Action Date:** 7/31/1991  
**Received Issue Date:**  
**Action:** Leak Reported

**Title Description Comments:**

**Action Type:** Cleanup Action  
**Action Date:** 7/31/1991  
**Received Issue Date:**  
**Action:** Excavation

**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b> Site Documents	<b>Size :</b>
<b>Document Date:</b> 9/9/1996	<b>Submitted By:</b> ASHA TURMAN (REGULATOR)
<b>Type:</b> STAFF LETTER	<b>Submitted:</b>
<b>Title:</b> SITE INVESTIGATIONS AND REMEDIAL ACTIVITIES	
<b>Title Link:</b> <a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&amp;enforcement_id=6264585">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&amp;enforcement_id=6264585</a>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Document Type:** Site Documents **Size :**  
**Document Date:** 5/25/1995 **Submitted By:** ASHA TURMAN (REGULATOR)  
**Type:** STAFF LETTER **Submitted:**  
**Title:** CUSTOM FOOD MACHINERY  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6261149](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6261149)

**Document Type:** Site Documents **Size :**  
**Document Date:** 4/28/1995 **Submitted By:** ASHA TURMAN (REGULATOR)  
**Type:** CLEAN UP FUND - LETTER TO RP **Submitted:**  
**Title:** SPILL, LEAKS, INVESTIGATIONS AND CLEANUPS (SLIC) PROGRAM FOR OVERSIGHT COSTS  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6261151](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6261151)

**Document Type:** Site Documents **Size :**  
**Document Date:** 8/13/1992 **Submitted By:** (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** SCVWD MICROFICHE OF FILES - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&document\\_id=5716389](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&document_id=5716389)

**Document Type:** Site Documents **Size :**  
**Document Date:** 8/13/1992 **Submitted By:** (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** SCVWD MICROFICHE OF FILES - REGULATOR RESPONSE  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&document\\_id=5716591](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&document_id=5716591)

**Document Type:** Site Documents **Size :**  
**Document Date:** 8/13/1992 **Submitted By:** (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER **Submitted:**  
**Title:** UNKNOWN  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500482&enforcement\\_id=6091110](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500482&enforcement_id=6091110)

<a href="#">57</a>	1 of 2	E	0.49 / 2,586.66	65.81 / -9	Blue's Roofing 1181 Campbell Ave San Jose CA	LOP SANTA CLARA
--------------------	--------	---	--------------------	---------------	--	--------------------

**SCVWD ID:** 07S1W01N02f  
**Closure Date:** 5/14/2004  
**Link:** <http://lustop.sccgov.org/files/07S1W01N02f/>

<a href="#">57</a>	2 of 2	E	0.49 / 2,586.66	65.81 / -9	BLUE'S ROOFING 1181 CAMPBELL AVE SAN JOSE CA 95126	LUST
--------------------	--------	---	--------------------	---------------	--	------

**Global ID:** T0608502018 **County:** SANTA CLARA  
**Status:** COMPLETED - CASE CLOSED **Latitude:**  
**Status Date:** **Longitude:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:** **Potential COC:** Gasoline  
**Local Case No:** **How Discovered:**  
**Begin Date:** 5/22/1996 **Stop Method:**  
**Lead Agency:** SANTA CLARA COUNTY LOP **Stop Description:**  
**Local Agency:** SANTA CLARA COUNTY LOP **Case Worker:** UST  
**CUF Case:** YES **File Location:** All Files are on GeoTracker or in the Local Agency Database

**Potential Media of Concern:** Other Groundwater (uses other than drinking water)  
**How Discovered Description:**  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 41-45%

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/19/2007
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report / Document
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	6/3/2005
<b>Action:</b>	Other Report
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	5/14/2004
<b>Action:</b>	Closure/No Further Action Letter
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	4/7/2004
<b>Action:</b>	Well Destruction Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	4/15/2001
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	4/2/2001
<b>Action:</b>	Monitoring Report - Quarterly
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	12/15/2000
<b>Action:</b>	Staff Letter - #23520
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	12/4/2000
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	11/9/2000
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	10/17/2000
<b>Action:</b>	Staff Letter - #23518
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	5/28/1999
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	4/22/1999
<b>Action:</b>	Soil and Water Investigation Report
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	4/19/1999
<b>Action:</b>	Staff Letter - #23515
<b>Action Type:</b>	ENFORCEMENT
<b>Date :</b>	3/23/1999
<b>Action:</b>	Staff Letter - #23513
<b>Action Type:</b>	RESPONSE
<b>Date :</b>	3/12/1999
<b>Action:</b>	Other Workplan

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Action Type:** RESPONSE  
**Date :** 1/20/1999  
**Action:** Soil and Water Investigation Report

**Action Type:** ENFORCEMENT  
**Date :** 12/21/1998  
**Action:** Staff Letter - #23509

**Action Type:** RESPONSE  
**Date :** 1/1/1998  
**Action:** Correspondence

**Action Type:** Other  
**Date :** 7/21/1997  
**Action:** Leak Reported

**Action Type:** RESPONSE  
**Date :** 1/14/1997  
**Action:** Unauthorized Release Form

**Action Type:** RESPONSE  
**Date :** 6/11/1996  
**Action:** Preliminary Site Assessment Report

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Local Agency Caseworker  
**Contact Name:** UST CASE WORKER  
**City:** SAN JOSE  
**Organization Name:** SANTA CLARA COUNTY LOP  
**Address:** 1555 Berger Drive, Suite 300  
**Email:**  
**Phone No:** 4089183400

**Contact Type:** Regional Board Caseworker  
**Contact Name:** Regional Water Board  
**City:** OAKLAND  
**Organization Name:** SAN FRANCISCO BAY RWQCB (REGION 2)  
**Address:** 1515 CLAY ST SUITE 1400  
**Email:**  
**Phone No:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 5/14/2004

**Status:** Open - Site Assessment  
**Status Date:** 5/22/1996

**Status:** Open - Case Begin Date  
**Status Date:** 5/22/1996

**LUST Sites from GeoTracker Search - Regulatory Profile**

**Site Facility Name:** BLUE'S ROOFING  
**Site Facility Type:** LUST CLEANUP SITE  
**Cleanup Status:** COMPLETED - CASE CLOSED  
**Project Status:**  
**WDR Place Type:**  
**WDR File:**  
**WDR Order:**  
**CUF Priority Assig:** C  
**CUF Amount Paid:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T0608502018](https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608502018)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 5/14/2004  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T0608502018&tabname=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608502018&tabname=regulatoryhistory)

**Potential COC:** GASOLINE  
**Facility Type:**  
**Composting Method:**  
**Address:** 1181 CAMPBELL AVE  
**City:** SAN JOSE  
**Zip:** 95126  
**County:** SANTA CLARA  
**CUF Claim:** 16714

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Potential Media of Concern:** OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)  
**User Defined Beneficial Use:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD)  
CASEWORKER: UST CASE WORKER  
SAN FRANCISCO BAY RWQCB (REGION 2)  
CASEWORKER: Regional Water Board  
SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W01N02f

**Gndwater Monitoring Freque:**  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Site History:**  
No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

**Status:** Completed - Case Closed  
**Date :** 5/14/2004

**Status:** Open - Site Assessment  
**Date :** 5/22/1996

**Status:** Open - Case Begin Date  
**Date :** 5/22/1996

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 6/19/2007  
**Received Issue Date:** 6/19/2007  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502018&doc\\_id=5927315](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&doc_id=5927315)  
**Title Description Comments:**

State Information 06/19/2007

**Action Type:** Reports  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502018&enforcement\\_id=6324273&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&enforcement_id=6324273&temptable=ENFORCEMENT)  
**Title Description Comments:**

Map & Metroscan Information 06/03/2005

**Action Type:** Response Requested - Other  
**Action Date:** 6/3/2005  
**Received Issue Date:** 6/3/2005  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608502018&doc\\_id=5927313](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&doc_id=5927313)  
**Title Description Comments:**

Phone Log 06/03/2005

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/14/2004  
**Received Issue Date:** 5/14/2004  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?](https://geotracker.waterboards.ca.gov/view_documents?)

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
global_id=T0608502018&enforcement_id=6324272&temptable=ENFORCEMENT						
<b>Title Description Comments:</b>						
Closure 05/14/2004						
<b>Action Type:</b> Response Requested - Reports						
<b>Action Date:</b> 4/7/2004						
<b>Received Issue Date:</b> 4/7/2004						
<b>Action:</b> Well Destruction Report						
<b>Doc Link:</b> <a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927318">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927318</a>						
<b>Title Description Comments:</b>						
Well Abandonment/Destruction 04/07/2004						
<b>Action Type:</b> Response Requested - Reports						
<b>Action Date:</b> 4/15/2001						
<b>Received Issue Date:</b> 4/19/2001						
<b>Action:</b> Monitoring Report - Quarterly						
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
Monitoring Report - Quarterly						
<b>Action Type:</b> Response Requested - Reports						
<b>Action Date:</b> 4/2/2001						
<b>Received Issue Date:</b> 4/2/2001						
<b>Action:</b> Monitoring Report - Quarterly						
<b>Doc Link:</b> <a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927312">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927312</a>						
<b>Title Description Comments:</b>						
GW Monitoring Report 04/02/2001 - 07/02/2001						
<b>Action Type:</b> Other Regulatory Actions						
<b>Action Date:</b> 12/15/2000						
<b>Received Issue Date:</b> 12/15/2000						
<b>Action:</b> Staff Letter - #23520						
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b> Response Requested - Reports						
<b>Action Date:</b> 12/4/2000						
<b>Received Issue Date:</b> 11/22/2000						
<b>Action:</b> Soil and Water Investigation Report						
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
Soil and Water Investigation Report						
<b>Action Type:</b> Response Requested - Reports						
<b>Action Date:</b> 11/9/2000						
<b>Received Issue Date:</b> 11/9/2000						
<b>Action:</b> Soil and Water Investigation Report						
<b>Doc Link:</b> <a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927316">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927316</a>						
<b>Title Description Comments:</b>						
Soil & Water Investigation Report 11/09/2000						
<b>Action Type:</b> Other Regulatory Actions						
<b>Action Date:</b> 10/17/2000						
<b>Received Issue Date:</b> 10/17/2000						
<b>Action:</b> Staff Letter - #23518						
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					4/22/1999	
<b>Received Issue Date:</b>					4/15/1999	
<b>Action:</b>					Soil and Water Investigation Report	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
					Soil and Water Investigation Report	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					4/19/1999	
<b>Received Issue Date:</b>					4/19/1999	
<b>Action:</b>					Staff Letter - #23515	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					3/23/1999	
<b>Received Issue Date:</b>					3/23/1999	
<b>Action:</b>					Staff Letter - #23513	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Workplans	
<b>Action Date:</b>					3/12/1999	
<b>Received Issue Date:</b>					3/12/1999	
<b>Action:</b>					Other Workplan	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927319">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927319</a>	
<b>Title Description Comments:</b>						
					Work Plan 03/12/1999 - 03/18/1999	
<b>Action Type:</b>					Other Regulatory Actions	
<b>Action Date:</b>					12/21/1998	
<b>Received Issue Date:</b>					12/21/1998	
<b>Action:</b>					Staff Letter - #23509	
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					1/1/1998	
<b>Received Issue Date:</b>					1/1/1998	
<b>Action:</b>					Correspondence	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927311">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927311</a>	
<b>Title Description Comments:</b>						
					Correspondence 1998	
<b>Action Type:</b>					Response Requested - Other	
<b>Action Date:</b>					1/14/1997	
<b>Received Issue Date:</b>					1/14/1997	
<b>Action:</b>					Unauthorized Release Form	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927317">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927317</a>	
<b>Title Description Comments:</b>						
					Unauthorized Release Form 01/14/1997 - 05/02/2007	
<b>Action Type:</b>					Response Requested - Reports	
<b>Action Date:</b>					6/11/1996	
<b>Received Issue Date:</b>					6/11/1996	
<b>Action:</b>					Preliminary Site Assessment Report	
<b>Doc Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927314">https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608502018&amp;doc_id=5927314</a>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Title Description Comments:**

Preliminary Site Assessment Report 06/11/1996 - 04/05/1999

**Action Type:** Response Requested - Reports  
**Action Date:** 5/28/1999  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Response Requested - Reports  
**Action Date:** 1/20/1999  
**Received Issue Date:**  
**Action:** Soil and Water Investigation Report  
**Doc Link:**  
**Title Description Comments:**

Soil and Water Investigation Report

**Action Type:** Leak Action  
**Action Date:** 7/21/1997  
**Received Issue Date:**  
**Action:** Leak Reported  
**Doc Link:**  
**Title Description Comments:**

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents **Size :** 293 KB  
**Document Date:** 10/4/2007 **Submitted By:** CYNTHIA MANA-AY (REGULATOR)  
**Type:** LETTER **Submitted:**  
**Title:** CLOSURE LETTER & SITE CLOSURE SUMMARY  
**Title Link:** [https://geotracker.waterboards.ca.gov/site\\_documents/1835575699/CLOS%5FL%5F2004%2D04%2D27%2Epdf](https://geotracker.waterboards.ca.gov/site_documents/1835575699/CLOS%5FL%5F2004%2D04%2D27%2Epdf)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/19/2007 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** STATE INFORMATION 06/19/2007  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502018&document\\_id=5927315](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&document_id=5927315)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT / DOCUMENT **Submitted:**  
**Title:** PHONE LOG 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502018&document\\_id=5927313](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&document_id=5927313)

**Document Type:** Site Documents **Size :**  
**Document Date:** 6/3/2005 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** OTHER REPORT **Submitted:**  
**Title:** MAP & METROSCAN INFORMATION 06/03/2005  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502018&enforcement\\_id=6324273](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&enforcement_id=6324273)

**Document Type:** Site Documents **Size :**  
**Document Date:** 5/14/2004 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** CLOSURE/NO FURTHER ACTION LETTER **Submitted:**  
**Title:** CLOSURE 05/14/2004  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608502018&enforcement\\_id=6324272](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&enforcement_id=6324272)

**Document Type:** Site Documents **Size :**  
**Document Date:** 4/7/2004 **Submitted By:** MICHAEL SCHUSTER (REGULATOR)  
**Type:** WELL DESTRUCTION REPORT **Submitted:**  
**Title:** WELL ABANDONMENT/DESTRUCTION 04/07/2004

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>		<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927318">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927318</a>				
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,269 KB	
<b>Document Date:</b>	4/2/2001			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 04/02/2001 - 07/02/2001 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4565978109/GWM%5FR%5F2001%2D07%2D02%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4565978109/GWM%5FR%5F2001%2D07%2D02%2Epdf</a>					
<b>Document Type:</b>	Monitoring Reports			<b>Size :</b>	1,735 KB	
<b>Document Date:</b>	4/2/2001			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	MONITORING REPORT - QUARTERLY			<b>Submitted:</b>		
<b>Title:</b>	GW MONITORING REPORT 04/02/2001 - 07/02/2001 -					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4565978109/GWM%5FR%5F2001%2D04%2D02%2Epdf">https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4565978109/GWM%5FR%5F2001%2D04%2D02%2Epdf</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	11/9/2000			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	SOIL AND WATER INVESTIGATION REPORT			<b>Submitted:</b>		
<b>Title:</b>	SOIL & WATER INVESTIGATION REPORT 11/09/2000					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927316">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927316</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	3/12/1999			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	OTHER WORKPLAN			<b>Submitted:</b>		
<b>Title:</b>	WORK PLAN 03/12/1999 - 03/18/1999					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927319">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927319</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/1/1998			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	CORRESPONDENCE			<b>Submitted:</b>		
<b>Title:</b>	CORRESPONDENCE 1998					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927311">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927311</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	1/14/1997			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	UNAUTHORIZED RELEASE FORM			<b>Submitted:</b>		
<b>Title:</b>	UNAUTHORIZED RELEASE FORM 01/14/1997 - 05/02/2007					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927317">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927317</a>					
<b>Document Type:</b>	Site Documents			<b>Size :</b>		
<b>Document Date:</b>	6/11/1996			<b>Submitted By:</b>	MICHAEL SCHUSTER (REGULATOR)	
<b>Type:</b>	PRELIMINARY SITE ASSESSMENT REPORT			<b>Submitted:</b>		
<b>Title:</b>	PRELIMINARY SITE ASSESSMENT REPORT 06/11/1996 - 04/05/1999					
<b>Title Link:</b>	<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927314">https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608502018&amp;document_id=5927314</a>					

58

1 of 1

E

0.49 /  
2,607.0966.32 /  
-9SAFWAY  
1177 CAMPBELL AVENUE  
SAN JOSE CA 95126

ENVIROSTOR

<b>Estor/EPA ID:</b>	70000012	<b>Assembly District:</b>	28
<b>Site Code:</b>		<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-56-031, 23013012	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	EVALUATION	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1177 CAMPBELL AVENUE	<b>Latitude:</b>	37.3469528891293
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.9280397892
<b>Special Program:</b>		<b>Acres:</b>	2.67 ACRES
<b>Funding:</b>	NOT APPLICABLE	<b>Supervisor:</b>	KAREN TOTTH
<b>Cleanup Status:</b>	NO ACTION REQUIRED AS OF 10/21/2005		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	NONE		
<b>Potential Media Affected:</b>	NO MEDIA AFFECTED		
<b>Potential Contamin of Concern:</b>			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

NO CONTAMINANTS FOUND

**Site History:**

The site is located at 1177 Campbell Avenue, San Jose, Santa Clara County, California 95126. The Site property consists of 2.67 acres. The site has one single-story warehouse type building, which is 23,480 square feet in size. The building is split into three tenant areas. The front of the property is fenced off and used as a storage area for scaffolding material. There is a small landscaped area and a parking lot at the front of the building. A driveway on the northwest side of the site leads to the back of the building to a paved area which is used as a storage yard and has one aboveground propane tank and a fueling station. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists of mixed commercial/industrial and residential developments. Adjacent to the northwest boundary of the property is Sanmina Corporation. Beyond Sanmina Corporation to the northwest is Stephen Schott Stadium. To the northeast across Campbell Avenue are Silicon Valley Microelectronics, Precision Specialties, Variety Metal Finishing and Southern Pacific Railroad Newhall Yard. Beyond the Railroad to the northeast is the former FMC Corporation Facility and San Jose International Airport. Adjacent to the southeast boundary of the property are A.J. Commercial Laundry and ALL Chem Supply and to the southwest are residential buildings. Prior to 1981, it was a vacant lot owned by Owens Illinois. In 1981, South Bay Construction started developing the property. Since 1986, Cobalt Associates became the owner of the property. From approximately 1981 to 1989, Kadas LTD, Barbary Coast Furniture occupied the site. Since June 2001 to present, Safway Services, Inc. occupied the Site. Safway is a nationwide scaffolding company with over 70 company-owned branches and offers scaffold sales, rental, labor services, training, engineering, design and computerized inventory management. The facility at 1177 Campbell Avenue is used for the purpose of distribution of construction equipment to job sites.

**Status:** NO ACTION REQUIRED  
**Program Type:** EVALUATION  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000012](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000012)

**Completed Activities**

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000012&doc\\_id=6008025](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000012&doc_id=6008025)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 10/18/2005  
**Comments:** In house site screening report determined that there were no releases at the site.

<a href="#">59</a>	1 of 2	S	0.50 / 2,621.40	88.98 / 14	Exxon #7-0960 36 Washington St Santa Clara CA	LOP SANTA CLARA
--------------------	--------	---	--------------------	---------------	---	--------------------

**SCVWD ID:** 07S1W11G02f  
**Closure Date:** 5/17/2000  
**Link:** <http://lustop.sccgov.org/files/07S1W11G02f/>

<a href="#">59</a>	2 of 2	S	0.50 / 2,621.40	88.98 / 14	EXXON #7-0960 36 WASHINGTON ST SANTA CLARA CA 95050	LUST
--------------------	--------	---	--------------------	---------------	---	------

**Global ID:** T0608500570  
**Status:** COMPLETED - CASE CLOSED  
**Status Date:**  
**Case Type:** LUST CLEANUP SITE  
**Date Source:** LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download  
**County:** SANTA CLARA  
**Latitude:**  
**Longitude:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

**RB Case No:**  
**Local Case No:**  
**Begin Date:** 4/9/1990  
**Lead Agency:** SANTA CLARA COUNTY LOP  
**Local Agency:** SANTA CLARA COUNTY LOP  
**CUF Case:** NO  
**Potential Media of Concern:** Other Groundwater (uses other than drinking water)  
**Potential COC:** Gasoline  
**How Discovered:**  
**Stop Method:**  
**Stop Description:**  
**Case Worker:** UST  
**File Location:** Stored on Microfiche

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**How Discovered Description:**

**Calwater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**DWR GW Subbasin Name:** Santa Clara Valley - Santa Clara (2-009.02)  
**Disadvantaged Community:**  
**Calenviroscreen Score:** 21-25%  
**Site History:**

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

**Action Type:** RESPONSE  
**Date :** 6/13/2000  
**Action:** Other Report / Document

**Action Type:** ENFORCEMENT  
**Date :** 5/17/2000  
**Action:** Closure/No Further Action Letter

**Action Type:** RESPONSE  
**Date :** 10/31/1999  
**Action:** Monitoring Report - Quarterly

**Action Type:** RESPONSE  
**Date :** 7/31/1999  
**Action:** Monitoring Report - Quarterly

**Action Type:** ENFORCEMENT  
**Date :** 6/16/1999  
**Action:** Staff Letter - #22342

**Action Type:** RESPONSE  
**Date :** 12/15/1997  
**Action:** Monitoring Report - Quarterly

**Action Type:** ENFORCEMENT  
**Date :** 12/10/1997  
**Action:** Staff Letter - #22335

**Action Type:** RESPONSE  
**Date :** 3/27/1997  
**Action:** Other Report / Document

**Action Type:** ENFORCEMENT  
**Date :** 1/28/1997  
**Action:** Staff Letter - #22328

**Action Type:** RESPONSE  
**Date :** 10/22/1993  
**Action:** Other Report / Document

**Action Type:** ENFORCEMENT  
**Date :** 2/6/1991  
**Action:** Notice of Responsibility - #39646

**Action Type:** REMEDIATION  
**Date :** 10/15/1990  
**Action:** Excavation

**Action Type:** REMEDIATION  
**Date :** 10/15/1990  
**Action:** Soil Vapor Extraction (SVE)

**Action Type:** REMEDIATION  
**Date :** 10/15/1990  
**Action:** In Situ Physical/Chemical Treatment (other than SVE)

**Action Type:** Other  
**Date :** 4/9/1990

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Action: Leak Reported

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

<b>Contact Type:</b>	Local Agency Caseworker	<b>Address:</b>	1555 Berger Drive, Suite 300
<b>Contact Name:</b>	UST CASE WORKER	<b>Email:</b>	
<b>City:</b>	SAN JOSE	<b>Phone No:</b>	4089183400
<b>Organization Name:</b>	SANTA CLARA COUNTY LOP		

<b>Contact Type:</b>	Regional Board Caseworker	<b>Address:</b>	1515 CLAY ST SUITE 1400
<b>Contact Name:</b>	Regional Water Board	<b>Email:</b>	
<b>City:</b>	OAKLAND	<b>Phone No:</b>	
<b>Organization Name:</b>	SAN FRANCISCO BAY RWQCB (REGION 2)		

**LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 5/17/2000

**Status:** Open - Site Assessment  
**Status Date:** 4/13/1990

**Status:** Open - Case Begin Date  
**Status Date:** 4/9/1990

**Status:** Open - Site Assessment  
**Status Date:** 4/9/1990

**LUST Sites from GeoTracker Search - Regulatory Profile**

<b>Site Facility Name:</b>	EXXON #7-0960	<b>Potential COC:</b>	GASOLINE
<b>Site Facility Type:</b>	LUST CLEANUP SITE	<b>Facility Type:</b>	
<b>Cleanup Status:</b>	COMPLETED - CASE CLOSED	<b>Composting Method:</b>	
<b>Project Status:</b>		<b>Address:</b>	36 WASHINGTON ST
<b>WDR Place Type:</b>		<b>City:</b>	SANTA CLARA
<b>WDR File:</b>		<b>Zip:</b>	95050
<b>WDR Order:</b>		<b>County:</b>	SANTA CLARA
<b>CUF Priority Assig:</b>		<b>CUF Claim:</b>	
<b>CUF Amount Paid:</b>			
<b>File Location:</b>	STORED ON MICROFICHE		
<b>Designated Beneficial Use:</b>	MUN, AGR, IND, PROC		
<b>Project Oversight Agencies:</b>			
<b>Report Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500570">https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608500570</a>		
<b>Cleanup Status Detail:</b>	COMPLETED - CASE CLOSED AS OF 5/17/2000		
<b>Cleanup History Link:</b>	<a href="https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500570&amp;tabname=regulatoryhistory">https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608500570&amp;tabname=regulatoryhistory</a>		
<b>Potential Media of Concern:</b>	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)		
<b>User Defined Beneficial Use:</b>			
<b>DWR GW Sub Basin:</b>	Santa Clara Valley - Santa Clara (2-009.02)		
<b>Calwater Watershed Name:</b>	Santa Clara - Palo Alto (205.50)		
<b>Post Closure Site Management:</b>			
<b>Future Land Use:</b>			
<b>Cleanup Oversight Agencies:</b>	SANTA CLARA COUNTY LOP (LEAD) CASEWORKER: UST CASE WORKER SAN FRANCISCO BAY RWQCB (REGION 2) CASEWORKER: Regional Water Board SANTA CLARA VALLEY WATER DISTRICT - CASE #: 07S1W11G02f		
<b>Gndwater Monitoring Freque:</b>			
<b>Designated Beneficial Use Desc:</b>	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply		
<b>Site History:</b>			

No site history available

**LUST Sites from GeoTracker Search - Cleanup Status History**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Status:** Completed - Case Closed  
**Date :** 5/17/2000

**Status:** Open - Site Assessment  
**Date :** 4/13/1990

**Status:** Open - Case Begin Date  
**Date :** 4/9/1990

**Status:** Open - Site Assessment  
**Date :** 4/9/1990

**LUST Sites from GeoTracker Search - Cleanup Action Report (as of Sep 15, 2021)**

**Action Type:** IN SITU PHYSICAL/CHEMICAL TREATMENT (OTHER THAN SVE) **Begin Date:** 10/15/1990

**Phase:** **End Date:** 5/17/2000

**Contaminant Mass Removed:**  
**Description:**

**Action Type:** SOIL VAPOR EXTRACTION (SVE) **Begin Date:** 10/15/1990

**Phase:** **End Date:** 5/17/2000

**Contaminant Mass Removed:**  
**Description:**

**Action Type:** EXCAVATION **Begin Date:** 10/15/1990

**Phase:** **End Date:** 5/17/2000

**Contaminant Mass Removed:**  
**Description:**

**LUST Sites from GeoTracker Search - Regulatory Activities (as of Sep 15)**

**Action Type:** Response Requested - Other  
**Action Date:** 6/13/2000  
**Received Issue Date:** 6/13/2000  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500570&doc\\_id=5873199](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500570&doc_id=5873199)  
**Title Description Comments:**

SCVWD ELECTRONIC FILES

**Action Type:** Other Regulatory Actions  
**Action Date:** 5/17/2000  
**Received Issue Date:** 5/17/2000  
**Action:** Closure/No Further Action Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T0608500570&enforcement\\_id=6271537&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500570&enforcement_id=6271537&temptable=ENFORCEMENT)

**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 10/31/1999  
**Received Issue Date:** 12/20/1999  
**Action:** Monitoring Report - Quarterly

**Doc Link:**  
**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Response Requested - Reports  
**Action Date:** 7/31/1999  
**Received Issue Date:** 8/27/1999  
**Action:** Monitoring Report - Quarterly

**Doc Link:**

**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Other Regulatory Actions  
**Action Date:** 6/16/1999  
**Received Issue Date:** 6/16/1999  
**Action:** Staff Letter - #22342  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Reports  
**Action Date:** 12/15/1997  
**Received Issue Date:** 12/15/1997  
**Action:** Monitoring Report - Quarterly  
**Doc Link:**  
**Title Description Comments:**

Monitoring Report - Quarterly

**Action Type:** Other Regulatory Actions  
**Action Date:** 12/10/1997  
**Received Issue Date:** 12/10/1997  
**Action:** Staff Letter - #22335  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Other Regulatory Actions  
**Action Date:** 1/28/1997  
**Received Issue Date:** 1/28/1997  
**Action:** Staff Letter - #22328  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 10/22/1993  
**Received Issue Date:** 10/22/1993  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T0608500570&doc\\_id=5873203](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0608500570&doc_id=5873203)  
**Title Description Comments:**

SCVWD ELECTRONIC FILES

**Action Type:** Notices  
**Action Date:** 2/6/1991  
**Received Issue Date:** 2/6/1991  
**Action:** Notice of Responsibility - #39646  
**Doc Link:**  
**Title Description Comments:**

**Action Type:** Response Requested - Other  
**Action Date:** 3/27/1997  
**Received Issue Date:**  
**Action:** Other Report / Document  
**Doc Link:**  
**Title Description Comments:**

Additional Information Report

**Action Type:** Cleanup Action  
**Action Date:** 10/15/1990  
**Received Issue Date:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Action:</b>		In Situ Physical/Chemical Treatment (other than SVE)				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		10/15/1990				
<b>Received Issue Date:</b>						
<b>Action:</b>		Soil Vapor Extraction (SVE)				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Cleanup Action				
<b>Action Date:</b>		10/15/1990				
<b>Received Issue Date:</b>						
<b>Action:</b>		Excavation				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						
<b>Action Type:</b>		Leak Action				
<b>Action Date:</b>		4/9/1990				
<b>Received Issue Date:</b>						
<b>Action:</b>		Leak Reported				
<b>Doc Link:</b>						
<b>Title Description Comments:</b>						

**LUST Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	6/13/2000	<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT	<b>Submitted:</b>	
<b>Title:</b>	SCVWD ELECTRONIC FILES		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500570&document_id=5873199		
<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	5/17/2000	<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)
<b>Type:</b>	CLOSURE/NO FURTHER ACTION LETTER	<b>Submitted:</b>	
<b>Title:</b>	UNKNOWN		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500570&enforcement_id=6271537		
<b>Document Type:</b>	Site Documents	<b>Size :</b>	
<b>Document Date:</b>	10/22/1993	<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)
<b>Type:</b>	OTHER REPORT / DOCUMENT	<b>Submitted:</b>	
<b>Title:</b>	SCVWD ELECTRONIC FILES		
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608500570&document_id=5873203		

<a href="#">60</a>	1 of 1	<i>E</i>	0.50 / 2,621.74	66.09 / -9	<b>CAMPBELL AVE ASSOCIATES 1166 CAMPBELL AVE SAN JOSE CA 95126</b>	<b>CLEANUP SITES</b>
<b>Global ID:</b>	T10000009000			<b>Latitude:</b>	37.3473	
<b>Status:</b>	COMPLETED - CASE CLOSED			<b>Longitude:</b>	-121.92803	
<b>Status Date:</b>	8/31/2018			<b>County:</b>	SANTA CLARA	
<b>Site Facility Type:</b>	CLEANUP PROGRAM SITE					
<b>Data Source:</b>	Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download					

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail**

<b>RB Case No:</b>		<b>Stop Method:</b>	
<b>Local Case No:</b>	2016-24s	<b>CUF Case:</b>	NO
<b>Begin Date:</b>	6/7/2016	<b>Case Worker:</b>	GOR
<b>File Location:</b>	All Files are on GeoTracker or in the Local Agency Database		
<b>Lead Agency:</b>	SANTA CLARA COUNTY LOP		

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Local Agency:</b>		SANTA CLARA COUNTY LOP				
<b>Potential COC:</b>		Cyanide				
<b>Potential Media of Concern:</b>		Soil				
<b>How Discovered:</b>						
<b>How Discovered Description:</b>						
<b>Stop Description:</b>						
<b>CalWater Watershed Name:</b>		Santa Clara - Palo Alto (205.50)				
<b>DWR GW Subbasin Name:</b>		Santa Clara Valley - Santa Clara (2-009.02)				
<b>Disadvantaged Community:</b>						
<b>CalEnviroScreen Score:</b>		56-60%				
<b>Site History:</b>						

The site was the location of a plating shop that recently closed. Shallow soil samples beneath the plating shop location reported cyanide and other metals above screening levels. Additionally, grab groundwater and soil vapor samples throughout the property reported detections of VOCs. The RP plans to remediate the soil hot spots through excavation.

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity**

<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2018-08-27 00:00:00
<b>Action:</b>	Closure Summary
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2018-08-16 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2018-08-16 00:00:00
<b>Action:</b>	Removal Action Complete
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2017-12-15 00:00:00
<b>Action:</b>	Remedial Action Complete
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2017-08-14 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2017-05-12 00:00:00
<b>Action:</b>	CAP/RAP - Other Report - Regulator Responded
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2017-03-10 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2016-12-09 00:00:00
<b>Action:</b>	Electronic Reporting Submittal Due
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2016-11-14 00:00:00
<b>Action:</b>	Staff Letter
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2016-06-02 00:00:00
<b>Action:</b>	Cost Recovery Agreement / N. of Reimbursement
<b>Action Type:</b>	ENFORCEMENT
<b>Date:</b>	2016-05-12 00:00:00
<b>Action:</b>	Letter - Notice
<b>Action Type:</b>	RESPONSE
<b>Date:</b>	2016-05-04 00:00:00
<b>Action:</b>	Other Report / Document

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History**

**Status:** Completed - Case Closed  
**Status Date:** 2018-08-31 00:00:00

**Status:** Open - Case Begin Date  
**Status Date:** 2016-06-07 00:00:00

**Status:** Open - Assessment & Interim Remedial Action  
**Status Date:** 2016-06-07 00:00:00

**Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts**

**Contact Type:** Local Agency Caseworker  
**Contact Name:** Gerald O'Regan  
**Phone No:**  
**Organization Name:** SANTA CLARA COUNTY LOP  
**Email:** gerald.o'regan@deh.sccgov.org

**Address:** 1555 BERGER DRIVE STE 300  
**City:** SAN JOSE

**Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of Sep 15, 2021)**

**Project Status:**  
**Cuf Claim No:**  
**CUF Priority Assign:**  
**CUF Amount Paid:**  
**Composting Method:**  
**File Location:** ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE  
**User Defined Beneficial Use:**  
**Designated Beneficial Use:** MUN, AGR, IND, PROC  
**Designated Beneficial Use Desc:** Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply  
**Project Oversight Agencies:**  
**Report Link:** [https://geotracker.waterboards.ca.gov/profile\\_report?global\\_id=T10000009000](https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000009000)  
**Cleanup Status Detail:** COMPLETED - CASE CLOSED AS OF 8/31/2018  
**Potential COC:** CYANIDE  
**Potential Media of Concern:** SOIL  
**Groundwater Monitoring**  
**Frequen:**  
**DWR GW Sub Basin:** Santa Clara Valley - Santa Clara (2-009.02)  
**CalWater Watershed Name:** Santa Clara - Palo Alto (205.50)  
**Post Closure Site Management:**  
**Future Land Use:**  
**Cleanup Oversight Agencies:** SANTA CLARA COUNTY LOP (LEAD) - CASE #: 2016-24s  
CASEWORKER: Gerald O'Regan  
SAN FRANCISCO BAY RWQCB (REGION 2)  
**Cleanup History Link:** [https://geotracker.waterboards.ca.gov/profile\\_report\\_include?global\\_id=T10000009000&tablename=regulatoryhistory](https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000009000&tablename=regulatoryhistory)  
**Site History:**

The site was the location of a plating shop that recently closed. Shallow soil samples beneath the plating shop location reported cyanide and other metals above screening levels. Additionally, grab groundwater and soil vapor samples throughout the property reported detections of VOCs.

The RP plans to remediate the soil hot spots through excavation.

**Sites from GeoTracker Search - Regulatory Activities (as of Sep 15, 2021)**

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/27/2018  
**Received Issue Date:** 8/27/2018  
**Action:** Closure Summary  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009000&enforcement\\_id=6368531&template=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&enforcement_id=6368531&template=ENFORCEMENT)

**Title Description Comments:**

Case Closure Letter and CCS

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/16/2018  
**Received Issue Date:** 8/16/2018  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009000&enforcement\\_id=6367037&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&enforcement_id=6367037&temptable=ENFORCEMENT)

**Title Description Comments:**

Conditional Approval of Removal Action Completion Report

**Action Type:** Response Requested - Reports  
**Action Date:** 8/16/2018  
**Received Issue Date:** 8/16/2018  
**Action:** Removal Action Complete  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000009000&doc\\_id=5972713](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000009000&doc_id=5972713)

**Title Description Comments:**

Removal Action Completion Report

**Action Type:** Response Requested - Reports  
**Action Date:** 12/15/2017  
**Received Issue Date:** 8/16/2018  
**Action:** Remedial Action Complete  
**Doc Link:**

**Title Description Comments:**

Remedial Action Completion Report

**Action Type:** Other Regulatory Actions  
**Action Date:** 8/14/2017  
**Received Issue Date:** 8/14/2017  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009000&enforcement\\_id=6329801&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&enforcement_id=6329801&temptable=ENFORCEMENT)

**Title Description Comments:**

Remedial Action Completion Report

**Action Type:** Response Requested - Reports  
**Action Date:** 5/12/2017  
**Received Issue Date:** 8/14/2017  
**Action:** CAP/RAP - Other Report - Regulator Responded  
**Doc Link:**

**Title Description Comments:**

Remedial Action Plan - See Directive Letter dated August 14, 2017. Draft RAP is dated May 21, 2107. Final RAP received by email on August 14, 2017 and is dated May 21, 2017.

**Action Type:** Other Regulatory Actions  
**Action Date:** 3/10/2017  
**Received Issue Date:** 3/10/2017  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T10000009000&enforcement\\_id=6314007&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&enforcement_id=6314007&temptable=ENFORCEMENT)

**Title Description Comments:**

Remedial Action Plan

**Action Type:** Response Requested - Other  
**Action Date:** 12/9/2016  
**Received Issue Date:** 1/19/2017  
**Action:** Electronic Reporting Submittal Due  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T10000009000&doc\\_id=5905354](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000009000&doc_id=5905354)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Title Description Comments:**

Upload all relevant environmental documents

**Action Type:** Other Regulatory Actions  
**Action Date:** 11/14/2016  
**Received Issue Date:** 11/14/2016  
**Action:** Staff Letter  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T1000009000&enforcement\\_id=6303532&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000009000&enforcement_id=6303532&temptable=ENFORCEMENT)

**Title Description Comments:**

Upload all relevant environmental documents

**Action Type:** Agreements  
**Action Date:** 6/2/2016  
**Received Issue Date:** 6/2/2016  
**Action:** Cost Recovery Agreement / N. of Reimbursement  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T1000009000&enforcement\\_id=6286894&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000009000&enforcement_id=6286894&temptable=ENFORCEMENT)

**Title Description Comments:**

Remedial Action Agreement

**Action Type:** Notices  
**Action Date:** 5/12/2016  
**Received Issue Date:** 5/12/2016  
**Action:** Letter - Notice  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T1000009000&enforcement\\_id=6286895&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000009000&enforcement_id=6286895&temptable=ENFORCEMENT)

**Title Description Comments:**

State Notification

**Action Type:** Response Requested - Other  
**Action Date:** 5/4/2016  
**Received Issue Date:** 5/4/2016  
**Action:** Other Report / Document  
**Doc Link:** [https://geotracker.waterboards.ca.gov/view\\_documents\\_all?global\\_id=T1000009000&doc\\_id=5890654](https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T1000009000&doc_id=5890654)

**Title Description Comments:**

VCP Application

**Sites from GeoTracker Search - Documents (as of Sep 15, 2021)**

**Document Type:** Site Documents  
**Document Date:** 3/8/2019\*  
**Size :** 13,387 KB  
**Title:** REMOVAL ACTION COMPLETION REPORT \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/309255112/T1000009000.PDF](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/309255112/T1000009000.PDF)  
**Type:** REQUEST FOR CLOSURE

**Submitted:**  
**Submitted By:** TOM MCCLOSKEY (AUTH\_RP)

**Document Type:** Site Documents  
**Document Date:** 8/27/2018  
**Size :**  
**Title:** CASE CLOSURE LETTER AND CCS \*\*Note: Many records provided by the department have a truncated [Title] field.  
**Title Link:** [https://geotracker.waterboards.ca.gov/view\\_documents?global\\_id=T1000009000&enforcement\\_id=6368531](https://geotracker.waterboards.ca.gov/view_documents?global_id=T1000009000&enforcement_id=6368531)  
**Type:** CLOSURE SUMMARY

**Submitted:**  
**Submitted By:** GERALD O'REGAN (REGULATOR)

**Document Type:** Site Documents  
**Document Date:** 8/16/2018  
**Size :**

**Submitted:**  
**Submitted By:** GERALD O'REGAN (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title:</b>					CONDITIONAL APPROVAL OF REMOVAL ACTION COMPLETION REPORT **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6367037">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6367037</a>	
<b>Type:</b>					STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/16/2018				<b>Submitted By:</b>	GERALD O'REGAN (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					REMOVAL ACTION COMPLETION REPORT **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;document_id=5972713">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;document_id=5972713</a>	
<b>Type:</b>					REMOVAL ACTION COMPLETE	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	8/14/2017				<b>Submitted By:</b>	SOMIRA PECH (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					REMEDIAL ACTION COMPLETION REPORT **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6329801">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6329801</a>	
<b>Type:</b>					STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/1/2017*				<b>Submitted By:</b>	TOM MCCLOSKEY (AUTH_RP)
<b>Size :</b>	4,923 KB					
<b>Title:</b>					REMOVAL WORK PLAN **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1403604865/T10000009000.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1403604865/T10000009000.PDF</a>	
<b>Type:</b>					REMOVAL ACTION WORK PLAN	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	3/10/2017				<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					REMEDIAL ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6314007">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6314007</a>	
<b>Type:</b>					STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	1/19/2017*				<b>Submitted By:</b>	TOM MCCLOSKEY (AUTH_RP)
<b>Size :</b>	14,423 KB					
<b>Title:</b>					PHASE II INVESTIGATION SUMMARY REPORT **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5075532913/T10000009000.PDF">https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5075532913/T10000009000.PDF</a>	
<b>Type:</b>					SITE INVESTIGATION	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	11/14/2016				<b>Submitted By:</b>	CANDACE GARCIA (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					UPLOAD ALL RELEVANT ENVIRONMENTAL DOCUMENTS **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6303532">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6303532</a>	
<b>Type:</b>					STAFF LETTER	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	6/2/2016				<b>Submitted By:</b>	AARON COSTA (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					REMEDIAL ACTION AGREEMENT **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6286894">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6286894</a>	
<b>Type:</b>					COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/12/2016				<b>Submitted By:</b>	AARON COSTA (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					STATE NOTIFICATION **Note: Many records provided by the department have a truncated [Title] field.	
<b>Title Link:</b>					<a href="https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6286895">https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&amp;enforcement_id=6286895</a>	
<b>Type:</b>					LETTER - NOTICE	
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/4/2016				<b>Submitted By:</b>	AARON COSTA (REGULATOR)
<b>Size :</b>						
<b>Title:</b>					VCP APPLICATION **Note: Many records provided by the department have a truncated [Title] field.	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000009000&document_id=5890654					
<b>Type:</b>	OTHER REPORT / DOCUMENT					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	5/17/2013*				<b>Submitted By:</b>	TOM MCCLOSKEY (AUTH_RP)
<b>Size :</b>	2,591 KB					
<b>Title:</b>	GEORESTORATION 2013 PHASE II REPORT **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3397436738/T10000009000.PDF					
<b>Type:</b>	SITE INVESTIGATION					
<b>Document Type:</b>	Site Documents				<b>Submitted:</b>	
<b>Document Date:</b>	7/20/2010*				<b>Submitted By:</b>	TOM MCCLOSKEY (AUTH_RP)
<b>Size :</b>	18,941 KB					
<b>Title:</b>	PHASE I ESA **Note: Many records provided by the department have a truncated [Title] field.					
<b>Title Link:</b>	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1799661993/T10000009000.PDF					
<b>Type:</b>	SITE ASSESSMENT REPORT					

**Sites from GeoTracker Search - Cleanup Status History (as of Sep 15, 2021)**

<b>Status:</b>	Completed - Case Closed
<b>Date:</b>	8/31/2018
<b>Status:</b>	Open - Assessment & Interim Remedial Action
<b>Date:</b>	6/7/2016
<b>Status:</b>	Open - Case Begin Date
<b>Date:</b>	6/7/2016

<a href="#">61</a>	1 of 1	W	0.50 / 2,624.40	86.28 / 11	HUBBLE QUARRY AND MILL SANTA CLARA COUNTY SANTA CLARA CA 95050	MRDS
<b>Dep ID:</b>	10189377			<b>I1:</b>	28	
<b>Dev Status:</b>	UNKNOWN			<b>Latitude:</b>	37.346313	
<b>Code List:</b>	GRT			<b>Longitude:</b>	-121.946777	
<b>Url:</b>	http://mrddata.usgs.gov/mrds/show-mrds.php?dep_id=10189377					

**Commodity**

<b>I1:</b>	48	<b>Line:</b>	1
<b>Code:</b>	GRT	<b>Inserted By:</b>	MAS migration
<b>Commodity:</b>	Granite	<b>Insert Date:</b>	29-OCT-02
<b>Commodity Type:</b>	Non-metallic	<b>Updated By:</b>	USGS
<b>Commodity Group:</b>	Stone	<b>Update Date:</b>	29-OCT-02
<b>Importance:</b>	Primary		

**Names**

<b>I1:</b>	13	<b>Inserted By:</b>	MAS migration
<b>Status:</b>	Current	<b>Insert Date:</b>	29-OCT-02
<b>Site Name:</b>	Hubble Quarry and Mill	<b>Updated By:</b>	USGS
<b>Line:</b>	1	<b>Update Date:</b>	29-OCT-02

<a href="#">62</a>	1 of 1	E	0.50 / 2,628.28	66.24 / -9	VARIETY METAL FINISHING, INC. 1166 CABELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
<b>Estor/EPA ID:</b>	71002872			<b>Assembly District:</b>	27	
<b>Site Code:</b>				<b>Senate District:</b>	15	
<b>Nat Priority List:</b>	NO			<b>Permit Renewal Lead:</b>		
<b>APN:</b>	NONE SPECIFIED			<b>Public Partici Spclst:</b>		
<b>Census Tract:</b>	6085505203			<b>Project Manager:</b>		
<b>Site Type:</b>	TIERED PERMIT			<b>County:</b>	SANTA CLARA	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

<b>Address Description:</b>	1166 CAMBELL AVENUE	<b>Latitude:</b>	37.347307
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.9280309
<b>Special Program:</b>		<b>Acres:</b>	NONE SPECIFIED
<b>Funding:</b>		<b>Supervisor:</b>	
<b>Cleanup Status:</b>	INACTIVE - NEEDS EVALUATION AS OF		
<b>Cleanup Oversight Agencies:</b>	NONE SPECIFIED		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	NONE SPECIFIED		
<b>Potential Media Affected:</b>	NONE SPECIFIED		
<b>Potential Contaminant of Concern:</b>			

NONE SPECIFIED

**Site History:**

<b>Status:</b>	INACTIVE - NEEDS EVALUATION
<b>Program Type:</b>	TIERED PERMIT
<b>CalEnviroScreen Score:</b>	56-60%
<b>Summary Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71002872">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71002872</a>

<a href="#">63</a>	1 of 1	<b>NNW</b>	<b>0.52 / 2,755.61</b>	<b>65.19 / -10</b>	<b>SANTA CLARA POLICE STATION 501 EL CAMINO REAL SANTA CLARA CA 95050</b>	<b>ENVIROSTOR</b>
--------------------	--------	------------	------------------------	--------------------	---	-------------------

<b>Estor/EPA ID:</b>	43360129	<b>Assembly District:</b>	25
<b>Site Code:</b>	201015	<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-06-052	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	CLAUDE JEMISON
<b>Site Type:</b>	VOLUNTARY CLEANUP	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	501 EL CAMINO REAL	<b>Latitude:</b>	37.354062
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.939069
<b>Special Program:</b>	VOLUNTARY CLEANUP PROGRAM	<b>Acres:</b>	4.7 ACRES
<b>Funding:</b>	SITE PROPONENT	<b>Supervisor:</b>	CHERYL PROWELL
<b>Cleanup Status:</b>	CERTIFIED / OPERATION & MAINTENANCE AS OF 12/8/2000		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	MANUFACTURED GAS PLANT, RAILROAD RIGHT OF WAY		
<b>Potential Media Affected:</b>	SOIL		
<b>Potential Contaminant of Concern:</b>			

LEAD NICKEL POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)

**Site History:**

The 4.7-acre Site was used by the City of Santa Clara as a utility yard from approximately 1890 through the 1960s. Coal gas used to power gas street lights and to generate electricity was generated onsite from the 1890s through the 1930s. The City of Santa Clara remains the current owner of the property, which is currently used as the Santa Clara Police Headquarters building.

<b>Status:</b>	CERTIFIED / OPERATION & MAINTENANCE - LAND USE RESTRICTIONS
<b>Program Type:</b>	VOLUNTARY CLEANUP
<b>CalEnviroScreen Score:</b>	56-60%
<b>Summary Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43360129">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43360129</a>

**Land Use Restrictions**

<b>Site Management Requirements:</b>	ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL ASPHALT COVER NOT TO BE DISTURBED WITHOUT APPROVAL DAY CARE CENTER PROHIBITED HOSPITAL USE PROHIBITED LAND USE COVENANT NO EXCAVATION OF CONTAMINATED SOILS WITHOUT AGENCY REVIEW AND APPROVAL NOTIFY AFTER CHANGE OF PROPERTY OWNER NOTIFY PRIOR TO SUBSURFACE WORK PERFORM H&S PLAN PRIOR TO SUBSURFACE WORK
--------------------------------------	---

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED  
RESIDENCE USE PROHIBITED

**Title:** Deed Restriction / Land Use Covenant  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/deliverable\\_documents/1461118400/SantaClara%2EPolice%2EDeedRestrict%2Epdf](https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/1461118400/SantaClara%2EPolice%2EDeedRestrict%2Epdf)  
**Date Recorded:** 9/29/2000

**Currently Scheduled Activities**

**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** 5 Year Review Reports  
**Due Date:** 3/23/2022  
**Revised Date:**

**Completed Activities**

**Title:** Annual Oversight Cost Estimate Letter  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&enforcement\\_id=60337728](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&enforcement_id=60337728)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Annual Oversight Cost Estimate  
**Date Completed:** 10/28/2013  
**Comments:**

**Title:** Certification  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&enforcement\\_id=5002462](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&enforcement_id=5002462)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Certification  
**Date Completed:** 12/8/2000  
**Comments:** Certified Removal Action Workplan implementation as described in the Removal Action Completion Report.

**Title:** Health and Safety Plan  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&doc\\_id=6009496](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&doc_id=6009496)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Other Report  
**Date Completed:** 3/10/1998  
**Comments:**

**Title:** Operations and Maintenance Plan  
**Title Link:**  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Operation and Maintenance Plan  
**Date Completed:** 9/12/2000  
**Comments:** O&M Plan approved describing required cap maintenance activities.

**Title:** RP Annual Inspection Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&doc\\_id=6010295](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&doc_id=6010295)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Operation and Maintenance Report  
**Date Completed:** 2/7/2006

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Comments:**

**Title:** RP Annual Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&doc\\_id=60279340](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&doc_id=60279340)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Operation and Maintenance Report  
**Date Completed:** 3/6/2012  
**Comments:** The City of Santa Clara submitted its Annual Summary Report as required by the Land Use Covenant and Operation and Maintenance Agreement. The cap was observed to be in good condition during a January 24, 2012 inspection.

**Title:** RP Annual Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&doc\\_id=60279342](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&doc_id=60279342)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Operation and Maintenance Report  
**Date Completed:** 3/11/2014  
**Comments:** The City of Santa Clara performed an annual inspection of the parking lot of the City police station where contaminated soil remains in place. During the inspection, the parking lot pavement that serves as a cap was observed to be in good condition with a approximately 20 lineal feet of minor visible cracks. No significant deterioration that would allow surface water to penetrate to cap was observed..

**Title:** Annual Oversight Cost Estimate Letter  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&enforcement\\_id=60337733](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&enforcement_id=60337733)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Annual Oversight Cost Estimate  
**Date Completed:** 9/14/2018  
**Comments:**

**Title:** Annual Oversight Cost Estimate Letter  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&enforcement\\_id=60416242](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&enforcement_id=60416242)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Annual Oversight Cost Estimate  
**Date Completed:** 10/5/2020  
**Comments:** Emailed cost estimate letter on 10/5/2020. -EC, 10/5/2020

**Title:** Annual Oversight Cost Estimate letter  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&enforcement\\_id=60302574](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&enforcement_id=60302574)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Annual Oversight Cost Estimate  
**Date Completed:** 9/13/2012  
**Comments:**

**Title:** Removal Action Workplan  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&doc\\_id=5002464](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&doc_id=5002464)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Removal Action Workplan  
**Date Completed:** 1/26/1998  
**Comments:** Sample results from a soil quality evaluation conducted in 1997 under DTSC oversight indicated lead, nickel, and polynuclear aromatic hydrocarbons (PAHs) including but not limited to anthracene, benzo(a)pyrene, and pyrene were found in soil. Lead contaminated soil was found to be the major issue, with concentrations up to 4,100 mg/kg. The RAW required consolidation and capping of impacted soil as well as underground tank removal and capping.

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Title:</b>			2009 DTSC Cost Estimate			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6017456">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6017456</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			10/13/2009			
<b>Comments:</b>						
<b>Title:</b>			Annual Oversight Cost Estimate Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60337732">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60337732</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			10/3/2017			
<b>Comments:</b>						
<b>Title:</b>			DTSC Annual Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60254680">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60254680</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			* Land Use Restriction Monitoring Report			
<b>Date Completed:</b>			3/23/2011			
<b>Comments:</b>			It was observed that the asphalt surface of the cap was in very good condition, with no signs of cracking or deterioration observed.			
<b>Title:</b>			Five-Year Review Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60194787">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60194787</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			5 Year Review Reports			
<b>Date Completed:</b>			3/23/2016			
<b>Comments:</b>			ATC, on the behalf of the City of Santa Clara, performed a 5-year review of the capped consolidation cells. A site visit was conducted on December 14, 2015 to assess the City's compliance with the Land Use Covenant and the Operation and Maintenance Agreement requirements for the consolidation cells. The asphalt consolidation area cap appeared to be well- maintained and in good condition, and there appeared to be no significant drainage problem affecting the consolidation cells. Based on a technical assessment as part of the 5-year review, it was concluded that the site remedial actions remain protective of human health and the environment.			
<b>Title:</b>			2007 DTSC Cap Inspection and Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6008819">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6008819</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Land Use Restriction - Site Inspection/Visit			
<b>Date Completed:</b>			1/24/2007			
<b>Comments:</b>						
<b>Title:</b>			Annual Oversight Cost Estimate			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60287382">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60287382</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			12/15/2011			
<b>Comments:</b>						
<b>Title:</b>			Operation and Maintenance Agreement			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002460">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002460</a>			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation & Maintenance Order/Agreement			
<b>Date Completed:</b>			9/12/2000			
<b>Comments:</b>			Approved requiring annual inspection of the cap for signs of deterioration and repair of significant deterioration within thirty days of inspection.			
<b>Title:</b>			RP Annual Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60279343">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60279343</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			2/5/2015			
<b>Comments:</b>			The annual inspection was conducted as required by the Land Use Covenant and Operation and Maintenance Plan/Agreement. The cap was observed to be in good condition and showed no signs of significant deterioration that would allow surface water to penetrate through the cap.			
<b>Title:</b>			Voluntary Cleanup Agreement (VCA)			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002465">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002465</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Standard Voluntary Agreement			
<b>Date Completed:</b>			10/10/1997			
<b>Comments:</b>			The City of Santa Clara signed the VCA for DTSC to oversee remediation activities onsite.			
<b>Title:</b>			2007 RP Annual Inspection Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6012383">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6012383</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			1/16/2007			
<b>Comments:</b>						
<b>Title:</b>			2008 RP Annual Summary Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6014528">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6014528</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Monitoring Report			
<b>Date Completed:</b>			1/23/2009			
<b>Comments:</b>			DTSC has no comments.			
<b>Title:</b>			2010 DTSC Annual Site Inspection and Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6013848">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6013848</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Land Use Restriction - Site Inspection/Visit			
<b>Date Completed:</b>			7/8/2010			
<b>Comments:</b>						
<b>Title:</b>			5 Year Review Reminder letter			
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Correspondence			
<b>Date Completed:</b>			9/14/2015			

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Comments:</b>					DTSC sent an email to the City of Santa Clara providing a reminder of the Five-Year Review Report due to be submitted by December 14, 2015.	
<b>Title:</b>					Annual Inspection Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60396532">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60396532</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					2/13/2017	
<b>Comments:</b>						
<b>Title:</b>					Annual Inspection Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60416239">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60416239</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					1/10/2020	
<b>Comments:</b>						
<b>Title:</b>					CEQA	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002461">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002461</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					CEQA - Notice of Exemption	
<b>Date Completed:</b>					1/26/1998	
<b>Comments:</b>					CEQA Notice of Exemption approved.	
<b>Title:</b>					Removal Action Completion Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=5002463">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=5002463</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Removal Action Completion Report	
<b>Date Completed:</b>					5/4/1999	
<b>Comments:</b>					The remedial actions consisted of debris removal, excavation and encapsulation of 5,560 cubic yards of lampblack and metal contaminated soil in two onsite consolidation areas, excavation and offsite disposal of approximately 5,720 cubic yards of hydrocarbon impacted soil, removal of a 400-gallon underground storage tank and other concrete debris, as well as proper closure and destruction of four previously unknown onsite abandoned water supply wells. A two-foot cap of clean material including the parking lot baserock layer asphalt concrete layer was then installed over the excavated and consolidated lampblack impacted soil. The impacted soils were consolidated under an asphalt parking area.	
<b>Title:</b>					5 Year Review Reports	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=5002457">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=5002457</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					5 Year Review Reports	
<b>Date Completed:</b>					2/23/2006	
<b>Comments:</b>					Implemented remedy (Cap) continues to be adequately protective of human health and the environment.	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/16/2014	
<b>Comments:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Title:</b>					Fact Sheet	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6010046">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6010046</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Fact Sheets	
<b>Date Completed:</b>					12/10/1997	
<b>Comments:</b>					Fact Sheet approved and distributed to the mailing list 12/11/1997.	
<b>Title:</b>					Public Notice	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6010047">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6010047</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Public Notice	
<b>Date Completed:</b>					12/10/1997	
<b>Comments:</b>					Published in the Santa Clara Weekly, December 10-16, 1997.	
<b>Title:</b>					2008 DTSC Annual Inspection/Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6010502">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6010502</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Land Use Restriction - Site Inspection/Visit	
<b>Date Completed:</b>					2/1/2008	
<b>Comments:</b>					The Asphalt surface of the cap was in good condition.	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60337730">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60337730</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					10/13/2015	
<b>Comments:</b>						
<b>Title:</b>					RP Annual Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60279341">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60279341</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					2/19/2013	
<b>Comments:</b>					The City of Santa Clara conducted an annual inspection and submitted the annual summary report as required by section 1.02 of the Land Use Covenant and section 2.4 of the Operation and Maintenance Agreement. About 20 feet of small cracks were observed in the asphalt of the parking lot over the cells where contaminated soil is contained. The cracks are small and will not let significant water penetrate the asphalt. The City Street Department plans to seal the cracks when the weather is drier and warmer.	
<b>Title:</b>					Annual Oversight Cost Estimate Letter	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60507575">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60507575</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>					Annual Oversight Cost Estimate	
<b>Date Completed:</b>					11/3/2021	
<b>Comments:</b>						
<b>Title:</b>					2007 RP Annual Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6014527">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6014527</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Monitoring Report			
<b>Date Completed:</b>			2/4/2008			
<b>Comments:</b>			DTSC has no comments and hereby approves the report.			
<b>Title:</b>			2009 Annual Inspection Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6011977">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=6011977</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Land Use Restriction - Site Inspection/Visit			
<b>Date Completed:</b>			3/25/2009			
<b>Comments:</b>			It was observed that the asphalt surface of the cap was in very good condition, with no signs of cracking or deterioration observed.			
<b>Title:</b>			Annual Inspection Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60396533">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60396533</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			2/2/2018			
<b>Comments:</b>						
<b>Title:</b>			Annual Inspection Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60396534">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=60396534</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Operation and Maintenance Report			
<b>Date Completed:</b>			1/16/2019			
<b>Comments:</b>			City of San Jose personnel performed an annual cap inspection on the December 27, 2018 of the parking lot where impacted soil remains on the site. Sealing of the asphalt concrete pavement was performed during the calendar year 2018. The cap conditions were found to be satisfactory and the site was found to be in compliance with the Land Use Covenant.			
<b>Title:</b>			Annual Oversight Cost Estimate Letter			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60337731">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=60337731</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Annual Oversight Cost Estimate			
<b>Date Completed:</b>			9/14/2016			
<b>Comments:</b>						
<b>Title:</b>			Deed Restriction / Land Use Covenant			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002458">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;enforcement_id=5002458</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Land Use Restriction			
<b>Date Completed:</b>			9/29/2000			
<b>Comments:</b>			Recorded Deed Restriction limiting future land use to commercial / industrial uses onsite.			
<b>Title:</b>			Phase I Report			
<b>Title Link:</b>			<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6009499">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&amp;doc_id=6009499</a>			
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>			Phase 1			
<b>Date Completed:</b>			9/3/1997			
<b>Comments:</b>			Phase I Report submitted.			

**Title:** RP Annual Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=43360129&enforcement\\_id=60193638](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=43360129&enforcement_id=60193638)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** \* Land Use Restriction Monitoring Report  
**Date Completed:** 5/24/2010  
**Comments:**

**Title:** Second 5-Year Review Report  
**Title Link:**  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** 5 Year Review Reports  
**Date Completed:** 3/29/2011  
**Comments:**

<a href="#">64</a>	1 of 3	E	0.54 / 2,825.93	66.65 / -8	PRECISION SPECIALTIES 1158 CAMPBELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	---	-----------------	------------	--	------------

<b>Estor/EPA ID:</b>	70000009	<b>Assembly District:</b>	28
<b>Site Code:</b>	000000	<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-14-016, 23014016	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	EVALUATION	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1158 CAMPBELL AVENUE	<b>Latitude:</b>	37.3478222954585
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.927466580577
<b>Special Program:</b>		<b>Acres:</b>	1.6 ACRES
<b>Funding:</b>	NOT APPLICABLE	<b>Supervisor:</b>	
<b>Cleanup Status:</b>	REFER: LOCAL AGENCY AS OF 4/25/2007		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	METAL PLATING - OTHER		
<b>Potential Media Affected:</b>	AQUIFER USED FOR DRINKING WATER SUPPLY AFFECTED		
<b>Potential Contamin of Concern:</b>			

TPH-DIESEL TPH-GAS TETRACHLOROETHYLENE (PCE) TRICHLOROETHYLENE (TCE)

**Site History:**

The site has three single-story warehouse type building, which are 29,808 square feet in size. The building is split into three tenant sites: Silicon Valley Microelectronics and Precision Specialties occupy the front of the building; Variety Metal Finishing (Variety) occupies the back of the building. There are paved parking lots both at the front and back of the building. The surrounding area consists primarily of industrial/ commercial businesses. The property is owned by Campbell Avenue Associates. Precision Specialties occupied the site since 1984 was previously located in a different unit in the same building (1170 Campbell Campbell Avenue).

**Status:** REFER: LOCAL AGENCY  
**Program Type:** EVALUATION  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000009](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000009)

**Completed Activities**

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000009&doc\\_id=6008573](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000009&doc_id=6008573)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 4/25/2007

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Comments:</b>		While DTSC could not document any releases of hazardous substances to soil or groundwater at the property, use of hazardous materials and poor housekeeping practices indicate that the potential for release exists. Referred to San Jose Fire Department.				

<a href="#">64</a>	2 of 3	E	0.54 / 2,825.93	66.65 / -8	SILICON VALLEY MICROELECTRONICS 1150 CAMPBELL AVENUE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	---	-----------------	------------	--	------------

<b>Estor/EPA ID:</b>	70000008	<b>Assembly District:</b>	28
<b>Site Code:</b>		<b>Senate District:</b>	10
<b>Nat Priority List:</b>	NO	<b>Permit Renewal Lead:</b>	
<b>APN:</b>	230-14-016, 23014016	<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505203	<b>Project Manager:</b>	
<b>Site Type:</b>	EVALUATION	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1150 CAMPBELL AVENUE	<b>Latitude:</b>	37.3478222954585
<b>Office:</b>	CLEANUP BERKELEY	<b>Longitude:</b>	-121.927466580577
<b>Special Program:</b>		<b>Acres:</b>	1.6 ACRES
<b>Funding:</b>	NOT APPLICABLE	<b>Supervisor:</b>	KAREN TOTH
<b>Cleanup Status:</b>	NO ACTION REQUIRED AS OF 10/18/2005		
<b>Cleanup Oversight Agencies:</b>	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>	NONE		
<b>Potential Media Affected:</b>	NO MEDIA AFFECTED		
<b>Site History:</b>			

The site is located at 1150 Campbell Avenue, San Jose, Santa Clara County, California 95126. The site has one single-story warehouse type building, which is 29,808 square feet in size. The building is split into three tenant sites: Silicon Valley Microelectronics and Precision Specialties occupy the front of the building, Variety Metal Finishing occupies the back of the building. The site is located approximately four and one half miles northwest of downtown San Jose, California. The surrounding area consists primarily of industrial/ commercial businesses. Adjacent to the northeast boundary of the property is the Southern Pacific Railroad Newhall Yard. Beyond the Railroad to the northeast is the FMC Corporation Facility and San Jose International Airport. To the south across Campbell Avenue are Blues Roofing, Kilman Sales, and Safway. Adjacent to the northwest boundary are Odyssey, On Time Transport, and Ryan's Express Freight. To the southeast construction works are in progress for Pulte Homes. To the southeast are large warehouse type buildings with fenced area (1140 Campbell Avenue). Silicon Valley Microelectronics (SVM) has occupied the site since April 2000. The suite was used as a metal plating shop earlier but was vacant for a year before SVM occupied the site. SVM is a distributor and supplier of wafers made of silicon, gallium arsenide, indium phosphide, and silicon carbide and used the subject property as a sales office and with a warehouse for product storage, shipping and receiving. They do not generate any hazardous waste and there was no report of release for this business. They moved out of this location as of May 15, 2005.

**Potential Contamin of Concern:**

NO CONTAMINANTS FOUND

<b>Status:</b>	NO ACTION REQUIRED
<b>Program Type:</b>	EVALUATION
<b>CalEnviroScreen Score:</b>	56-60%
<b>Summary Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000008">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000008</a>

**Completed Activities**

<b>Title:</b>	Site Screening Report
<b>Title Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000008&amp;doc_id=6008576">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000008&amp;doc_id=6008576</a>
<b>Area Name:</b>	
<b>Area Link:</b>	
<b>Sub Area:</b>	
<b>Sub Area Link:</b>	
<b>Document Type:</b>	Site Screening
<b>Date Completed:</b>	10/18/2005
<b>Comments:</b>	No action required since there is no evidence of release at the property.

<a href="#">64</a>	3 of 3	E	0.54 / 2,825.93	66.65 / -8	VARIETY METAL FINISHING 1166 CAMPBELL DRIVE SAN JOSE CA 95126	ENVIROSTOR
--------------------	--------	---	-----------------	------------	---	------------

<b>Estor/EPA ID:</b>	70000007	<b>Assembly District:</b>	28
<b>Site Code:</b>		<b>Senate District:</b>	10

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<b>Nat Priority List:</b>		NO			<b>Permit Renewal Lead:</b>	
<b>APN:</b>		230-14-016, 23014016			<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>		6085505203			<b>Project Manager:</b>	
<b>Site Type:</b>		EVALUATION			<b>County:</b>	SANTA CLARA
<b>Address Description:</b>		1166 CAMPBELL DRIVE			<b>Latitude:</b>	37.3478222954585
<b>Office:</b>		CLEANUP BERKELEY			<b>Longitude:</b>	-121.927466580577
<b>Special Program:</b>					<b>Acres:</b>	1.6 ACRES
<b>Funding:</b>		NOT APPLICABLE			<b>Supervisor:</b>	MARK PIROS
<b>Cleanup Status:</b>		INACTIVE - NEEDS EVALUATION AS OF 12/17/2008				
<b>Cleanup Oversight Agencies:</b>		DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY				
<b>School District:</b>						
<b>Past Use that Caused Contam:</b>		METAL PLATING - OTHER				
<b>Potential Media Affected:</b>		AQUIFER USED FOR DRINKING WATER SUPPLY AFFECTED				
<b>Potential Contamin of Concern:</b>						

TPH-DIESEL TPH-GAS TETRACHLOROETHYLENE (PCE) TRICHLOROETHYLENE (TCE)

**Site History:**

The site is located at 1166 Campbell Avenue, San Jose, Santa Clara County, California 95126. The site has three single-story warehouse type building, which are 29,808 square feet in size. The building is split into three tenant sites: Silicon Valley Microelectronics and Precision Specialties occupy the front of the building; Variety Metal Finishing (Variety) occupies the back of the building. The surrounding area consists primarily of industrial/ commercial businesses. The property is owned by Campbell Avenue Associates. Variety Metal Finishing Inc. (Variety) has occupied the business since 1987. Variety has been in metal finishing business since 1986. They use several electroplating processes such as: gold plating, silver plating, nickel plating, tin plating, copper plating, passivate, soft and hard anodizing. During San Jose Fire Department file review, an inspection report for September 1993 revealed that a release of chemicals (cyanide plating bath, nickel sulfate tank) had occurred to secondary containment. Since the site has a tiered permit, it is subject to corrective action. The site is referred to Hazardous Waste Management Plan (HWMP).

**Status:** INACTIVE - NEEDS EVALUATION  
**Program Type:** EVALUATION  
**CalEnviroScreen Score:** 56-60%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=70000007](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=70000007)

**Completed Activities**

**Title:** Site Screening Report  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?global\\_id=70000007&doc\\_id=6008572](https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=70000007&doc_id=6008572)  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 12/17/2008  
**Comments:** The City of San Jose has indicated that they have determined that no further action was required in response to the 1993 report of inspection. Since the operators have used volatile organic compounds and plating solutions and no samples have been taken on the site DTSC can not make a no further action determination.

[65](#) 1 of 1 **NE** **0.66 / 3,472.07** **63.50 / -12** **FMC CORP ORDANCE PLANT** **ENVIROSTOR**  
**1125 COLEMAN AVE**  
**SAN JOSE CA 95110**

**Estor/EPA ID:** 43330027  
**Site Code:** 200244  
**Nat Priority List:** NO  
**APN:** 230-46-032  
**Census Tract:** 6085505100  
**Site Type:** EVALUATION  
**Address Description:** 1125 COLEMAN AVE  
**Office:** CLEANUP BERKELEY  
**Special Program:** \* SITE CHAR & ASSESS GRANT (CERCLA 104)  
**Funding:**  
**Cleanup Status:** REFER: RCRA AS OF 1/2/2000  
**Cleanup Oversight Agencies:** DTSC - HAZARDOUS WASTE MANAGEMENT PROGRAM - LEAD AGENCY DTSC - SITE CLEANUP PROGRAM RWQCB 2 - SAN FRANCISCO BAY  
**School District:**  
**Past Use that Caused Contam:** LABORATORIES- UNSPECIFIED, MANUFACTURING - INDUSTRIAL MACHINERY, RESEARCH - WEAPONS

**Assembly District:** 25  
**Senate District:** 10  
**Permit Renewal Lead:**  
**Public Partici Spclst:**  
**Project Manager:**  
**County:** SANTA CLARA  
**Latitude:** 37.3526313253012  
**Longitude:** -121.92825  
**Acres:** 99 ACRES  
**Supervisor:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Potential Media Affected:** OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL  
**Potential Contaminant of Concern:**

CYANIDE (FREE) METALS PETROLEUM VOLATILE ORGANICS (8260B VOCS)

**Site History:**

The site, located to the west of San Jose Municipal Airport, was in operation from 1905 to 1996 as FMC Corporation. Research, development, and manufacturing of military tracked vehicles was conducted at the site, primarily under U.S. Department of Defense contracts from 1951 to 1996 when the facility closed. The site operated an on-site landfill (1/4-acre) from 1946 to 1979. The 1125 Coleman address consisted of two areas, the North Test Track and the Central Plant. The site is undergoing a Resource Conservation and Recovery Act (RCRA) Facility Investigation pursuant to a Corrective Action Consent Agreement (CACA), Docket HWCA FY 95/96-2002 with the Department of Toxic Substances Control (DTSC). An Interim Remedial Measures Work Plan was approved December 18, 2000 for the Central Plant area. Shallow soil samples detected total petroleum hydrocarbons (TPH) and metals (manganese, hexavalent chromium). Contaminated soil was excavated to industrial standards and disposed off-site. A groundwater investigation is also on-going at the site under DTSC oversight. Identified contaminants included volatile organic compounds (VOCs), total petroleum hydrocarbons (grease and diesel) and metals (arsenic, hexavalent chromium, and manganese). A dual phase extraction (DPE) system, with approximately 80 wells, has been installed. It treats the soil vapor and groundwater with granular-activated carbon units. The treated water is discharged under a NPDES permit.

**Status:** REFER: RCRA  
**Program Type:** EVALUATION  
**CalEnviroScreen Score:** 66-70%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=43330027](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=43330027)

**Completed Activities**

**Title:** Site Screening  
**Title Link:**  
**Area Name:**  
**Area Link:**  
**Sub Area:**  
**Sub Area Link:**  
**Document Type:** Site Screening  
**Date Completed:** 4/24/1987  
**Comments:** SITE SCREENING DONE

<a href="#">66</a>	1 of 1	ENE	0.70 / 3,710.64	59.15 / -16	FMC Corporation SAN JOSE CA	FUDS
--------------------	--------	-----	--------------------	----------------	--------------------------------	------

**FUDS Property No:** J09CA1123  
**EMS Map Link:** <https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=57503>  
**FUDS INST ID:** CA99799F727800  
**Status:** Properties without projects  
**SDS ID:**  
**NPL Status Code:** Not on the NPL  
**Eligibility:** Ineligible  
**Site Eligib:**  
**Current Owner:**  
**Has Project:** No  
**DOD FUDS Pro:**  
**Project Required:** No  
**No Further Action:**  
**Congressional District:** 19  
**EPA Region:** 09  
**County:** SANTA CLARA  
**Latitude:** 37.35111111  
**Longitude:** -121.92583333  
**Fiscal year:** 2019  
**USACE Division:** SPD  
**USACE District:** Sacramento District (SPK)  
**Shape Area:**  
**Shape Len:**  
**Centroid Latitude:**  
**Centroid Longitude:**  
**Media ID:**  
**Metadata ID:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Feature Desc:**

**Property History:** According to the Inventory Project Report (INPR) prepared by the Earth Technology Corporation for the United States Army Corps of Engineers (USACE), Sacramento District, dated October 1990, the Food Machinery and Chemical Corporation (FMCC) purchased the

<a href="#">67</a>	1 of 4	NE	0.72 / 3,795.50	57.29 / -18	FMC CORPORATION 1125 COLEMAN AVENUE SAN JOSE CA 951030000	ENVIROSTOR
--------------------	--------	----	--------------------	----------------	---	------------

<b>Estor/EPA ID:</b>	CAD077184745	<b>Assembly District:</b>	25
<b>Site Code:</b>	520019	<b>Senate District:</b>	10
<b>Nat Priority List:</b>		<b>Permit Renewal Lead:</b>	
<b>APN:</b>		<b>Public Partici Spclst:</b>	
<b>Census Tract:</b>	6085505100	<b>Project Manager:</b>	
<b>Site Type:</b>	CLOSED	<b>County:</b>	SANTA CLARA
<b>Address Description:</b>	1125 COLEMAN AVENUE	<b>Latitude:</b>	37.354374
<b>Office:</b>		<b>Longitude:</b>	-121.929014
<b>Special Program:</b>		<b>Acres:</b>	
<b>Funding:</b>		<b>Supervisor:</b>	
<b>Cleanup Status:</b>			
<b>Cleanup Oversight Agencies:</b>			
<b>School District:</b>			
<b>Past Use that Caused Contam:</b>			
<b>Potential Media Affected:</b>			
<b>Potential Contamin of Concern:</b>			

**Site History:**

<b>Status:</b>	NO ACTION
<b>Program Type:</b>	INSPECTION
<b>CalEnviroScreen Score:</b>	66-70%
<b>Summary Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=CAD077184745">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=CAD077184745</a>
<b>Status:</b>	CLOSED - LAND USE RESTRICTIONS
<b>Program Type:</b>	HAZ WASTE
<b>CalEnviroScreen Score:</b>	66-70%
<b>Summary Link:</b>	<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=CAD077184745">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=CAD077184745</a>

**Land Use Restrictions**

<b>Site Management Requirements:</b>	NONE SPECIFIED
<b>Title:</b>	
<b>Title Link:</b>	
<b>Date Recorded:</b>	6/1/1998
<b>Site Management Requirements:</b>	NONE SPECIFIED
<b>Title:</b>	
<b>Title Link:</b>	
<b>Date Recorded:</b>	5/31/2007

**Permit Units - Completed Activities**

<b>Date:</b>	2/26/1986
<b>Event Description:</b>	NEW OPERATING PERMIT - APPLICATION PART B RECEIVED
<b>Unit:</b>	
<b>Doc Link:</b>	
<b>Unit Link:</b>	
<b>Date:</b>	4/1/1993
<b>Event Description:</b>	NEW OPERATING PERMIT - FINAL PERMIT - WITHDRAWAL REQUEST RECEIVED
<b>Unit:</b>	
<b>Doc Link:</b>	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

**Unit Link:**

**Date:** 6/15/1992  
**Event Description:** NEW OPERATING PERMIT - APPLICATION PART A RECEIVED  
**Unit:**  
**Doc Link:**  
**Unit Link:**

**Units Undergoing Closure**

**Date:** 11/27/1996  
**Event Description:** CLOSURE FINAL - ISSUE CLOSURE VERIFICATION  
**Unit:** MULTIPLE UNITS  
**Doc Link:** [https://www.envirostor.dtsc.ca.gov/public/https://www.hwmpenvirostor.dtsc.ca.gov/public/site\\_documents/1143476188/FMC%5FTestTrack%5FClosureCertApprovEntireSite%5F112796%2Epdf](https://www.envirostor.dtsc.ca.gov/public/https://www.hwmpenvirostor.dtsc.ca.gov/public/site_documents/1143476188/FMC%5FTestTrack%5FClosureCertApprovEntireSite%5F112796%2Epdf)

**Permit Maintenance - Completed Activities**

**Title:** Annual 2018 Groundwater Monitoring Report  
**Title Link:**  
**Document Type:** MONITORING REPORT - GROUNDWATER  
**Date Completed:** 3/29/2019

**Title:** Annual 2018 Groundwater Monitoring Report - North Test Track Area  
**Title Link:**  
**Document Type:** MONITORING REPORT - GROUNDWATER  
**Date Completed:** 5/2/2019

**Title:** Ammended LUC for the FMC Corp dated 5/31/2007.  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/hwmp\\_final\\_documents?cmd=radocuments&global\\_id=CAD077184745&enforcement\\_id=60001410](https://www.envirostor.dtsc.ca.gov/public/hwmp_final_documents?cmd=radocuments&global_id=CAD077184745&enforcement_id=60001410)  
**Document Type:** DEED RESTRICTION / LUC ISSUED  
**Date Completed:** 5/31/2007

**Title:** LUC1 for the FMC Corp dated 6/1/1998  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/hwmp\\_final\\_documents?cmd=radocuments&global\\_id=CAD077184745&enforcement\\_id=60001409](https://www.envirostor.dtsc.ca.gov/public/hwmp_final_documents?cmd=radocuments&global_id=CAD077184745&enforcement_id=60001409)  
**Document Type:** DEED RESTRICTION / LUC ISSUED  
**Date Completed:** 6/1/1998

<a href="#">67</a>	2 of 4	NE	0.72 / 3,795.50	57.29 / -18	FMC 1125 COLEMAN AVENUE SAN JOSE CA 951030000	ENVIROSTOR
--------------------	--------	----	--------------------	----------------	---	------------

<b>Estor/EPA ID:</b> 80001683	<b>Assembly District:</b> 25
<b>Site Code:</b> 520019, 202214	<b>Senate District:</b> 10
<b>Nat Priority List:</b> NO	<b>Permit Renewal Lead:</b>
<b>APN:</b> 23022006, 23022008, 23046055, 23046059, 23046062, 23046063, 23057001, 23057002	<b>Public Partici Spclst:</b>
<b>Census Tract:</b> 6085505100	<b>Project Manager:</b> ARTHUR MACHADO
<b>Site Type:</b> CORRECTIVE ACTION	<b>County:</b> SANTA CLARA
<b>Address Description:</b> 1125 COLEMAN AVENUE	<b>Latitude:</b> 37.354374
<b>Office:</b> CLEANUP BERKELEY	<b>Longitude:</b> -121.929014
<b>Special Program:</b>	<b>Acres:</b> 99 ACRES
<b>Funding:</b>	<b>Supervisor:</b> WHITNEY SMITH
<b>Cleanup Status:</b> ACTIVE AS OF 11/8/2006	
<b>Cleanup Oversight Agencies:</b> DTSC - HAZARDOUS WASTE MANAGEMENT PROGRAM - LEAD AGENCY	
<b>School District:</b>	
<b>Past Use that Caused Contam:</b> DEGREASING FACILITY, FUEL - VEHICLE STORAGE/ REFUELING, HAZARDOUS WASTE STORAGE - TANKS/CONTAINERS, MACHINE SHOP, MAINTENANCE / CLEANING, MANUFACTURING - INDUSTRIAL MACHINERY, METAL FINISHING	
<b>Potential Media Affected:</b> OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER)	
<b>Potential Contamin of Concern:</b>	

1,1,1-TRICHLOROETHANE (TCA) 1,4-DIOXANE TPH-MOTOR OIL TRICHLOROETHYLENE (TCE)

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

**Site History:**

FMC operated a facility at the site for the design, production, and testing of military tracked vehicles under US Department of Defense contracts from 1951 to 1997. FMC was a hazardous waste storage and treatment facility under an interim status document and the facility was certified closed in November 1996. The Site is comprised of three areas—Test Track Area (TTA), Central Plant Area (CPA), and Plant No. 7 Area—that have been investigated and remediated separately. FMC proposed the final corrective measures for the TTA and CPA in November 2001 and December 2005 Corrective Measures Study Reports, respectively. Groundwater impacted with volatile organic compounds continues to be pumped and treated by FMC. Most of the Plant No. 7 Area is a shopping complex. The San Jose Earthquakes Avaya Stadium is located in the CPA and commercial buildings are being constructed on a portion of the TTA.

**Status:** ACTIVE - LAND USE RESTRICTIONS  
**Program Type:** CORRECTIVE ACTION  
**CalEnviroScreen Score:** 66-70%  
**Summary Link:** [https://www.envirostor.dtsc.ca.gov/public/profile\\_report?global\\_id=80001683](https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683)

**Land Use Restrictions**

**Site Management Requirements:** ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL  
DAY CARE CENTER PROHIBITED  
ELDER CARE CENTER PROHIBITED  
HOSPITAL USE PROHIBITED  
LAND USE COVENANT  
MAINTAIN FENCING TO CONTROL ACCESS  
MAINTAIN MONITORING OF GROUNDWATER  
NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL  
NO OIL OR GAS EXTRACTION AT ANY DEPTH  
NOTIFY AFTER CHANGE OF PROPERTY OWNER  
NOTIFY DAMAGES TO REMEDY AND MONITORING SYSTEMS UPON DISCOVERY  
NOTIFY PRIOR TO CHANGE IN LAND USE  
NOTIFY PRIOR TO DEVELOPMENT  
PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED  
RAISING OF FOOD PROHIBITED  
RESIDENCE USE PROHIBITED

**Title:** Institutional Controls Estab-Government Control (CA772GC)  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/deliverable\\_documents/2913236320/FMC%5FTestTrack%5FLUC%5F022102%2Epdf](https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/2913236320/FMC%5FTestTrack%5FLUC%5F022102%2Epdf)  
**Date Recorded:** 2/21/2002

**Site Management Requirements:** ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL  
DAY CARE CENTER PROHIBITED  
ELDER CARE CENTER PROHIBITED  
HOSPITAL USE PROHIBITED  
LAND USE COVENANT  
MAINTAIN FENCING TO CONTROL ACCESS  
MAINTAIN MONITORING OF GROUNDWATER  
NO EXCAVATION OF CONTAMINATED SOILS WITHOUT AGENCY REVIEW AND APPROVAL  
NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL  
NO OIL OR GAS EXTRACTION AT ANY DEPTH  
NOTIFY AFTER CHANGE OF PROPERTY OWNER  
NOTIFY DAMAGES TO REMEDY AND MONITORING SYSTEMS UPON DISCOVERY  
NOTIFY PRIOR TO CHANGE IN LAND USE  
NOTIFY PRIOR TO DEVELOPMENT  
NOTIFY PRIOR TO SUBSURFACE WORK  
ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED  
PERFORM H&S PLAN PRIOR TO SUBSURFACE WORK  
PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED  
RAISING OF FOOD PROHIBITED  
RESIDENCE USE PROHIBITED

**Title:** Institutional Controls Estab-Government Control (CA772GC)  
**Title Link:** [https://www.envirostor.dtsc.ca.gov/public/final\\_documents2?cmd=radocuments&global\\_id=80001683&enforcement\\_id=6015875](https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&global_id=80001683&enforcement_id=6015875)  
**Date Recorded:** 5/31/2007

**Site Management Requirements:** DAY CARE CENTER PROHIBITED  
ELDER CARE CENTER PROHIBITED  
HOSPITAL USE PROHIBITED

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
					<p>LAND USE COVENANT  NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL  NO OIL OR GAS EXTRACTION AT ANY DEPTH  NOTIFY AFTER CHANGE OF PROPERTY OWNER  PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED  RAISING OF FOOD PROHIBITED</p> <p><b>Title:</b> Covenant to Restrict Use of Property  <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/5053883194/HWMP%5FLandUseCovenant%5FFMC%2Epdf">https://www.envirostor.dtsc.ca.gov/public/deliverable_documents/5053883194/HWMP%5FLandUseCovenant%5FFMC%2Epdf</a>  <b>Date Recorded:</b> 6/1/1998</p>	
<b><u>Currently Scheduled Activities</u></b>						
					<p><b>Area Name:</b> PROJECT WIDE  <b>Area Link:</b>  <b>Sub Area:</b>  <b>Sub Area Link:</b>  <b>Document Type:</b> Removal Action Completion Report  <b>Due Date:</b> 2/13/2022  <b>Revised Date:</b></p>	
<b><u>Future Activities</u></b>						
					<p><b>Area Name:</b> PROJECT WIDE  <b>Area Link:</b>  <b>Sub Area:</b>  <b>Sub Area Link:</b>  <b>Document Type:</b> Cleanup Complete  <b>Due Date:</b> 2050</p>	
<b><u>Completed Activities</u></b>						
					<p><b>Title:</b> 2020 Annual Groundwater Verification Monitoring Report, Central Plant Area (CPA)  <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60496838">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60496838</a>  <b>Area Name:</b>  <b>Area Link:</b>  <b>Sub Area:</b> Central Plant Area  <b>Sub Area Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>  <b>Document Type:</b> Monitoring Report  <b>Date Completed:</b> 8/17/2021  <b>Comments:</b> DTSC approves of the 2020 annual GW verification report in the CPA.</p>	
					<p><b>Title:</b> Aquifer Test Work Plan Technical Memorandum for CPA  <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60476225">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60476225</a>  <b>Area Name:</b>  <b>Area Link:</b>  <b>Sub Area:</b> Central Plant Area  <b>Sub Area Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>  <b>Document Type:</b> Other Report  <b>Date Completed:</b> 5/7/2020  <b>Comments:</b> DTSC approval of the Technical Memorandum for the Central Plant Area to address DTSC comments on the Annual Groundwater Verification Monitoring Report.</p>	
					<p><b>Title:</b> Downgradient Investigation Report  <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60413278">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60413278</a>  <b>Area Name:</b>  <b>Area Link:</b>  <b>Sub Area:</b> Central Plant Area  <b>Sub Area Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>  <b>Document Type:</b> Monitoring Report  <b>Date Completed:</b> 9/29/2017  <b>Comments:</b> The downgradient investigation was implemented to determine the extent of the volatile organic compound (VOC) plume to the north of the Central Plant Area. The groundwater samples collected from hydropunch locations at the San Jose International Airport confirmed that VOCs have migrated beyond the sentinel wells and into the Airport. Additional investigation at the Airport is not planned due to access limitation due to the Airport runways. FMC plans to continue monitoring the sentinel wells as part of their groundwater monitoring program.</p>	

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Title:</b>					Downgradient Investigation Workplan	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60399657">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60399657</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>					Central Plant Area	
<b>Sub Area Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>	
<b>Document Type:</b>					Technical Workplan	
<b>Date Completed:</b>					6/15/2016	
<b>Comments:</b>					The Work Plan for Offsite Plume Definition describes a groundwater investigation to determine the extent of the volatile organic compound plume to the north of and downgradient from the Central Plant Area of the former FMC Corporation property. The groundwater investigation will be performed on City of San Jose property within the southeastern portion of the San Jose International Airport, and is to consist of hydropunch sampling at six locations and installation of three monitoring wells.	
<b>Title:</b>					Groundwater Monitoring Report Received (CA805)	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6026391">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6026391</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>					Central Plant Area	
<b>Sub Area Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>	
<b>Document Type:</b>					Monitoring Report	
<b>Date Completed:</b>					5/15/2008	
<b>Comments:</b>					Approval of Amended Groundwater Monitoring Plan	
<b>Title:</b>					Stadium: Groundwater Use Request	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60336026">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60336026</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>					Central Plant Area	
<b>Sub Area Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>	
<b>Document Type:</b>					Technical Workplan	
<b>Date Completed:</b>					9/12/2013	
<b>Comments:</b>						
<b>Title:</b>					Work Plan Technical Memorandum for Groundwater Extraction Well Installation and Construction	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60502528">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60502528</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>					Central Plant Area	
<b>Sub Area Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>	
<b>Document Type:</b>					Technical Workplan	
<b>Date Completed:</b>					11/30/2021	
<b>Comments:</b>					Work Plan which outlines the proper measures for the installation of a groundwater extraction well within the Central Plant Area.	
<b>Title:</b>					2012 Annual Groundwater Compliance Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60318778">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60318778</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>					Test Track Area	
<b>Sub Area Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>	
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					7/8/2013	
<b>Comments:</b>						
<b>Title:</b>					2014 Annual Groundwater Compliance Monitoring Report	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60335997">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60335997</a>	
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>					Test Track Area	
<b>Sub Area Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>	
<b>Document Type:</b>					Operation and Maintenance Report	
<b>Date Completed:</b>					6/23/2015	
<b>Comments:</b>						
<b>Title:</b>					Institutional Controls Estab-Government Control (CA772GC)	
<b>Title Link:</b>					<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=6015874">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=6015874</a>	
<b>Area Name:</b>						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Land Use Restriction				
<b>Date Completed:</b>		2/21/2002				
<b>Comments:</b>		Test Track Area				
<b>Title:</b>		Operation and Maintenance Groundwater Compliance Workplan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6025616">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6025616</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Operation and Maintenance Plan				
<b>Date Completed:</b>		11/18/2002				
<b>Comments:</b>		Approval of Revised Operation & Maintenance of GW Compliance Monitoring Plan				
<b>Title:</b>		RFI REPORT APPROVED (CA200)				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6024571">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6024571</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		RFI Report				
<b>Date Completed:</b>		10/23/2001				
<b>Comments:</b>		RFI Report Approved - Test Track				
<b>Title:</b>		Review Site Safety Plan and Soil Management Plan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60189969">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60189969</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Soils Management Plan				
<b>Date Completed:</b>		4/15/2011				
<b>Comments:</b>						
<b>Title:</b>		Subsurface Site Investigation Report Coleman Highline Tranche 2 (Frisbee Way Property)				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60461929">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60461929</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Technical Report				
<b>Date Completed:</b>		7/25/2019				
<b>Comments:</b>		DTSC contingent approval of Report				
<b>Title:</b>		Work Notice: Coleman Highline Development				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60381350">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60381350</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Work Notice				
<b>Date Completed:</b>		9/19/2014				
<b>Comments:</b>		Work Notice mailed on Sept 19, 2014 informing neighboring area of construction activities on the former Test Track Area. Soil Management Plan will be implemented during the construction.				
<b>Title:</b>		Annual Oversight Cost Estimate FY 21/22				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60507781">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60507781</a>				
<b>Area Name:</b>		PROJECT WIDE				
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Annual Oversight Cost Estimate				
<b>Date Completed:</b>		9/17/2021				
<b>Comments:</b>						
<b>Title:</b>		Historical Well Abandonment Methods				

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Title Link:</b>						
<b>Area Name:</b>		PROJECT WIDE				
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Correspondence				
<b>Date Completed:</b>		7/7/2015				
<b>Comments:</b>						
<b>Title:</b>		NPDES Report, Test Track Area, 1st Quarter 2011				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60271558">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60271558</a>				
<b>Area Name:</b>		PROJECT WIDE				
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/27/2011				
<b>Comments:</b>		Document reviewed and accepted. DTSC does not provide comments on NPDES report.				
<b>Title:</b>		Monitoring Well Modification Workplan				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60334199">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60334199</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Technical Workplan				
<b>Date Completed:</b>		9/5/2013				
<b>Comments:</b>						
<b>Title:</b>		NPDES Report, Central Plant Area, 2st Quarter 2012				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60305744">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60305744</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		8/6/2012				
<b>Comments:</b>		Document received.				
<b>Title:</b>		NPDES Report, Central Plant, 1st Quarter 2011				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60266663">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60266663</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		5/2/2011				
<b>Comments:</b>		The Report was submitted in accordance with the Regional Water Quality Control Board NPDES permit. No DTSC comment was required.				
<b>Title:</b>		PA OR CERCLA INSPECTION-NOT A PA PLUS (CA049PA)				
<b>Title Link:</b>						
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Preliminary Assessment Report				
<b>Date Completed:</b>		6/29/1990				
<b>Comments:</b>						
<b>Title:</b>		Work Notice for San Jose Earthquakes Stadium				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60318774">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60318774</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Work Notice				
<b>Date Completed:</b>		3/22/2013				
<b>Comments:</b>		The Work Notice notified the community of initial phase of work that would be occurring in the Central Plant Area				

<b>Map Key</b>	<b>Number of Records</b>	<b>Direction</b>	<b>Distance (mi/ft)</b>	<b>Elev/Diff (ft)</b>	<b>Site</b>	<b>DB</b>
					as part of the construction of the San Jose Earthquakes soccer stadium.	
					<b>Title:</b> Landscape and Utility Trench Soil Sampling Summary - Phase 1 of the Coleman Highline Development <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60424940">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60424940</a> <b>Area Name:</b> <b>Area Link:</b> <b>Sub Area:</b> Test Track Area <b>Sub Area Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a> <b>Document Type:</b> Phase 1 <b>Date Completed:</b> 3/20/2017 <b>Comments:</b>	
					<b>Title:</b> Well Abandonment and Installation Workplan <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60405133">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60405133</a> <b>Area Name:</b> <b>Area Link:</b> <b>Sub Area:</b> Test Track Area <b>Sub Area Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a> <b>Document Type:</b> Technical Workplan <b>Date Completed:</b> 3/16/2016 <b>Comments:</b>	
					<b>Title:</b> 2009 LUC site inspection <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60188094">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60188094</a> <b>Area Name:</b> PROJECT WIDE <b>Area Link:</b> <b>Sub Area:</b> <b>Sub Area Link:</b> <b>Document Type:</b> Land Use Restriction - Site Inspection/Visit <b>Date Completed:</b> 1/20/2010 <b>Comments:</b>	
					<b>Title:</b> Annual Cost Estimate 2011-2012 <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60287493">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60287493</a> <b>Area Name:</b> PROJECT WIDE <b>Area Link:</b> <b>Sub Area:</b> <b>Sub Area Link:</b> <b>Document Type:</b> Annual Oversight Cost Estimate <b>Date Completed:</b> 12/14/2011 <b>Comments:</b>	
					<b>Title:</b> Annual Oversight Cost Estimate <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60431128">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60431128</a> <b>Area Name:</b> PROJECT WIDE <b>Area Link:</b> <b>Sub Area:</b> <b>Sub Area Link:</b> <b>Document Type:</b> Annual Oversight Cost Estimate <b>Date Completed:</b> 9/14/2017 <b>Comments:</b> DTSC letter with oversight cost estimate for project activities for fiscal year 2017/2018.	
					<b>Title:</b> Annual Oversight Cost Estimate FY19/20 <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60472899">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60472899</a> <b>Area Name:</b> PROJECT WIDE <b>Area Link:</b> <b>Sub Area:</b> <b>Sub Area Link:</b> <b>Document Type:</b> Annual Oversight Cost Estimate <b>Date Completed:</b> 12/12/2019 <b>Comments:</b>	
					<b>Title:</b> GPRA: Ready for Anticipated Use - Yes <b>Title Link:</b> <a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60458387">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=60458387</a> <b>Area Name:</b> PROJECT WIDE <b>Area Link:</b> <b>Sub Area:</b> <b>Sub Area Link:</b> <b>Document Type:</b> Ready for Anticipated Use	

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
<b>Date Completed:</b>		3/29/2018				
<b>Comments:</b>		RAU completed 3/29/2018.				
<b>Title:</b>		NPDES Report, Central Plant Area, 3rd Quarter 2010				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60257577">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60257577</a>				
<b>Area Name:</b>		PROJECT WIDE				
<b>Area Link:</b>						
<b>Sub Area:</b>						
<b>Sub Area Link:</b>						
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		11/2/2010				
<b>Comments:</b>						
<b>Title:</b>		2009 Groundwater Verification Monitoring Report, Central Plant Area				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6027477">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6027477</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		6/3/2010				
<b>Comments:</b>		comments sent. Report accept. Change in pump type recommended.				
<b>Title:</b>		Annual Groundwater Compliance Monitoring Report				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60335998">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60335998</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Operation and Maintenance Report				
<b>Date Completed:</b>		7/12/2016				
<b>Comments:</b>		The 2015 Annual Groundwater Compliance Monitoring Report describes and presents the results of groundwater monitoring performed at the Test Track Area from January through December 2015. Semi-annual groundwater sampling events occurred in April and October 2015.				
<b>Title:</b>		DTE FOR PUBLIC NOTICE ON PROPOSED REMEDY (CA380)				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6025695">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=6025695</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Test Track Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008875</a>				
<b>Document Type:</b>		Public Notice				
<b>Date Completed:</b>		11/13/2001				
<b>Comments:</b>		Fact Sheet for Remedy Selection, Test Track Area				
<b>Title:</b>		Incident Report for Accidental Release and GW Treatment System Shutdown				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60375380">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60375380</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Other Report				
<b>Date Completed:</b>		8/11/2014				
<b>Comments:</b>						
<b>Title:</b>		Institutional Controls Estab-Government Control (CA772GC)				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=6015875">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;enforcement_id=6015875</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						
<b>Sub Area:</b>		Central Plant Area				
<b>Sub Area Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874">https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001683&amp;site_id=2008874</a>				
<b>Document Type:</b>		Land Use Restriction				
<b>Date Completed:</b>		5/31/2007				
<b>Comments:</b>		Land Use Covenants filed with Santa Clara County				
<b>Title:</b>		NPDES Report, Central Plant, 4th Quarter 2010				
<b>Title Link:</b>		<a href="https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60261886">https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001683&amp;doc_id=60261886</a>				
<b>Area Name:</b>						
<b>Area Link:</b>						